



**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
LARGE AIRCRAFT**

BIWEEKLY 2002-01

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Delegation and Airworthiness Programs Branch, AIR-140
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-4104

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2002-01

2001-23-12	R1	SAAB Aircraft	SAAB SF340A Series and SAAB 340B Series
2001-23-15	C, S 01-05-05	Boeing	747 Series
2001-24-25	COR	McDonnell Douglas	DC-9-10, -20, -30, -40 Series; and C-9
2001-24-27	C, S 96-02-05	McDonnell Douglas	DC-9-10, -20, -30, -40, -50 Series; DC-9-81, -82, -83, -87 Series; MD-88; and C-9 Series
2001-25-11	S 01-15-12 & 99-17-16	Pratt and Whitney	Engine: PW4050, PW4052, PW4056, PW4060, PW4060A, PW4060C, PW4062, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, and PW4650
2001-26-11	S 00-24-26	Rolls-Royce	Engine: RB211 Trent 875, RB211 Trent 877, RB211 Trent 884, RB211 Trent 892, and RB211 Trent 892B Series
2001-26-12	S 01-12-05	Boeing	747-100, 747-200, 747-300, and 747SR Series
2001-26-14	S 96-12-13	Dornier Luftfahrt	328-100
2001-26-15		McDonnell Douglas	DC-9-81, -82, -83, -87; and MD-88
2001-26-16		McDonnell Douglas	DC-9-81, -82, -83, -87 Series; and MD-88
2001-26-17		Airbus Industrie	A330-202, -223, -243, -301, -321, -322, -323, -341, -342, and -343 Series
2001-26-18		Dornier Luftfahrt	328-300 Series
2001-26-19		Boeing	767 Series
2001-26-20		Airbus Industrie	A319, A320, and A321 Series
2001-26-21		Airbus Industrie	A319, A320, and A321 Series
2001-26-22		BAE Systems Limited	Avro 146-RJ Series
2001-26-23		Bombardier	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2001-26-24		McDonnell Douglas	DC-9-10, -20, -30, -40, -50 Series; and C-9
2001-26-51	FR	Bombardier	CL-600-2B19 Series
2002-01-03		GE Aircraft	Engine: CT7-5A2, -5A3, -7A, and -7A1

BW 2002-01

**SAAB AIRCRAFT AB
AIRWORTHINESS DIRECTIVE
REVISION
LARGE AIRCRAFT**

2001-23-12 R1 Saab Aircraft AB: Amendment 39-12576. Docket 2001-NM-91-AD. Revises AD 2001-23-12, Amendment 39-12511.

Applicability: Model SAAB SF340A series airplanes having serial numbers -004 through -159 inclusive, and SAAB 340B series airplanes having serial numbers -160 through -459 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct damage to the aluminum skin of the airplane, which could result in a weakening of the structure of the airplane, accomplish the following:

Review of Records

(a) Within 2,000 flight hours or 1 year after December 31, 2001 (the effective date of AD 2001-23-12, amendment 39-12511), whichever occurs first: Perform a review of records to determine whether an airplane subject to this AD has been repainted since its delivery from the factory. If the airplane has not been repainted, no further action is needed.

Inspection and Corrective Action

(b) If an airplane has been repainted since its delivery from the factory: Within 2,000 flight hours or 1 year after December 31, 2001, whichever occurs first, perform chemical stripping of local areas of the skin and inspection to detect damage to (or removal of) the protective coat of bonding primer, in accordance with Saab Service Bulletin 340-51-020, Revision 01, dated May 16, 2001.

(1) If no damage to the protective coat of bonding primer is detected: Prior to further flight, repaint the stripped areas, in accordance with the service bulletin.

(2) If damage to (or removal of) the protective coat of bonding primer is detected: Prior to further flight, perform additional chemical stripping and inspection of the skin for pitting corrosion, in accordance with the service bulletin.

(i) If pitting corrosion is detected: Perform corrective action in a manner and within a compliance time approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, or the Luftfartsverket (or its designated agent).

(ii) If no pitting corrosion is detected: Prior to further flight, measure the thickness of the skin of the airplane, in accordance with the service bulletin.

(A) If a reduction in skin thickness is detected: Perform corrective action in a manner and within a compliance time approved by the Manager, International Branch, ANM-116, or the Luftfartsverket (or its designated agent).

(B) If no reduction in skin thickness is detected: Prior to further flight, check records to determine whether the airplane was repainted using an approved paint system. For purposes of this AD, criteria for an "approved" paint system are found in section 51-20-43 of the Saab 340 Structural Repair Manual.

(1) If the airplane was repainted using an approved paint system: Prior to further flight, repaint the stripped areas of the airplane, in accordance with the service bulletin.

(2) If the airplane was repainted using an unapproved paint system: Prior to further flight, repaint the stripped areas in accordance with the service bulletin; and within 4,000 flight hours or 2 years after detection of the damage or removed protective coating, whichever occurs first, chemically strip and repaint the airplane as specified by and in accordance with the service bulletin.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) Except as required by paragraphs (a), (b)(2)(i), and (b)(2)(ii)(A) of this AD: The actions shall be done in accordance with Saab Service Bulletin 340-51-020, Revision 01, dated May 16, 2001. This incorporation by reference was approved previously by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51 as of December 31, 2001 (66 FR 58927, November 26, 2001). Copies may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Swedish airworthiness directive SAD 1-161R2, dated March 13, 2001.

Effective Date

(f) The effective date of this amendment remains December 31, 2001.

Issued in Renton, Washington, on December 20, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-85 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1149.

BW 2002-01

BOEING AIRWORTHINESS DIRECTIVE CORRECTION LARGE AIRCRAFT

2001-23-15 Boeing: Amendment 39-12514. Docket 2001-NM-02-AD. Supersedes AD 2001-05-05, amendment 39-12141.

Applicability: Model 747 series airplanes, line numbers 1 through 1046 that have accomplished Airworthiness Directives 95-10-16, 95-13-05, 95-13-06, or 95-13-07; and line numbers 1047 through 1271 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To find and fix discrepancies of the installation of the midspar fuse pins of the inboard and outboard strut, which could result in loss of the secondary retention capability of the fuse pins, migration of the fuse pins, and consequent loss of the strut and engine from the airplane; accomplish the following:

Restatement of the Requirements of AD 2001-05-05

Inspections/Follow-On Actions

(a) At the time specified in paragraph (a)(1) or (a)(2) of this AD, as applicable: Do a detailed visual inspection to find discrepancies (e.g., incorrect thread protrusion, which is less than two threads protruding from the nut between the nut and the secondary retention washer; incorrect gap between the fuse pin primary nut and secondary retention washer; cracked or broken torque stripe) of the installation of the midspar fuse pins of the inboard and outboard struts, per Figure 2 of Boeing Service Bulletin 747-54A2206, Revision 1, dated February 22, 2001, or Revision 2, dated May 17, 2001.

(1) For airplanes having the production equivalent of one of the AD's listed in Table 1 of this AD: Do the inspection at the later of the times specified in paragraphs (a)(1)(i) and (a)(1)(ii) of this AD.

(i) Before the accumulation of 8,000 total flight hours, or within 24 months since manufacture of the airplane, whichever occurs first.

(ii) Within 90 days after March 21, 2001 (the effective date of AD 2001-05-05, amendment 39-12141).

(2) For airplanes modified per one of the AD's listed in Table 1 of this AD: Do the inspection at the later of the times specified in paragraphs (a)(2)(i) and (a)(2)(ii) of this AD. Table 1 follows:

Table 1	
AD number	Amendment number
AD 95-10-16.....	39-9233
AD 95-13-05.....	39-9285
AD 95-13-06.....	39-9286
AD 95-13-07.....	39-9287

- (i) Within 8,000 flight hours or 24 months after the modification, whichever occurs first.
- (ii) Within 90 days after March 21, 2001.

Note 2: Where there are differences between the AD and the service bulletin, the AD prevails.

Note 3: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(A) If no discrepancy is found: Repeat the inspection at intervals not to exceed 8,000 flight hours or 24 months, whichever occurs first, until you do the terminating modification specified in paragraph (b) of this AD.

(B) If any discrepancy is found, and the primary nut has backed off and contacts the secondary retention washer: Before further flight, do the terminating modification specified in paragraph (b) of this AD.

(C) If any discrepancy is found, and the primary nut does not contact the secondary retention washer: Repeat the inspection at intervals not to exceed 90 days. Within 18 months after the initial finding, or before March 21, 2001, whichever occurs later, do the terminating modification specified in paragraph (b) of this AD.

Note 4: Inspections done prior to the effective date of this AD per Boeing Alert Service Bulletin 747-54A2206, dated October 19, 2000, are acceptable for compliance with the inspections required by paragraph (a) of this AD.

New Requirements of this AD

Terminating Action

(b) Within 6 years after the effective date of this AD: Do the terminating modification (replacement of the primary nut of the midspar fuse pin, installation of torque strip, a detailed visual inspection of the fuse pin threads for damage, and replacement, if necessary) per Figure 3 of Boeing Service Bulletin 747-54A2206, Revision 1, dated February 22, 2001, or Figure 3 of Boeing Service Bulletin 747-54A2206, Revision 2, dated May 17, 2001. Doing this modification ends the repetitive inspections required by this AD.

Note 5: Doing the terminating modification prior to the effective date of this AD per Boeing Alert Service Bulletin 747-54A2206, dated October 19, 2000, is acceptable for compliance with the terminating action required by paragraph (b) of this AD.

Alternative Methods of Compliance

(c) (1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(2) Any alternative method of compliance which was approved previously in accordance with AD 2001-05-05 is approved for compliance with this AD.

Note 6: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Boeing Service Bulletin 747-54A2206, Revision 1, dated February 22, 2001; or Boeing Service Bulletin 747-54A2206, Revision 2, dated May 17, 2001.

(1) The incorporation by reference of Boeing Service Bulletin 747-54A2206, Revision 2, dated May 17, 2001, was approved previously by the Director of the Federal Register, as of December 31, 2001 (66 FR 58913, November 26, 2001).

(2) The incorporation by reference of Boeing Service Bulletin 747-54A2206, Revision 1, dated February 22, 2001, was approved previously by the Director of the Federal Register as of March 21, 2001 (66 FR 13424, March 6, 2001).

(3) Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on December 31, 2001.

Issued in Renton, Washington, on December 20, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-84 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Tamara Anderson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2771; fax (425) 227-1181.

BW 2002-01

MCDONNELL DOUGLAS AIRWORTHINESS DIRECTIVE CORRECTION LARGE AIRCRAFT

2001-24-25 McDonnell Douglas: Amendment 39-12542. Docket 2001-NM-104-AD.

Applicability: Model DC-9-10, -20, -30, and -40 series airplanes, and C-9 airplanes, as listed in Boeing Alert Service Bulletin DC9-27A147, Revision 03, dated May 8, 2001; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent smoke/fire in the flight compartment in the event that the automatic spoiler actuator overheats, and/or loss of the spoiler control system, which could significantly reduce the braking effectiveness of the airplane; accomplish the following:

Modification of the Spoiler Control System

(a) Within 18 months after the effective date of this AD, modify the spoiler control system by accomplishing all actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin DC9-27A147, Revision 03, dated May 8, 2001, per the service bulletin.

Note 2: Modification per McDonnell Douglas Service Bulletin DC9-27-147, dated January 7, 1972; Revision 1, dated July 30, 1974; or Revision 2, dated May 9, 1975; before the effective date of this AD; is considered acceptable for compliance with paragraph (a) of this AD.

Installation of Protective Interlock Box Assemblies

(b) Prior to or in conjunction with the requirements of paragraph (a) of this AD, install protective interlock box assemblies in the spoiler circuit, per McDonnell Douglas DC-9 Service Bulletin 27-103, dated March 19, 1968.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permit

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Boeing Alert Service Bulletin DC9-27A147, Revision 03, dated May 8, 2001, and McDonnell Douglas DC-9 Service Bulletin 27-103, dated March 19, 1968; as applicable. This incorporation by reference was approved previously by the Director of the Federal Register as of January 16, 2002 (66 FR 64114, December 12, 2001). Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) The effective date of this amendment remains January 16, 2002.

Issued in Renton, Washington, on December 20, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-86 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Elvin Wheeler, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5344; fax (562) 627-5210.

BW 2002-01

MCDONNELL DOUGLAS AIRWORTHINESS DIRECTIVE CORRECTION LARGE AIRCRAFT

2001-24-27 McDonnell Douglas: Amendment 39-12544. Docket 2001-NM-206-AD. Supersedes AD 96-02-05, Amendment 39-9493.

Applicability: Model DC-9-10, -20, -30, -40, and -50 series airplanes; Model DC-9-81, -82, -83, and -87 series airplanes; Model MD-88 airplanes; and C-9 series airplanes; as listed in McDonnell Douglas Service Bulletin DC9-27-325R02, Revision 02, dated December 12, 1995; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of rudder pedals control and reduction of braking capability, accomplish the following:

Restatement of Requirements of AD 96-02-05

Repetitive Inspections and Replacement, If Necessary

(a) For airplanes listed in McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 1, dated February 3, 1992: Prior to the accumulation of 15,000 landings or within 270 days after January 22, 1993 (the effective date of AD 92-27-07, amendment 39-8441), whichever occurs later, conduct a visual and eddy current inspection to detect cracks of the rudder pedals adjuster hub assembly, part number 4616066, in accordance with McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 1, dated February 3, 1992, or Revision 2, dated January 27, 1995.

(1) If no cracks are detected as a result of the inspections required by this paragraph, repeat the inspections at intervals not to exceed 3,500 landings.

(2) If cracks are detected as a result of the inspections required by this paragraph, prior to further flight, replace the rudder pedal adjuster hub assembly, part number 4616066, with a new assembly having the same part number, in accordance with McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 2, dated January 27, 1995. Thereafter, conduct visual and eddy current inspections of the replacement rudder pedals adjuster hub assembly in accordance with this paragraph.

(b) For airplanes listed in McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 2, dated January 27, 1995, and not subject to paragraph (a) of this AD: Prior to the accumulation of 15,000 landings or within 270 days after March 25, 1996 (the effective date of AD 96-02-05, amendment 39-9493), whichever occurs later, conduct a visual and eddy current inspection to detect cracks of the rudder pedals adjuster hub assembly, part number 4616066, in accordance with McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 1, dated February 3, 1992, or Revision 2, dated January 27, 1995.

(1) If no cracks are detected as a result of the inspections required by this paragraph, repeat the inspections at intervals not to exceed 3,500 landings.

(2) If cracks are detected as a result of the inspections required by this paragraph, prior to further flight, replace the rudder pedals adjuster hub assembly, part number 4616066, with a new assembly having the same part number, in accordance with McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 2, dated January 27, 1995. Thereafter, conduct visual and eddy current inspections of the replacement rudder pedals adjuster hub assembly in accordance with this paragraph.

New Actions Required By This AD

Replacement and Reidentification

(c) Prior to the accumulation of 15,000 total landings, or within 18 months after the effective date of this AD, whichever occurs later, do the actions specified in paragraphs (c)(1) and (c)(2) of this AD in accordance with the Accomplishment Instructions of McDonnell Douglas Service Bulletin DC9-27-325R02, Revision 02, dated December 12, 1995. Accomplishment of these actions constitutes terminating action for the requirements of this AD.

(1) Replace the existing magnesium casting hub assembly of the rudder pedal adjuster, part number (P/N) 4616066-3, and bearing, P/N AN201KP4A, in the rudder pedal mechanism between stations X=69.000 and X=120.000 in the flight compartment with a new aluminum assembly, part number (P/N) 5965435-3, and new bearing, P/N MS27641-4; and

(2) Reidentify rudder pedal adjuster, P/N 5641294-501 or -503, as P/N 5641294-507.

Note 2: Installation of the aluminum rudder pedal adjuster hub assembly per McDonnell Douglas Service Bulletin DC9-27-325, Revision 1, dated November 30, 1994, before the effective date of this AD, is considered acceptable for the requirements of paragraph (c) of this AD.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) The actions shall be done in accordance with McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 1, dated February 3, 1992; McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 2, dated January 27, 1995; or McDonnell Douglas Service Bulletin DC9-27-325R02, Revision 02, dated December 12, 1995; as applicable.

(1) The incorporation by reference of McDonnell Douglas Service Bulletin DC9-27-325R02, Revision 02, dated December 12, 1995, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 2, dated January 27, 1995, was approved previously by the Director of the Federal Register as of March 25, 1996 (61 FR 6922, February 23, 1996).

(3) The incorporation by reference of McDonnell Douglas DC-9 Alert Service Bulletin A27-325, Revision 1, dated February 3, 1992, was approved previously by the Director of the Federal Register as of January 22, 1993 (57 FR 60116, December 18, 1992).

(4) Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(g) This amendment becomes effective on January 16, 2002.

Issued in Renton, Washington, on November 28, 2001.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-30203 Filed 12-11-01; 8:45 am]

BILLING CODE 4910-13-P

FOR FURTHER INFORMATION CONTACT: Wahib Mina, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (562) 627-5324; fax (562) 627-5210.

BW 2002-01

**PRATT & WHITNEY
AIRWORTHINESS DIRECTIVE
ENGINE
LARGE AIRCRAFT**

2001-25-11 Pratt and Whitney: Amendment 39-12564. Docket No. 2000-NE-47-AD. Supersedes Amendment 39-12346, and Amendment 39-11263.

Applicability: This airworthiness directive (AD) is applicable to Pratt and Whitney (PW) model PW4050, PW4052, PW4056, PW4060, PW4060A, PW4060C, PW4062, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, and PW4650 turbofan engines. These engines are installed on, but not limited to, certain models of Airbus Industrie A300, Airbus Industrie A310, Boeing 747, Boeing 767, and McDonnell Douglas MD-11 series airplanes.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (o) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Compliance with this AD is required as indicated, unless already done.

To prevent engine power losses due to high pressure compressor (HPC) surge, do the following:

(a) When complying with this AD, determine the configuration and category of each engine on each airplane as follows:

(1) Use the following table 1 to determine the configuration of the engine:

Table 1.--Engine Configuration Listing		
Configuration	Configuration designator	Description
(i) Phase 1 without high pressure turbine (HPT) 1st turbine vane cut back (1TVCB).	A	Engines that did not incorporate the Phase 3 configuration at the time they were originally manufactured, or have not been converted to Phase 3 configuration; and have not incorporated HPT1TVCB using any revision of SB PW4ENG 72-514.
(ii) Phase 1 with 1TVCB.....	B	Same as configuration (1) except that HPT1TVCB has been incorporated using any revision of SB PW4ENG 72-514.

(iii) Phase 3, 2nd Run.....	C	Engines that incorporated the Phase 3 configuration at the time they were originally manufactured, or have been converted to the Phase 3 configuration during service; and that have had at least one HPC overhaul since new.
(iv) Phase 3, 1st Run.....	D	Same as configuration (3) except that that the engine has not had an HPC overhaul since new.
(v) HPC Cutback Stator Configuration Engines.	E	Engines that currently incorporate any revision of SB's PW4ENG72-706, PW4ENG72-704, or PW4ENG72-711
(vi) Engines that have passed Testing-21.	F	Engines which have successfully passed Testing-21 performed in accordance with paragraph (h)(1) of this AD. Once an engine has passed a Testing-21, it will remain a Configuration F engine until the HPC is overhauled, or is replaced with a new or overhauled HPC.

(2) Use the following Table 2 to determine the category of Airbus engines:

Table 2.--Airbus Airplane Engine Category Listing

Engine model	Category	Engine serial number (SN)
(i) PW4156, PW4156A, and PW4158 engines.	1	717201, 717205, 717702, 717703, 717710, 717752, 717788, 717798, 717799, 724023, 724026, 724027, 724033, 724034, 724036, 724037, 724040, 724041, 724044, 724045, 724048, 724049, 724050, 724051, 724052, 724055, 724056, 724059, 724061, 724062, 724063, 724065, 724067, 724073, 724074, 724075, 724079, 724088, 724089, 724090, 724091, 724094, 724095, 724551, 724552, 724555, 724556, 724557, 724558, 724561, 724562, 724563, 724564, 724567, 724568, 724569, 724570, 724571, 724572, 724573, 724574, 724575, 724576, 724577, 724578, 724640, 724806, 724807, 724808, 724809, 724811, 724820, 724821, 724827, 724833, 724835, 724836, 724840, 724841, 724848, 724849, 724855, 724857, 724858, 724861, 724862, 724865, 724866, 724868, 724909, 724910, 724913, 724914, 724924, 724925, 724926, 724927, 727912, 728519, 728520, 728521, 728522, 728523, 728524, 728525, 728526, 728527, 728528, 728534, 728535, 728536, 728537, 728538, 728539, 728540, 728541, 728542, 728543, 728544, 728545, 728546, 728547, 728548, 728549, 728550, 728551, 728552, 728553, 728554, 728557, 728558, 728559, 728560, 728561, 728562, 728563, 728564.

(ii) PW4158 engines.....	2	717704, 724001, 724002, 724004, 724005, 724006, 724007, 724008, 724009, 724010, 724011, 724019, 724020, 724031, 724035, 724038, 724039, 724042, 724043, 724047, 724068, 724069, 724071, 724076, 724077, 724080, 724085, 724086, 724087, 724092, 724093, 724096, 724097, 724801, 724802, 724803, 724804, 724805, 724813, 724814, 724819, 724823, 724824, 724825, 724826, 724828, 724831, 724832, 724843, 724846, 724847, 724851, 724852, 724853, 724854, 724859, 724860, 724863, 724864, 724867, 724869, 724870, 724871, 724872, 724873, 724874, 724875, 724876, 724880, 724881, 724882, 724883, 724884, 724885, 724886, 724887, 724888, 724889, 724890, 724892, 724893, 724894, 724895, 724896, 724897, 724898, 724899, 724900, 724932, 727315, 727436, 728501, 728502, 728503, 728504, 728505, 728506, 728507, 728508, 728509, 728510, 728511, 728515, 728518, 728531, 728532, 728533.
(iii) PW4156, PW4156A, and PW4158..	3	All others not listed by SN in this Table.

Engines Used on Boeing Airplanes

(b) Except as provided in paragraph (g) of this AD, within 50 airplane cycles after the effective date of this AD, limit the number of engines that exceed the engine cycles-since-new (CSN), engine cycles-since-overhaul (CSO), or engine cycles since passing Testing-21 (CST) limits listed in the following Table 3, to:

- (1) No more than one engine per airplane for dual-engine airplanes.
- (2) No more than two engines per airplane for three-engine airplanes.
- (3) No more than three engines per airplane for four-engine airplanes:

Table 3.--Engine Stagger Limits for Boeing Airplanes

Configuration designator	B747-PW4056	B767-PW4052	B767-PW4056	B767-PW4060/ PW4060A/ PW4060C/ PW4062	MD-11 PW4460/ PW4462
A.....	1,400 CSN or CSO.	3,000 CSN or CSO.	1,600 CSN or CSO	900 CSN or CSO..	800 CSN or CSO.
B.....	2,100 CSN or CSO.	4,400 CSN or CSO.	2,800 CSN or CSO	2,000 CSN or CSO	1,200 CSN or CSO.
C.....	2,100 CSN or CSO.	4,400 CSN or CSO.	2,800 CSN or CSO	2,000 CSN or CSO	1,300 CSN or CSO.

D.....	2,600 CSN or CSO.	4,400 CSN or CSO.	3,000 CSN or CSO	2,200 CSN or CSO	2,000 CSN or CSO.
E.....	750 CSN or CSO...	750 CSN or CSO...	750 CSN or CSO..	750 CSN or CSO..	750 CSN or CSO.
F.....	800 CST.....	800 CST.....	800 CST.....	800 CST.....	800 CST.

(c) Except as provided in paragraph (g) of this AD, within 100 airplane cycles after the effective date of this AD, limit the number of engines that exceed the CSN, CSO, or CST limits listed in Table 3, to:

- (1) No more than one engine per airplane for three-engine airplanes.
- (2) No more than two engines per airplane for four-engine airplanes.

(d) Within 200 airplane cycles after the effective date of this AD, limit the number of engines that, exceed the CSN, CSO, or CST limits listed in Table 3, to no more than one engine per airplane for four-engine airplanes.

(e) Thereafter, ensure that no more than one engine per airplane exceeds the CSN, CSO, or CST limit listed in Table 3.

Engines Used on Airbus Airplanes

(f) For engines installed on Airbus airplanes, do the following:

(1) Within 50 airplane cycles after the effective date of this AD, limit the number of engines that exceed, the CSN, CSO, or CST limits listed in the following Table 4, to no more than one engine per airplane:

Configuration designator	A310 PW4156 and PW4156A and A300 PW4158 Category 1	A300 PW4158 Category 2	A310 PW4156 and PW4156A and A300 PW4158 Category 3	A310 PW4152
A.....	900 CSN or CSO...	1,850 CSN or CSO.	500 CSN or CSO..	1,050 CSN or CSO
B.....	2,200 CSN or CSO.	4,400 CSN or CSO.	1,600 CSN or CSO	4,000 CSN or CSO
C.....	2,200 CSN or CSO.	4,400 CSN or CSO.	1,600 CSN or CSO	4,000 CSN or CSO
D.....	4,400 CSN or CSO.	4,400 CSN or CSO.	4,400 CSN or CSO	4,400 CSN or CSO
E.....	750 CSN or CSO...	750 CSN or CSO...	750 CSN or CSO..	750 CSN or CSO
F.....	800 CST.....	800 CST.....	800 CST.....	800 CST

(2) Thereafter, ensure that no more than one engine per airplane, that exceeds the CSN, CSO, or CST limit listed in Table 4.

Configuration E Engines

(g) For all configuration E engines, do the following:

(1) Before further flight, limit the number of engines with configuration E from Table 1 of this AD to one on each airplane.

(2) Remove all engines with configuration E from service before accumulating 1,300 CSN or cycles-since-conversion to configuration E, whichever is later.

Stability Testing Requirement

(h) Engines removed from service in accordance with paragraphs (b), (c), (d) or (f) of this AD may be returned to service under the following conditions:

(l) After passing a cool-engine fuel spike stability test (Testing-21) that has been done in accordance with one of the following PW4000 Engine Manual (EM) Temporary Revisions (TR's) as applicable, except for engines configured with Configuration E, or engines that have experienced a Group 3 takeoff surge:

(i) PW4000 PW EM 50A443, Temporary Revision No. 71-0026, dated November 14, 2001.

(ii) PW EM 50A822, Temporary Revision No. 71-0018, dated November 14, 2001.

(iii) PW EM 50A605, Temporary Revision No. 71-0035, dated November 14, 2001.

(iv) Engines tested before the effective date in accordance with PW IEN 96KC973D, dated October 12, 2001, meets the requirements of Testing-21, or

(2) The HPC was replaced with an HPC that is new from production with no time in service, or

(3) An engine whose HPC has been overhauled, or replaced with an overhauled HPC.

Minimum Build Standard

(i) For any engine that undergoes an HPC overhaul after the effective date of this AD, do the following:

(1) Inspect the HPC mid-hook and rear-hook of the HPC inner case for wear in accordance with PW4000 Clean, Inspect and Repair (CIR) Manual PN 51A357, Section 72-35-68 Inspection/Check-04, Indexes 8-11, revised September 15, 2001. If the HPC rear hook is worn beyond serviceable limits, replace the HPC inner case rear hook with an improved durability hook in accordance with PW SB PW4ENG72-714, issued June 27, 2000. If the HPC inner case mid hook is worn beyond serviceable limits, repair the HPC inner case mid hook in accordance with any revision of PW4000 CIR PN 51A357 Section 72-35-68, Repair-16, issued June 15, 1996.

(2) After the effective date of this AD, any engine that undergoes an HPC overhaul may not be returned to service unless it meets the build standard of the following PW SB's: PW4ENG 72-484, PW4ENG 72-486, PW4ENG 72-514, and PW4ENG 72-575. Engines that incorporate the Phase 3 configuration already meet the build standard defined by PW SB PW4ENG 72-514.

(j) After the effective date of this AD, any engine that undergoes separation of the HPC and HPT modules must not be installed on an airplane unless it meets the build standard of PW SB PW4ENG 72-514. Engines that incorporate the Phase 3 configuration already meet the build standard defined by PW SB PW4ENG 72-514.

(k) After the effective date of this AD, Testing-21 must be performed in accordance with paragraph (h) of this AD, before an engine can be returned to service after having undergone maintenance in the shop, except under any of the following conditions;

(1) The HPC was overhauled, or replaced with an overhauled HPC, or

(2) The HPC was replaced with an HPC that is new from production with no time in service, or

(3) The shop visit did not result in the separation of a major engine flange, with the exception of the "A" flange or "T" flange.

(l) When a thrust rating change has been made by using the Electronic Engine Control (EEC) programming plug, or an installation change has been made, during an HPC overhaul period, use the lowest cyclic limit associated with any configuration used during that overhaul period.

(m) For engines that experience a surge, do the following:

(1) For engines that experience a Group 3 takeoff surge, remove the engine from service and perform an HPC overhaul.

(2) For engines that experience a surge at Engine Pressure Ratios (EPR's) greater than 1.25, remove the engine from service within 25 cycles and perform Testing-21.

Definitions

(n) For the purposes of this AD, the following definitions apply:

(1) An HPC overhaul is defined as restoration of the HPC stages 5 through 15 blade tip clearances to the limits specified in the applicable fits and clearances section of the engine manual.

(2) A Phase 3 engine is identified by a (-3) suffix after the engine model number on the data plate if incorporated at original manufacture, or a "CN" suffix after the engine serial number if the engine was converted using PW SB's PW4ENG 72-490, PW4ENG 72-504, or PW4ENG 72-572 after original manufacture.

(3) A Group 3 takeoff surge is defined as the occurrence of any of the following engine symptoms during takeoff operation (either at reduced, derated or full rated takeoff power setting) after takeoff power set, which can be attributed to no specific and correctable fault condition after following aircraft level surge-during-forward-thrust troubleshooting procedures:

- (i) Engine noises, including rumblings and loud "bang(s)."
- (ii) Unstable engine parameters (EPR, N1, N2, and fuel flow) at a fixed thrust setting.
- (iii) Exhaust gas temperature (EGT) increase.
- (iv) Flames from the inlet, the exhaust, or both.

Alternative Methods of Compliance

(o) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(p) Special flight permits may be issued in accordance with Secs. 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

Testing-21 Reports

(q) Report the results of the cool engine fuel spike stability assessment tests (Testing-21) to the ANE-142 Branch Manager, Engine Certification Office, 12 New England Executive Park, Burlington, MA 01803-5299, or by electronic mail to 9-ane-surge-ad-reporting@faa.gov. The following data must be reported:

- (1) Engine serial number.
- (2) Engine configuration designation per Table 1.
- (3) Date of the cool engine fuel spike stability test.
- (4) HPC Serial Number, and HPC time and cycles since new and since compressor overhaul at the time of the test.
- (5) Results of the test (Pass/Fail).

Documents That Have Been Incorporated by Reference

(r) The inspection shall be done in accordance with the following Pratt & Whitney service bulletin (SB), Internal Engineering Notice (IEN), Temporary Revisions (TR's), Clean, Inspection, and Repair Manual (CIR) repair procedures:

Document No.	Pages	Revision	Date
PW SB PW4ENG72-714.....	1-2..... 3..... 4..... 5-12.....	1..... Original..... 1..... Original.....	November 8, 2001. June 27, 2000. November 8, 2001 June 27, 2000.
	Total pages: 12.		
PW IEN 96KC973D.....	All.....	Original.....	October 12, 2001.
	Total pages: 19.		
PW TR 71-0026.....	All.....	Original.....	November 14, 2001.
	Total pages: 24.		
PW TR 71-0018.....	All.....	Original.....	November 14, 2001.
	Total pages: 24.		
PW TR 71-0035.....	All.....	Original.....	November 14, 2001.
	Total pages: 24.		
PW CIR 51A357, Section 72-35-68, Inspection/Check-04, Indexes 8-11.	All.....	Original.....	September 15, 2001.
	Total pages: 5.		
PW CIR 51A357, Section 72-35-68, Repair 16.	All.....	Original.....	June 15, 1996.
	Total pages: 1.		

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Pratt & Whitney, 400 Main St., East Hartford, CT 06108, (860)565-6600, fax (860)565-4503. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Effective Date

(s) This amendment becomes effective on January 17, 2002.

Issued in Burlington, Massachusetts, on December 12, 2001.

Robert G. Mann,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 01-31296 Filed 12-31-01; 8:45 am]

BILLING CODE 4910-13-P

FOR FURTHER INFORMATION CONTACT: Peter White, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7128; fax (781) 238-7199.

BW 2002-01

**ROLLS-ROYCE, PLC
AIRWORTHINESS DIRECTIVE
ENGINE
LARGE AIRCRAFT**

2001-26-11 Rolls-Royce, plc: Amendment 39-12575. Docket No. 98-ANE-33-AD. Supersedes AD 2000-24-26, Amendment 39-12033.

Applicability

This airworthiness directive (AD) is applicable to Rolls-Royce plc (RR) RB211 Trent 875, RB211 Trent 877, RB211 Trent 884, RB211 Trent 892, and RB211 Trent 892B series turbofan engines, with low pressure compressor (LPC) fan blades, part numbers (P/N's) FK23750, FK25975, FK25548, or FK26757 installed. These engines are installed on, but not limited to Boeing 777 series airplanes.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (i) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Compliance with this AD is required as indicated, unless already done.

To prevent LPC fan blade failure due to cracking, which could result in multiple fan blade release, uncontained engine failure, and possible damage to the airplane, do the following:

Initial Inspection

(a) Ultrasonically inspect the dovetail roots of LPC fan blades for cracks, in accordance with Appendix 1 (Method A) of RR Service Bulletin (SB) RB.211-72-C445, Revision 7, dated May 10, 2001, at the Initial Inspection Threshold cyclic times listed in the following Table 1 of this AD:

Engine model (rating)	Initial inspection threshold, cycles-since- new (CSN)	Inspection intervals, cycles-since- last inspection (CSLI)	Part life threshold, CSN
(1) Trent 875.....	3,000	400	4,200
(2) Trent 877.....	2,000	350	3,050
(3) Trent 884.....	1,500	350	2,200
(4) Trent 892 and Trent 892B.....	900	200	1,300

Dry Film Lubricant Renewal

(b) Apply an approved dry film lubricant to LPC fan blade roots of blades inspected by Method A. Procedures for renewing the dry film lubricant on the blade roots are specified in the AMM task 72-31-11-300-801-R00 (Repair Scheme FRS A031 by air spray method only) or engine manual 72-31-11-R001 (Repair Scheme FRS A028). For purposes of this AD, approved lubricants are Dow Corning 321R (Rolls-Royce (RR) Omat item 4/52), Rocol Dry Moly Spray (RR Omat item 4/52), Molydag 709 (RR Omat item 444), or PL.237/R1 (RR Omat item 4/43).

Repetitive Inspections

(c) Except for the first inspection after exceeding the Part Life Threshold listed in Table 1 of this AD, ultrasonically inspect the dovetail roots of LPC fan blades for cracks and renew dry film lubricant when specified in accordance with Appendix 1 (Method A) or Appendix 2 (Method B) of RR SB RB.211-72-C445, Revision 7, dated May 10, 2001, and the Inspection Intervals listed Table 1 of this AD.

First Inspection After Exceeding Part Life Threshold

(d) For the first inspection after exceeding the Part Life Threshold listed in Table 1 of this AD, ultrasonically inspect the dovetail roots of LPC fan blades for cracks in accordance with Appendix 1 (Method A) of RR SB RB.211-72-C445, Revision 7, dated May 10, 2001. Thereafter, the repetitive inspections may be done using either Appendix 1 (Method A) or Appendix 2 (Method B), as specified in paragraph (c) of this AD.

Fan Blades Exceeding Initial Inspection Threshold

(e) For blades that have, on the effective date of the AD, more cycles since installation than the initial compliance criteria in Table 1, inspect blades within 100 cycles in service after the effective date of this AD.

Engine Rating Changes

- (f) For an engine that has changed its rating, inspect fan blades at the correct cycle time as follows:
- (1) From higher rating to lower rating, inspect fan blades before further flight, as specified in this AD and reinspect at the interval applicable to the lower rating.
 - (2) From lower rating to higher rating, inspect fan blades at intervals applicable to the higher rating.

Method A Acceptance Criteria

(g) For Method A, replace blades that do not meet the acceptance criteria in Appendix 1 of RR SB RB.211-72-C445, Revision 7, dated May 10, 2001.

Method B Acceptance Criteria

(h) For Method B, for blades that do not meet the acceptance criteria in Appendix 2 of RR SB RB.211-72-C445, Revision 7, dated May 10, 2001, remove blades and ultrasonically inspect the dovetail roots for cracks in accordance with Appendix 1 (Method A) of RR SB RB.211-72-C445, Revision 7, dated May 10, 2001.

Alternative Methods of Compliance

(i) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(j) Special flight permits may be issued in accordance with Secs. 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

Documents That Have Been Incorporated by Reference

(k) The inspection must be done in accordance with Rolls-Royce plc Service Bulletin(SB) No. RB.211-72-C445, Revision 7, dated May 10, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Rolls-Royce plc, Technical Publications Department, PO Box 31, Derby, England DE248BJ; telephone 44 1332 242424, fax, 1332 249936. Copies may be inspected, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Civil Aviation Authority airworthiness directive AD 003-04-98, issued on May 10, 2001.

Effective Date

(l) This amendment becomes effective on January 30, 2002.

Issued in Burlington, Massachusetts, on December 17, 2001.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 01-31699 Filed 12-28-01; 8:45 am]

BILLING CODE 4910-13-P

FOR FURTHER INFORMATION CONTACT: Keith Mead, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7744; fax (781) 238-7199.

BW 2002-01

BOEING AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-12 Boeing: Amendment 39-12578. Docket 2001-NM-124-AD. Supersedes AD 2001-12-05, Amendment 39-12260.

Applicability: Model 747-100, 747-200, 747-300, and 747SR series airplanes; certificated in any category; powered by General Electric CF6-45/50 series engines, or Pratt & Whitney JT9D-70 series engines.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent heat damage to the diagonal brace, which could cause cracking or fracture of the diagonal brace, and possible loss of the diagonal brace load path and consequent separation of the strut and engine from the airplane, accomplish the following:

Restatement of Certain Requirements of AD 2000-12-05:

Verification

(a) Within 90 days after June 27, 2001 (the effective date of AD 2001-12-05, amendment 39-12260), do the actions required by paragraph (a)(1) or (a)(2) of this AD, as applicable.

(1) If an operator's maintenance records verify that, during the accomplishment of AD 95-13-07, amendment 39-9287, the seal backup plates were restored and BMS 5-63 high-temperature sealant was used in that restoration, no further action is required by this AD.

(2) If an operator's maintenance records do not verify that the actions specified in paragraph (a)(1) of this AD were accomplished, do the actions required by paragraph (b) of this AD.

Inspections and Corrective Actions

(b) Within 90 days after June 27, 2001, do the inspections and applicable corrective actions specified by paragraphs (b)(1) and (b)(2) of this AD per the Accomplishment Instructions of Boeing Alert Service Bulletin 747-54A2208, dated March 29, 2001. Thereafter, repeat the inspections at intervals not to exceed 6 months, until accomplishment of paragraph (c) of this AD.

Outboard Strut Diagonal Brace

(1) Do a detailed visual inspection of the forward 20 inches of the outboard strut diagonal brace, including all areas of the forward clevis lugs and brace body, for signs of heat damage or cracks, per Part 1 of the Accomplishment Instructions of the service bulletin.

(i) If no sign of heat damage or cracking is found, repeat the detailed visual inspection at intervals not to exceed 6 months, per the service bulletin, until accomplishment of paragraph (c) of this AD.

(ii) If any primer discoloration is found, before further flight, do a non-destructive test (NDT) inspection of the area to determine if the diagonal brace has heat damage per Part 1 of the Accomplishment Instructions of the service bulletin.

(A) If no heat damage is found during the NDT inspection, and no cracking is found during the detailed visual inspection, repeat the detailed visual inspection specified by paragraph (b)(1) of this AD at intervals not to exceed 6 months.

(B) If any heat damage is found during the NDT inspection, or any cracking is found during the detailed visual inspection, before further flight, do the actions specified in paragraph (c)(2) of this AD. Thereafter, repeat the detailed visual inspection specified by paragraph (b)(1) of this AD at intervals not to exceed 6 months.

Firewall Openings of the Strut Aft Bulkhead

(2) Do a detailed visual inspection of the firewall openings of the strut aft bulkhead to verify installation of seal backup plates and condition of the sealant application per Part 1 of the Accomplishment Instructions of the service bulletin.

(i) If no discrepancy (including damaged or missing seal backup plates, or damaged or missing sealant) is found, repeat the detailed visual inspection specified by paragraph (b)(1) of this AD at intervals not to exceed 6 months.

(ii) If the seal backup plates are not installed, before further flight, install the seal backup plates and apply heat-resistant sealant, BMS 5-63, per Part 2 of the Accomplishment Instructions of the service bulletin. Accomplishment of this action terminates the repetitive inspections required by this AD.

(iii) If the seal backup plates are installed, but the sealant application is damaged or missing, before further flight, remove any existing sealant and apply heat-resistant sealant, BMS 5-63, per Part 3 of the Accomplishment Instructions of the service bulletin. Accomplishment of this action terminates the repetitive inspections required by this AD.

Note 2: Because it is difficult to distinguish between BMS 5-95 and BMS 5-63 sealants, removal and replacement of the existing sealant is required to ensure that the correct heat-resistant sealant, BMS 5-63, is used.

New Requirements of This AD

Terminating Action and Corrective Action

(c) Within 18 months after the effective date of this AD: Do the action specified by paragraph (c)(1), (c)(2), or (c)(3) of this AD, as applicable. Accomplishment of the applicable action constitutes terminating action for the repetitive inspections required by this AD.

(1) Following the inspections required by paragraphs (b)(1) and (b)(2) of this AD, if no cracking or heat damage is found during those inspections, and the seal backup plates are installed, before further flight, remove any existing sealant and apply heat-resistant sealant BMS 5-63, per Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-54A2208, dated March 29, 2001.

(2) If any sign of heat damage or cracking is found during the inspections required by paragraph (b) of this AD, before further flight, do the actions specified by either paragraph (c)(2)(i) or (c)(2)(ii) of this AD.

(i) Replace the diagonal brace per Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-54A2208, dated March 29, 2001.

(ii) Repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved by the Manager, Seattle ACO, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

(3) If the seal back-up plates are not installed, before further flight, install the seal backup plates and apply heat-resistant sealant BMS 5-63, per Part 2 of the Accomplishment Instructions of the service bulletin.

Alternative Methods of Compliance

(d) (1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(2) Alternative methods of compliance, approved previously in accordance with AD 2001-12-05, amendment 39-12260, are approved as alternative methods of compliance with this AD.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) Except as provided by paragraphs (a) and (c)(2)(ii) of this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin 747-54A2208, dated March 29, 2001. The incorporation by reference of Boeing Alert Service Bulletin 747-54A2208, dated March 29, 2001, was approved previously by the Director of the Federal Register as of June 27, 2001 (66 FR 31527, June 12, 2001). Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(g) This amendment becomes effective on February 11, 2002.

Issued in Renton, Washington, on December 20, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-87 Filed 1-4-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Tamara Anderson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2771; fax (425) 227-1181.

BW 2002-01

DORNIER LUFTFAHRT AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-14 Dornier Luftfahrt GMBH: Amendment 39-12580. Docket 97-NM-187-AD. Supersedes AD 96-12-13, Amendment 39-9656.

Applicability: Model 328-100 airplanes, equipped with a Honeywell GP-300 guidance and display controller having part number (P/N) 7015327-901 or -902; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a defective light bulb from causing a short circuit that emits smoke and fumes into the cockpit, or causing damage to the circuit cards and various components, which may lock the autopilot into the engaged mode, accomplish the following:

Restatement of Requirements of AD 96-12-13

(a) Within 60 days after June 26, 1996 (the effective date of AD 96-12-13, amendment 39-9656), modify the Honeywell GP-300 guidance and display controller, having P/N 7015327-901 or -902, in accordance with Honeywell Service Bulletin 7015327-22-2, dated March 4, 1996.

New Requirements of This AD

(b) Within 60 days after the effective date of this AD, verify that the wiring of the Honeywell GP-300 guidance and display controller is correct by conducting a re-test of the circuit card assemblies, in accordance with Honeywell Service Bulletin 7015327-22-4, dated March 31, 1997. If any discrepancy is found, prior to further flight, repair in accordance with the service bulletin.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Honeywell Service Bulletin 7015327-22-2, dated March 4, 1996; and Honeywell Service Bulletin 7015327-22-4, dated March 31, 1997.

(1) The incorporation by reference of Honeywell Service Bulletin 7015327-22-4, dated March 31, 1997, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Honeywell Service Bulletin 7015327-22-2, dated March 4, 1996, was approved previously by the Director of the Federal Register as of June 26, 1996 (61 FR 29465, June 11, 1996).

(3) Copies may be obtained from Honeywell, Inc., Attn: Customer Support Materiel, PO Box 21111, Phoenix, Arizona 85036. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in German airworthiness directive 96-239/2, dated June 19, 1997.

Effective Date

(f) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 21, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-143 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-P

FOR FURTHER INFORMATION CONTACT: Tom Groves, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

BW 2002-01

MCDONNELL DOUGLAS AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-15 McDonnell Douglas: Amendment 39-12581. Docket 2000-NM-161-AD.

Applicability: Model DC-9-81, -82, -83, and -87 series airplanes, and Model MD-88 airplanes, as listed in McDonnell Douglas Alert Service Bulletin MD80-24A126, Revision 02, dated September 22, 1999; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent smoke and fire in the flight deck and main cabin due to insufficient clearance between wire assemblies and the ice protection airduct and airstair door interlock rod; chafing; and consequent arcing of wire assemblies, accomplish the following:

Inspection and Modification

(a) Within 6 months after the effective date of this AD, perform a detailed visual inspection of wire runs in the electrical/equipment compartment to detect chafing and preload against the airduct shroud assembly of the strake ice protection system and/or airstair door interlock rod between stations Y=148.00 and Y=160.000, in accordance with McDonnell Douglas Alert Service Bulletin MD80-24A126, Revision 02, dated September 22, 1999.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(1) If no chafed or preloaded wire is found, prior to further flight, install spacers, sta-straps, and tie-back wire bundles, in accordance with the service bulletin.

(2) If any chafed or preloaded wire is found, prior to further flight, repair, and install spacers, sta-straps, and tie-back wire bundles, in accordance with the service bulletin.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permit

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The actions shall be done in accordance with McDonnell Douglas Alert Service Bulletin MD80-24A126, Revision 02, dated September 22, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(e) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 21, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-144 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-P

FOR FURTHER INFORMATION CONTACT: Elvin Wheeler, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5344; fax (562) 627-5210.

BW 2002-01

MCDONNELL DOUGLAS AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-16 McDonnell Douglas: Amendment 39-12582. Docket 2000-NM-162-AD.

Applicability: Model DC-9-81, -82, -83, and -87 series airplanes, and Model MD-88 airplanes, as listed in Boeing Alert Service Bulletin MD80-33A096, Revision 03, dated August 14, 2001; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent electrical shorting and arcing due to the presence of water in the lighting ballast interface connectors, which could result in smoke in the main cabin, accomplish the following:

Replacement or Incorporation of Interface Seals

(a) Within 18 months after the effective date of this AD, accomplish the actions specified in paragraph (a)(1) or (a)(2) of this AD per Boeing Alert Service Bulletin MD80-33A096, Revision 03, dated August 14, 2001.

(1) Replace the interface connectors of the cabin fluorescent lighting ballast in the wiring harness of the overhead stowage compartment with new connectors; or

(2) Add interface seals to the existing interface connectors of the cabin fluorescent lighting ballast between stations Y=218.000 to Y=1338.000 and reidentify the connector assemblies.

Note 2: Replacement of connectors prior to the effective date of this AD in accordance with McDonnell Douglas MD80 Service Bulletin 33-96, dated December 15, 1993; Revision 1, dated February 28, 1994; or Revision 02, dated November 1, 1999; is considered acceptable for compliance with the requirements of paragraph (a) of this AD.

Spares

(b) As of the effective date of this AD, no person shall install any connector, part number MB10R-6, on any airplane.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The replacement shall be done in accordance with Boeing Alert Service Bulletin MD80-33A096, Revision 03, dated August 14, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 21, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-145 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Elvin Wheeler, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5344; fax (562) 627-5210.

BW 2002-01

AIRBUS INDUSTRIE AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-17 Airbus Industrie: Amendment 39-12583. Docket 2001-NM-28-AD.

Applicability: Model A330-202, -223, -243, -301, -321, -322, -323, -341, -342, and -343 series airplanes, on which Airbus Modification 47707 has not been incorporated; or Airbus Service Bulletin A330-52-3058, dated April 7, 2000, or Revision 01, dated February 8, 2001, has not been accomplished; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the shear pins on the rear fixed panels of the center landing gear from failing, which could result in loss of the panels during flight with consequent injury to people on the ground, accomplish the following:

Replacement

(a) Within 18 months after the effective date of this AD: Remove the shear pins that keep the rear fixed panels of the center landing gear closed and install solid shear pins, in accordance with Airbus Service Bulletin A330-52-3058, Revision 01, dated February 8, 2001.

Note 2: Accomplishment of the replacement in accordance with Airbus Service Bulletin A330-52-3058, dated April 7, 2000, prior to the effective date of this AD, is acceptable for compliance with the requirements of this AD.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The actions shall be done in accordance with Airbus Service Bulletin A330-52-3058, Revision 01, dated February 8, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in French airworthiness directive 2001-042(B), dated January 24, 2001.

Effective Date

(e) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 21, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-146 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1181.

BW 2002-01

DORNIER LUFTFAHRT AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-18 Dornier Luftfahrt GMBH: Amendment 39-12584. Docket 2001-NM-174-AD.

Applicability: Model 328-300 series airplanes, on which a forward engine mount vibration isolator has been removed or reinstalled since the date of manufacture of the airplane, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the engine mount, which could result in separation of the engine from the airplane, accomplish the following:

One-Time Inspection

(a) For airplanes on which a forward engine mount vibration isolator has been removed or reinstalled prior to the effective date of this AD: Within 2,500 flight cycles after the first removal or reinstallation of a forward engine mount vibration isolator, or within 30 days after the effective date of this AD, whichever comes later, do a one-time torque test (inspection) of the attachment bolts of the forward engine mount vibration isolators on the left- and right-hand sides of the airplane to determine if the bolts are adequately torqued, according to Dornier Service Bulletin SB-328J-71-109, dated March 26, 2001, including Dornier 328JET Aircraft Maintenance Manual (AMM) Temporary Revision (TR) 71-130, dated March 8, 2001.

Replacement of Bolts

(b) During the inspection required by paragraph (a) of this AD, if the torque value of any attachment bolt is found to be outside the limits specified in Dornier Service Bulletin SB-328J-71-109, dated March 26, 2001, including Dornier 328JET AMM TR 71-130, dated March 8, 2001: Before further flight, do all actions associated with replacing all bolts on the vibration isolator on which the improperly torqued bolt was found (including performing a detailed visual inspection to determine the condition of components of the vibration isolator and replacement of any damaged components with new components, removing the existing bolts and washers that attach the forward engine mount vibration isolators to the engine, installing new bolts to reattach the forward engine mount vibration isolators to the engine, and torquing the new bolts to adequate torque values), according to the service bulletin.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Torque Requirements

(c) For all airplanes: As of the effective date of this AD, no one may install an attachment bolt on the forward engine mount vibration isolators on any airplane, unless the attachment bolt is torqued within the limits specified in Dornier 328JET AMM TR 71-130, dated March 8, 2001.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) The actions shall be done in accordance with Dornier Service Bulletin SB-328J-71-109, dated March 26, 2001, including Dornier 328JET Aircraft Maintenance Manual Temporary Revision 71-130, dated March 8, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from FAIRCHILD DORNIER, DORNIER Luftfahrt GmbH, P.O. Box 1103, D-82230 Wessling, Germany. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in German airworthiness directive 2001-163, dated June 14, 2001.

Effective Date

(g) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 21, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-147 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Tom Groves, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1503; fax (425) 227-1149.

BW 2002-01

BOEING AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-19 Boeing: Amendment 39-12585. Docket 2001-NM-311-AD.

Applicability: Model 767 series airplanes, line numbers 1 through 854 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Note 2: Boeing Service Letter 767-SL-25-101, dated August 30, 2001, provides information related to this AD; however, the actions required by this AD are not identical to those in the "Suggested Operator Action" section of that service letter. Where this AD differs from the service letter, this AD prevails.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of an entry or service door to open fully in the event of an emergency evacuation, which could impede exit from the airplane and result in injury to passengers or crewmembers, accomplish the following:

One-Time Inspection and Corrective Actions

(a) Within 60 days after the effective date of this AD, do a one-time detailed visual inspection for missing, damaged, or incorrectly installed parts in the separation link assembly on the deployment bar of the emergency escape system on the entry or service door, according to the procedures specified in paragraphs (a)(1), (a)(2), (a)(3), (a)(4), (a)(5), and (a)(6) of this AD.

(1) Remove the escape slide pack bustle according to Section 25-66-00 of the Boeing 767 Airplane Maintenance Manual (AMM).

(2) Position the deployment bar of the escape slide to expose the forward and aft separation links, according to Section 25-66-00 of the Boeing 767 AMM and Section 25-66-30 of the Boeing 767 Component Maintenance Manual (CMM), Revision 2, dated November 1, 2000.

(3) Do a detailed visual inspection to determine whether the snap ring, washer, and internal spring of the separation link assembly are installed correctly on both the forward and aft separation links, and to detect any damage of the snap ring, washer, and spring, according to Items 65 and 70 of Section 25-66-30 of the CMM, Revision 2, dated November 1, 2000.

(4) If any snap ring, washer, or internal spring is missing or found damaged or installed incorrectly during the inspection required by paragraph (a)(3) of this AD, before further flight, install a new snap ring, washer, and internal spring according to Section 25-66-30 of the CMM, Revision 2, dated November 1, 2000.

(5) Ensure that the separation links and deployment cables are installed as depicted on placard BAC27TPPS5141 or BAC27TPPS5142, as applicable. Placards are adjacent to each link on the deployment bar. If any separation link or deployment cable is installed incorrectly, before further flight, correct the installation as shown on the applicable placard.

(6) Reinstall the escape slide pack bustle according to Section 25-66-00 of the Boeing 767 AMM.

Note 3: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Reporting Requirement

(b) If there is any missing, damaged, or incorrectly installed part in the separation link assembly on the deployment bar of the emergency escape system on any entry or service door: Submit a report of inspection findings to the FAA Certification Management Office--Boeing, ANM-108B, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; at the applicable time specified in paragraph (b)(1) or (b)(2) of this AD. The report must include: the serial number of the affected airplane, the total number of doors inspected, the number of deployment bars with missing or damaged parts, an identification of what parts are missing or damaged, and the calendar date of the last inspection or test of any emergency escape system with missing or damaged parts. Information collection requirements contained in this AD have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 et seq.) and have been assigned OMB Control Number 2120-0056.

(1) For airplanes on which the inspection is accomplished after the effective date of this AD: Submit the report within 10 days after performing the inspection required by paragraph (a) of this AD.

(2) For airplanes on which the inspection has been accomplished before the effective date of this AD: Submit the report within 10 days after the effective date of this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.**Incorporation by Reference**

(e) The exposure of the forward and aft separation links; inspection for snap ring, washer, and internal spring; and installation of new snap ring, washer, and internal spring; shall be done in accordance with Section 25-66-30 of the Boeing 767 Component Maintenance Manual, Revision 2, dated November 1, 2000, which contains the following effective pages:

Page number	Revision level shown on page	Date shown on page
List of Effective Pages; Page 1.....	2	Nov. 1, 2000.

(Only the "Highlights" page of Section 25-66-30 shows the appropriate revision level; no other page of this document contains the revision level.) This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on January 18, 2002.

Issued in Renton, Washington, on December 21, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-148 Filed 1-2-02; 8:45 am]

BILLING CODE 4910-13-P

FOR FURTHER INFORMATION CONTACT: John Piccola, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1509; fax (425) 227-1181.

BW 2002-01

AIRBUS INDUSTRIE AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-20 Airbus Industrie: Amendment 39-12586. Docket 2001-NM-132-AD.

Applicability: Model A319, A320, and A321 series airplanes, certificated in any category, as listed in Airbus Service Bulletin A320-56-1007, Revision 01, dated February 9, 2001.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the inability of the flightcrew to open the left- or right-hand sliding window for evacuation in an emergency, due to a window jamming in the closed position, accomplish the following:

Inspection

(a) Within one year after the effective date of this AD: Perform a one-time detailed visual inspection of the forward and aft lower bogie of the left-hand and right-hand sliding windows to check for the presence of a lock pin, in accordance with Airbus Service Bulletin A320-56-1007, Revision 01, dated February 9, 2001.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Corrective Action

(b) If the inspection required by paragraph (a) of this AD reveals that a lock pin is missing: Prior to further flight, perform the action required by either paragraph (b)(1) or (b)(2) of this AD.

(1) Install a new bogie equipped with a lock pin, in accordance with paragraph C.(1) of the Accomplishment Instructions of Airbus Service Bulletin A320-56-1007, Revision 01, dated February 9, 2001, or

(2) Perform a temporary repair in accordance with paragraph C.(2) of the Accomplishment Instructions of Airbus Service Bulletin A320-56-1007, Revision 01, dated February 9, 2001. Within 500 flight hours of the temporary repair, install a new bogie equipped with a lock pin, in accordance with paragraph C.(1) of the Accomplishment Instructions of the service bulletin.

Note 3: Inspection and corrective actions accomplished prior to the effective date of this AD in accordance with Airbus Service Bulletin A320-56-1007, dated January 21, 2000, is considered acceptable for compliance with the requirements of this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Airbus Service Bulletin A320-56-1007, Revision 01, including Appendix 01, dated February 9, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 5: The subject of this AD is addressed in French airworthiness directive 2000-518-157(B), dated December 13, 2000.

Effective Date

(f) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 26, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-9 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-P

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2141; fax (425) 227-1149.

BW 2002-01

AIRBUS AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-21 Airbus Industrie: Amendment 39-12587. Docket 2001-NM-255-AD.

Applicability: Model A319, A320, and A321 series airplanes; on which Modification 21946 (Airbus Service Bulletin A320-35-1003) or 21999 has not been accomplished; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent faulty operation of the low-pressure solenoid valve for the oxygen supply, which could prevent oxygen from being supplied to the airplane crew when needed, such as in the event of smoke in the cabin or rapid depressurization of the airplane, accomplish the following:

Replacement

(a) Within 16 months after the effective date of this AD, replace the low-pressure solenoid valve, part number (P/N) DVE90-04, for the crew oxygen supply with a modified valve, P/N DVE90-05 or DVE90-06, as applicable. Do the replacement according to Airbus Service Bulletins A320-35-1003, Revision 1, dated January 28, 1993; or A320-35-1016, dated July 31, 1996; as applicable.

Note 2: Airbus Service Bulletin A320-35-1003, Revision 1, refers to EROS Service Bulletin DVE90-35-40, dated September 10, 1991, as the appropriate source of service information for modifying the low-pressure solenoid valve for the crew oxygen supply.

Note 3: Airbus Service Bulletin A320-35-1016 refers to EROS Service Bulletin DVE90-35-49, dated January 31, 1995, as the appropriate source of service information for modifying the low-pressure solenoid valve for the oxygen supply.

Spares

(b) As of the effective date of this AD, no person shall install a low-pressure oxygen valve, part number DVE90-04, on any airplane.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The replacement shall be done in accordance with Airbus Service Bulletin A320-35-1003, Revision 1, dated January 28, 1993; or Airbus Service Bulletin A320-35-1016, dated July 31, 1996; as applicable. Airbus Service Bulletin A320-35-1003, Revision 1, dated January 28, 1993, contains the following effective pages:

Page No	Revision level shown on page	Date shown on page
1-3, 5.....	1.....	Jan. 28, 1993.
4, 6.....	Original.....	Aug. 26, 1991.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 5: The subject of this AD is addressed in French airworthiness directive 2001-237(B) R1, dated July 25, 2001.

Effective Date

(f) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 26, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-8 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

BW 2002-01

BAE SYSTEMS (OPERATIONS) LIMITED AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-22 BAE Systems (Operations) Limited (Formerly British Aerospace Regional Aircraft):
Amendment 39-12588. Docket 2001-NM-90-AD.

Applicability: Model Avro 146-RJ series airplanes, certificated in any category, on which modification HCM01080W is installed.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the S4 and S5 static pipes of the pitot static system and consequent failure of the maximum differential pressure protection for the airplane, which could lead to the fuselage of the airplane being overstressed and result in reduced structural integrity of the airplane, accomplish the following:

General Visual Inspection/Follow-On Corrective Actions

(a) Within 90 days after the effective date of this AD, do a general visual inspection of the S4 and S5 static pipes of the pitot static system for discrepancies (i.e., chafing, damage to pipes, inadequate clearance), per BAE Systems (Operations) Limited Inspection Service Bulletin ISB.34-338, dated February 14, 2001.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(1) If any chafing is found, before further flight, do the applicable follow-on actions per the Accomplishment Instructions of the service bulletin. Where the service bulletin specifies to contact the manufacturer for disposition of certain repair conditions, the repair of those conditions is to be accomplished per a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Civil Aviation Authority (or its delegated agent).

(2) If no chafing is found and the clearance between the static pipes and the adjacent avionics structure is less than 0.10 inch, before further flight, do the applicable follow-on actions per the Accomplishment Instructions of the service bulletin.

(3) If no chafing is found and a minimum clearance of 0.10 inch exists between the static pipes and the adjacent avionics structure, no further action is required by this AD.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) Except as provided by paragraph (a)(1) of this AD, the actions shall be done in accordance with BAE Systems (Operations) Limited Inspection Service Bulletin ISB.34-338, dated February 14, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in British airworthiness directive 008-02-2001.

Effective Date

(e) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 26, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-7 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1149.

BW 2002-01

BOMBARDIER, INC. AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-23 Bombardier, Inc. (Formerly de Havilland, Inc.): Amendment 39-12589. Docket 2001-NM-241-AD.

Applicability: Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes; certificated in any category; serial numbers 408, 413, 434 through 507 inclusive; excluding serial numbers 452, 464, 490, and 506.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the observer's seat from separating from its attachment points in the event of an accident or emergency landing, accomplish the following:

Replacement

(a) Within 12 months after the effective date of this AD, replace the observer's seat latch assembly by incorporating ModSum 8Q100890 (including removing and discarding existing latch and installing serrated plate, shim, and new latch assembly), in accordance with Bombardier Service Bulletin 8-25-307, dated November 13, 2000.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The replacement shall be done in accordance with Bombardier Service Bulletin 8-25-307, dated November 13, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Canadian airworthiness directive CF-2001-18, dated May 4, 2001.

Effective Date

(e) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 26, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-6 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Serge Napoleon, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7512; fax (516) 568-2716.

BW 2002-01

MCDONNELL DOUGLAS AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT

2001-26-24 McDonnell Douglas: Docket 99-NM-290-AD. Amendment 39-12590

Applicability: Model DC-9-10, -20, -30, -40, and -50 series airplanes; and C-9 airplanes; as listed in McDonnell Douglas Alert Service Bulletin DC9-33A114, Revision 01, dated February 15, 2000; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent overheating of the ballast transformers due to aging fluorescent tubes that cause a higher power demand on the ballast transformers, which could result in smoke in the cockpit, accomplish the following:

Replacement

(a) Within 12 months after the effective date of this AD, replace the transformer ballast assembly from the pilot's console with a new, improved transformer ballast assembly, in accordance with McDonnell Douglas Alert Service Bulletin DC9-33A114, Revision 01, dated February 15, 2000.

Spares

(b) As of the effective date of this AD, no person shall install a transformer assembly, part number BA170-1, -11, -21, or -MOD.B, on any airplane.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with McDonnell Douglas Alert Service Bulletin DC9-33A114, Revision 01, dated February 15, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on February 8, 2002.

Issued in Renton, Washington, on December 26, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-5 Filed 1-3-02; 8:45 am]

BILLING CODE 4910-13-P

FOR FURTHER INFORMATION CONTACT: Elvin Wheeler, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5344; fax (562) 627-5210.

BW 2002-01

BOMBARDIER, INC. AIRWORTHINESS DIRECTIVE FINAL RULE OF EMERGENCY LARGE AIRCRAFT

2001-26-51 Bombardier, Inc. (Formerly Canadair): Amendment 39-12577. Docket 2001-NM-383-AD.

Applicability: Model CL-600-2B19 series airplanes, serial numbers 7003 and subsequent, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (h) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent ignition of fuel vapor in the center wing tank and consequent fire and explosion, accomplish the following:

Lock Ring Installation

(a) For all airplanes: Within 24 hours after the effective date of this AD, open circuit breakers identified in paragraph 2.B. of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-28-045, Revision "A," dated December 7, 2001, and install a lock ring on the circuit breakers, in accordance with PART A of the Accomplishment Instructions of the alert service bulletin.

Note 2: Accomplishment of the requirements of paragraphs (a) and (c) in accordance with Bombardier Alert Service Bulletin A601R-28-045, dated December 6, 2001, prior to the effective date of this AD is acceptable for compliance with the requirements of those paragraphs.

AFM Revision for Certain Airplanes

(b) For airplanes having serial numbers 7003 through 7109 inclusive: Concurrently with the accomplishment of the requirements of paragraph (a) of this AD, determine whether the fuel vent system has been modified in accordance with Bombardier Service Bulletin 601R-28-024, Revision "A," dated November 11, 1998.

(1) For airplanes on which the fuel vent system HAS been modified in accordance with the service bulletin: No further action is required by paragraph (b) of this AD.

(2) For airplanes on which the fuel vent system HAS NOT been modified in accordance with the service bulletin: Prior to further flight, revise the Limitations section of the Airplane Flight Manual (AFM) to include the following (this may be accomplished by inserting a copy of this AD into the AFM):

"THE AIRPLANE MUST NOT BE OPERATED WITH MORE THAN 200 POUNDS OF FUEL IN THE CENTER FUEL TANK."

Following accomplishment of the requirements of paragraph (d), the AFM revision shall be removed from the AFM. Where the provisions of this AD and the Master Minimum Equipment List (MMEL) differ, this AD prevails.

Disconnection and Stowage of Electrical Wiring

(c) For all airplanes: Within 4 days after the effective date of this AD, disconnect and stow the electrical wires from the circuit breakers opened as required by paragraph (a) of this AD, in accordance with Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-28-045, Revision "A," dated December 7, 2001.

Identification of Valve Part Number

(d) For all airplanes: Within 45 days after the effective date of this AD, determine the part number (P/N) of the fuel transfer shutoff valves installed in the center fuel tank, and accomplish the following, as applicable.

(1) If any valve has P/N 601R62256-5, remove the valve in accordance with Maintenance Manual task number 28-13-43-000-801, and replace it with a valve having P/N 601R62256-3 in accordance with Maintenance Manual task number 28-13-43-400-801; and reactivate the fuel transfer shutoff valve by accomplishing the requirements of paragraph (d)(1)(i) or (d)(1)(ii) of this AD, as applicable.

(i) For airplanes that have NOT been modified in accordance with Bombardier Service Bulletin 601R-28-022: Open the CBP-1; remove protective tubing, if applicable; release "Unstow" the wire and reconnect it to its respective breaker CB1-N9, in accordance with Wiring Manual 28-20-50; close the CBP-1; remove the "INOP" label and the lock ring from breaker CB1-N9; carry out AMM Task 28-13-43-710-801, "Operational Test of Fuel Transfer SOV"; and remove the AFM limitation required by paragraphs (b)(2) and (f) of this AD.

(ii) For airplanes that HAVE been modified in accordance with Bombardier Service Bulletin 601R-28-022: Open the CBP-1 and CBP-2; remove protective tubing, if applicable; release "Unstow" the wires and reconnect them to their respective breaker CB1-N9 or CB2-P9, in accordance with Wiring Manual 28-20-50; close the CBP-1 and CBP-2; remove the "INOP" labels and lock rings from breakers CB1-N9 and CB2-P9; carry out AMM Task 28-13-43-710-801, "Operational Test of Fuel Transfer SOV"; and remove the AFM limitation required by paragraph (f) of this AD.

(2) If all valves have P/N 601R62256-3, reactivate the fuel transfer shutoff valve by accomplishing the requirements of paragraph (d)(2)(i) or (d)(2)(ii) of this AD, as applicable.

(i) For airplanes that have NOT been modified in accordance with Bombardier Service Bulletin 601R-28-022: Open the CBP-1; remove protective tubing, if applicable; release "Unstow" the wire and reconnect it to its respective breaker CB1-N9, in accordance with Wiring Manual 28-20-50; close the CBP-1; remove the "INOP" label and the lock ring from breaker CB1-N9; carry out AMM Task 28-13-43-710-801, "Operational Test of Fuel Transfer SOV"; and remove the AFM limitation required by paragraphs (b)(2) and (f) of this AD.

(ii) For airplanes that HAVE been modified in accordance with Bombardier Service Bulletin 601R-28-022: Open the CBP-1 and CBP-2; remove protective tubing, if applicable; release "Unstow" the wires and reconnect them to their respective breaker CB1-N9 or CB2-P9, in accordance with Wiring Manual 28-20-50; close the CBP-1 and CBP-2; remove the "INOP" labels and lock rings from breakers CB1-N9 and CB2-P9; carry out AMM Task 28-13-43-710-801, "Operational Test of Fuel Transfer SOV"; and remove the AFM limitation required by paragraph (f) of this AD.

Dispatch of Airplane With Inoperative Valves

(e) Except as required by paragraph (b) of this AD: The airplane may be operated with the center fuel tank full and with both fuel transfer shutoff valves inoperative (applicable circuit breakers opened as specified by paragraph (a) of this AD), until accomplishment of paragraph (d) of this AD. Where the provisions of this AD and the MMEL differ, this AD prevails.

AFM Revision

(f) Concurrently with accomplishing the actions required by paragraph (a) of this AD, revise the Limitations section of the AFM to include the following (this may be accomplished by inserting a copy of this AD into the AFM):

Note: When the applicable circuit breakers are opened, power is removed from the fuel transfer shutoff valves (SOVs). The fuel transfer SOVs remain open and will continuously allow the transfer of the fuel from the center tank to the wings. The fuel in the center tank is usable. The wing tanks will indicate FULL until the center tank is empty, and an EICAS LR X-FER SOV message will either indicate ON GROUND, or the message may disappear during climb but will remain on during the remainder of the flight."

Following accomplishment of the requirements of paragraph (d), the AFM revision shall be removed from the AFM. Where the provisions of this AD and the MMEL differ, this AD prevails.

Spares

(g) As of the effective date of this AD, no person may install a fuel transfer shutoff valve having P/N 601R62256-5 on any airplane.

Alternative Methods of Compliance

(h) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

Special Flight Permits

(i) Special flight permits may be issued in accordance with Secs. 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(j) The actions required by paragraphs (a) and (c) of this AD shall be done in accordance with Bombardier Alert Service Bulletin A601R-28-045, Revision "A," dated December 7, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bombardier, Inc., Canadair, Aerospace Group, PO Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in Canadian airworthiness directive CF-2001-47, dated December 11, 2001.

Effective Date

(k) This amendment becomes effective on January 14, 2002, to all persons except those persons to whom it was made immediately effective by emergency AD 2001-26-51, issued December 14, 2001, which contained the requirements of this amendment.

Issued in Renton, Washington, on December 20, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-88 Filed 1-7-02; 8:45 am]

BILLING CODE 4910-13-U

FOR FURTHER INFORMATION CONTACT: Luciano L. Castracane, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7535; fax (516) 568-2716.

BW 2002-01

GE AIRCRAFT ENGINES AIRWORTHINESS DIRECTIVE ENGINE LARGE AIRCRAFT

2002-01-03 GE Aircraft Engines: Amendment 39-12594. Docket 2000-NE-61-AD.

Applicability: This airworthiness directive (AD) is applicable to GE Aircraft Engines (GE) CT7 Models CT7-5A2, -5A3, -7A, and -7A1 turboprop engines with part number (P/N) 6064T07P02 stage 2 aft cooling plates with serial numbers beginning with the letters GFF, installed on but not limited to Construcciones Aeronauticas, SA CN-235 series and SAAB Aircraft AB SF340 series airplanes.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Compliance is required at the next overhaul of the engine or hot section module, or within 8,000 cycles after the effective date of this AD, whichever occurs first, unless already done.

To prevent stage 2 turbine aft cooling plate cracking, which could result in uncontained engine failure, and damage to the airplane, do the following:

(a) Replace stage 2 aft cooling plates P/N 6064T07P02 with serial numbers that begin with the letters GFF with stage 2 aft cooling plate P/N 6064T07P05.

(b) After the effective date of this AD, do not install any stage 2 aft cooling plates P/N 6064T07P02 with serial numbers that begin with the letters GFF.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(d) Special flight permits may be issued in accordance Secs. 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

2002-01-03 2

Effective Date

(e) This amendment becomes effective on February 12, 2002.

Issued in Burlington, Massachusetts, on December 31, 2001.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02-302 Filed 1-7-02; 8:45 am]

BILLING CODE 4910-13-P

FOR FURTHER INFORMATION CONTACT: Barbara Caufield, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone: (781) 238-7146; fax: (781) 238-7199.