
		NTSB ID: FTW01FA115		Aircraft Registration Number: N917AL	
		Occurrence Date: 05/04/2001		Most Critical Injury: None	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place Vermillion 44		State GM	Zip Code 00000	Local Time 1616	Time Zone CDT
Airport Proximity: Off Airport/Airstrip		Distance From Landing Facility:			
Aircraft Information Summary					
Aircraft Manufacturer Bell		Model/Series 407		Type of Aircraft Helicopter	
Revenue Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
HISTORY OF FLIGHT					
<p>On May 4, 2001, at 1616 central daylight time, a Bell 407 single-engine helicopter, N917AL, sustained substantial damage due to a drive shaft component failure while operating off shore in the Gulf of Mexico. The commercial pilot and his passenger were not injured. The helicopter was registered to and operated by Air Logistics LLC, of New Iberia, Louisiana. Visual meteorological conditions prevailed and a company visual flight rules flight plan was filed for the 14 Code of Federal Regulations Part 135 on-demand air taxi flight. The helicopter departed the High Island 368 offshore platform at 1535, and was destined for Intracoastal City, Louisiana.</p> <p>In an interview with the NTSB investigator-in-charge (IIC), the pilot reported that while in cruise flight at 700 feet agl, enroute from High Island 368 to Intracoastal City, a "slight vibration became noticeable." After a few minutes, the vibration became more pronounced, and was accompanied by a noise. During an attempted precautionary landing to an offshore platform, the vibration and noise level increased again, and total engine power was lost. The pilot then initiated an autorotation to the water, deployed the skid floats, and landed safely. After landing, the pilot retarded the throttles, shut off the fuel valve and placed the electrical switches to the OFF position. While the helicopter was being towed in the water, the helicopter rolled over inverted. Examination of the helicopter, after recovery by the operator, revealed that the KAFlex engine-to-transmission driveshaft had fractured, and the forward section of the tail rotor driveshaft had separated.</p>					
PERSONNEL INFORMATION					
<p>The pilot held an airline transport pilot certificate with helicopter, airplane single-engine land and multi-engine land ratings. In addition, he held helicopter and airplane instrument ratings. The pilot was issued a second-class medical certificate on March 8, 2001, with the limitation, "Glasses near and intermediate." His total flight time, as of May 4, 2001, was 15,100 hours, of which 2,800 hours were in the Bell 407. He had flown 166 operational flight hours in the Bell 407 during the 90 days prior to the accident.</p>					
AIRCRAFT INFORMATION					
<p>Manufactured at Bell Helicopter Textron Canada (BHTC), the Bell model 407 helicopter, S/N 53381, was certified on September 15, 1999, and delivered to Air Logistics L.L.C., of New Iberia, on September 21, 1999, with 14.6 total flight hours. The helicopter was powered by a 630 horsepower turboshaft Rolls Royce Allison 250-C-47B engine, S/N CAE-847417. According to records provided by the operator, the helicopter had accumulated 2,114.2 total flight hours, 1,771 total cycles, and 4,476 total takeoffs at the time of the accident.</p>					
FACTUAL REPORT - AVIATION					

 <p>National Transportation Safety Board <b>FACTUAL REPORT</b> AVIATION</p>	NTSB ID: FTW01FA115
	Occurrence Date: 05/04/2001
	Occurrence Type: Accident

## Narrative (Continued)

The maintenance records revealed that the fractured KAflex driveshaft, P/N 206-340-300-105, S/N KC734, was last removed and reinstalled on the helicopter on April 10, 2001, at a helicopter time of 1,998 hours. The KAflex driveshaft is often removed when maintenance is performed near the transmission area, pylon mounts, engine, etc. The records indicated that the helicopter's KAflex driveshaft had been removed and reinstalled nine times for both scheduled and unscheduled maintenance prior to accident. The KAflex driveshaft had a total time of 2,114.2 hours and an airworthiness life limit of 5,000 hours.

According to the BHTC maintenance manual, each end of the KAflex driveshaft is comprised of four rectangular flex frames that are attached with bolts to each other and to each end of the shaft. A flange adapter is attached to each flex frame assembly with bolts. One flange adapter bolts to the transmission input adapter, and the other flange adapter bolts to the rotor disk and to the freewheel adapter. The driveshaft turns at 6,317 rpms and transmits the power from the engine to the transmission. The driveshaft is designed to flex to accommodate the misalignment between the engine and transmission that occurs during operation. According to Transport Canada (TC), three incidents involving cracked flex frames on the forward (transmission) end of the driveshaft had previously been reported.


## WRECKAGE AND IMPACT INFORMATION

Initial examination of the wreckage was conducted by the NTSB at the operator's base in New Iberia, on May 8, 2001. The helicopter's fuselage and tail boom were predominately intact. The chin bubbles, forward windscreens, and skid gear floats were damaged during recovery. The mast and rotor system were removed from the helicopter prior to the examination and were also substantially damaged during the recovery. The upper cowlings, with the exception of the hydraulic flight control actuators' cowling, were removed prior to the examination. The engine was observed mounted to the airframe and the engine mounts were found to be secure. The steel tail rotor drive shaft had been torsionally separated approximately 2 inches forward of the dynamic balance weight. The tail rotor gearbox case displayed evidence of salt-water corrosion, and the tail rotor hub and blades were securely mounted to the output shaft with no anomalies noted. The cockpit controls were manually manipulated with no anomalies noted, and continuity was established from the cockpit throughout the entire flight control system. The cockpit switch positions were all in their normal shutdown positions, with the exception of the hydraulic system and the avionics master switches, which were ON. The only open circuit breaker was the GPS circuit breaker.

The KAflex driveshaft was found separated from the transmission input side. The anti-flail device was observed separated from the transmission side of the driveshaft. Separated portions of the driveshaft flex frames were found on the roof deck. The roof deck immediately below the transmission end of the driveshaft had been punctured and displayed signatures of rotational scoring and tearing. In addition, the fuel vent line had been punctured. The oil line that connects to the oil manifold for the freewheeling unit had also been severed. The driveshaft and its fractured components, along with the separated forward tail rotor drive shaft, were retained by the NTSB for further examination.

## TESTS AND RESEARCH

On May 17, 2001, at the facilities of Bell Helicopter, Hurst, Texas, under the supervision of the NTSB, the KAflex driveshaft and tail rotor driveshaft were examined by Bell engineers. Bell Helicopter's materials laboratory examination of the KAflex driveshaft "revealed fatigue fractures at a bolt hole in the first flex frame at the transmission end of the shaft and fatigue fractures in the end fitting at the transmission end. The primary fracture was a fatigue crack that occurred in a bolt hole where a bolt joined the first flex frame to the center flex frame. All the other fractures were a result of overstress." The driveshaft was determined to be manufactured within engineering specifications.

 <p>National Transportation Safety Board <b>FACTUAL REPORT</b> AVIATION</p>	NTSB ID: FTW01FA115
	Occurrence Date: 05/04/2001
	Occurrence Type: Accident

## Narrative (Continued)

Bell Helicopter's materials laboratory report also stated that "the fractured tail rotor driveshaft was a result of torsional overstress. The direction of overstress was consistent with restraint of the driveshaft from the flywheel aft while the forward portion of the shaft was driven in a clockwise direction as viewed looking forward."

## ADDITIONAL INFORMATION

Transport Canada issued Airworthiness Directive (AD) CF-2001-24 on June 11, 2001. The AD discussed this accident and three other incidents involving cracked flex frames on the driveshaft. The AD required a one-time visual inspection for any obvious discrepancy of the driveshaft: "(a) within the next 25 hours air time for shafts with more than 1,000 hours, and for shafts with less than 1,000 hours which have been removed or installed since the helicopter was delivered; (b) or within the next 300 hours for shafts with less than 1,000 hours that have never been removed or installed since delivery." The one-time inspection was to be conducted in accordance with Bell Helicopter Alert Service Bulletin (ASB) 407-01-43, dated June 8, 2001. The ASB discussed the possibility of driveshaft failure due to fatigue cracking of the flex frames. The Federal Aviation Administration (FAA) issued AD 2001-13-51, dated June 27, 2001, which addressed the same subject matter as TC's CF-2001-24 AD and utilized the same inspection requirements and intervals.

Transport Canada also issued AD CF-2002-03, effective on February 28, 2002. The AD discussed this accident and the three additional incidents of cracked driveshaft flex frames. The AD stated that: "It has been determined that the KAflex driveshaft on model 407 helicopters is experiencing higher loads than on other helicopter models. Since the KAflex shaft P/N 206-340-3---105 can also be installed on Models 206L-4 and 427, this directive requires a component review to determine if the KAflex shaft was previously installed on Model 407." The corrective actions called for in the AD were:

"Part 1. Models 206L-4 and 427

Review of the Historical Service Record of the KAflex driveshaft to determine if it was ever installed on a Bell Model 407 helicopter:

(a) If the KAflex driveshaft has never been installed on a Bell Model 407 helicopter, then annotate the helicopter log book as follows: P/N 206-340-300-105 KAflex driveshaft has not been installed on a Bell 407. AD CF-2002-03 accomplished;

(b) If the KAflex driveshaft P/N 206-340-300-105 has been previously installed for any length of time on a Bell 407 helicopter, remove from service as per the applicable schedule published in BHTC Alert Service Bulletin 206L-01-123 or 427-01-45, both dated 12 October 2001, or later revisions approved by the Director, Aircraft Certification, Transport Canada."

Part 2. Model 407

Remove shaft P/N 206-340-300-105 as per the compliance schedule provided in BHTC Alert Service Bulletin 407-01-45 Rev "A" dated 21 November 2001, or later revisions approved by the Director, Aircraft Certification, Transport Canada.

The BHTC ASB 407-01-45 was issued to introduce the a new engine-to-transmission driveshaft, P/N 206-340-300-107, with a 1,250-hour overhaul interval and end identification marks. The bulletin requires the removal of driveshafts 206-340-300-105 per a described compliance schedule. The overhauled driveshafts are renumbered and retain an airworthiness life limit of 5,000 hours from new.

At the time of this writing, the FAA has not adopted an AD regarding Transport Canada's AD CF-2002-03.

National Transportation Safety Board

**FACTUAL REPORT  
AVIATION**




NTSB ID: FTW01FA115


Occurrence Date: 05/04/2001

Occurrence Type: Accident

Narrative (Continued)

The helicopter was released to the owner.

 <b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b>		NTSB ID: FTW01FA115			
		Occurrence Date: 05/04/2001			
		Occurrence Type: Accident			
<b>Landing Facility/Approach Information</b>					
Airport Name	Airport ID:	Airport Elevation Ft. MSL	Runway Used	Runway Length	Runway Width
Runway Surface Type: Water					
Runway Surface Condition: Unknown					
Approach/Arrival Flown: NONE					
VFR Approach/Landing: Forced Landing					
<b>Aircraft Information</b>					
Aircraft Manufacturer Bell		Model/Series 407		Serial Number 53381	
Airworthiness Certificate(s): Normal					
Landing Gear Type: Skid					
Amateur Built Acft? No	Number of Seats: 7	Certified Max Gross Wt.	5250 LBS	Number of Engines: 1	
Engine Type: Turbo Shaft	Engine Manufacturer: Rolls Royce Allison	Model/Series: 250-C-47B	Rated Power: 630 HP		
- Aircraft Inspection Information					
Type of Last Inspection AAIP	Date of Last Inspection 04/2001	Time Since Last Inspection 139 Hours	Airframe Total Time 2114.2 Hours		
- Emergency Locator Transmitter (ELT) Information					
ELT Installed?/Type Yes /	ELT Operated? No	ELT Aided in Locating Accident Site? No			
<b>Owner/Operator Information</b>					
Registered Aircraft Owner Air Logistics L.L.C.		Street Address 4605 Industrial Dr.			
		City New Iberia	State LA	Zip Code 70560	
Operator of Aircraft Air Logistics L.L.C.		Street Address 4605 Industrial Dr.			
		City New Iberia	State LA	Zip Code 70560	
Operator Does Business As:			Operator Designator Code: ALGL		
- Type of U.S. Certificate(s) Held:					
Air Carrier Operating Certificate(s): On-demand Air Taxi					
Operating Certificate:			Operator Certificate: Aircraft External Load		
Regulation Flight Conducted Under: Part 135: Air Taxi & Commuter					
Type of Flight Operation Conducted: Non-scheduled; Domestic; Passenger/Cargo					

 <p><b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b></p>	NTSB ID: FTW01FA115
	Occurrence Date: 05/04/2001
	Occurrence Type: Accident

**First Pilot Information**

Name On File	City On File	State On File	Date of Birth On File	Age 51
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Right	Occupational Pilot? Civilian Pilot	Certificate Number: On File
--------	----------------------	------------------------------------	-----------------------------

Certificate(s): Airline Transport

Airplane Rating(s): Multi-engine Land; Single-engine Land

Rotorcraft/Glider/LTA: Helicopter

Instrument Rating(s): Airplane; Helicopter

Instructor Rating(s): None

Current Biennial Flight Review? 03/2001

Medical Cert.: Class 2	Medical Cert. Status: Valid Medical--w/ waivers/lim.	Date of Last Medical Exam: 03/2001
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	15100	2800	285	1970		363				
Pilot In Command(PIC)	14100	2800	248	1140						
Instructor										
Instruction Received										
Last 90 Days	180	166								
Last 30 Days	72	72								
Last 24 Hours	6	6								

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? No
--------------------	----------------------------	--------------------------	------------------

**Flight Plan/Itinerary**

Type of Flight Plan Filed: VFR

Departure Point HI-338	State GM	Airport Identifier 368	Departure Time 1535	Time Zone CDT
---------------------------	-------------	---------------------------	------------------------	------------------

Destination Intercoastal	State LA	Airport Identifier 7RA	
-----------------------------	-------------	---------------------------	--


Type of Clearance: Unknown

Type of Airspace: Class G

**Weather Information**

Source of Wx Information:

Unknown


 <p>National Transportation Safety Board <b>FACTUAL REPORT</b> AVIATION</p>	NTSB ID: FTW01FA115
	Occurrence Date: 05/04/2001
	Occurrence Type: Accident

<b>Weather Information</b>					
WOF ID	Observation Time	Time Zone	WOF Elevation Ft. MSL	WOF Distance From Accident Site NM	Direction From Accident Site Deg. Mag.
Sky/Lowest Cloud Condition: Clear			Ft. AGL	Condition of Light: Day	
Lowest Ceiling: None		Ft. AGL	Visibility: 10	SM	Altimeter: "Hg
Temperature: 28 °C	Dew Point: °C	Weather Conditions at Accident Site: Visual Conditions			
Wind Direction:		Wind Speed:		Wind Gusts:	
Visibility (RVR): Ft.	Visibility (RVV) SM				
Precip and/or Obscuration:					

<b>Accident Information</b>		
Aircraft Damage: Substantial	Aircraft Fire: None	Aircraft Explosion: None

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot					
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants					
Other Crew					
Passengers				1	1
- TOTAL ABOARD -				2	2
Other Ground					
- GRAND TOTAL -				2	2

--

 National Transportation Safety Board <b>FACTUAL REPORT</b> AVIATION	NTSB ID: FTW01FA115	
	Occurrence Date: 05/04/2001	
	Occurrence Type: Accident	

Administrative Information

Investigator-In-Charge (IIC)  
Alexander Lemishko

Additional Persons Participating in This Accident/Incident Investigation:

Mark S Evans  
FAA FSDO  
Baton Rouge, LA

Matthew Rigsby  
Bell Helicopter Textron Canada  
Fort Worth, TX

Gary Tucker  
Air Logistics, L.L.C.  
Lafayette, LA

Jeffery M Post  
Kamatics Corporation  
Bloomfield, CT