

Failure Report on HPR/CR at KEK/Nomura

SMTF meeting

6 October 2005

Takayuki SAEKI (KEK)

Introduction

- What happened since 1st ILC WS at KEK (Nov. 2004) are reported.
- We have two HPR facilities, at KEK and at Nomura Plating Co.
- Oil contamination in HPR water at KEK.
- Valve usage in HPR at Nomura.
- Clean-room for assembly at KEK

Three problems mixed

In cavity performance

In EP operations

1) Field emission



1) Oil contamination
in HPR water

2) Q-disease

2) EP acid level
& temp. control

3) Q-slope at low field
(only partially solved?)

3) HF density in EP acid




Oil-contamination problem


RE-cavity 4th meas.

Q_0 vs. E_{acc}

2005/06/04 Sat.




Oil contamination problem



KEK clean assembly system in KEK
Air-compressor was miss-chosen

Added

New oil-free compressor + cleaning tank and pipes.



KEK clean assembly system after cleaning work

Stop using this compressor

Oil-contamination level before/after cleaning work




Fig.5 : Oil contamination level decreased to 1/4 by the cleaning work.

No in-line water monitor

=> contamination was found after several VTs.

Even after cleaning work at KEK, we are using HPR @ Nomura (UPW).
All high-gradient results of single-cell cavities are with HPR @ Nomura (UPW).

What was learned (Oil contamination)

Cause of failure

- The water system needed minor change because Cold-Evaporator (CE) line terminated.
- Miss-choice of an air-compressor.



Current status

- New oil-free air-compressor was bought.
- Clean-up the tank and pipes.
- For the moment, HPR at Nomura (UPW) becomes the default process.




Recommended system


- Future plan: in-line monitor of TOC and particle counter. Periodic analysis of bacteria by KEK staff.

Cavity performance with / without oil-contamination problem

Q0 vs Eacc with HPR (UPW @ Nomura) and
Field-emission at low Eacc with HPR (oil-contamination at KEK)



Cable problem



**Pickup cable :
Bad contact at connector.**

**Cycling of cool-down and
warm-up damages the cable.**




**Changing pick-up cable
solved this problem.**

HPR clean-room problem at Nomura

LL-No.1 11th meas.

Aneal(750C*3hr)+EP(30um)+HPR@Nomura
assembling without air blower+Baking(120C*48hr)

2005/06/13 Mon.



HPR clean-room problem at Nomura



**HPR at Nomura is in clean-room (class 1000).
But the clean-room is not clean enough.**

HPR clean-room problem at Nomura

After HPR, operator seals top and bottom flanges of cavity.
Then KEK staff carry it to KEK for assembly in clean-room.
But it seemed that, during this sealing operation, particles
may go inside the cavity....


Valve is put on the bottom
flange of cavity before HPR.




After setting the valve and starting
HPR, operator goes out the clean-
room. No operator in the clean-
room during HPR.



15 min. before the end of HPR,
operator comes in the clean-
room again to sit inside the CR.
Then, operator closes calve at the
end of HPR. => carry to KEK.



RE single-cell cavity achieved 47 MV/m on 30 July 2005.




: Vertical test (9th) on reentrant cavity

Re-annealed (750°C,3hr) +EP(30μm)+HPR(Nomura, ultra-pure water)+Bake(120°C, 48hr)

RE cavity HPR at Nomura

2005Sep14 Nomura HPR



Class = # of particles (>0.5 um) per CF

Assembly of cavity in clean-room at KEK

After HPR at Nomura (UPW),
KEK staff carries cavity to KEK
for assembly in clean-room.

HEPA filter (class 100)


ULPA filter (class 10)



Clean-room at KEK


RE cavity assemble at KEK

2005Sep14 RE cavity assemble



28 particles ($>0.3\mu\text{m}$) / CF = class 10

RE cavity performance with HPR @ Nomura (on 14 Sept.) and assembly @ KEK (on 14 Sept.)



Clean-room in KEK

- We cleaned up the clean-room at KEK (swept wall, floor, curtain...etc)
- Compared the cleanness of CR before/after the cleaning of CR by particle counter.
- It seems that cleaning CR does not affect so much in cavity performance.
- Operator's moving & acting calmly during assembly is most effective to avoid particle's going inside cavity.
- Also, cleaning CR-wear seems a bit effective.

Summary

- Oil-contamination in HPR water @ KEK caused field emission.
- Oil-free compressor was bought, and water-tank and pipes were cleaned up.
- But, default HPR = HPR at Nomura (UPW).
- Cable problem was solved by changing cable.
- CR for HPR @ Nomura is not clean enough. => caused field emission.
- Valve operation during HPR @ Nomura solved the field emission problem.
- Assembly in CR @ KEK: Operator's moving & acting calmly is most effective.