
ELECTRICAL SAFETY OCCURRENCES IN CY 2006

Rate of Electrical Safety Occurrences

Trends:

- DOE facilities experienced 166 electrical safety occurrences in CY 2006 (see Appendices I and II for details). This is near the 165 experienced in 2005, slightly more than the 149 in 2004, and significantly more than the yearly average of 106.5 reported for 2002-2003.
- The monthly rate of occurrences generally decreased during 2006 (see chart below). However, there were 16 electrical safety occurrences in January 2007, so the downward trend has not continued since.



- There were 26 electrical shocks reported in 2006. This is less than the 39 reported in 2005, near the 25 in 2004 and more than the yearly average of 17.5 per year experienced in 2002-2003.
- There were 3 burns from electrical occurrences in 2006, which was less than the 5 experienced in 2005, and the same as the yearly rate for 2004 and 2002-2003. The three burns in 2006 were 1st and 2nd degree burns resulting from arc flashes. One initiated a Type B Accident Investigation.
- 41% of the electrical safety occurrences in 2006 were categorized as "Near Miss (Electrical)" by HQ Keywords in ORPS. (In contrast, 68% of the 2005 electrical safety occurrences and 77% of the 2004 electrical safety occurrences were categorized as near misses. The lower percentage of near misses in 2007 is more likely due to a shift in philosophy towards near miss categorization rather than changes in the nature of the occurrences.)
- Slightly more than half of the 2006 electrical safety occurrences (i.e., 84 of 166) involved non-electrical workers.
- 39% of the electrical safety occurrences in 2006 involved subcontractor. (In contrast, only 21% of all 2006 ORPS occurrences involved subcontractors.)

Work Activities Associated with 2006 Electrical Safety Occurrences

Trends:

- 23% of the 2006 electrical safety occurrences involved lockout/tagout issues.
- 10% involved cutting or drilling activities.
- 8% involved vehicles striking electrical power lines.
- 7% involved excavation.
- The following is a breakdown of work activities associated with the 2006 electrical safety occurrences, as defined in the ORPS reports:

| ORPS Activity Category | number |
|--|--------|
| Normal Operations (other than Activities listed below) | 62 |
| Maintenance | 44 |
| Construction | 34 |
| Facility Decontamination/Decommissioning | 8 |
| Research | 8 |
| Facility/System/Equipment Testing | 5 |
| Startup | 2 |
| Inspection/Monitoring | 2 |
| Transportation Onsite | 1 |
| Total | 166 |

Causes of Electrical Safety Occurrences

Trends:

- ORPS reports identified a wide variety of apparent causes for electrical safety occurrences in 2006.
- Deficiencies in management policy guidance, job scoping, check of work, and communication were the four most commonly identified apparent causes for the 2006 electrical safety occurrences. These were also the top four apparent causes for the 2004 and 2005 electrical safety occurrences.
- 56% of the 2006 electrical safety occurrences had "Conduct of Operations" assigned in the HQ Keywords.
- "Analyze the hazards," "develop and implement hazard controls," and "perform work within controls" were the leading ISM Core Functions cited by ORPS report writers for electrical safety occurrences.

| ORPS Code | Apparent Cause Description ¹ | CY06 No. |
|-----------|---|----------|
| A4B1C01 | Management policy guidance / expectations not well- | 32 |
| | defined, understood or enforced | |
| A4B3C08 | Job scoping did not identify special circumstances and/or | 28 |
| | conditions | |
| A3B1C01 | Check of work was LTA | 14 |
| A5B4C01 | Communication between work groups LTA | 14 |
| A4B3C11 | Inadequate work package preparation | 12 |
| A5B2C08 | Incomplete / situation not covered | 12 |
| A3B1C03 | Incorrect performance due to mental lapse | 10 |
| A3B2C05 | Situation incorrectly identified or represented results in | 10 |
| | wrong rule used | |
| A4B3C09 | Work planning not coordinated with all departments | 10 |
| | involved in task | |
| A4B5C04 | Risks / consequences associated with change not adequately | 10 |
| | reviewed / assessed | |
| A3B3C05 | Incorrect assumption that a correlation exists between two or | 9 |
| | more facts | |
| A3B1C06 | Wrong action selected based on similarity with other actions | 8 |
| A3B3C03 | Individual justified action by focusing on biased evidence | 8 |
| A3B3C01 | Attention was given to wrong issues | 7 |
| A3B3C06 | Individual underestimated the problem by using past events | 7 |
| | as basis | |
| A4B1C03 | Management direction created insufficient awareness of the | 7 |
| | impact of actions on safety / reliability | |
| A4B1C04 | Management follow-up or monitoring of activities did not | 7 |
| | identify problems | |
| A1B5C02 | Physical environment LTA | 6 |
| A2B6C01 | Defective or failed part | 6 |
| A3B1C04 | Infrequently performed steps are performed incorrectly | 6 |
| A3B2C02 | Signs to stop were ignored and step performed incorrectly | 6 |
| A4B1C07 | Responsibility of personnel not well defined or personnel not | 6 |
| | held accountable | |
| A4B3C06 | Planning not coordinated with inputs from walkdowns/task | 6 |
| | analysis | |
| A4B4C02 | Progress/status of task not adequately tracked | 6 |
| A4B4C03 | Appropriate level of in-task supervision not determined prior | 6 |
| | to task | |
| A6B1C02 | Training requirements not identified | 6 |
| | (87 other causal "C nodes" identified, in quantities of 1 to 5.) | |
| | of apparent courses in this table does not cover all of the electrical accurrence | |

^{1.} The distribution of apparent causes in this table does not cover all of the electrical occurrences in 2006. Thirty four of the 166 electrical safety occurrences were reported as Significance Category 4 and thus did not require a causal analysis. Because this analysis was made in early February 2007, there may have been a few occurrences in late 2006 that had not completed their causal analyses, and so their apparent causes are not included in the table above.

| ORPS Code | ORPS "HQ Keyword" Description | CY06 No. |
|-----------|---|----------|
| 01A | Conduct of Operations (miscellaneous) | 93 |
| 08H | Safety Compliance | 88 |
| 12C | Electrical Safety | 87 |
| 07D | Electrical Wiring | 77 |
| 14E | Work Process | 70 |
| 08J | Near Miss (Electrical) | 68 |
| 01M | Inadequate Job Planning (Electrical) | 67 |
| 11G | Subcontractor | 59 |
| 12K | Near Miss (Could have been a serious injury or fatality) | 55 |
| 01Q | Personnel error | 47 |
| 01B | Configuration Management/Control | 41 |
| 01R | Management issues | 40 |
| 01K | Lockout/Tagout (Electrical) | 39 |
| 01P | Communication | 38 |
| 13E | Facility Call Sheet | 31 |
| 08A | Electrical Shock | 26 |
| 14D | Documents and Records | 26 |
| 08F | Industrial Operations | 25 |
| 01F | Training | 23 |
| 01N | Inadequate Job Planning (Other) | 21 |
| 010 | Maintenance | 21 |
| 12I | Lockout/Tagout (Electrical or Mechanical) | 20 |
| 01G | Inadequate Procedure | 19 |
| 07C | Power Outage | 19 |
| 01E | Operations Procedures | 15 |
| 07E | Electrical Equipment | 10 |
| 14B | Training and Qualification | 10 |
| | (33 other keyword categories with counts between 1 and 9) | |

| ISM Core Functions Cited for Electrical Occurrences | CY06 No. |
|---|----------|
| Define the Scope of Work | 21 |
| Analyze the Hazards | 80 |
| Develop and Implement Hazard Controls | 67 |
| Perform Work Within Controls | 67 |
| Provide Feedback and Continuous Improvement | 19 |
| N/A (Not applicable to ISM Core Functions as determined by management | 8 |
| review.) | |

Distribution of Electrical Safety Occurrences by Secretarial Offices

Trends:

- In 2006, NA had the largest percentage of electrical safety occurrences of all DOE Secretarial Offices. (In contrast, EM had the largest percentage electrical safety occurrences in 2002 through 2005.)
- NE had a significantly larger percentage of electrical safety occurrences in 2006 than it had in 2002 through 2005.

| Sec Office | No.CY06 | % CY06 | % CY05 | % CY04 | % CY02 & 03 ¹ |
|------------|---------|--------|--------|--------|--------------------------|
| NA | 61 | 37% | 42% | 31% | 28% |
| EM | 53 | 32% | 42% | 51% | 46% |
| SC | 34 | 20% | 13% | 14% | 18% |
| NE | 17 | 10% | 2% | 1% | 3% |
| EE | 1 | <1% | 0% | 0% | 0% |
| RW | 0 | 0% | <1% | 2% | 4% |
| FE | 0 | 0% | 0% | <1% | 1% |
| total | 166 | 100% | 100% | 100% | 100% |

^{1.} Percentages based on distribution in slide from <u>Electrical Safety Occurrences - Overview of Nature</u>, <u>Causes and Frequency</u>, <u>July 27</u>, 2004.

Distribution of Electrical Safety Occurrences by Operations, Field & Site Offices

Trends:

- In 2006, electrical safety occurrences happened at most DOE Operations and Field Offices.
- Facilities under the Idaho Operations Office experienced the largest number of electrical safety occurrences in CY 2006.

| Operations, Field or Site Office with Electrical Occurrences | No. CY06 |
|--|----------|
| Idaho Operations | 26 |
| Los Alamos Site Office | 19 |
| Richland Operations | 15 |
| Sandia Site Office | 13 |
| Livermore Site Office | 9 |
| River Protection Operations | 8 |
| Stanford Site Office | 8 |
| Oak Ridge Operations Office | 7 |
| Savannah River Operations | 7 |
| Brookhaven Site Office | 7 |
| Pantex Site Office | 7 |
| Y12 Site Office | 7 |
| Argonne Site Office | 6 |
| Berkeley Site Office | 5 |

| Ohio Operations (includes West Valley & Fernald) | 4 |
|--|-----|
| Pacific Northwest Site Office | 4 |
| Kansas City Site Office | 3 |
| Carlsbad Field Office | 2 |
| NNSA Service Center | 2 |
| Fermi Site Office | 2 |
| Portsmouth Paducah Project Office | 2 |
| Golden Field Office | 1 |
| Nevada Site Office | 1 |
| Savannah River Site Office | 1 |
| Total | 166 |

Summary and Conclusions

The Department-wide number of electrical safety occurrences in CY 2006 was near the same as the number experienced in CY 2005. The monthly totals for CY 2006 showed an encouraging decreasing trend. However, the monthly total for January 2007 rose significantly and so the trend has not continued.

The causes for electrical safety occurrences appear to be the same as identified in several analyses performed in the last few years. (See the reports listed on the HSS Electrical Safety website: http://www.hss.energy.gov/CSA/Analysis/electrical.html.) A Special Operations Report (SOR) issued in August 2006 attempted to solicit more detailed causal information but, as of early February 2007, the SOR findings had not been finalized and issued by the Undersecretaries' offices.

While the SOR addresses the operations and training of electrical workers, it is important to note that typically half of the electrical safety occurrences involve non-electrical workers. Online training for non-electrical workers is available at: http://www.efcog.org/wg/ism_estg/elecsafetytng.htm.

APPENDIX I – Identification of the 166 electrical safety occurrences in CY 2006.

ORPS was searched using the following search criteria to "screen-in" electrical safety occurrences:

Discovery dates (not notification dates) were set for dates in 2006. The following ORPS "HQ keywords" were also keyed in the searches.

01K – Lockout/Tagout Electrical

01M - Inadequate Job Planning (Electrical)

08A – Electrical Shock

08J – Near Miss (Electrical)

12C – Electrical Safety

The initial search yielded 179 occurrences. Each occurrence was next read to see it really involved electrical hazard hazards. "Recurring Occurrences" were discounted to avoid double counting. The following thirteen 2006 occurrences were culled out for the reasons so cited:

- 1. EM-ID--CWI-LANDLORD-2006-0007, "Deviation from Work Control Procedure" LOTO is to prevent alarms, voltage was below 28 VAC.
- 2. EM-ID--CWI-PHASEOUT-2006-0001, "Lock out Tagout Violation on Crane" LOTO was for crane movement, not electrical hazard.
- 3. EM-RL--PHMC-GPP-2006-0004, "Incorrect Isolation Information" LOTO was for a 24V circuit.
- 4. EM-RL--PHMC-GENERAL-2006-0002, "Repetitive Issue: Hazardous Energy Control/Lockout-Tagout Process" Recurring Occurrence
- 5. EM-RL--PHMC-SOLIDWASTE-2006-0009, "Management Concern Related to Compliance with Work Package Requirements" Hazard was from rotating equipment, not electrical.
- 6. EM-RL--WCH-GENAREAS-2006-0005, "Recurring Events Associated with Work Control Issues Resulting in Electrical Hazards" Recurring Occurrence
- 7. EM-RP-BNRP-RPPWTP-2006-0011, "Subcontractor Violates WTP Procedure" LOTO violations was for HVAC ventilation, not electrical hazard
- 8. EM-SR--WSRC-FCAN-2006-0003, "Severed Antenna Tower Ground Cable (U)" Hazard from lightning strikes, not conventional electrical hazard.
- 9. NA--LASO-LANL-TARGETFAB-2006-0001, "Failure to follow equipment postings results in confined space violation" Hazard was confined space, not electrical.
- 10. NA--PS-BWXP-PANTEX-2006-0051, "Failure to Adhere to BWXT Subcontractor LO/TO Procedures" LOTO violation was for HVAC ventilation, not electrical hazard.
- 11. NA--SS-SNL-NMSITE-2006-0004, "Recurring Occurrence Reports Associated with Performance Analysis of Cause Code A4B5C04" Recurring Occurrence
- 12. NA--SS-SNL-SNLCORP-2006-0001, "Hazardous Energy Recurring Occurrence" Recurring Occurrence
- 13. SC--PSO-PPPL-PPPL-2006-0002, "Lockout/Tagout Violation" Heat hazard, not electrical.

The screening and culling above yielded the 166 electrical safety occurrences for 2006 that were considered in this analysis.

APPENDIX II – List of 166 electrical safety occurrences in 2006.

| ORPS Report Number | Subject/Title |
|-----------------------------------|---|
| 1 EE-GONREL-NREL-2006-0008 | Roofing screws penetrate data and electrical conduits |
| 2 EMLSO-ETEC-GENL-2006-0003 | Forklift Damages Electrical Conduit |
| 3 EMPPPO-PRS-PGDPENVRES-2006-0017 | Exterior Bracket Installation Results in Power Interruption in Office Trailer |
| 4 EMPPPO-UDS-PORTDUCON-2006-0001 | Contractor failed to follow requirements of Activity Hazards Analysis |
| 5 EM-CAFOWTS-WIPP-2006-0004 | Worker Received Electrical Shock |
| 6 EM-CAFOWTS-WIPP-2006-0006 | Worker Discovers Energized Wire |
| 7 EM-IDBBWI-AMWTF-2006-0001 | 480V Cable Entangled in Snow Blower Blades during Snow Removal Activity Outside WMF-636 |
| 8 EM-IDBBWI-AMWTF-2006-0002 | Lighting Panel Damaged During Snow Removal Activities Outside WMF-1604 |
| 9 EM-IDBBWI-AMWTF-2006-0010 | Worn Insulation On Heat Trace Terminations Creates Potential Electrical Shock Hazard |
| 10 EM-IDBBWI-AMWTF-2006-0013 | LockOut/Tagout of Incorrect Isolation Point |
| 11 EM-IDCWI-BIC-2006-0002 | Damaged 120 V power cord at TRA-644 |
| 12 EM-IDCWI-FUELRCSTR-2006-0002 | Electrician Fails to Lockout 110 Volt Energy Sources During Repair Work |
| 13 EM-IDCWI-FUELRCSTR-2006-0018 | Work Performed Without Using Flash Calculations Identified in Work Order |
| 14 EM-IDCWI-LANDLORD-2006-0014 | Oven Malfunction Causes Cafeteria Worker to Receive an Electric Shock |
| 15 EM-IDCWI-RWMC-2006-0001 | Snow Removal Equipment Ran Off Road |
| 16 EM-IDCWI-RWMC-2006-0004 | Damaged Electrical Cord During Ice/Snow Removal Activities |
| 17 EM-IDCWI-TAN-2006-0001 | Electrical Cord Severed While Performing Snow Removal |
| 18 EM-OH-FCP-FFI-FEMP-2006-0003 | Pipefitter Inadvertently Cuts Live 120-v Double-Insulated Grinder Power Cord |
| 19 EM-OH-FCP-FFI-FEMP-2006-0027 | Heavy Equipment Operator Strikes Overhead 13.2 KV Lines while Operating a CAT 375 Excavator |
| 20 EM-OH-WVDP-WVNS-CF-2006-0001 | Cut Heat Trace Wire During Removal of Gutter Downspout |
| 21 EM-OH-WVDP-WVNS-UR-2006-0001 | Incorrect Conduit Cut during Boiler Demolition |
| 22 EM-OROBJC-K25ENVRES-2006-0005 | Energized 120 Volt AC Line Cut in K-1401 |
| 23 EM-OROBJC-X10ENVRES-2006-0003 | Lockout/Tagout Violation - Trench 7, ORNL |
| 24 EM-OROFWEC-TRUWPFAC-2006-0001 | Failure to follow procedure resulted in potential for unsafe work condition |
| 25 EM-RLPHMC-CSB-2006-0003 | Energized Heat Trace Found During Routine Preventative Maintenance |
| 26 EM-RLPHMC-FFTF-2006-0001 | 120 volt power found in Motor Control Center EF-2 Breaker Cubicle after safe conditions check had been performed. |
| 27 EM-RLPHMC-PFP-2006-0003 | 120-vac circuit discovered energized after the identified breaker was shut off at the lighting panel |
| 28 EM-RLPHMC-PFP-2006-0021 | Extraneous electrical extension cord damaged during demolition activities resulting in a tripped GFCI |
| 29 EM-RLPHMC-PFP-2006-0024 | Performance of High Mast Lighting Drilling prior to hanging Lock & Tag as required by procedure |

| 30 EM-RLPHMC-SNF-2006-0002 | Failure to Follow Prescribed Hazardous Energy Control Process at KW Basin |
|---|--|
| 31 EM-RLPHMC-SNF-2006-0003 | Failure to Follow Prescribed Hazardous Energy Control Process at KE Basin |
| 32 EM-RLPHMC-SNF-2006-0007 | Hose-In-Hose Lock and Tag Issue |
| 33 EM-RLPHMC-SNF-2006-0009 | Exposure to Static Electricity While Working Within the Vicinity of High Voltage Power Lines |
| 34 EM-RLPHMC-SOLIDWASTE-2006-0008 | Electrical Cord Pulled Loose from Female Cord Cap of Handheld Portable Equipment |
| 35 EM-RLPHMC-WESF-2006-0002 | Energized Neutral Wire Found During Replacement of Light Ballast |
| 36 EM-RLWCH-DND-2006-0006 | Pipefitter Receives Electric Shock Through Pipe Cut By Portaband Saw |
| 37 EM-RLWCH-GENAREAS-2006-0003 | Electrical Wires Encountered While Digging in the 331 LSL Drain Field |
| 38 EM-RLWCH-REMACT-2006-0007 | Road Grader Disconnects Underground Electrical Cable from Junction Box at 100-N |
| 39 EM-RLWCH-RISS-2006-0002 | Worker Cuts Into Live Electrical Wire During Transite Panel Removal at 105-N Building |
| 40 EM-RPBNRP-RPPWTP-2006-0002 | Configuration Management Discovery |
| 41 EM-RPBNRP-RPPWTP-2006-0005 | Electrical Arc Between Welding Lead and Welding Machine |
| 42 EM-RPBNRP-RPPWTP-2006-0014 | Vendor Violates WTP Lock Out/Tag Out Procedure |
| 43 EM-RPBNRP-RPPWTP-2006-0019 | Tractor/Truck Backs Trailer Over Above Ground (live 480-V) Conduit |
| 44 EM-RPBNRP-RPPWTP-2006-0026 | 240-Volt Electrical Line Severed by Descending Scissor Lift |
| 45 EM-RPCHG-ANALLAB-2006-0002 | Forklift Driver Pulls Electrical Junction Box And Conduit From Wall |
| 46 EM-RPCHG-TANKFARM-2006-0003 | Bare Wire In An Existing Excavation In AN Farm Discovered |
| 47 EM-RPCHG-TANKFARM-2006-0032 | Energized Wire Found While Performing Safe To Work Check Of Field Electrical Skid |
| 48 EM-SRGOSR-GOSR-2006-0002 | Temporary Un-energized Power Pole Removal Incident at SRS |
| 49 EM-SRWSRC-ETP-2006-0001 | Unexpected Voltage Found on Plant Air Compressor #1 |
| 50 EM-SRWSRC-HTANK-2006-0001 | Discovery of Inadequate L/T Boundary |
| 51 EM-SRWSRC-HTANK-2006-0010 | 8Q32 Single Point Lockout (SPLT) Program Nonconformance |
| 52 EM-SRWSRC-LTA-2006-0004 | Voltage Found on Common Neutral Lead after L/T was Established |
| 53 EM-SRWSRC-SW&I-2006-0003 | Employee Receives Electrostatic Discharge |
| 54 EM-SRWSRC-WVIT-2006-0003 | 704-S Cafeteria Coffee Maker Electrical Shock |
| 55 NAGOAL-NNSASC-2006-0001 | Failure to Lockout/Tagout by Contractor |
| 56 NAGOAL-NNSASC-2006-0002 | Near Miss with Energized Electrical Circuit |
| 57 NAKCSO-AS-FMTNM-2006-0002 | Discovery of Energized Neutral Wire During Repair of Light Fixture |
| 58 NAKCSO-AS-KCP-2006-0001 | 120 Volts AC Electrical Plug Near Miss |
| 59 NAKCSO-AS-KCP-2006-0006 | Damaged Overhead Communications Cable |
| 60 NALASO-LANL-ACCCOMPLEX-2006-0001 | Workers Discover Uncontrolled Hazardous Energy While Penetrating A Concrete Wall |
| 61 NALASO-LANL-ACCCOMPLEX-2006- 0006 | Unauthorized Electrical Work Results in Near Miss to Injury |
| | |

| 62 NALASO-LANL-ADOADMIN-2006- 0003 | Inadequate Work Verification Results in an Electrical Arc Flash During Switching Process |
|---|---|
| 63 NALASO-LANL-ADOADMIN-2006- 0006 | Lockout/Tagout Violation Identified on Construction Project |
| 64 NALASO-LANL-BOP-2006-0001 | Contract Worker hits 480V Circuit with Jackhammer |
| 65 NALASO-LANL-BOP-2006-0003 | Contract Worker hits 120V Circuit with Jackhammer |
| 66 NALASO-LANL-BOP-2006-0006 | Crane Contact with 480 Volt Buss Bar |
| 67 NALASO-LANL-ESHSUPT-2006-0001 | Forklift Mast Contacts Overhead Power Line During Transport |
| 68 NALASO-LANL-FIRNGHELAB-2006- 0001 | Electric shock with no injury from contacting live wires inside control chassis |
| 69 NALASO-LANL-FIRNGHELAB-2006- 0003 | Damaged plug strip leads to spark and unexpected discovery of hazardous energy. |
| 70 NALASO-LANL-FIRNGHELAB-2006- 0004 | Worker strikes 120v circuit within modular furniture power pole |
| 71 NALASO-LANL-FIRNGHELAB-2006- 0005 | Arc flash from contacting 480V power within motor control center |
| 72 NALASO-LANL-HEMACHPRES-2006- 0004 | Management Concern; Change of Scope Introduced Unevaluated Hazards |
| 73 NALASO-LANL-LANL-2006-0002 | Buildings Flooded Due to Excess Rain |
| 74 NALASO-LANL-MATSCCMPLX-2006- 0001 | Worker Cuts Energized Electrical Wire |
| 75 NALASO-LANL-PHYSTECH-2006-0007 | Upright Vehicle Antenna Mast Snags and Severs Overhead Communication Line During Transport |
| 76 NALASO-LANL-PHYSTECH-2006-0008 | Unplanned Power Outage Occurs Due to Inadvertent Tripping of Circuit Breaker in the Electrical Distribution System |
| 77 NALASO-LANL-TA55-2006-0008 | Management Concern: Combination Fluorescent Light and Emergency Light Failed When Test Button was Pushed After Tube Replacement |
| 78 NALASO-LANL-TA55-2006-0023 | Employee Cut Electrical Cord While the Cord was Plugged Into a 120 Volt Wall Outlet |
| 79 NALSO-LLNL-LLNL-2006-0005 | Improper Use of a Crimping tool for Electrical Wiring Work |
| 80 NALSO-LLNL-LLNL-2006-0008 | Building 131 Elevator Replacement - 110V Electrical Arc |
| 81 NALSO-LLNL-LLNL-2006-0010 | Off-site Warehouse Exit Sign Installation - Electrical Arc |
| 82 NALSO-LLNL-LLNL-2006-0017 | Near Miss to Electrical Shock |
| 83 NALSO-LLNL-LLNL-2006-0033 | Electrical Panel LOTO - Management Concern in Building 451 |
| 84 NALSO-LLNL-LLNL-2006-0038 | Electric Outlet with Reverse Polarity and Disconnected Ground Wire (110v) Results in Mild Shock |
| 85 NALSO-LLNL-LLNL-2006-0041 | Electrical Line Severed (480v) During Building 490 Re-Roof Project |
| 86 NALSO-LLNL-LLNL-2006-0050 | Electrical Arc Inside Wire-Way Gutter Outside of Building 162 |
| 87 NANVSO-NST-NTS-2006-0003 | Energized Underground Power Lines Cut By Grader |
| 88 NAPS-BWXP-PANTEX-2006-0012 | Cut Electrical Wire at Extraction Well Field |
| 89 NAPS-BWXP-PANTEX-2006-0020 | Failure to Control Known Hazardous Energy |
| 90 NAPS-BWXP-PANTEX-2006-0030 | 12-5C Bridge Crane Electrical Short |
| 91 NAPS-BWXP-PANTEX-2006-0056 | Electric Arc at an Abandoned Conduit Containing Energized 208 Volt Wiring |
| 92 NAPS-BWXP-PANTEX-2006-0073 | Unexpected Discovery of Electrical Energy (83 Volts) |
| 93 NAPS-BWXP-PANTEX-2006-0075 | Cut 110 Volt, Three Conductor Wiring, Zone 4 Magazine |

| 94 NAPS-BWXP-PANTEX-2006-0113 | Release of Hazardous Energy Due to Site Condition |
|---|--|
| 95 NASRSO-WSRC-TRIT-2006-0001 | Incorrect Performance of UPS #2 Annual Maintenance |
| 96 NASS-SNL-1000-2006-0017 | Contract Employee Received Shock from Plasma Torch Cutter at the 6710 Welding Shop |
| 97 NASS-SNL-12000-2006-0001 | Unexpected Discovery of Exposed Live Electrical Circuit at Manzano Non-Nuclear Storage Bunker |
| 98 NASS-SNL-12000-2006-0002 | Unexpected Discovery of an Uncontrolled Hazardous Energy Source on Air Handler #2 at MBC-H that Damaged Wiring and Components |
| 99 NASS-SNL-2000-2006-0003 | Defeat of Electrical Interlock |
| 100 NASS-SNL-2000-2006-0006 | Drilling into Dock Impacted Energized Electrical Wire at WETL, Pantex |
| 101 NASS-SNL-2000-2006-0007 | Metal Oxide Varistor (MOV) Accelerated Life Tester Electrical Shock in Bldg. 878 |
| 102 NASS-SNL-3000-2006-0002 | Office Worker Receives Shock from Task Light Fixture |
| 103 NASS-SNL-6000-2006-0001 | Worker Receives a Minor Shock While Testing a Data Acquisition System |
| 104 NASS-SNL-CASITE-2006-0002 | Unexpected Discovery of an Uncontrolled Electrical Energy Source |
| 105 NASS-SNL-CASITE-2006-0004 | Building 912 Photo Studio Electrical Shock |
| 106 NASS-SNL-NMFAC-2006-0001 | Subcontract Electrician Performs Unauthorized Energized Work on 110-Volt #12 Conductors |
| 107 NASS-SNL-NMFAC-2006-0002 | Asbestos Abatement Worker Receives Shock while Vacuuming in 9990 Containment Area |
| 108 NASS-SNL-NMFAC-2006-0008 | Electrical Subcontractor Performs Energized Electrical Work in Building 890 Without an Energized Work Permit |
| 109 NAYSO-BWXT-Y12CM-2006-0002 | Subcontractor Employee Shock |
| 110 NAYSO-BWXT-Y12CM-2006-0004 | Cut Conduit at 9996 |
| 111 NAYSO-BWXT-Y12NUCLEAR-2006- 0003 | Discovery of an uncontrolled hazardous energy source - cover plate missing on an electrical junction box on the Kathabar 3360 control panel. |
| 112 NAYSO-BWXT-Y12NUCLEAR-2006- 0022 | Loss of Power to Emergency Notification System Horns and Lights |
| 113 NAYSO-BWXT-Y12SITE-2006-0001 | Dump Truck Snaps Overhead Communication Line Which Contacts Adjacent Power Line |
| 114 NAYSO-BWXT-Y12SITE-2006-0004 | Mear Miss - Electrical Shock to Utilities Operator's Hand |
| 115 NAYSO-BWXT-Y12SITE-2006-0005 | LO/TO Concern Associated with the Compressed Air Upgrade Project (CAUP) |
| 116 NE-IDBEA-AL-2006-0001 | Lockout/Tagout Management Concern |
| 117 NE-IDBEA-ATR-2006-0001 | Near Miss - Snow Removal Activities Snag Energized Temporary 480V Power Cord |
| 118 NE-IDBEA-ATR-2006-0003 | Work Performed Under Lockout/Tagout Without Zero Energy Check Verification |
| 119 NE-IDBEA-ATR-2006-0011 | Discovery of Uncontrolled Hazardous Energy Source |
| 120 NE-IDBEA-ATR-2006-0013 | Energy Discovered in Motor Control Center After Lockout/Tagout |
| 121 NE-IDBEA-ATR-2006-0017 | Work Performed on Sonoxide System Electrical Panel Prior to Zero Energy Checks Being Performed |

| 122 NE-IDBEA-CFA-2006-0001 | Underground Electrical Conduit Severed by Subcontractor - INL |
|---|--|
| 123 NE-IDBEA-FCF-2006-0002 | Inadequate Posting for Exposed Electrical Hazard |
| 124 NE-IDBEA-INLLABS-2006-0002 | Personnel Shock at CFA-625 Laboratory 120 |
| 125 NE-IDBEA-MFC-2006-0004 | Radioactive Liquid Waste Treatment Facility Lockout/Tagout |
| | Administrative Errors - MFC |
| 126 NE-IDBEA-MFC-2006-0006 | Workers Exposed to 120 Volt Electrical |
| 127 NE-IDBEA-RTC-2006-0006 | Energized 2400 V Power Cable Breached During Excavation |
| 128 NE-IDBEA-SMC-2006-0001 | Snow removal activities snag 120 volt power cord |
| 129 NE-IDBEA-STC-2006-0003 | Worker Receives Shock from Light Switch - STC - INL |
| 130 NE-IDBEA-STC-2006-0004 | Tripped Ground Fault - WCB - STC |
| 131 NE-OROORNL-X10HFIR-2006-0006 | Phase Rotation Testing - Near Miss |
| 132 NE-OROORNL-X10HFIR-2006-0010 | Unauthorized Facility Modification Outside Work Control Process |
| 133 SCASO-ANLE-ANLE-2006-0007 | Unexpected Energized Shared Neutral Wires While Removing Light Fixture |
| 134 SCASO-ANLE-ANLEAPS-2006-0004 | Heat Tape Power Wire Unknowingly Energized While Unterminated and Shorts to Ground |
| 135 SCASO-ANLE-ANLEAPS-2006-0005 | Electrical Transformer Found Unexpectedly Energized After Precautionary LOTO |
| 136 SCASO-ANLE-ANLEER-2006-0001 | Improper implementation of lockout/tagout requirements for electrical energy |
| 137 SCASO-ANLE-ANLEER-2006-0003 | Noninjurious Electrical Hand Shock When Switching on Light Fixture Above Glovebox |
| 138 SCASO-ANLE-ANLEIPNS-2006-0002 | Improper Cord Causes Short Circuit in 110 Volt GFCI Wall Plug |
| 139 SCBHSO-BNL-AGS-2006-0002 | 400 Amp Electrical Switch Failure |
| 140 SCBHSO-BNL-AGS-2006-0003 | Unsafe Protection Scheme for Electrical Hazard |
| 141 SCBHSO-BNL-BNL-2006-0001 | Energized Conductor Discovered in Cut Conduit |
| 142 SCBHSO-BNL-BNL-2006-0009 | Exposed Electrical Terminals in Legacy Installed Light Timer |
| 143 SCBHSO-BNL-BNL-2006-0014 | Painter's spackling knife contacts abandoned live electrical wiring |
| 144 SCBHSO-BNL-BNL-2006-0020 | Work on Energized Equipment by Vendor |
| 145 SCBHSO-BNL-NSLS-2006-0002 | Unexpected Energized Cord Cut |
| 146 SCBSO-LBL-AFRD-2006-0001 | Unexpected discovery of electrical current from heater |
| 147 SCBSO-LBL-ENG-2006-0001 | Potential Heater Tape electrical shorting |
| 148 SCBSO-LBL-OPERATIONS-2006-0004 | B55A LOTO violation |
| 149 SCBSO-LBL-OPERATIONS-2006-0006 | Misidentified source of electrical power during precautionary |
| 150 SCBSO-LBL-OPERATIONS-2006-0007 | Management Concern due to Penetration Permit Incidents |
| 151 SCFSO-FNAL-FERMILAB-2006-0009 | Following procedures avoided injury during saw cutting operations |
| 152 SCFSO-FNAL-FERMILAB-2006-0010 | Loose Ground Pin Causes Internal Fault of 250 VAC, 30 amp, 3 phase Connector |
| 153 SCPNSO-PNNL-PNNLBOPER-2006- 0005 | Management Concern Related to Hazardous Energy Control |
| 154 SCPNSO-PNNL-PNNLBOPER-2006- 0007 | Discovery of Unknown Energy Source and Near Miss to Reportable Injury |
| 155 SCPNSO-PNNL-PNNLBOPER-2006- | Failure to Follow Hazardous Energy Control at PDL-E |

| 0010 | |
|---|--|
| 156 SCPNSO-PNNL-PNNLBOPER-2006- 0019 | Management Concern Associated with Electrical Shock |
| 157 SCSSO-SU-SLAC-2006-0002 | Carpenter's Screw Penetrates Romex Wire |
| 158 SCSSO-SU-SLAC-2006-0004 | Working Without Applying Personal Locks and Tags |
| 159 SCSSO-SU-SLAC-2006-0006 | Subcontractor Cut Lighting Cable. |
| 160 SCSSO-SU-SLAC-2006-0007 | Subcontractor Cut 110/208V AC Energized Electrical Lines |
| 161 SCSSO-SU-SLAC-2006-0008 | Contractor Cuts Energized 110V Line |
| 162 SCSSO-SU-SLAC-2006-0009 | 110V Extension Cord Jacket Nick |
| 163 SCSSO-SU-SLAC-2006-0011 | Equipment Electric Fan Shock |
| 164 SCSSO-SU-SLAC-2006-0012 | Cutting of Energized Electrical Wire |
| 165 SC-OROORAU-ORISE-2006-0001 | Exposed Live Electrical Wiring in SC-1 Annex Remodeling Project |
| 166 SC-OROORNL-X10SNS-2006-0001 | Near-Miss: Subcontractor Electrician Accidentally Drills Into Energized 480-volt Cable |