National Transportation Safety Board NTSB ID: LAX95LA332 Aircraft Registration Number: N5689T FACTUAL REPORT Most Critical Injury: Fatal Occurrence Date: 09/10/1995 AVIATION Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 94550 1123 PDT LIVERMORE CA Distance From Landing Facility: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft **ENSTROM** F-28C /F-28C Helicopter

Revenue Sightseeing Flight: Yes Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On September 10, 1995, at 1123 hours Pacific daylight time, an Enstrom F-28C helicopter, N5689T, collided with the ground following a loss of power about 2.5 miles northeast of the Livermore, California, airport. The helicopter was operated by Calaveras Aviation of San Andreas, California, and was engaged in providing 5-minute-for-hire sightseeing rides to patrons attending an airshow at the airport. Visual meteorological conditions prevailed at the time and no flight plan was filed for the operation. The helicopter was destroyed in the collision sequence. The certificated commercial pilot and one passenger sustained serious injuries; however, the second passenger onboard expired at the hospital as a result of his injuries. The flight originated at 1120 for a 5-minute flight around the airport environment.

In a verbal statement to FAA inspectors, the pilot reported that he had no memory of the accident flight. The operator declined three written and one verbal requests to complete a written aircraft accident report.

Airborne pilots in other helicopters participating in the ride program, and ground witnesses, reported hearing the pilot transmit over the local control frequency that he had a power failure and was going down. The pilot of one helicopter said he immediately looked toward the position of the accident aircraft when he heard the transmission. The witness observed the helicopter about 300 feet above ground level in a nose-high attitude and yawing to the right as it descended vertically. The witness said the helicopter's yaw continued during the descent until it was slightly nose low at ground impact.

A Livermore Fire Department battalion chief in charge of fire units responding to the accident site was interviewed. He reported that the helicopter was initially examined for evidence of fuel leakage or spillage as emergency medical technician personnel were attending to the occupants trapped in the wreckage. No fuel was observed leaking from the helicopter, and the ground under the fuel tanks was dry. No fuel smell was detected by the fire personnel.

The helicopter was examined by Federal Aviation Administration airworthiness inspectors from the Flight Standards District Office, Oakland, California, immediately after the accident, and again after recovery from the site. The examining inspector reported that the fuel system was intact with no evidence of tank or line rupture. The right fuel tank was found to have a crack in the outer fiberglass shell; however, the internal rubber bladder was found intact following removal of the outer shell. About 1 pint of fuel was drained from each of the fuel tanks during recovery of the helicopter.

The aircraft owner/operator was interviewed by telephone. He reported that for the sightseeing rides during the airshow on Friday and Saturday, a computed tabulation system was used to keep track of the fuel onboard the helicopter. On a sheet of paper estimated fuel usage was subtracted from the amount believed onboard, and fuel put into the tanks during the day was added to the

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX95LA332

Occurrence Date: 09/10/1995

Occurrence Type: Accident

Narrative (Continued)

total. No calibrated dipstick was used to definitively determine the amount of fuel in the tanks. The tabulation sheet is attached to this report.

After recovery of the helicopter from the accident site, it was examined by an FAA airworthiness inspector with technical assistance provided by Enstrom Helicopter Corporation.

Control system and drive train continuity was established throughout the helicopter. All three main rotor blades were found coned upwards. The tail rotor blades were not damaged.

According to Enstrom, the fuel system consists of two 20-gallon bladder fuel tanks encapsulated in fiberglass shells. The unusable fuel quantity is 1 gallon per tank. The fuel quantity indicating system consists of one gage calibrated in pounds which presents the cumulative amount in both tanks. The Enstrom technical representative stated that the helicopter was designed and certificated under CAR 6 regulations and the fuel gage is only required to read accurately at zero.

The fuel gage and indicating system calibration was tested. One tank sending unit was disabled and the system rigged so that only one tank was being read by the gage for the test. Water was used in place of fuel. One gallon of water, comprising the unusable fuel quantity for the tank, was added.

The gage read zero. One gallon increments were then added to the tank to a total of five, and the resultant gage readings noted. The following table presents the as-tested gage readings compared to the computed values:

USABLE TANK	OUANTITY	GAGE	READING	CITIOHS	READ

	1 Gallon	10	12	2 Gallons	40
24	3 Gallons	60	36	4 Gallons	80
48	5 Gallons	115	60		

The engine driven fuel pump was removed and installed in a calibrated test bench where it flowed to specifications. The engine was shipped to the Textron Lycoming factory for examination under the supervision of an FAA inspector. The inspector's report is attached to this report. The engine was installed in a production test cell where it was operated through a normal test protocol. Normal engine operation and performance was observed.

Fuel system annunciator light assemblies for low fuel pressure (red) and normal fuel pressure (green) were removed from the instrument panel and sent to the Safety Board's metallurgical laboratory for analysis.

The filament from the red assembly was intact and showed no sign of elongation.

A major portion of the filament from the green assembly was separated and lying loose inside the bulb glass. No stretching was observed. Examination of the filament pieces which remained attached to the post and the separated segment revealed a blocky appearance typical of an aged filament. Small amounts of molten and resolidified filament material was found adjacent to the separated ends.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX95LA332

Occurrence Date: 09/10/1995

AVIATION	AVIATION Occurrence Type: Accident												
Landing Facility/Approach In	formation					•							
Airport Name		Aiı	rport ID:	Airport Elevation	Rur	nway Used	Runwa	y Length	n Ru	nway Width			
				Ft. MSL	. 0								
Runway Surface Type:							<u> </u>		I				
Runway Surface Condition:													
Approach/Arrival Flown: NONE	=												
VFR Approach/Landing: Forced L	anding												
Aircraft Information													
Aircraft Manufacturer ENSTROM				Series /F-28C				Serial N 474-2	Number				
Airworthiness Certificate(s): Normal													
Landing Gear Type: Skid													
Amateur Built Acft? No	Number of Seats: 3	3	Certified	d Max Gross Wt.	2350 LBS Number			er of Engines: 1					
				Engine Manufacturer: Model/Series: LYCOMING HIO-360-E1AD						Rated Power: 205 HP			
- Aircraft Inspection Information						•			•				
Type of Last Inspection		D	Date of Last Inspection Time Si			Since Last Inspection			Airframe Total Time				
Annual		(07/1995 132 Hours					ours	1412 Hours				
- Emergency Locator Transmitter (I	ELT) Information							•					
ELT Installed?/Type Yes /		E	ELT Operated? Yes ELT Aided in Locating Accident Site?						No				
Owner/Operator Information													
Registered Aircraft Owner			Street Address P.O. BOX 344										
RODGER L. AINSWORTH			City						State	Zip Code			
		Ctue et A	SAN ANDRE	AS				CA	95249				
Operator of Aircraft			Street Address P.O. BOX 1450										
CALAVERAS AVIATION			City		State	Zip Code							
				SAN ANDREAS CA Operator Designator Code:									
Operator Does Business As: - Type of U.S. Certificate(s) Held: N		10	perator Design	nator Co	ode:								
Air Carrier Operating Certificate(s):													
7.11 Carrier Sporating Continuation													
Operating Certificate:				Operator Certific	cate:								
Regulation Flight Conducted Under	r: Part 91: Genera	l Aviation	n										
Type of Flight Operation Conducted	d: Business												
]	FACTU <i>A</i>	AL REPO	RT - AVIATION						Page 2			

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX95LA332

Occurrence Date: 09/10/1995

AVIATION Occurrence Type: Acciden				cident									
First Pilot Information													
Name					City				S	tate	Date	e of Birth	Age
On File					On File	On File On File On File						38	
Sex: M Seat Occupied:	Left	Occ	cupational Pi	lot? Unkno	own				Certific	ate Num	ber:	On File	
Certificate(s): Comr	mercial												
Airplane Rating(s): None													
Rotorcraft/Glider/LTA: Helicopter													
Instrument Rating(s): None)												
Instructor Rating(s): None	;												
Current Biennial Flight Review	w?												
Medical Cert.: Class 2	Medica	al Cert. Status	: Valid Med	dicalno wa	aivers/lir	m.		Date	of Last I	Medical E	Exam	n: 06/1995	
	•							_					
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		In Actual	strument Sim	ulated	Rotorcraft		Glider	Lighter Than Air
Total Time	270	40				26				2	70		
Pilot In Command(PIC)	150					10				1	50		
Instructor											_		
Instruction Received											\Box		
Last 90 Days	12	12			1						12		
Last 30 Days	4	4								4			
Last 24 Hours					<u> </u>								
Seatbelt Used? Yes	Shou	lder Harness	Used? Yes		1	oxico	logy Perf	ormed?	No	S	econ	id Pilot? No)
Flight Plan/Itinerary													
Type of Flight Plan Filed: No	ne												
Departure Point						State Airport Identi			ntifier	ier Departure Time			Time Zone
Same as Accident/Incider	nt Location						Ľ	٧K		1120			PDT
Destination						State	A	rport Ide	ntifier				
Local Flight													
Type of Clearance: VFR													
Type of Airspace: Class D)												
Weather Information													
Source of Wx Information:													
			FACTUAL	REPORT	- AVIA	TION	I						Page 3

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: LAX95LA332

Occurrence Date: 09/10/1995

AVIATION			Occ	Occurrence Type: Accident									
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF	Elevation		WOF Di	WOF Distance From Accident Site				Direction From Accident Site		
LVK	1125	PDT		397 Ft. MS	L_				2 NM			10 D	eg. Mag.
Sky/Lowes	st Cloud Condition: Clear	·					0 Ft. AG	;L	Condition o	of Ligh	nt: Day		
Lowest Ceiling: None 0 F						Visibi	ility:	20	SM	Alti	meter:	30.00	"Hg
Temperatu	ıre: °C [Dew Point:		°C W	eath	ner Condi	tions at Acc	ident S	ite: Visual (Conc	litions		
Wind Direc	ction: 260	Wind Sp	eed: 10				d Gusts:						
Visibility (R	RVR): 0 Ft.	Visibility	(RVV)	0 SI	м								
	d/or Obscuration:												
Accident	Information												
Aircraft Dar	mage: Destroyed		Airc	raft Fire: N	one				Aircraft Exp	losio	n None		
- Injury Sur	mmary Matrix	Fatal	Serious	Minor		None	TOTAL						
First Pil	lot		1		$oxed{\Box}$		1						
Second	d Pilot			 	\mathbb{L}								
Student	t Pilot				\mathbb{L}								
Flight Ir	nstructor				\mathbb{L}								
Check F	Pilot				L]					
Flight E	Engineer				\mathbb{L}								
Cabin <i>F</i>	Attendants				\mathbb{L}								
Other C	Crew				Τ								
Passen	ngers	1	1				2						
- TOTAL A	ABOARD -	1	2		\top		3	1					
Other G	Ground	0	0	(0	1					
- GRAND	O TOTAL -	1	2	($\overline{}$		3	1					

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: LAX95LA332

Occurrence Date: 09/10/1995

Occurrence Type: Accident

	istrat			

Investigator-In-Charge (IIC)

JEFF RICH

Additional Persons Participating in This Accident/Incident Investigation:

KIM O DAVIES OAKLAND, CA

WILLIAM TAYLOR MENOMINEE, MI