

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2005-63

Napa Valley Railroad (NVRR) St. Helena, California August 6, 2005

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.


FEDERAL RAILROA				FRA F	ACTUA	L RA	ILR	OAD A	CCI	DENT I	REPOR'	Γ]	FRA Fi	ile#	HQ-200)5-63	
1.Name of Railroad Oper	1a. Alphabetic Code					1b. 1	b. Railroad Accident/Incident No.											
Napa Valley RR [NVR		NVRR					AXRR080605											
2.Name of Railroad Opera	2a.	2a. Alphabetic Code					b. Railroad Accident/Incident											
N/A	20	N/A					N/A 3b. Railroad Accident/Incident No.											
3.Name of Railroad Respo	3a. Alphabetic Code					30.1												
Napa Valley RR [NVR 4. U.S. DOT_AAR Grade	NVRR					6 Т	AXRR 080605											
4. O.S. DOI_MIN Grade		5. Date of Accident/Incident Month Day Year					0. 1	6. Time of Accident/Incident										
			08 05 2005					08:15: ☐ AM 🗸 PM										
7. Type of Accident/India	collision		7. Hwy-rail crossing 10. Explosion															
(single entry in code b	llision	8. RR grade crossing 11. Fire/violent rupture (describe in narrative) 9. Obstruction 12. Other impacts										06						
8. Cars Carrying HAZMAT 0		MAT C ed/Dera		0	10. Cars HAZMA		ıg	0		11. People Evacuated			0	12. Division System			-	
13. Nearest City/Town	13 Negreet City/Town				14. Milepost				15. St	15. State			16. County					
-		Helena			(to nearest t			h) 86.8		Abbr Cod N/A C				NAPA				
17. Temperature (F) (specify if minus)	18. V	isibility' 1. Daw					Veather (single entry) . Clear 3. Rain 5.Sleet			Code		20. Typ				Code		
75 F 2. Day								2. Cloudy 4. Fog 6.Snow							Siding Industry		1	
21. Track Name/Number				22. FRA Track				Code 23. Annual Trac			ck Density		24. Tim	Direc	ction	(Code	
	in Tracl	k	Class (1-9, X) (gross tons in						in 1		1. North 3. East 2					2		
						OPER	ATI	NG TRA	IN#	1			•					
25. Type of Equipment	1. Freigl	t train	4. W	ork train 7	. Yard/swi	tching	A.	Spec. Mo	W Equ	ip. Code			ment (Code	27. T	rain Nu	mber/	Symbol
Consist (single entry) 2. Passenger train 5. Single car 8. Light loco(s								1.2				ended? . Yes 2. No 1			NVRR			
20 G 1			in 6. Cu). Maint./in			1 ()	.1 .		1.	Yes	2. No 30a. Rem					
28. Speed (recorded spee	ed, if availal	ole) Co	- 1	. Method(s)	•	on (. Autom		r code(s)		.pply) ecial instru	etions						omoti	ve?
R - Recorded a. ATCS g. Auto E - Estimated 11 MPH R b. Auto train control h. Curr										0 = Not a 4 control of the state of the stat								
	Time ta	able/t	rain orders		2 = Remote control tower													
29. Trailing Tons (gross tonnage, d. Cab j.Track								nt control	tive)	3 = Remote control								
excluding power un			ic control			transmitter - more than one remote control transmitter												
	1	300	f.	. Interlockin	g 1.	Yard lin	nits		k	N/A N	I/A N/A	N/A	remote	control	transi	nitter	0)
31. Principal Car/Unit	a. Ini	tial and	Number	b. Positi	on in Trair	n c. l	Load	ded(yes/no) 32. If railroad employee(s) tested for drug/alcohol use,										
(1) First involved		N/A			2			NI/A			er the number that were			n		Alcohol	Γ	Drugs
(derailed, struck, etc)		14/21	•					the appropriate box.				N/A					N/A	
(2) Causing (if mechan cause reported)		N/A				N/A	33	. Was this	nsporti	ing passen	igers? (Y/N)		ı	N/A			
34. Locomotive Units a. Head			Mid 7	Mid Train				35. Car	s				ade	Empty				
(1) Total in Train	End tal in Train 2		Manual 0	c. Remote	d. Manual c. Re			(1) Total i		sinmont C		reight 0	b. Pass.	c. Free		d. Pass.	e. C	aboose 0
` '		-	0	0	0	-				•	JIISIST	0	,	-	_			
(2) Total Derailed	0		0	0	0	0		(2) Total	Derai	led		0	0	C)	0		0
36. Equipment Damage	1000			ack, Signal,	•	0		38. Prim	ary Ca	use			39. Cont	ributing	g Caus	se		
This Consist	& Structure Damage 0				Code H310					Code N/A								
,	embers				<u> </u>					of Time on Duty 45, Conductor								
Operators	111111111111111111111111111111111111111			onductors	43. Bra	43. Brakemen		44. Engi		eer/Operator			45. Con		r _{mo}	7	Mi	15
N/A	N/A			1		N/A			Hrs			15						
Casualties to: 46.	Railroad Er	road Employees 47. Train Passenger				s 48. Other		49. EOT Device?			_		50. Was EOT Device Properly Armed? 1. Yes 2. No N/A					
Fatal	0			0		0		1. Yes 2. No 2				1.	Yes 2. No				N/A	
Nonfatal	N/A	N/A		0		0	51.		. Caboose Occupied by Crew? 1. Yes			2. No			N/A			N/A
'					Ol	PERAT	ΓINO	G TRAIN	I #2									
52. Type of Equipment	1. Freigh	t train	4. Wo	ork train 7	. Yard/swit					in Code	53. Was	Equip	ment C	Code	54 T	rain Nur	nher/	Symbol
Consist (single entry) 2. Passenger train 5. Single car 8. I						Light loco(s).						nded?			54. Train Number/Symbol			
	3. Comm	uter trai	n 6. Cu	t of cars 9	. Maint./in:	spect.ca	r			N/A	1.	Yes	2.110	I/A		N/.		
55. Speed (recorded spee	ed, if availa	ole) Co	ode 57.	. Method(s)	of Operation	on (enter code(s) that apply)						57a. Remotely Controlled Locomotive?					
								natic block m.Special instructions n. Other than main track						0 = Not a remotely controlled 1 = Remote control portable				
E - Estimated N/A	A MPH	N/A	, p	. Auto train	control h	. Curren	t of t	raffic	n. Otl	ioi uiali illi	um nack		I = Rem	ote con	trol po	ortable		

Form FRA F 6180.39 (11/06) Page 1 of 5

	DEPARTMENT OF TRANSPORTATION FRA FACTUAL RAILROAD ACCIDENT REPORT FRA File # HQ-2005-63 FEDERAL RAILROAD ADMINISTRATION																		
56. Trailing Tons (gross tonnage, excluding power units) Output Outp							j. k	Time table Track warra . Direct traf Yard limits	ant control	control p. Other (Specify in narrative)					2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter				
58. Principal Car/Unit a. Initial and Number b. Position							ion in Trai	n c. Lo	aded(yes/no)	s/no) 59. If railroad employee(s) tes					ted for drug/alcohol use,				
(1) First involved (derailed, struck, etc)					A	N/A					enter the r the approp		er that were box.	positive in	Drugs N/A				
(2) Causing (if mechanical cause reported) N/A					A		N/A		N/A	60.	Was this	consi	st transporti	ng passen	N/A				
61. Locomotive	e Units a. Head			Mid '	Γrain c. Remote		ear End	62. Cars	62. Cars L					Em c. Freight	pty d. Pass.	e. Caboose			
(1) Total in	Train				N/A	N/A	N/A	N/A		(1) Total in Equipment Consist N/A					N/A	N/A	N/A		
(2) Total D	(2) Total Derailed N/A			N/A	N/A	N/A	N/A	(2) Total I	(2) Total Derailed N/A					N/A	N/A	N/A			
					64. Tra	ck, Signal,	Way,	NI/A	65. Primar Code	ry Caus	se			66. Contributing Cause					
This Consist N/A Number of Cre						& Structure Damage N/A w Members						N/A	A Length of T	Code Time on D	N/A				
67. Engineer/		Fire	nen		69. Co	nductors	70. Bı	akemen	71. Engin	eer/Op	erator			72. Cond	ductor				
Operators	N/	N/A				N/A		N/A		Hrs N/A Mi					N/A	Mi N/A			
Casualties to:	73. I	Railro	ad Empl	oyees	74. Tra	in Passenge	rs 75. Ot	her		76. EOT Device? 1. Yes 2. No N					EOT Devic	Armed?			
Fatal			N/A			N/A		N/A		1. Yes 2. No N/A 78. Caboose Occupied by Crew?					1. Yes 2. No				
Nonfatal			N/A	* 1		N/A		N/A		1. Y			2. No				N/A		
70 Type	ser Inv	olved		83 Fauin	Rail Equipment Involved														
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian T. Truck-Trailer. F. Bus J. Other Motor Vehicle 1. Train(units pulling) 4. Car(s) (mov												(moving)	7.Light(s) (standing)						
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) N/A 80 Vehicle Speed 81 Direction geographical) Code										2.Train(units pushing) 5.Car(s) (standing) 8.Other (specify in narrative) N 84. Position of Car Unit in Train									
80. Vehicle Speed (est. MPH at impact) N/A 81. Direction geographical) Code 1.North 2.South 3.East 4.West N/A										N/A									
82. Position Code 85. Circ											5. Circumstance								
1.Stalled on 4. Trapped	Ioving Ove	r Crossing	N/A		Rail Equipment Struck Highway User Rail Equipment Struck by Highway User														
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 86b. Was there a hazardous materials release by													Code						
1. Highway U	•	_				4. Neither		N/A	1. High	way U	Jser 2. F	Rail E	quipment	3. Both	4. Neither	r	N/A		
86c. State here th	he name ar	ıd qua	antity of	the ha	nzardous	materials r	eleased, if	•	•								-		
Crossing	87. Type of 1.Gates 4.Wig Wags 7.Crossbucks 10.Flagged by crew Crossing 2.Cantilever FLS 5.Hwy. traffic signals 8.Stop signs 11.Other (spec. in narr.) (See instructions for codes) 1. Yes														Code				
	Warning 3.Standard FLS 6.Audible 9.Watchman Code(s) N/A N/A N/A N/A N/A							2.None	NI/A					N/A	2. No 3. Un	known	N/A		
Code(s) 90. Location of V	N/A Warning	1	N/A	1N/	Λ	N/A Code	N/A 91. Cross	N/A ing Warning	N/A g Interconnect	nterconnected Code 92. Crossing Illuminated by Street							Code		
1. Both Sides with Highway S 2. Side of Vehicle Approach 1. Yes									ignals				Lights or S ₁ 1. Yes	pecial Ligh	nts				
3. Opposite Side of Vehicle Approach N/A								2. No . Unknown		N/A			2. No 3. Unkno	own		N/A			
93. Driver's Age		Driver's Gender Code 95. Driver Drove Behind of and Struck or was Struck								1 Decrease and a street that Catalana and a second						on Crossin	Code		
N/A	2 Female 1. Yes 2. No							3. Unknov	vn I	2. Stopped and then Proceeded 5. Other (specify and then Proceeded 5. Other (specify and an arrative process).						ecify in	N/A		
97. Driver Passed Standing Code 98. View of Track Obscured by (primary obstruction)																			
Highway Ve 1. Yes 2. No 3		/n	N/A			nanent Stru ding Railro			sing Train 5. ography 6.	-			Other (s Not obstru		arrative)		N/A		
101. Casulties to Highway-Rail			Kille		Injured	99. Drive	r Was		Code			100. Was D		Code N/A					
				N/A		N/A	102. High	way Vehic		Property Damage 103. Total Number of					2. No Highway-				
104 Locamati	A 118212	T : ~1-	to?	1 N/ P	<u> </u>	1 1/ 1 1	(est.	dollar dama	Ť			Y · ·		le driver)		N/A			
104. Locomotive 1. Ye	-	rign	2. No	0				Code N/A		motive Yes	Auxiliary	/ Ligh	nts Operatio 2. No	nai?			Code N/A		
106. Locomotive	e Headligh	t Illun						Code	+	107. Locomotive Audible Warning Sounded?							Code		
1. Yes 2. No N/A									1. Yes 2. No										

Form FRA F 6180.39 (11/06) Page 2 of 5

 $108.\ DRAW\ A\ SKETCH\ OF\ ACCIDENT\ AREA\ INCLUDING\ ALL\ TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.\\ HQ-63-\\ 2005.jpg$



Form FRA F 6180.39 (11/06) Page 3 of 5

FRA File # HQ-2005-63

109. SYNOPSIS OF THE ACCIDENT

On Saturday, August 6, 2005, at 8:15 p.m. PDT, an NVRR passenger/dinner train became uncoupled while southbound from St. Helena, CA. The train became uncoupled between the trailing locomotive and the leading passenger car. The air brakes applied in emergency, the locomotives stopped suddenly, and were struck by the following cars and the train re-coupled.

The accident involved southbound NVRR train # 70, with locomotives 70, 72, and 9 passenger cars traveling at a recorded speed of 11 mph. The train was traversing the Mills Lane highway-rail grade crossing at the time of the accident.

NVRR train 70 originated as train 72 at Napa, CA departing at 6:30 p.m. and traveled north to St. Helena, CA where it stopped. The locomotives were run around the train and coupled to the south end of the train for the return trip to Napa, CA at 8:15 p.m.

The accident occurred at dusk and the weather conditions were clear skies, calm wind, with the temperature about 75 Fahrenheit.

There were 199 passengers 2 train crew and 30 onboard service staff on the train when the accident occurred. Seven injuries were reported involving seven onboard service employees. The most serious was a broken finger. Two passengers were transported to a local hospital for observation and released. Subsequent to the accident, none of the passengers provided NVRR with documentation of the extent of their injuries.

After all the injured persons were removed from the train by ambulances, the train resumed the southbound trip at 10:17 p.m. and arrived in Napa at 11:41 p.m.

Damage totaled \$1,000 for repairs to the deck plates between two passenger cars.

Probable cause: Failure of the crew to properly couple and stretch the train prior to the return from St. Helena.

110. NARRATIVE

The following information was obtained from an investigation the was conducted by the Federal Railroad Administration.

On Saturday, August 6, 2005, at 8:15 p.m. PDT, an NVRR passenger/dinner train became uncoupled while southbound from St. Helena, CA. The train became uncoupled between the trailing locomotive and the leading passenger car. The air brakes applied in emergency, the locomotives stopped suddenly, were struck by the following cars and the train re-coupled.

The accident involved southbound NVRR train # 70, which departed St. Helena, with locomotives 70, 72, and 9 passenger cars traveling at a recorded speed of 11 mph. The train was traversing the Mills Lane highway-rail grade crossing (milepost 86.81) at the time of the accident.

NVRR train 72 originated as train 70 at Napa, CA departing at 6:30 p.m. and traveled north to St. Helena, CA where it stopped. The locomotives were run around the train and coupled to the south end of the train for the return trip to Napa, CA at 8:15 p.m. Lead passenger car NVRR 1018 was coupled to locomotive NVRR 72.

The accident occurred at dusk and the weather conditions were clear skies, calm wind, with the temperature about 75 Fahrenheit.

There were 199 passengers 2 train crew and 30 onboard service staff on the train when the accident occurred. Seven injuries were reported involving seven onboard service employees. The most serious was a broken finger. Two passengers were transported to a local hospital for observation and released. Subsequent to the accident, none of the passengers provided NVRR with documentation of the extent of their injuries.

After all the injured persons were removed from the train by ambulances, the train resumed the southbound trip at 10:17 p.m. and arrived in Napa at 11:41 p.m.

Damage was \$1,000 for repairs to the deck plates between two passenger cars.

Probable cause: Failure of the crew to properly couple and stretch the train prior to the return from St. Helena.

Analysis and Conclusion:

The two crew members of NVRR 70 were interviewed. They described their action immediately prior to the accident. As described, the crew followed the proper operating procedure by testing the coupling between the locomotive consist and the lead passenger car prior to departing St. Helena, CA. They said a standing air test was performed before departing St. Helena and a running air test was made shortly after departing.

Observation of the same crew members during a re-enactment while recoupling locomotives to the train for a return from St. Helena was conducted. FRA observed the conductor having difficulty coupling trailing locomotive NVRR 72 and passenger car NVRR 1018. The draw bar of the locomotive was out of line with the draw bar of the car. After repeated attempts to re-couple, assistance of a supervisor at the scene was required to complete the task. Following the re-coupling, a FRA inspector rode the leading car, NVRR1018 to observe buff and draft action of the train. He did not observe anything unusual and the return trip form St. Helena to Napa was uneventful.

Departing St. Helena, the track is on a slight descending grade of .01 percent. As the train departed St. Helena, the train draft gear was in buff (compressed). At the point where the train came uncoupled, the track is level. At this point FRA observed the slack change from buff to draft (stretched) which would have caused the train to come uncoupled if one of the coupler pins was not locked.

Form FRA F 6180.39 (11/06) Page 4 of 5

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FRA FACTUAL RAILROAD ACCIDENT REPORT

FRA File # HQ-2005-63

A mechanical inspection by FRA and CPUC was conducted of the couplers and draft gear of the lead car, NVRR 1018 and trailing locomotive NVRR 72. Normal wear of the coupler parts was found, but no defects were discovered.

The effects of the uncoupling of the train and subsequent run-in of the train against the stopped locomotives could have been reduced if the locomotive engineer had released the locomotive brakes following the emergency air brake application. This action would have allowed the locomotives to continue to roll away from the train and probably would have averted the injuries and damages to the train. FRA recommended NVRR conduct train handling technics training with all locomotive engineers.

FRA recommended NVRR provide training to operating employees on proper train and air brake handling as proper coupling of locomotives and cars. NVRR conducted training of locomotive engineers on proper train handling under the conditions of this accident and provided additional instruction to conductors and locomotive engineers for assuring that couplings are secure between equipment before proceeding.

A review of NVRR Operational Testing records from July 2004 through July 2005 which showed all observations were made at Napa, California. There were no recorded failures of NVRR operating rules FRA strongly recommended that operational testing be conducted at various locations on the system and not at only one location. NVRR management has conducted operation testing observations of crew members coupling locomotives to trains at Napa and at St. Helena, California.

The same locomotives and cars have continued in everyday service on NVRR without further incident.

Post accident toxicological testing was conducted with negative results.

Based on the FRA post accident investigation of FRA and CPUC, it has been concluded that despite the statements by the NVRR crew, the crew did not follow the proper procedures in testing the coupling between the trailing locomotive and the lead passenger car at St. Helena on the day of the accident. As a result the coupler lock pin was not the proper lock position and allowed the coupler to open while the train was underway.

Form FRA F 6180.39 (11/06) Page 5 of 5