

Week in Review: 12/16/02 -12/22/02

Ron Moore – FNAL


- Store Summary (Studies Week)
- Studies Review
- Schedule for Week



Store Summary


Store	Initial Lumi	CDF Deliv'd Lumi	Termination	Comments
2078	28.4	1229	Intentional	Proton bunch length blow-up at 980 GeV
2087	22.9	894	Intentional	New feaddowns implemented @ 150 GeV
2090	27.9	-	Abort	Safety system dropped power supplies for 7 sec Bad UPS?
2091	24.8	827	“Intentional”	Longitudinal dampers cause proton blow-up; TEL failure; proton removal study
2094	32.6	750	Abort kicker prefire	Horz and vert dampers ON @ 150 GeV; longitudinal damper OFF
2097	29.5	-	<i>ongoing</i>	Horz and vert dampers ON @ 150 GeV; longitudinal damper OFF

Collider Run IIA Peak Luminosity



▲ Peak Luminosity ◆ Peak Lum 20X Average

Collider Run IIA Integrated Luminosity



f

Recycler Pbar Shots

- Stack to ≈ 30 E10 following HEP shot, then shoot to RR
- 5 opportunities since 12/16
 - 1 cancelled due to losing TeV store #2090 early
 - Lots of small pilot shots on first try
 - Usually 1 or 2 shots in subsequent attempts
- Initial goal is to streamline shot procedure
 - Only 2 individual transfers “failed” – no beam unstacked in Acc.
 - Time of no stacking ~ 60 -65 minutes
 - 2 shots delayed by Booster, MI problems during setup
- Average transfer efficiency $\approx 60\%$
 - Leaving 10% beam in MI – need to improve coalescing
- Shots successful overall – still learning and adjusting to minimize impact on Tevatron operations

- Adjusted feeddowns @ 150 GeV to improve decoupling
 - Minimum horizontal, vertical tune split < 0.002 on both helices
 - Chromaticity on proton helix 2 units larger than before
 - Can now run both horizontal, vertical transverse dampers to allow lower chromaticities to improve lifetimes
 - Pbars lost @ 150: **Store 2078 – 15%** \Rightarrow **Store 2097 – 8%**
- Pbar removal to compare flying wire / synch light monitor
 - Try to understand differing emittances from the two systems
 - TEL removed 30 pbar bunches, then vert collimator scraped rest
 - Initial flying wire emittance high (43π vs $20-24\pi$ expected)
 - Sync light had significant offset $12-18\pi$ when essentially no beam
- Measure transverse impedance of C0 lambertson
 - Lambertsons now thought to be large source of impedance (up to $5\text{ M}\Omega/\text{m}$) and strong head/tail instability

f

Hardware Problems Friday-Sunday

- Lost store #2090 due to safety system – bad UPS
- Longitudinal damper blew-up proton bunch length (store #2091)
 - Losses in abort gap grow – CDF turned off Si
- TEL failed as abort gap losses began to decrease (store #2091)
 - First replaced melted capacitor array
 - Then found water leak
 - Required tunnel access and 8 hours to repair
- Booster extraction kicker MP02 regulator failed
 - Related to elevated temperature in Booster gallery?
 - Required a few hours to finally understand, replace chassis
- Booster injection Lambertson supply failed (only ~1 hour down)
- Proton abort kicker prefire ended store #2094
 - Got lucky with timing – almost in abort gap
 - No additional damage to CDF Si
 - Conditioned all 10 thyatron tubes for 6 hours

Store #2091

Blow-up

Proton removal

TEL failure begins

4
 8000
 1000
 10
 T:SBDPSS
 .Inst1 NSEC


 3.4
 6400
 800
 8
 C:FBIPNG
 .Inst1 1E09

 2.8
 4800
 600
 6
 T:L1COLI
 .Mau mA

 2.2
 3200
 400
 4
 C:B0ILUM
 .CDF E30

 1.6
 1600
 200
 2
 C:D0FZTL
 .Ctrls E30

 1
 0
 0
 0



T1 = Sat Dec 21 07:00:00 2002 T2 = Sat Dec 21 17:33:45 2002

Store #2091

Mon 23-DEC-2002 14:45:20

T:SBDPSS
.Inst1 NSEC
4
100000
10
8


C:B0PAGC
.CDF HZ
3.4
80000
6
6.4

T:LDM1GV
.Mech2 Volt
2.8
60000
2

T:L1COLI
.Mau mA
4.8
2.2
40000
-2
3.2

1.6
20000
-6
1.6

1
0
-10
0



Blow-up

TEL failure begins

Abort gap losses decrease when damper off

Abort gap losses grow

T1 = Sat Dec 21 07:00:00 2002 T2 = Sat Dec 21 12:00:00 2002

f

Other happenings this past week

- Shutdown Tuesday > 1 shift
 - Tevatron surveys for C0 lambertson, magnet rolls
 - Main Injector (4.5 hours) and Tevatron safety system tests
 - Cryo maintenance
 - Electrical/power supply maintenance
 - Various tunnel tours in preparation for January shutdown
- Completed safety system tests after store #2090 lost
 - 3 hour Tev test + collision halls
 - No need for variance to extend grace period
 - No need to shutdown to complete tests
- Impromptu proton removal study at end of store #2091
 - Needed to scrape beam anyway to eliminate DC beam without TEL
 - First time for proton removal without quench
 - Took more than 2.5 hours, but gained valuable info on removal process and flying wire, sync light comparison

- Various hardware failures: only delivered 3.7 pb⁻¹
- Completed safety system tests whose grace period expiring
- “Fast” Recycler pbar shots progressing well
- Tevatron transverse dampers on @ 150 GeV
 - Continue to improve lifetimes, leading to better luminosity
- This week is stack and store.

- These talks available on the web via:
<http://www-runii.fnal.gov/RunCoord/RunCoord.htm>