

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0294; Directorate Identifier 2007-NM-288-AD; Amendment

15558 124
39-*****; AD 2008-**-**]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Falcon 2000EX Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Analyses of in-service reports revealed that in case of failure of the wings anti-ice valve, indications of untimely anti-icing with the wings anti-ice selector on "OFF" or of insufficient anti-icing with the wings anti-ice selector on "AUTO" might not be properly displayed to the flight crew. It may result, on ground, in potential structural damages due to a leading edge overheat, or in-flight, in an insufficient anti-ice power.

* * * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective [insert date 35 days after date of publication in the FEDERAL REGISTER].

The Director of the Federal Register approved the incorporation by reference of

CONCURRENCES
ROUTING SYMBOL ANM-7
INITIALS/SIGNATURE CA
DATE 5/23/08
ROUTING SYMBOL -114
INITIALS/SIGNATURE [Signature]
DATE 6/3/08
ROUTING SYMBOL -101
INITIALS/SIGNATURE [Signature] for MK
DATE 6/3/08
ROUTING SYMBOL -100
INITIALS/SIGNATURE [Signature]
DATE 6/3/08
ROUTING SYMBOL
INITIALS/SIGNATURE
DATE
ROUTING SYMBOL
INITIALS/SIGNATURE
DATE
ROUTING SYMBOL
INITIALS/SIGNATURE
DATE
ROUTING SYMBOL
INITIALS/SIGNATURE
DATE