National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 04/25/2007

SEA07LA043

File No. 21326 01/07/2007 Boise, ID Aircraft Reg No. N1882 Time (Local): 11:45 MST Make/Model: Bell / 206B Fatal Serious Minor/None Engine Make/Model: Rolls-royce / 250/C20B Crew 0 0 1 Aircraft Damage: Substantial Pass 0 0 0 Number of Engines: 1 Operating Certificate(s): Aircraft External Load Type of Flight Operation: Other Work Use Reg. Flight Conducted Under: Part 133: Rotorcraft Ext. Load Last Depart. Point: Same as Accident/Incident Location Condition of Light: Day Destination: Local Flight Weather Info Src: Pilot Airport Proximity: Off Airport/Airstrip Basic Weather: Visual Conditions Lowest Ceiling: 7000 Ft. AGL, Broken Visibility: 10.00 SM Wind Dir/Speed: Temperature (°C): 4 Precip/Obscuration: No Obscuration; No Precipitation Pilot-in-Command Flight Time (Hours)

Age: 51

Certificate(s)/Rating(s)

Airline Transport; Single-engine Land; Helicopter

Instrument Ratings Airplane; Helicopter

Total All Aircraft: 11389

Last 90 Days: 36 Total Make/Model: 3217 Total Instrument Time: UnK/Nr

Printed on: 2/13/2009 9:28:11 PM

After completing two local deer herding flights, the pilot landed the helicopter and waited about five minutes for the ground crew to be ready for him to start another herding flight. At the beginning of the third flight, he lifted off into a hover, and then performed a pedal-turn into the wind prior to entering translational lift. During the turn, the snow pad on one of the helicopter's skids caught in some tall brush, resulting in a dynamic rollover into the terrain. According to the pilot, there was no problem with the helicopter's flight controls, but he simply failed to see that there was tall brush (approximately six feet high) behind and to the right of the aircraft.

Brief of Accident (Continued)

SEA07LA043

File No. 21326 01/07/2007 Boise, ID Aircraft Reg No. N1882 Time (Local): 11:45 MST

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: HOVER - IN GROUND EFFECT

Findings

1. (C) CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

2. (F) TERRAIN CONDITION - HIGH VEGETATION

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

The pilot's failure to maintain clearance from tall brush during a low-hover pedal turn. A factor was the six foot-tall brush located adjacent to the area where the pilot was operating.