

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39 0830

[Docket No. FAA-2008-*****; Directorate Identifier 2007-NM-285-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Falcon 2000EX Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above that would supersede an existing AD. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Investigations after a CAS (crew alerting system) message "ENG 1 FIRE DETECT FAIL" that occurred on an in-service aircraft revealed that the detector threshold tolerances could not permit to identify the failure of one single engine fire detector loop out of the two present on each engine. The fire detection system integrity is therefore not correctly monitored.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by [insert date 30 days after date of publication in the FEDERAL REGISTER].

ADDRESSES: You may send comments by any of the following methods:

CONCURRENCES
ROUTING SYMBOL AMM/12/CS
INITIALS/SIGNATURE TD
DATE 6/11/08
ROUTING SYMBOL AMM/12/CS
INITIALS/SIGNATURE TD
DATE 6/11/08
ROUTING SYMBOL SEA/EEG
INITIALS/SIGNATURE BKS
DATE 6/20/08
ROUTING SYMBOL ANM-7
INITIALS/SIGNATURE CR
DATE 7/7/08
ROUTING SYMBOL -114
INITIALS/SIGNATURE EG
DATE 7/15/08
ROUTING SYMBOL -101
INITIALS/SIGNATURE MNR
DATE 7/21/08
ROUTING SYMBOL -100
INITIALS/SIGNATURE HBS
DATE 7/23/08
ROUTING SYMBOL
INITIALS/SIGNATURE
DATE