# UNAPPROVED PARTS NOTIFICATION



Flight Standards Service

No.: 2008-S20080226009

Date: July 31, 2008

http://www.faa.gov/aircraft/safety/programs/sups/upn

# **AFFECTED PRODUCTS**

Aircraft parts produced and sold by Mid Continent Aircraft Corp. for installation on agricultural aircraft.

### PURPOSE

This notification advises all aircraft owners, operators, manufacturers, maintenance organizations, parts suppliers, and parts distributors regarding unapproved parts being introduced into the aviation community.

### BACKGROUND

Information received during a Federal Aviation Administration (FAA) suspected unapproved parts investigation revealed that between January 2005 and February 2008, Mid Continent Aircraft Corp. (Mid Continent) located at 1601 Highway 84 East, Hayti, Missouri 63851, produced parts for sale without having the required FAA approvals. Mid Continent holds FAA Air Agency Certificate No. DFQR172R.

Evidence indicates that Mid Continent produced and sold aircraft parts without having a FAA Parts Manufacturing Authorization (PMA). Some of these parts were sold in a kit advertised by Mid Continent as the "Load Hawg" kit.

Below is a list of the parts sold by Mid Continent individually or in the above mentioned kit.

# RECOMMENDATIONS

Regulations require that modification or replacement parts produced for sale on type certificated aircraft be produced pursuant to a PMA. Aircraft owners, operators, manufacturers, maintenance organizations, parts suppliers, and parts distributors should inspect their aircraft, aircraft records, and/or parts inventory for any of the parts listed. If any parts are installed on aircraft, you should take appropriate action. If any parts are found in existing inventory, it is recommended they be quarantined to prevent installation until a determination can be made as to their disposition.

# **FURTHER INFORMATION**

You can obtain further information concerning this investigation and guidance regarding the above referenced parts from the FAA Flight Standards District Office (FSDO) given below. In addition to the above recommendations, the FAA would appreciate any information concerning the discovery of these parts from any source, the means used to identify the source, and the action taken to remove these parts from service.

This notice originated from the St. Louis FSDO, 10801 Pear Tree Lane, St. Ann, Missouri 63074, telephone (314)890-4800, fax (314)890-4600.

List	of	Parts
------	----	-------

Part #	Part Description	
HP-208	Power Supply	
151-2302	Hydraulic Motor	
22020113	Directional Valve	
PBDB-LNN-EBP	Reducing Valve	
AD03SPS6P	Sub Plate	
J-302	Bolt	
H-095.75-DUZ	Hydraulic Cylinder	
VF35-116M	Bearing	
1A041	Flow Control Valve	
1 ¼ X .120	304 Coupling Auger	
3/8-304	Threaded Lock Rod	
Auger 402	Auger Assy	
Strawn's 402	Frame Door Kit	
Auger 510	Auger Assy	
Strawn's 510	Frame Door Kit	
Strawn's 550/660	Frame Door Kit	
Auger 550/660	Auger Assy	
Auger 502	Auger Assy	
Strawn's 502	Frame Door Kit	
Forward Auger	Motor Bracket Assy	
Aft Auger	Bearing Bracket Assy	
Sock Alignment	Bracket Assy	
Auger 602	Auger Assy	
Strawn's 602	Frame Door Kit	
ANL 130	Current Limiter	