Printed on: 3/16/2009 2:43:51 PM

National Transportation Safety Board FACTUAL REPORT AVIATION			D: FTW98LA1	63	Aircraft Registration Number: N2628B					
			ence Date: 03/3	1/1998	Most Critical Injury: None					
			nce Type: Acci	dent	Investigated By: NTSB					
Location/Time										
Nearest City/Place	State		Zip Code	Local Time	Time Zone					
RIVIERA	TX		78379	1230	CST					
Airport Proximity: Off Airport/Airstrip	rip Distance From L			:						
Aircraft Information Summary										
Aircraft Manufacturer			Model/Serie	es .		Type of Aircraft				
Robinson			R22 BETA	R22 BETA /R22 BETA Helicopte						
Revenue Sightseeing Flight: No	Air Medical Transport Flight: No									

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 31, 1998, at 1230 central standard time, a Robinson R22 Beta helicopter, N2628B, registered to and operated by Mesquite Helicopter Services, Inc., of Alice, Texas, was substantially damaged during a forced landing following a tail rotor ground strike while hovering near Riviera, Texas. The commercial pilot, the sole occupant, was not injured. No flight plan was filed and visual meteorological conditions prevailed for the Title 14 CFR Part 91 local business flight.

The pilot reported that he was using the helicopter to herd cattle. With the helicopter "at an altitude of 3-5 feet AGL," he was attempting to move a bull towards a corral when the animal charged the helicopter. As the pilot maneuvered to avoid the bull, the helicopter's tail rotor contacted the water in a stock tank (pond), resulting in failure of the tail rotor drive shaft. The pilot performed an autorotation. The helicopter "spun twice" to the right, touched down in a level attitude in the stock tank, and rolled onto its right side.

According to the pilot, the helicopter "came to rest on its right side in about 2 1/2 feet of water." He reported that the fuselage was dented, the main rotors were "severely bent," and the tail cone was "chopped."

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW98LA163

Occurrence Date: 03/31/1998

AVIATION	ence Type:	Acciden	t	1								
Landing Facility/Approach Info	ormation						•					
Airport Name		A	irport ID:	Airport E	Elevation	Rur	nway Used	Runway Length		h I	Runway	Width
					Ft. MSL	. 0						
Runway Surface Type:		l				<u> </u>						
Runway Surface Condition:												
Approach/Arrival Flown: NONE												
VFR Approach/Landing: Forced La	nding											
Aircraft Information												
Aircraft Manufacturer				Series	/D.00	DET 4				Number		
Robinson			R22 E	BETA	/R22	BETA			0771			
Airworthiness Certificate(s): Normal												
Landing Gear Type: Skid												
Amateur Built Acft? No	eur Built Acft? No Number of Seats: 2					Certified Max Gross Wt.					gines: 1	
= - 11			Engine Manufacturer: Model/Series: Uycoming O-320-B2C							Rated Po		
- Aircraft Inspection Information												
Type of Last Inspection Da			Date of Last Inspection Time S			Time Si	ince Last Inspe	Airframe Total Time				
100 Hour								Hours		Hours		
- Emergency Locator Transmitter (El	LT) Information	•							•			
ELT Installed?/Type Yes /		E	ELT Operated? No ELT Aided in Locating Accident Site?						>			
Owner/Operator Information												
Registered Aircraft Owner			Street Address AIRPORT RD HANGAR 2									
MESQUITE HELICOPTER SER	RVICES		City State								Zip	Code
			ALICE								783	332
Operator of Aircraft			Street Address AIRPORT RD HANGAR 2									
MESQUITE HELICOPTER SER	RVICES		City State								Zip	Code
WEGGOTTE TIELIOOT TER OERVIOES				ALICE							783	332
Operator Does Business As:				0	perator Desig	nator Co	de:					
- Type of U.S. Certificate(s) Held: No	one											
Air Carrier Operating Certificate(s):												
Operating Certificate:				Opera	ator Certific	cate:						
Regulation Flight Conducted Under: Part 91: General Aviation												
Type of Flight Operation Conducted:	Other Work Use											
]	FACTU	AL REPO	RT - AV	IATION						F	Page 2

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: FTW98LA163

Occurrence Date: 03/31/1998

AVIATI	Occurrence Type: Accident]							
First Pilot Information												
Name					City			S	State Da		Birth	Age
On File		On File			0	n File	On Fi	le	40			
Sex: M Seat Occupied	own			Certific	ate Num	ber: On	File	•				
Certificate(s): Com												
Airplane Rating(s): Single-engine Land												
Rotorcraft/Glider/LTA: Helicopter												
Instrument Rating(s): Airplane												
Instructor Rating(s): None												
Current Biennial Flight Review?												
Medical Cert.: Class 2	Medica	al Cert. Status	S: Valid Med	dicalw/ wa	aivers/lim.		Date of	of Last I	Medical E	xam: 0	5/1997	
	•											
- Flight Time Matrix All A/C This Make and Model			Airplane Single Engine	Airplane Mult-Engine	Night	Instrument Actual		ated	Rotorcraft		Glider	Lighter Than Air
Total Time	12000	2000	800		400	5	0	50	112	00		
Pilot In Command(PIC)	11500	2000	700		375							
Instructor												
Instruction Received												
Last 90 Days	150	150								50		
Last 30 Days	40	40			1					40		
Last 24 Hours Seatbelt Used? Yes	3 Shou	3 Ilder Harness	Usad? Yes		Toxi	L cology Perfe	ormed2 N	Jo		3	ilot? No	<u> </u>
	31100	iluei Hamess	Osed: 163		TOXI	Joiogy Ferri	Jilleu: [NO	3	econa r	not: MC	,
Flight Plan/Itinerary												
Type of Flight Plan Filed: No	one											
Departure Point Same as Accident/Incide	nt Location				Sta	e Ai				Departure Time 0000		Time Zone
Destination												
Local Flight	Sta	e Ai	rport Identifier									
Type of Clearance: None												
Type of Airspace: Class	G											
Weather Information												
Source of Wx Information:												
FACTUAL REPORT - AVIATION Page 3										Page 3		

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: FTW98LA163

Occurrence Date: 03/31/1998

TACIDAL REI OKI				Occurrence Date: 03/31/1996									
AVIATION			Occ	currence Typ	e: Accid	ent							
Weather	Information												
WOF ID	Observation Time	Time Zone	ne WOF Elevation			WOF Distance From Accident Site				Direction From Accident Site			
	0000			0 Ft. MSL				0 NM		0 Deg. Mag.			
Sky/Lowes	st Cloud Condition: Clea	ır		0 Ft. AGL					Condition of Light: Day				
Lowest Ce	eiling: None		0 Ft. AGL Visibility: 10				SM	SM Altimeter: "Ho					
Temperati	ure: 21 °C	Dew Point:		°C We	ather Co	nditions at Ac	cident S	Site: Visual (Cond	itions			
Wind Direct	ction: 130	Wind S	peed: 15	<u> </u>	W	ind Gusts: 20	0						
Visibility (F	RVR): 0 Ft.	Visibilit	y (RVV)	0 SM	T								
Precip and	d/or Obscuration:												
Accident	Information												
Aircraft Da	mage: Substantial		Airc	Aircraft Fire: None					losior	None			
			•										
- Injury Su	mmary Matrix	Fatal	Serious	Minor	None	TOTAL							
First P	ilot					1	1						
Secon	d Pilot						7						
Studer	nt Pilot						1						
Flight I	Instructor						1						
Check	Pilot						1						
Flight E	Engineer						7						
Cabin	Attendants						7						
Other (Crew						7						
Passer	ngers						7						
- TOTAL /	ABOARD -					1	1						
Other 0	Ground	0	0	0		-	o o						
- GRAND TOTAL - 0 0				0			1						
						•	•						

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: FTW98LA163

Occurrence Date: 03/31/1998

Occurrence Type: Accident

A 1 ' ' ' ' '		
Administrative	Intormation	١
Administrative	IIIIOIIIIalioi	ı

Investigator-In-Charge (IIC)

GEORGIA R. SNYDER

Additional Persons Participating in This Accident/Incident Investigation:

ROBERT P ANDERSON SAN ANTONIO, TX