Printed on: 3/16/2009 1:00:56 PM

National Transportation Safety Board	N	NTSB ID:	SEA97LA21	3	Aircraft Regist	Aircraft Registration Number: N812AB			
FACTUAL REPORT	С	Occurrence	e Date: 09/21	/1997	Most Critical Ir	Most Critical Injury: Minor			
AVIATION Occurre			e Type: Accid	lent	Investigated B	Investigated By: NTSB			
Location/Time									
Nearest City/Place	State		Code	Local Time	Time Zone				
GOLDENDALE	WA	98	620	1315	PDT				
Airport Proximity: On Airport/Airstrip Distance From			Landing Facility: 0						
Aircraft Information Summary									
Aircraft Manufacturer			Model/Series			Type of Aircraft			
BARRIGAR			RV-6 /RV-6				Airplane		
Revenue Sightseeing Flight: No	Air Medical Transport Flight: No								

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On September 21, 1997, approximately 1315 hours Pacific daylight time, a Barrigar homebuilt RV-6, N812AB, registered to and being flown by a private pilot, was substantially damaged during a loss of control on touchdown and subsequent nose over during the landing roll at the Goldendale airport, Goldendale, Washington. The pilot and his wife sustained minor injuries. No flight plan had been filed and visual meteorological conditions prevailed at the time of the accident. The flight, which was personal, was to have been operated under 14CFR91, and originated from Prineville, Oregon, approximately 1234 hours.

The pilot reported that he touched down approximately 500 feet beyond the east end of the 3,490 foot long runway 25 and that his "flare was early and the plane bounced several time, 6 to 8." He reported that "When it (the aircraft) finally quit bouncing I was heading for the left side of the runway. I applied full right rudder but the plane's left wheel left the hard surface and ran into loose gravel along the edge of the runway." As the aircraft continued to pull to the left the pilot "applied full power and attempted to regain directional control and abort the landing." The aircraft then departed the left side of the runway, rolled down an embankment and nosed over in the soft terrain alongside the runway (refer to photograph 1).

The pilot reported that the airport windsock was "hanging limp" at the time of the landing and there was no mechanical malfunction with his aircraft. He also reported in the "Recommendation" section of NTSB Form 6120.1/2 submitted (How could this accident have been prevented): "Add power after (the) first bounce and abort the landing."

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: SEA97LA213

Occurrence Date: 09/21/1997

TACIONE REI ON	. 1			00/21/1001						
AVIATION			ence Type:							
Landing Facility/Approach Inf	formation									
Airport Name		Ai	rport ID:	Airport Elevation	Run	way Used	Runwa	ay Length F		Runway Width
GOLDENDALE	20	1660 Ft. MSL	_ 25	3490				40		
Runway Surface Type: Asphalt										
Runway Surface Condition: Dry										
Approach/Arrival Flown: NONE										
VFR Approach/Landing: Full Stop	; Traffic Pattern									
Aircraft Information										
Aircraft Manufacturer BARRIGAR	Aircraft Manufacturer							Serial 1	Number 9	
Airworthiness Certificate(s): Exper	rimental (Special)		RV-6	/RV-6						
Landing Coor Type Talkyhaal										
Landing Gear Type: Tailwheel	Number of Seats: 2	10	-1.04				Nicordo			
Amateur Built Acft? Yes Engine Type:		d Max Gross Wt.		1600		Number of Engines:		nes: 1 Rated Power:		
Reciprocating		Engine Manufacturer: Model/Series: Lycoming O-320							160 HP	
- Aircraft Inspection Information										
Type of Last Inspection		D	Date of Last Inspection Time Sin			ince Last Inspection			Airframe Total Time	
Annual		(08/1997	997 18 H				ours 30 Hours		
- Emergency Locator Transmitter (E	ELT) Information									
ELT Installed?/Type Yes /		E	ELT Operated? Yes ELT Aided in Locating Accident Site? No							
Owner/Operator Information										
Registered Aircraft Owner			Street A	Address 407 ORCHAF	RD HFIO	GHTS LANE				
BARRIGAR, ALAN, R.						State	Zip Code			
			Street A	GOLDENDAL	<u>-</u> E				WA	98620
Operator of Aircraft			Oliccia	407 ORCHAF	RD HEI	GHTS LANE				
BARRIGAR, ALAN, R.	City GOLDENDALE							Zip Code 98620		
Operator Does Business As:		GOLDENDALE WA 98620 Operator Designator Code:								
- Type of U.S. Certificate(s) Held: N					•					
Air Carrier Operating Certificate(s):										
On anating Contification				On a veter Cardiff						
Operating Certificate:	- Dort 01: Conse	J Aviotic	<u> </u>	Operator Certifi	cale.					
Regulation Flight Conducted Under		ıı Aviatioi	11							
Type of Flight Operation Conducted	. Personal									
	J	FACTUA	AL REPO	RT - AVIATION						Page 2

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: SEA97LA213

Occurrence Date: 09/21/1997

AVIATION Occurrence						ccident								
First Pilot Information														
					City					Sta	ate	Date of Birth	Age	
On File On F										On	File	On File	53	
Sex: M Seat Occupied: Left Occupational Pilot? Unknown									Certificate Number: On File					
Certificate(s): Private														
Airplane Rating(s): Single-engine Land														
lone														
lone														
lone														
eview?	?													
	Medica	l Cert. Status	: Valid Med	dicalw/ wa	aivers/l	im.		ı	Date of L	ast M	edical E	xam: 11/1996		
ght Time Matrix All A/C This Make and Model			Airplane Single Engine	Airplane Mult-Engine	Nig	jht	Actua		ent Simulated		Rotorcraft	Glider	Lighter Than Air	
al Time 165 35		165			3				3					
\perp	96	30	96							_				
+										+				
+	10	40	40							+				
+										_				
+					+			-+		\dashv				
						Toxico	ology Pe	erform	rformed? No Second Pilot? No					
: None	<u> </u>													
						State		Airpo	port Identifier Departure Time Tim			Time Zone		
PRINEVILLE											PDT			
						State		Airpo	rt Identifi	er				
Same as Accident/Incident Location S20														
Type of Clearance: None														
Type of Airspace: Class G														
)														
Weather Information Source of Wx Information:														
			EACTILAT	DED∩DT	A 371	A TION	J						Page 3	
S S S S S S S S S S S S S S S S S S S	pied: L Private Single- None None Review d: Non d: Non acident one ass G	pied: Left Private Single-engine La None None None Review? Medica All A/C 165 96 16 16 2 Shou d: None	pied: Left Occ Private Single-engine Land None None None Medical Cert. Status All A/C This Make and Model 165 35 96 30 16 16 16 16 16 16 2 2 Shoulder Harness d: None did: None ass G n on:	pied: Left Occupational Pil Private Single-engine Land None None None Medical Cert. Status: Valid Medical Cert.	pied: Left	City On Fi pied: Left Occupational Pilot? Unknown Private Single-engine Land None None None None None Medical Cert. Status: Valid Medicalw/ waivers/l All A/C This Make and Model Single Engine Mult-Engine Note 165 35 165 96 30 96 116 16 16 16 16 16 16 16 16 16 16 16 1	City On File	City	City	City	City	City	City	

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: SEA97LA213

Occurrence Date: 09/21/1997

	AVIATION		Occ	currence Type	e: Accider	nt					
Weather	Information		·				•				
WOF ID	Observation Time	Time Zone	WOF	Elevation	WOF D	istance From A	ccident Site		Direction I	rom Accident	Site
DLS	1249	PDT		243 Ft. MSL			19 NM			195 🗅	eg. Mag.
				143 i t. IVIOL							
Sky/Lowes	st Cloud Condition: Clea	ŧr				0 Ft. AGL	Condition of	Condition of Light: Day			
Lowest Ce	eiling: None			0 Ft. AGL	0 SM	Alti	timeter: 30.00				
Temperatu	ure: 26 °C	Dew Point:		9 °C Wea	ather Cond	itions at Accide	nt Site: Visual (Conc	ditions		
Wind Direct	ction:	Wind Sp	peed: Calm		Win	d Gusts:					
Visibility (F	RVR): 0 Ft.	Visibility	/ (RVV)	0 SM							
Precip and	d/or Obscuration:										
Accident	Information										
	: Information mage: Substantial		Airci	raft Fire: Non	ıe		Aircraft Exp	olosio	n None		
			Airci	raft Fire: Non	ıe		Aircraft Exp	olosio	n None		
Aircraft Da		Fatal	Airco	raft Fire: Non	ne None	TOTAL	Aircraft Exp	olosio	n None		
Aircraft Da	mage: Substantial	Fatal				TOTAL 1	Aircraft Exp	olosio	n None		
Aircraft Da	mage: Substantial	Fatal		Minor		 	Aircraft Exp	olosio	n None		
Aircraft Da - Injury Su First Pi	mage: Substantial	Fatal		Minor		 	Aircraft Exp	olosio	n None		
- Injury Su First Pi Second	mage: Substantial	Fatal		Minor		 	Aircraft Exp	olosio	n None		
- Injury Su First Pi Second	mage: Substantial mmary Matrix ilot d Pilot ht Pilot	Fatal		Minor		 	Aircraft Exp	olosio	n None		
- Injury Su First Pi Second Studer Flight I	mage: Substantial mmary Matrix ilot d Pilot ht Pilot	Fatal		Minor		 	Aircraft Exp	olosio	n None		
- Injury Su First Pi Second Studer Flight I Check	mage: Substantial mmary Matrix ilot d Pilot nt Pilot Instructor	Fatal		Minor		 	Aircraft Exp	blosio	n None		
- Injury Su First Pi Second Studer Flight I Check	immage: Substantial immary Matrix illot d Pilot nt Pilot Instructor Pilot Engineer Attendants	Fatal		Minor		 	Aircraft Exp	blosio	n None		
- Injury Su First Pi Second Studer Flight I Check Flight Cabin A	Image: Substantial Immary Matrix Illot Id Pilot Instructor Pilot Engineer Attendants Crew	Fatal		Minor		 	Aircraft Exp	blosio	n None		
- Injury Su First Pi Second Studer Flight I Check Flight E Cabin A Other C	Image: Substantial Immary Matrix Illot Id Pilot Instructor Pilot Engineer Attendants Crew	Fatal		Minor 1		1	Aircraft Exp	blosio	n None		
- Injury Su First Pi Second Studer Flight I Check Flight E Cabin A Other C	Image: Substantial Immary Matrix Illot Id Pilot Instructor Pilot Engineer Attendants Crew Ingers ABOARD -	Fatal		Minor 1		1	Aircraft Exp	olosio	n None		

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: SEA97LA213

Occurrence Date: 09/21/1997

Occurrence Type: Accident

Λdm	unicti	つけいへ	Into	rmation
Aum	เมาเอน	auve	HIIO	ппаноп

Investigator-In-Charge (IIC)

STEVEN A. MCCREARY

Additional Persons Participating in This Accident/Incident Investigation:

RON HOLLOWAY HILLSBORO, OR