

PROBLEM DESCRIPTION**EQUIPMENT**TTR Number **18895**

THE STRING-B TRANSMITTER AT CANBERRA FAULTED, REASON UNKNOWN. A FAILOVER TO THE BACK-UP STRING-A TRANSMITTER CORRECTED THE PROBLEM. THE IMPACT WAS A LOSS OF COMMAND CAPABILITY FOR 1 MINUTE 43 SECONDS.

FAILOVER INFO**REFERENCE DOCUMENTATION****GRTS CONFIGURATION INFORMATION**

USER	U/L D/L	U/L D/L	MA CAL	F/O INFO
TURFTS				

SGLT ANTENNA ASSIGNMENTS			CONFIG #		EQUIPMENT		TTR #		18895				
TDRS 1 H1300MS	SGLT ETGT S1		STGT-STTC TDRS-6 SGLT-4 SHADOWING TDRS-1 SGLT-3 SHADOWING TDRS-1										
TDRS 3 H1302MS	SGLT RGRT												
TDRS 4 H1303MS	SGLT 1 STGT N19												
TDRS 5 H1304MS	SGLT 2 STGT												
TDRS 6 H1305MS	SGLT 5 WSGT												
TDRS 7 H1306MS	SGLT ETGT S2		STTC	Uplink	Downlink	SSI	SHUTTLE						
			STGT	B	B	119	A						
			WSGT	A	A								
GCE CHAIN	SGLT1	SGLT2	SGLT3	SGLT4	SGLT5	ADPE	STGT			WSGT			
TTC U/L	A	A	B	A	B		SGLT1	SGLT2	SGLT3	SGLT4	SGLT5	STTC	DIS
TTC D/L	B	B	B	A	B	TTC	A	B	A	A	A	STGT	
SSA1F	A	A	A	A	B	EXEC	B	A	B	A	B	B	B
SSA1R	A	A	A	A	A	SA1	A	A	A	A	B	WSGT	
KSA1F	A	A	A	A	A	SA2	A	B	A	A	A	A	A
KSA1R	A	A	A	A	A	MA	A	A		B	A		
SSA2F	A	A	A	A	A	DIS			STGT		WSGT		
SSA2R	A	A	A	A	A	XSM	A	B	LRBS	A	B		
KSA2F	A	A	A	A	B	MUX	A	B	HRBS	A	B		
KSA2R	A	A	A	A	A	MDM	A	B	REC				
MAF	A	A		A	B	NCC STATUS							
MAR	2	2		2	2	SPS	2		NFE	1			
CAL LINK		1		0	0	CCS	2		NCC SSI	470			
WILEY, C		COOMBS, G			MURRAY, S			YEDNOCK, S					
PA		TM			NM			SWO					
SNAC DATE RCVD			INVESTIGATING ELEMENT				TTR COORD						
Extra Notes:													