[4910-13-U]

## DEPARTMENT OF TRANSPORTATION

**Federal Aviation Administration** 

14 CFR Part 39

[Docket No. FAA-2007-28989; Directorate Identifier 2007-NM-070-AD;

Amendment 39-\*\*; AD \*\* 2007-26-17

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation

(DOT).

**ACTION:** Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to certain Boeing Model 747-200B, 747-200C, 747-200F, 747-300, 747-400, and 747SP series airplanes. That AD currently requires doing a detailed inspection of the effection of the left symbol of the left and right longeron extension fittings, and corrective action if necessary. This new AD adds airplanes to the applicability of the existing AD. This AD results from reports that AD accidental drilling damage to the longeron extension fittings was found on airplanes not symbol subject to the existing AD. We are issuing this AD to detect and correct accidental drilling damage of the longeron extension fittings, which could lead to cracking of the

DATES: This AD becomes effective [insert date 35 days after date of publication in the FEDERAL REGISTER].

longeron extension fittings and result in rapid decompression of the airplane.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of [insert date 35 days after date of publication in Instruction in Ins the FEDERAL REGISTER].

INITIALS/SIGNATURE INITIALS/SIGNATURE BOUTING SYMBOL

DATE

DATE