

Figure 104: et0_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 105: et1_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 106: et2_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 107: et3_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 108: et4_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 109: es1_l302_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 110: es2_l302_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 111: es4_l302_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 112: es5_l302_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 113: es6_l302_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 114: es7_l302_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 115: es9_l302_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 116: es10_l302_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 117: es1_l303_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 118: es2_l303_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 119: es4_l303_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 120: es5_l303_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 121: es6_l303_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 122: es7_l303_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 123: es9_l303_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.



Figure 124: es10_l303_combine: The plots show the distributions of means of fitted centroids from Combine runs as a function of time (in sec) for 4 CCDs.