	Qtr 1, 2001	Qtr 2, 2001	Qtr 3, 2001	Qtr 4, 2001	Qtr 1, 2002	Qtr 2, 2002	Qtr 3, 2002	Qtr 4, 2002	Qtr 1, 2003
Welder 1					256 hrs	520 hrs	528 hrs	504 hrs	
Assemble 1st Half of Full Planes					256 hrs	224 hrs			
Assemble 2nd Half of Full planes						296 hrs	8 hrs		
Assemble 1st Half of Partial Planes							512 hrs		
Assemble 2nd Half of Partial Planes							8 hrs	504 hrs	
Weld Connections									
Welder 2									
Electrician 1						160 hrs	216 hrs		104 hrs
Install Rack Internal Electrical Connections						160 hrs	40 hrs		
Install Power Raceway							80 hrs		
Connect Racks to Power							96 hrs		
Connect P.S. to power									24 hrs
Install Water Cooled Bus									80 hrs
Electrician 2						160 hrs	216 hrs		104 hrs
Install Rack Internal Electrical Connections						160 hrs	40 hrs		
Install Power Raceway							80 hrs		
Connect Racks to Power							96 hrs		
Connect P.S. to power									24 hrs
Install Water Cooled Bus									80 hrs
Electrician 3							136 hrs		
Install Cable Trays							40 hrs		
Connect Racks to Power							96 hrs		
Electrician 4							136 hrs		
Install Cable Trays							40 hrs		
Connect Racks to Power							96 hrs		
Pipefitter 1							424 hrs	16 hrs	32 hrs
Install Rack Internal Plumbing Connections							112 hrs		
Install LCW Piping around detector							160 hrs		
Install Central LCW System							80 hrs		
Connect Racks to LCW							24 hrs		
Install piping to Coil Bus & P.S.							48 hrs	16 hrs	
Connect P.S. to LCW									16 hrs
Connect Bus to LCW									16 hrs
Pipefitter 2							424 hrs	16 hrs	32 hrs
Install Rack Internal Plumbing Connections							112 hrs		
Install LCW Piping around detector							160 hrs		
Install Central LCW System							80 hrs		
Connect Racks to LCW							24 hrs		
Install piping to Coil Bus & P.S.							48 hrs	16 hrs	
Connect P.S. to LCW									16 hrs
Connect Bus to LCW									16 hrs
Pipefitter 3									
Pipefitter 4									
Total					256 hrs	840 hrs	2,080 hrs	536 hrs	272 hrs

	Qtr 2, 2003	Qtr 3, 2003	Qtr 4, 2003	Total
Welder 1	160 hrs			1,968 hrs
Assemble 1st Half of Full Planes				480 hrs
Assemble 2nd Half of Full planes				304 hrs
Assemble 1st Half of Partial Planes				512 hrs
Assemble 2nd Half of Partial Planes				512 hrs
Weld Connections	160 hrs			160 hrs
Welder 2				
Electrician 1				480 hrs
Install Rack Internal Electrical Connections				200 hrs
Install Power Raceway				80 hrs
Connect Racks to Power				96 hrs
Connect P.S. to power				24 hrs
Install Water Cooled Bus				80 hrs
Electrician 2				480 hrs
Install Rack Internal Electrical Connections				200 hrs
Install Power Raceway				80 hrs
Connect Racks to Power				96 hrs
Connect P.S. to power				24 hrs
Install Water Cooled Bus				80 hrs
Electrician 3				136 hrs
Install Cable Trays				40 hrs
Connect Racks to Power				96 hrs
Electrician 4				136 hrs
Install Cable Trays				40 hrs
Connect Racks to Power				96 hrs
Pipefitter 1				472 hrs
Install Rack Internal Plumbing Connections				112 hrs
Install LCW Piping around detector				160 hrs
Install Central LCW System				80 hrs
Connect Racks to LCW				24 hrs
Install piping to Coil Bus & P.S.				64 hrs
Connect P.S. to LCW				16 hrs
Connect Bus to LCW				16 hrs
Pipefitter 2				472 hrs
Install Rack Internal Plumbing Connections				112 hrs
Install LCW Piping around detector				160 hrs
Install Central LCW System				80 hrs
Connect Racks to LCW				24 hrs
Install piping to Coil Bus & P.S.				64 hrs
Connect P.S. to LCW				16 hrs
Connect Bus to LCW				16 hrs
Pipefitter 3				
Pipefitter 4				
Total	160 hrs			4,144 hrs