TAC Consumer Flow chart



Error definition

- Is there enough data for fitting?
- Is there any zero value in fitting parameters?
  (Fitted parameter must be nonzero value.)
- Is value of parameters of each PMTs in 5 sigma region?
  (|parameter value – mean value| < 5 sigma)
- Etc...
- Please inform us any other error cases!

Error Display

- What kind of error
- Id number of PMT which has error.
- Known problem?

Plan

-02/28 Implement error algorithm

03/01-03/07 Test and debug the module