

COMPANY	MING KEE MANUFACTORY	DATE	Mon, 4 Jul 2005 06:48:23 HKT
ATT.	-, -	OUR INDEX	ISR-K1J-Z0N-E30
C.C		FROM	S.Birtles

Dear Supplier,
following the inspection at your factory on the: 24/06/2005 Please find below the product status

PASS

MODEL NO.	QUANTITY	BATCH NUMBER	OUR REPORT REF
PL15014	1,700	267228/0506	IR1JL-00A-Q4H-1
PL48505	500	265984/0506	IR1JQ-0P8-6SB-0
PL48518	300	265984/0506	IR1JQ-0PH-5NP-0
PL48530	150	265984/0506	IR1JQ-0PR-1MX-0
PL48540	200	265984/0506	IR1JQ-0PW-PZ9-0
PL48506	300	265984/0506	IR1JQ-0P8-GIV-0

Fail-Rework

MODEL NO.	QUANTITY	BATCH NUMBER	OUR REPORT REF
PL48501	3,300	265984/0506	IR1JQ-0P7-8B8-0
PL48525	1,200	265984/0506	IR1JQ-0PP-TUE-0
PL48519	250	265984/0506	IR1JQ-0PH-BP1-0
PL48517	500	265984/0506	IR1JQ-0PH-0JU-0
PL48507	250	265984/0506	IR1JQ-0P8-PRO-0

Released for Shipment But item's may have Issues


MODEL NO.	QUANTITY	BATCH NUMBER	OUR REPORT REF
PL48512	800	265984/0506	IR1JQ-0PG-262-0
PL48528	150	265984/0506	IR1JQ-0PQ-KTF-0
PL48535	200	265984/0506	IR1JQ-0PS-0U3-0

GENERAL COMMENTS

1. The above reflects our findings at the time of inspection. This document does not relive the seller/supplier from their contractual responsibilities with regard to Quality/quantity of this delivery nor does it prejudice the Buyer's right of claim towards seller/suppliers for compensation for any apparent and/or hidden defects not detected during our random inspection of the goods or occurring thereafter.

2. Any corrective action form (C.A.F) must be completed and returned to this office within 2 working days of receipt. Reworked goods must be booked using the Inspection booking system.
Any Product Defect Advice note (P.D.A.N) is for your reference ONLY. It gives a complete list of all faults.

micromark HONG KONG


Manager

S.W.Birtles

	1st Insp.	To Spec.	O.K As a %	N.T.S	Bad As a %	Ttl. Flts.
This Month*	0	0	0	0	0	0
1 Year Rolling	530	446	84.15	84	15.85	102

N.T.S=Not to Spec. FIGURES
*=may not include above report Last Updated 2005-07-04 04:16:13.0