


50-F or E 10 Operation



| | Indicator On | Indicator Off |
|--------------|--------------|---------------|
| Off/On | Unit On | Unit Off |
| Indicator T1 | T1 On | Fuse Blown |
| Indicator T2 | T2 On | Fuse Blown |