

Bluetooth Devices



Adapter Device View Help



Search



Setup...



Send File



Canon MX350 series-1

Imaging

00:1A:7D:DA:71:13



G7 ThinQ

Smart phone

08:D4:6A:7B:0E:53



Failed to change profile to a2dp_source





674.80 KB 16.00 B/s 36.83 MB 27.00 B/s

Feb 27 2016 - The receiver is awake because kernel 1.3.39.1.37.20944491 Bluetooth

Sound



Output volume: 




Output

Input

Sound Effects

Applications

Input volume: 



Input level:



Profile:

High Fidelity Capture (A2DP Source)



Choose a device for sound input:



Internal Microphone - Built-in Audio



Phone - G7 ThinQ

Sound




Output volume: 



Output Input Sound Effects Applications

Choose a device for sound output:

 Speakers - Built-in Audio

 Phone - G7 ThinQ

Settings for the selected device:

Balance:



Profile:

Analog Stereo Output



Test Speakers

```
[673751.251498] Bluetooth: hci0: last event is not cmd complete (0x0f)
[673760.561428] Bluetooth: hci0: SCO packet for unknown connection handle 6
[673767.120421] Bluetooth: hci0: last event is not cmd complete (0x0f)
[673782.995416] Bluetooth: hci0: last event is not cmd complete (0x0f)
[673798.867452] Bluetooth: hci0: last event is not cmd complete (0x0f)
[673815.251577] Bluetooth: hci0: last event is not cmd complete (0x0f)
[673831.123486] Bluetooth: hci0: last event is not cmd complete (0x0f)
[root@BRSINC-01Fed Sources]# dmesg | grep -i packet
[540802.254152] Bluetooth: hci0: ACL packet for unknown connection handle 11
[541070.268166] Bluetooth: hci0: corrupted ACL packet
[673760.561428] Bluetooth: hci0: SCO packet for unknown connection handle 6
[root@BRSINC-01Fed Sources]#
```