

**Certification Test Results, rhcert 6.2 R20181120 2018-12-05 13:41:37**

arch: x86\_64

model: ThinkSystem SR590 -[7X98CTO1WW]-

make: ThinkSystem

vendor: Lenovo

Certification for:

vendor:

Red Hat Enterprise Linux 7.6 rh76.a.test 192.168.150.185

**test: info**

non-interactive certification

**run 1: 2018-12-05 14:03:45****Kernel: Verify installed kernel package**

```
+ rpm -ql kernel-3.10.0-957.el7
```

\*\*\* Check that the installed kernel rpm belongs to Red Hat \*\*\*

Installed Kernel package version: 'kernel-3.10.0-957.el7'.

1. Check the kernel rpm buildhost

```
rpm -q kernel-3.10.0-957.el7 --qf '%{buildhost} ' | grep -q redhat.com  
returned: 0
```

Test Passed: Installed kernel rpm belongs to Red Hat.

2. Check if kernel package modified

```
rpm -V --nomtime --nomode --nocontexts kernel-3.10.0-957.el7  
returned: 0
```

Test Passed: Kernel package is consistent.

\*\*\* Check that the running kernel is released by Red Hat for use with the RHEL version \*\*\*

Product Information:

-----  
Name: Red Hat Enterprise Linux

ShortName: RHEL

Version: 7.6

Installed Kernel Package Version: 'kernel-3.10.0-957.el7'.

Fetching Versions for Red Hat Kernel Packages ...

The installed kernel package, kernel-3.10.0-957.el7, is a GA.

\*\*\* Check if kernel is tainted \*\*\*

Kernel Taint value: 536870912

**FAIL**