| | | | | | | | a en : 2/ 6/2000 1.00.0 | 0 / | | |
|--|---|--|--|---|---|--|---|-----|--|--|
| TRANSP National Transportation Safety Board | NT | SB ID: | DFW07WA1 | 66 | Aircraft Regist | Aircraft Registration Number: HR-ASO | | | | |
| FACTUAL REPORT | Oc | currence | e Date: 07/22 | 2/2007 | Most Critical I | Most Critical Injury: Fatal | | | | |
| AVIATION | Oc | currence | _{e Type:} Accic | lent | Investigated E | Investigated By: Foreign | | | | |
| Location/Time | | | | | • | | | | | |
| Nearest City/Place | State | Zip | Code | Local Time | Time Zone | | | | | |
| San Salvador | | 00 | 000 | 1232 | UTC | | | | | |
| Airport Proximity: Off Airport/Airstrip | Distance From Landing Facility: | | | | | | | | | |
| Aircraft Information Summary | | | | | | | | | | |
| Aircraft Manufacturer | | | Model/Series | | Type of Aircraft | | | | | |
| Robinson | | R22 Beta II Helicopter | | | | | | | | |
| Revenue Sightseeing Flight: No | | | Air N | ledical Trans | port Flight: No | | | | | |
| Narrative | | | | | | | | | | |
| On July 22, 2007, at 1232 un helicopter, Salvadorian regis circumstances near San Salvad of the helicopter, was fatally operated by a private indivi for the personal flight. approximately 3 minutes prior t According to the authorities, takeoff. Additionally, a 1 helicopter perform several turn The accident investigation is of El Salvador. Additional inf Republica de El Autoridad de Av Carretera Panam Ilopango, El Sa This report is for informat obtained from the AAC of the Re | tration or, in t injured dual. V The loc o the mi the hel ocal ne s before under t ormation Salvado iacion C ericana, lvador ional p | HR-A the Re the Re the Re the Re the Re the set the set | ASO, was d epublic of the helicop interest impact ther impact ther report tending in the obtain (AAC) thetro 9 1/ these only | estroyed up El Salvado ter, serial ogical cond iginated f ed the grou ted that a to the fore jurisdicti ed from: 2 and conta | on impact with r. The privat number 2818, itions prevail rom the Ilop nd approximate witness to the sted area. on of the Gove | n terra te pilo was re led thr pango ely thr e accid | ain under unknown ot, sole occupant egistered to, and coughout the area Airport (MSSS) cee minutes after dent observed the c of the Republic | | | |
| | EAC | TUAL | REDORT | VIATION | | | | | | |
| | FAC | TUAL | REPORT - A | VIATION | | | Page | e 1 | | |

| National Transportation Safety | | | | | | | | | | | | | |
|---|---|-----------------------------|------------|---|------------------------------------|-----------------------------------|------------------------------|-----------|-------------------|--------------|---------------------|--|--|
| FACTUAL REPOR | | Occurrence Date: 07/22/2007 | | | | | | | | | | | |
| AVIATION | | Осси | urrence T | Гуре: | Accident | | | | | | | | |
| Landing Facility/Approach In | formation | | | | | | | | | | | | |
| Airport Name | | | Airport II | irport ID: Airport Elevation Runway Used Runway | | | | | | h R | unway Width | | |
| llopango International | | | MSSS | ; | Ft. MSL | Ft. MSL NA | | | | | | | |
| Runway Surface Type: | | | | | | | | | | | | | |
| Runway Surface Condition: | | | | | | | | | | | | | |
| Approach/Arrival Flown: NONE | | | | | | | | | | | | | |
| VFR Approach/Landing: None | | | | | | | | | | | | | |
| Aircraft Information | | | | | | | | | | | | | |
| Aircraft Manufacturer Robinson | | | | | | Model/SeriesSerialR22 Beta II2818 | | | | | | | |
| Airworthiness Certificate(s): Normal | | | | | | | | | | | | | |
| Landing Gear Type: Skid | | | | | | | | | | | | | |
| Amateur Built Acft? No Number of Seats: 2 | | | | | Max Gross Wt. | | | LBS | Numbe | er of Engi | nes: 1 | | |
| Engine Type: | | | | | Engine Manufacturer: Model/Series: | | | | | Rated Power: | | | |
| - Aircraft Inspection Information | | | | | | | | | | | | | |
| Type of Last Inspection D | | | | Date of Last Inspection Time Sir | | | nce Last Inspection Hours | | | Airframe | Total Time Hours | | |
| - Emergency Locator Transmitter (| ELT) Information | | 1 | | | | | | l | | | | |
| | | | | | ed? No | led in Locating | g Accide | ent Site? | ? No | | | | |
| Owner/Operator Information | | | | | | | | | | | | | |
| Registered Aircraft Owner Street Address | | | | | | | | | | | | | |
| Hinmer O. Benitez | City | City State | | | | | | | Zip Code 00000 | | | | |
| Operator of Aircraft | | | | | Street Address | | | | | | | | |
| Hinmer O. Benitez | | | | | City San Salvador | | | | | | Zip Code 00000 | | |
| | Operator Does Business As: Personal Operator Designator Code: | | | | | | | | | | | | |
| - Type of U.S. Certificate(s) Held: | | | | | | | | | | | | | |
| Air Carrier Operating Certificate(s) | : | | | | | | | | | | | | |
| Operating Certificate: | | | | | Operator Certifi | cate: | | | | | | | |
| Regulation Flight Conducted Unde | r: Non-U.S., Non- | Comm | nercial | | | | | | | | | | |
| Type of Flight Operation Conducted | : Personal | | | | | | | | | | | | |
| FACTUAL REPORT - AVIATION Page 2 | | | | | | | | | | | | | |

| Nation | nal Transportation | Safety Board | d | | NTSB ID: | | | | | | | | | | |
|--|---------------------|--------------|------------------------|--------|-----------------------------|---|----------|-------|---------|---------------------|------------------|---------------------------------------|----------------|---------------|---------------------|
| F | ACTUAL RI | EPORT | | ſ | Occurrence Date: 07/22/2007 | | | | | | | | | | |
| | AVIATI ETYBO | < | | ľ | Occurren | ce Type: A | Accident | | | | | | | | |
| Circt Dile | ot Information | | | | | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | | | | | | | | |
| Name | or mormation | | | | | | City | | | | | State | <u>а</u> Г | Date of Birth | Age |
| On File | | | | | | | | | | | | | | | , ige |
| | 1 | | | | | | | | | | | | | | |
| Sex: Seat Occupied: Occupational Pilot? | | | | | | | | | | Certificate Number: | | | | | |
| Certificate(s): | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| Airplane Rating(s): | | | | | | | | | | | | | | | |
| Rotorcraft/ | /Glider/LTA: | | | | | | | | | | | | | | |
| Instrument | t Rating(s): | | | | | | | | | | | | | | |
| Instructor | Rating(s): | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| Current Big | ennial Flight Revie | -w/2 | | | | | | | | | | | | | |
| Current Biennial Flight Review? Medical Cert. Medical Cert. Status: | | | | | | | | | to of I | oot Mo | dical Ex | · · · · · · · · · · · · · · · · · · · | | | |
| Medical Ce | en | Medic | | natus. | | | | | | | | | | dill. | |
| | | 1 | | | | | | | | | | | | | 1 |
| - Flight Tir | me Matrix | All A/C | This Make and Model | | Airplane Single Engine | Airplane Mult-Engine | N | ight | Actual | | Simulated | | otorcraft | Glider | Lighter Than Air |
| Total Time | e | | | | | | | | | | | | | | |
| Pilot In Co | ommand(PIC) | | | | | | | | | | | | | _ | |
| Instructor | | | | | | | | | | | | | | _ | |
| Instruction Last 90 Da | | | | | | | | | | | | | | | |
| Last 30 Da | | | | | | | | | | | | | | | |
| Last 24 Ho | - | | | | | | | | | | | | | | |
| Seatbelt Used? Shoulder Harness Used? Toxicology Pe | | | | | | | erformed | 1? | | See | cond Pilot? No |) | | | |
| Elight Pla | an/Itinerary | | | | | | | | | | | | | | |
| | ight Plan Filed: VI | | | | | | | | | | | | | | |
| Departure | | F N | | | | | | State | | Airport | Idoptifi | or | Dopart | uro Timo | Time Zone |
| | | | | | | | | Siale | , | | rport Identifier | | Departure Time | | UTC |
| San Salv | | | | | | | | | | MSSS | | | 1229 | | |
| Destination | | | | | | | | State | ; | Airport | rport Identifier | | | | |
| Local Flig | ght | | | | | | | | | | | | | | |
| Type of Cl | learance: VFR | | | | | | | | | | | | | | |
| Type of Ai | rspace: | | | | | | | | | | | | | | |
| | Information | | | | | | | | | | | | | | |
| | Wx Information: | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| | Unkno | wn | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |

| Sky/Lowest Cloud Condition: Lowest Ceiling: | Time Zone | Occurren WOF Eleva | ce Type: | 07/22/2 Accider | | n Accio | dent Site | | Direction From Accident Site | | |
|--|-----------------|-----------------------|---|--------------------|--------------|---------|-------------------|---------|------------------------------|--|--|
| Aviation Weather Information WOF ID Observation Time Sky/Lowest Cloud Condition: Lowest Ceiling: Temperature: °C | | Occurren WOF Eleva | ce Type: | Accider | it | n Accio | dent Site | | Direction From Accident Site | | |
| Weather Information WOF ID Observation Time Sky/Lowest Cloud Condition: Lowest Ceiling: Temperature: °C | Time Zone | WOF Eleva | tion | | | n Accio | dent Site | | Direction From Accident Site | | |
| WOF ID Observation Time Sky/Lowest Cloud Condition: Lowest Ceiling: Temperature: °C De | Time Zone | | | WOF D | istance Fron | n Accio | dent Site | | Direction From Accident Site | | |
| Sky/Lowest Cloud Condition: Lowest Ceiling: Temperature: °C De | | | | | Istance From | 1 ACCIC | ient Site | | Direction From Accident Site | | |
| Lowest Ceiling: Temperature: °C De | | F | MSI | | | | | | | | |
| Lowest Ceiling: Temperature: °C De | | | Ft. MSL | | | | | | Deg. Mag. | | |
| Temperature: °C De | | | Ft. AGL | | | | | of Ligh | ıt: | | |
| · · · | Lowest Ceiling: | | | | | | SM Altimeter: "Hg | | | | |
| Wind Direction: | ew Point: | °C | °C Weather Conditions at Accident Site: | | | | | | itions | | |
| | Wind Spe | eed: | | Wind | d Gusts: | | | | | | |
| Visibility (RVR): Ft. | Visibility | (RVV) | SM | | | | | | | | |
| Precip and/or Obscuration: | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| Accident Information | | | | | | | | | | | |
| Aircraft Damage: Destroyed | | Aircraft Fi | re: | | | | Aircraft Exp | losio | ı | | |
| | | | | | | | | | | | |
| - Injury Summary Matrix | Fatal | Serious Min | or | None | TOTAL | | | | | | |
| First Pilot | 1 | | | | 1 | | | | | | |
| Second Pilot | | | | | | | | | | | |
| Student Pilot | | | | | | | | | | | |
| Flight Instructor | | | | | | | | | | | |
| Check Pilot | | | | | | | | | | | |
| Flight Engineer | | | | | | | | | | | |
| Cabin Attendants | | | | | | | | | | | |
| Other Crew | | | | | | | | | | | |
| Passengers | | | | | | | | | | | |
| - TOTAL ABOARD - | 1 | | | | 1 | | | | | | |
| Other Ground | | | | | | | | | | | |
| - GRAND TOTAL - | 1 | | | | 1 | | | | | | |

| National Transportation Safety Board | NTSB ID: DFW07WA166 | |
|---|-----------------------------|--|
| FACIDAL REPORT | Occurrence Date: 07/22/2007 | |
| AVIATION | Occurrence Type: Accident | |
| Administrative Information | · | |
| Investigator-In-Charge (IIC) | | |
| Hector R. Casanova | | |
| Additional Persons Participating in This Accident/Incid | ent Investigation: | |
| Ramon Barrera San Antonio, Texas | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |