



(FD 05)



FD05 EZ ACTIVITIES:
 PGSC REBOOT
 OCAC FILTER INSPECTION
 TEPC (STATUS CHECK)
 (ORB OPS, CREW SYS)
 OSVS POWERCYCLE - Perform:
 OSVS POWERDOWN Step 1
 OSVS POWERUP Step 2
 (PDRS, OSVS)
 EXERCISE CDR,PLT

REPLANNED

(FD 05)



REPLANNED

3-45


FLT PLN/103/FIN

10/27/99


PET Re1

(FD 05)


TDRS CDR PLT MS2 (RMS) GND CMD MCC




REPLANNED




REPLANNED



REPLANNED




REPLANNED




REPLANNED

(FD 05)



REPLANNED

(FD 05)



REPLANNED