

BLM Office of Pipeline Monitoring 1992 NEPA Documents

| <i>NEPA Document Number:</i> | <i>Case File Number</i> | <i>Applicant</i> | <i>Proposed Action:</i> | <i>TAPS Geographic - PLMP Location:</i> | <i>Legal Land Description:</i> | <i>Status of NEPA Review:</i> | <i>Contact:</i> |
|------------------------------|---|----------------------------------|-------------------------|---|--------------------------------|-------------------------------|---|
| EA-993-92-001 | none | Alyeska Pipeline Service Company | Chandalar Project | Chandalar Shelf | | 10/30/1991 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-002 | FF-20688, FF-20717, FF-21537, FF-84777 | Alyeska Pipeline Service Company | OSCP roads | various | | 3/4/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-003 | FF-88186, FF-88191, FF-88192, FF-88194, FF- | Alyeska Pipeline Service Company | OSCP roads | various | | 3/5/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-004 | FF-88193, FF88196 | Alyeska Pipeline Service Company | OSCP Roads | Kanutu River | | 3/10/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-005 | FF-88193, FF-88196 | Alyeska Pipeline Service Company | OSCP roads | Atigun River | | 3/12/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-006 | FF-88187, FF-88188, FF-88189, FF-88190 | Alyeska Pipeline Service Company | OSCP roads | Koyukuk River | | 3/17/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-007 | FF-88218, FF-88220, FF-88223 | Alyeska Pipeline Service Company | OSCP roads | Dietrich River | | 4/15/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |

BLM Office of Pipeline Monitoring 1992 NEPA Documents

| <i>NEPA Document Number:</i> | <i>Case File Number</i> | <i>Applicant</i> | <i>Proposed Action:</i> | <i>TAPS Geographic - PLMP Location:</i> | <i>Legal Land Description:</i> | <i>Status of NEPA Review:</i> | <i>Contact:</i> |
|------------------------------|-------------------------|----------------------------------|--------------------------|---|--------------------------------|-------------------------------|---|
| EA-993-92-008 | FF-88221 | Alyeska Pipeline Service Company | OSCP site | Atigun River | | 4/17/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-009 | FF-88222 | Alyeska Pipeline Service Company | Workpad realignment | Sheep Creek PLMP 216.3 | | 4/15/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-010 | FF-88241 | Alyeska Pipeline Service Company | Corrosion Repair | Linewide | | 5/6/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-011 | FF-88246 | Alyeska Pipeline Service Company | OSCP road | Koyukuk River | | 5/15/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-012 | AA-75690 | Alyeska Pipeline Service Company | OSCP road | Tsaina River | | 7/17/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-013 | FF-88485 | Alyeska Pipeline Service Company | Access road relocation | Dietrich River | | 8/21/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |
| EA-993-92-014 | AA-50930 | Alyeska Pipeline Service Company | Pump Station 12 overlook | Richardson Hwy MP 65 | | 9/3/1992 | Stan Bronczyk (907)257-1315 sbronczyk@jpo.doi.gov |