

Menu


HISTORY FILE MAP for year 2000-2001

Realtime

Playback

Recalled Realtime

Recalled Playback



DOY problems with TCT (Time Code Translator) at SPC40 (Canberra). Resulted in antenna halt with outages of 28m, 2m, 2m and 5m. DR A05008 & DR05009 refer.