

Menu


HISTORY FILE MAP for year 2001

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



64m, 6m & 5m RT 1024bps data lost at DSS54: LNA problem followed by antenna going off-point caused following data outages: 283.12:15-13:19 LNA/antenna offpointing probs. 283.13:24-13:30. Extra 2-way to 1-way. 283.14:13-14:18. Extra 1-way to 2-way. DRs M100197 & M100198 refer.

285.18:22-18:36. 15m RT 1024bps data lost at DSS63 due to bad U/L transfer causing unscheduled 1-way to 2-way transition. DR M100203 refers.