



### SAFETY RECALL THIRD NOTICE

May 18, 2007

**NHTSA SAFETY RECALL CAMPAIGN # - 04V-218**

Dear Harley-Davidson Motorcycle Owner:

In June of 2003, you and other registered owners were notified by the attached letter that a defect which relates to motor vehicle safety exists in the following XL's, Dyna's and Touring model motorcycles built between June 4, 2003 and August 22, 2003:

DYNA	XL	TOURING
FXD	XL 883	FLHT
FXDI	XL 883 Hugger	FLHTI
FXDL	XL 883C	FLHTC
FXDLI	XL 883R	FLHTCI
FXDWG	XL 1200	FLTRI
FXDWGI	XL 1200C	FLTR
FXDX	XL 1200R	FLHR
FXDXI	XL 1200S	FLHRI
FXDXT		FLHRCI
FXDP		FLHTPI
		FLHPI
		FLHPEI
		FLHTCSE
		FLHRSEI2
		FLHRS
		FLHRSI

This is a follow-up to that earlier communication.

Our records indicate you have not responded to our recall notice. Therefore, we are sending you this third notice in order to re-emphasize the importance of having your motorcycle serviced immediately to remedy the safety issues described in our earlier letter. A brief description of the defect and safety issue involved is described in the attached copy of our earlier letter to you.

Please contact your Harley-Davidson dealer immediately for an appointment to have your motorcycle serviced according to instructions contained in the letter attached.

If your dealer has already serviced your motorcycle under this recall, you are receiving this letter because we have not been notified that the work had been completed. We ask that you take the enclosed service card to your dealer, have it completed, signed by you and your dealer, and returned to us for our records as required by law. (Disregard this instruction if you have had the service completed recently, since it takes some time for mailing and our processing of information). This will assist us in accurately reporting vital information to NHTSA about your vehicle, as required by law.

If you have sold your motorcycle, please fill out and mail the enclosed Motorcycle Owner Card with the appropriate information about your purchaser. This will enable us to contact him/her and advise that person of this recall.

Sincerely,

Harley-Davidson Motor Company, Inc.  
Attachments 0114



**SAMPLE COPY**

June 3, 2004

**NHTSA SAFETY RECALL CAMPAIGN # - 04V-218**

Dear Harley-Davidson Motorcycle Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Harley-Davidson Motor Company, Inc. has decided that a defect which relates to motor vehicle safety exists in the following XL's, Dyna's and Touring model motorcycles built between June 4, 2003 and August 22, 2003:

<b>DYNA</b>	<b>XL</b>	<b>TOURING</b>
FXD	XL 883	FLHT
FXDI	XL 883 Hugger	FLHTI
FXDL	XL 883C	FLHTC
FXDLI	XL 883R	FLHTCI
FXDWG	XL 1200	FLTRI
FXDWGI	XL 1200C	FLTR
FXDX	XL 1200R	FLHR
FXDXI	XL 1200S	FLHRI
FXDXT		FLHRCI
FXDP		FLHTPI
		FLHPI
		FLHPEI
		FLHTCSE
		FLHRSEI2
		FLHRS
		FLHRSI

These motorcycles have a condition that could allow the tail light bulb to fall out of the socket, thereby rendering the tail light and the brake light inoperative, which could lead to a crash, causing the possibility of death or injury to the rider.

Our records indicate that you purchased one of the motorcycles involved in this safety recall identified by the VIN (Vehicle Identification Number) shown on this letter.

**We strongly urge you to take your motorcycle to your dealer to have the appropriate service performed as soon as possible. Should you choose to ride your motorcycle prior to this service, we urge you to be aware of this condition.**

Please contact your Harley-Davidson motorcycle dealer immediately and arrange an appointment to have your tail light bulb replaced. The dealer labor time to perform this service takes less than 1 hour and the parts and labor will be free of charge to you. Parts should be available at your dealership the week of May 17, 2004.

To verify that the service has been completed, Your dealer will ask you to sign a recall claim. If you have sold your motorcycle, please forward the appropriate information about your purchaser to us. This will enable us to contact him/her and advise that person of this recall. Also, Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you had this repair before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Harley-Davidson at 1-414-343-4056.

If you take your motorcycle to your dealer on a mutually agreed upon date and he does not perform the required service to your satisfaction, please contact Harley-Davidson Motor Company, Inc. for immediate assistance at the address or telephone number listed on this letterhead. If your dealer or Harley-Davidson Motor Company, Inc. fails or is unable to remedy your motorcycle without charge within a reasonable time, you may wish to inform the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590, or call the toll-free Auto Safety Hotline at 1-888-DASH-2DOT or contact NHTSA at [www.NHTSA.DOT.GOV](http://www.NHTSA.DOT.GOV).

We regret any inconvenience this may cause you, but we are initiating this action in the interest of your personal safety and satisfaction with our products. Thank you for your cooperation.

Sincerely,

Harley-Davidson Motor Company, Inc.