



DATE, 2007

REFRIGERATOR RECALL NOTICE

Dear RV Park Operator:

Dometic Corporation has recently identified a potential safety defect that could occur in an exceptionally small fraction of our recreation vehicle refrigerators. We are in the process of voluntarily recalling those cooling units that include two-door refrigerators manufactured between April 1997 and May 2003.

Safety is of the highest concern as we move forward with this recall and **we would appreciate your assistance in helping to notify consumers.** We have identified a solution and will be servicing the recalled units to ensure our customers will remain safe and content in all their RV travels.


Please place the enclosed notice in a prominent location so RVers who may have one of these affected units will become aware of the recall.

We appreciate your willingness to be of public service to us and your guests. We regret any inconvenience this may cause and we will continue to develop the safest, most innovative products possible as we move forward.

Thank you for your cooperation.

Patrick N. McConnell
Director of Engineering, Product Safety and Standards
Dometic Corporation

RECALL 06E-076



IMPORTANT

Dometic Recall Information

Dometic Corporation is continually committed to maintaining a high level of satisfaction and excellence now and in the future. That is why Dometic is voluntarily recalling certain refrigerators that may have a potential safety defect. The recall affects Dometic two-door refrigerators manufactured between April 1997 and May 2003.


The well-being of Dometic customers is of highest concern. A serious problem resulting in a fire may occur in an exceptionally small fraction of Dometic two-door refrigerators, but to address that potential risk, **please contact us immediately for more information.**

1-888-446-5157


www.DometicUSA.com

 **Dometic**

DOMESTIC RECAL INFORMATION



IMPORTANT



IMPORTANT

DOMESTIC RECAL INFORMATION

! IMPORTANT

Dometic Recall Information

DATA COLLECTION AND PAYMENT

RECALL 06E-076

It is essential to all parties that every rework installation associated with this recall be thoroughly documented. **Included in the box with each rework kit** Dometic sends out will be a Service Claim Card. A copy of that card is seen below.

Customer Information		Dealer/Repair Center Information	
Name		Dometic Dealer #	
Address		Name	
City and State		Address	
Zip		City and State	
		Zip	
		Work Order #	
Recalled Unit Information		Recreational Vehicle Information	
Model #		VIN #	
Serial #		Manufacturer	
Repair Date			

*This card must be thoroughly completed and returned within 2 days of completion of repair service to expedite reimbursement *

FORM NO 331 1232.000

Dometic has ordered hundreds of thousands of the above sheets. As the cards are collected, monthly statistical reporting will be available to you. Allowing Dometic and Stericycle to handle this recall program for your company will greatly minimize your administrative costs.

Below is the card information that was provided to the dealer/service center network:

DETAILS

- This is the sole information gathering piece that Dometic and Stericycle will use with this recall.
- We are required by federal law to submit complete information. Therefore, for each and every rework kit install, this card **MUST be filled out completely**. Payment will not be given for the installation unless every box on the card is completely and legibly filled in.
- The card features pre-paid postage on the reverse side, as well as the address that it must be mailed to. That address is:

Stericycle, Inc.
2670 Executive Drive, STE. A
Indianapolis, IN 46241

- The card must be mailed no later than 48 hours after the rework.