

Tue Apr 6 2010 08:49:37 EDT

Component: hplip Product: Fedora

251 bugs found.

ID	Sev	Pri	OS	Assignee	Status	Resolution	Summary
504193	low	low	Linux	Tim Waugh	NEW		[Feat/req] Add autostart entry for HP systray icon
507265	medium	low	Linux	Tim Waugh	NEW		hplip requires powering off/on hp laserjet 1018 after login
509176	medium	low	Linux	Tim Waugh	NEW		AVC errors while printing to HP Officejet Pro L7780 (Foomatic/hpijs)
538352	medium	low	Linux	Tim Waugh	NEW		Setup on HP network printer fails.
540721	medium	low	Linux	Tim Waugh	NEW		HP setup and other utils don't prompt for root pw when needed
552725	medium	low	Linux	Tim Waugh	NEW		SELinux is preventing /usr/bin/python "write" access on /usr/share/hplip /prnt.
552731	medium	low	Linux	Tim Waugh	NEW		alignment error with hpcups
553911	medium	low	Linux	Tim Waugh	NEW		[abrt] crash in hplip-gui-3.9.8-21.fc12
556153	medium	low	Linux	Tim Waugh	NEW		[abrt] hp-toolbox crash in _dbus_counter_get_value
558335	medium	low	Linux	Tim Waugh	NEW		HP L7650 margin off by 0.5 inch with duplex printing
562667	medium	low	Linux	Tim Waugh	NEW		SIGSEGV in "fileno" in /usr/bin/hp-toolbox
563560	medium	low	Linux	Tim Waugh	NEW		Cannot print anymore
566949	medium	low	Linux	Tim Waugh	NEW		USB-connected HP 2575 Printer occasionally hanging print jobs
571568	medium	low	Linux	Tim Waugh	NEW		SIGSEGV in "doc_QStringRef_0_length" in /usr/bin/hp-systray
573415	medium	low	Linux	Tim Waugh	NEW		[abrt] crash in xsane-0.997-3.fc12: Process /usr/bin/xsane was killed by signal 11 (SIGSEGV)
577262	medium	low	Linux	Tim Waugh	NEW		Missing Device ID for HP LaserJet p1006

235250	medium	low	Linux Tim Waudn	MODIFIED	mpib-3.10 is available		
235112	medium	low	Linux Tim Waudn	ASSIGNED	looking for printer-driver for bqobeu(INGT) ZIGZAG in file on call		
200000	medium	low	Linux Tim Waudn	ASSIGNED	on this system, "No system tray detected setting default options as models' without server HB 1 4012		
233851	medium	low	Linux Tim Waudn	ASSIGNED	request (mpib) (mcbp): OK need b1202n printer file postscript print to HB		
250500	medium	low	Linux Tim Waudn	ASSIGNED	printer variable to print to HB USB		
215410	medium	low	Linux Tim Waudn	ASSIGNED	3500 (USB-connected) selected for HB laserjet incorrect printer driver		
215411	high	low	Linux Tim Waudn	ASSIGNED	re-setup hands at startup		
210050	low	low	Linux Tim Waudn	ASSIGNED	low ink on HB b2c 310v mpib incorrectly reports toner		
210322	medium	low	Linux Tim Waudn	NEW	mpib-printer-language not B99 b9D - can't print to HB printer:		
210331	medium	low	Linux Tim Waudn	NEW	mcbp2 doesn't work		
210301	medium	low	Linux Tim Waudn	NEW	print low ink, is a reason to not mpib-3.10's think that		
211808	medium	low	Linux Tim Waudn	NEW	Officejet 1300 series Missing Device ID for HB		
211883	medium	low	Linux Tim Waudn	NEW	Color Laserjet 3800 Missing Device ID for HB		
211308	medium	low	Linux Tim Waudn	NEW	Laserjet 1500 Missing Device ID for HB		
211300	medium	low	Linux Tim Waudn	NEW	Laserjet 1050 Missing Device ID for HB		
211305	medium	low	Linux Tim Waudn	NEW	(Bluefoot) Photosmart 380 Missing Device ID for HB		
211505	medium	low	Linux Tim Waudn	NEW	Deskjet 020C Missing Device ID for HB		
211588	medium	low	Linux Tim Waudn	NEW	Deskjet 3040 Missing Device ID for HB		
211585	medium	low	Linux Tim Waudn	NEW	Laserjet 1018 Missing Device ID for HB		
ID	sev	pri	OS	Assignee	status	resolution	summary