

U.S. Department of Homeland Security

United States Coast Guard

LOCAL NOTICE TO MARINERS

District: 9 Week: 12/08

> Issued by: Commander (dpw) Ninth Coast Guard District 1240 East Ninth Street. Cleveland, OH 44199-2060 Telephone: (216) 902-6074

Direct questions about this LNM to the above address.

District Nine Internet Address http://www.uscg.mil/d9/uscgd9.html

** Navigation Information Service watchstander, 24 hours a day at (703) 313-5900 ** **Internet Address** http://www.navcen.uscg.gov/ Light List Reference: Commandant Publication P16502.7, VOL VII, 2007 Edition

Coast Pilot Reference: 2007 U.S. Coast Pilot 6 Great Lakes 35th Edition

Coast Pilot Corrections Reference download web page: http://nauticalcharts.noaa.gov/nsd/cpdownload.htm The Local Notice to Mariners is available on the Internet at http://www.navcen.uscg.gov/lnm/d9/default.htm. You will also have links to other government agencies- web pages including the US Army Corps of Engineers and the National Ocean Service. REPORT DISCREPANCIES IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

The Ninth District and all Sector offices for their areas of responsibility issue a BROADCAST NOTICE TO MARINERS. The following Broadcast Notice to Mariners have been incorporated into this week's Local Notice to Mariners:

Sector Buffalo, NY - B006-08 through B007-08 Ninth District - C023-08 through C023-08 Sector Detroit, MI - D016-08 through D016-08 Sector Lake Michigan, WI - M090-08 through M092-08 Sector Sault Ste Marie, MI - S028-08 through S034-08

ABBREVIATIONS

A through I

ACOE - Army Corps of Engineers

ADRIFT - Buoy Adrift

AICW - Atlantic Intracoastal Waterway

B - Buoy

BKW - Breakwater B - Refer to Light List

BNM - Broadcast Notice to Mariner

CG - Refer to Light List

CHAN - Channel

CGD - Coast Guard District CR - Refer to Light List

C/O - Cut Off

CONT - Contour

CONSTR - Construction

CRK - Creek

CONST - Construction

DBN - Daybeacon

DBD/DAYBD - Dayboard

DBN/DEST - Daybeacon Destroyed DBN IMCH - Daybeacon Improper

Characteristic

DISCON - Discontinued

DMGD - Daybeacon Damaged

EST - Established Aid **EVAL** - Evaluation EXT - Extinguished

FL - Flashing

FS - Fog Signal

K through M

KBG - Refer to Light List

KBG-I - Refer to Light List

KBR - Refer to Light List

KBR-I - Refer to Light List

KBW - Refer to Light List

KGB - Refer to Light List KGB-I - Refer to Light List

KGR - Refer to Light List

KGR-I - Refer to Light List

KGW - Refer to Light List KGW-I - Refer to Light List

KRB - Refer to Light List

 $\mathsf{KRB}\text{-}\mathsf{I}$ - Refer to $\bar{\mathsf{L}}\mathsf{ight}$ List

KRG - Refer to Light List

KRG-I - Refer to Light List

KRW - Refer to Light List

KWB - Refer to Light List

KWB-I - Refer to Light List

KWG - Refer to Light List

KWG-I - Refer to Light List

KWR - Refer to Light List

KWR-I - Refer to Light List LAT - Latitude

LB - Lighted Buoy

LBB - Lighted Bell Buoy

LHB - Lighted Horn Buoy LGB - Lighted Gong Buoy

LONG - Longitude

N through Z

NB - Refer to Light List

N/C - Not Charted

ND - Refer to Light List

NG - Refer to Light List

NGA - National Geospatial-Intelligence Agency

NL - Refer to Light List

NO - Number

NOS - National Ocean Service

NR - Refer to Light List

NW - Refer to Light List

NW - Notice Writer

NY - Refer to Light List

OBSCU - Obscured

OBST - Obstruction

OFF STA - Off Station

OBSTR - Obstruction

PRIV - Private Aid

RBN - Radio Beacon

REBUILT - Aid Rebuilt

RECOVERED - Aid Recovered

RED - Red Buoy

REDINT - Reduced Intensity

RRL - Range Rear Light

RELIGHTED - Aid Relighted

RELOC - Relocated

RESET ON STATION - Aid Reset on Station

RFL - Range Front Light

RIV - River

HAZ - Hazard to Navigation

HBR - Harbor

HOR - Horizontal Clearance

HT - Height

ICW - Intracoastal Waterway IMCH - Improper Characteristic

INL - Inlet

INT - Intensity ISL - Islet

INOP - Not Operating

MR - Refer to Light List MR-I - Refer to Light List

LWB - Lighted Whistle Buoy LWP - Left Watching Properly MISS - Missing

LT - Liaht

LNM - Local Notice to Mariners

LT CONT - Light Continuous

SG - Green Square

SEC - Section

SG-SY - Green Square with Yellow Square

SHL - Shoaling SND - Sound SS - Sound Signal

TEMP - Temporary Aid Change

TMK - Topmark St M - Statute Mile TR - Red Triangle

TRLB - Temporarily Replaced by Lighted Buoy TRLT - Temporarily Replaced by Light TR-TY - Red Triangle with Yellow Triangle

TRUB - Temporarily Replaced by Unlighted Buoy

Additional Abbreviations Specific to this LNM Edition:

DMGD - Damaged MSLD SIG - Misleading Signal REDUCED INT DAY - Burning During the Day SS - Sound Signal

SECTION I - SPECIAL NOTICES

This section contains information of special concern to the Mariner

WATERWAY CLOSURES FOR THE GREAT LAKES

LAKE HURON - 33 CFR 165.901 The South Channel - closed The waters between St. Ignace, MI and Mackinac Island - closed LAKE MICHIGAN - 33 CFR 165.901 Grays Reef Passage - closed ST MARYS RIVER - 33 CFR 162.117 West Neebish Channel - closed Pipe Island Passage - closed

LNM: 05/08

USACOE NOTICE TO NAVIGATION INTERESTS

All recent Federal Channels conditions that have conditional surveys can be found can be seen at the USACE Detroit District web site at: http://www.lre.usace.army.mil/who/operationsofficehomepage/latestnotices/index.cfm? and http://www.lre.usace.army.mil/who/operationsofficehomepage/noticetonavigationinterest/, the USACE Chicago District website at: http://www.lrc.usace.army.mil/co%2Do/Nav_Notice.htm, and the USACE Buffalo District website at: http://www.lrb.usace.army.mil/

LNM: 11/07

ST LAWRENCE SEAWAY - NAVIGATION NOTICES

All recent notices that have been created by the St Lawrence Seaway System can be found at the following web addresses: http://www.greatlakes-seaway.com/en/seaway/index.html

LNM: 13/07

The Dates of Latest Editions, Nautical Charts and Miscellaneous Maps

The Dates of Latest Editions, Nautical Charts and Miscellaneous Maps, dated October 1, 2007, published by the National Ocean Service, is available for issue. It may be obtained for free by mail from the FAA/National Aeronautical Charting Office, Distribution Division AVN-530, 10201 Good Luck Road, Glenn Dale MD, 20769-9700, by telephone at 1-800-638-8972, or from your local authorized nautical chart sales agent. This is a quarterly publication listing the most recent editions of nautical charts, miscellaneous maps and publications relating to navigation, weather, etc. with brief descriptions and newly updated prices for most of the publications listed. Much of this information may also be obtained online at: http://chartmaker.ncd.noaa.gov/mcd/dole.htm

LNM: 43/07

GREAT LAKES - Great Lakes Water Levels

The expected water levels on the Great Lakes for April 05, 2008. Connecting Channels and the St. Lawrence River, given in inches above (+) or below (-) Low Water Datum (LWD). LWD is a plane of reference used on a navigation chart. It is also known as chart Datum. Great Lakes:

Lake Ontario +29, Lake Erie +31, Lake St. Clair +18, Lake Michigan-Huron -6, Lake Superior -9.

St Lawrence River:

Above Long Sault Dam +45, Above Iroquois Dam +34, Ogdensburg +36, Alexandria Bay +31, Head of River at Cape Vincent +29. Detroit River:

Lake Erie at Pelee Passage +31, Mouth of River at Gibraltar +27, Head of River above Belle Isle +18

St. Clair River:

Mouth of River at St. Clair Flats +18, Algonac +12, St. Clair +5, Blue Water Bridge -1, Head of River at Fort Gratiot -6, Lake Huron Approach Channel -6.

St. Marys River:

Mouth of River at Detour -6, West and Middle Neebish -1, Head of Little Rapids -1, U.S. Slip 0 Above Locks -6, Head of River at Point Iroquois -9.

Available water depth is determined for a location by adding (if +) or subtracting (if -) the amount from the above to the water depth shown on National Oceanic and Atmospheric Administration (NOAA) navigational charts. Caution: Depths so determined are representative of a still water surface elevation, disturbed by neither wind nor other causes. Depth, however, may be reduced or increased as much as several feet for short periods of time due to these disturbances, or when sections of channels develop shoals. Vessel masters should refer to the Local Notice to Mariners for extent of shoaling and scattered bedrock projections in all channels. For further information direct inquires to: Department of the Army, Detroit District Corps of Engineers P. O. Box 1027, Detroit, MI 48231, (313) 226-6443. Additional information can be found on the U.S. Army Corps of Engineers Information Center website at

http://www.lre.usace.army.mil/greatlakes/hh/greatlakeswaterlevels/waterlevelforecasts/connectingchannelsforecasts/index.cfm?.

LNM: 12/08

NEW YORK STATE CANAL SYSTEM - NOTICE TO MARINERS - Champlain Canal - Chart 14786

Mariners are advised that shoaling to 6.5' has been reported between red buoys 72 and 72A, just to the south of Lock C-4 on the Champlain Canal. This shoaling has been reported and confirmed at a time when flashboards adjacent to Lock C-3 were fully deflated for maintenance, decreasing water levels to "normal pool" but much lower than typical for this area. At normal pool elevation of 67.5', vessels exceeding a 6.5' draft should not transit this area.

Typical navigation season elevation for this level is 73.5' due to inflatable flashboards maintained for the purpose of hydropower generation by a private company. Therefore, depth usually encountered in this area will be approximately 6' deeper than reported above. With flashboards fully inflated on this level, controlling minimum depth is approximately 12.5'.

Mariners requiring a controlling depth of greater than 6.5' should call ahead to verify pool levels prior to transiting this area.

For updates and information on Canal conditions please call 1-800-4CANAL4 or visit www.nyscanals.gov.

LNM: 39/07

NEW YORK STATE CANAL SYSTEM NOTICE TO MARINERS - Champlain Canal -Chart 14786

Mariners are advised that a strong crosscurrent may affect vessel maneuverability immediately above Lock C-2 in Mechanicville. This crosscurrent is related to operations at an adjacent hydroelectric facility not under ownership or control of the Canal Corporation. Vessels should remain mid channel and stay well clear of cribbing clusters when transiting this area. Work has been completed at Lock E-28A in Lyons. The lock is open for navigation.

LNM: 32/07

LAKE ONTARIO - Irondequoit Bay - Shoaling - Chart 14804

Heavy shoaling has been reported in Irondequoit Bay near the Bay Entrance Channel.

LNM: 34/07

LAKE ERIE - OH, Port Clinton - Rock Hazard - Chart 14846

The Coast Guard has received a report of a rock in the water located 260 yards off shore in 3 feet of water at postion 41-31-24N 082-57-34.2W. Mariners are urged to use caution when transiting this area.

LNM: 43/07

DETROIT RIVER - East Outer Channel - Chart 14848

East Outer Lighted Buoy 16 (LLNR 6960) has been changed to a year round lighted buoy. Range of the light is 3 miles.

LNM: 52/07

LAKE ST CLAIR - Chart 14850

Lake St. Clair Lighted Buoy "7" (LLNR 8445) has been changed to a year round lighted buoy. Range of the light is 3 miles.

LNM: 52/07

LAKE HURON - Lake Huron Cut - Chart 14862

Lake Huron Cut Lighted Buoy "1" (LLNR 10035) has been changed to a year round lighted buoy. Range of the light is 3 miles. Lake Huron Cut Lighted Buoy "11" (LLNR 10085) has been changed to a year round lighted buoy. Range of the light is 3 miles.

LNM: 52/07

LAKE HURON - Lexington Harbor, MI - Shoaling - Chart 14862

Surveys performed during July 2007 indicate shoaling in the Federal navigation channel at

Lexington Harbor, Michigan. The surveys are available on internet address: http://www.lre.usace.army.mil/who/operationsofficehomepage/Mariners are urged to use extreme caution in the area.

LNM: 31/07

ILLINOIS WATER WAY - IL, Illinois River - Shoaling

Shoaling has been reported near the left descending bank of the Illinois River at MM 200. All mariners use caution when transitting this area.

LNM: 47/07

LAKE MICHIGAN - Grand Traverse Bay - Aid Reduced Intensity - Chart 14913

Grand Traverse Light (LLNR 18110) has a range reduced from 24 Miles to 18 Miles.

LNM: 42/07

LAKE MICHIGAN - MI, Arcadia - Shoaling - Hazard to Navigation

The Coast Guard has received a report of shoaling in the vicinity of Arcadia channel entrance. All mariners are urged to use caution when transiting the channel.

LNM: 43/07

LAKE MICHIGAN - MI, Pentwater Harbor - Shoaling - Chart 14907

Shoaling has been reported perpendicular to the entrance of Pentwater Harbor. All mariners use caustion while transiting the area.

LNM: 29/07

LAKE MICHIGAN - Muskegon - Unpublished Winter mark - Chart 14934

A winter mark was placed in position of Muskegon Lake Lighted Buoy 3 (18750) 43-13-55.050N 086-18-04.217W. This winter mark is not published in the Great Lakes Light List. Mariners are urged to use caution while transiting this area.

LNM: 50/07

LAKE MICHIGAN - New Buffalo Harbor Entrance, MI - Severe Shoaling - Chart 14905

The Coast Guard has received a report of severe shoaling at the New Buffalo Harbor Entrance. All Mariners are urged to use caution when transiting the area.

LNM: 45/07

LAKE MICHIGAN - Waugoshance Point to Seul Choix Point - Chart 14911

White Shoal Light (LLNR 17750) The characteristic has been changed to FI W 4s. The range of the light has been reduced from 17 to 11 miles. The fog signal will be secured for the winter navigation season.

LNM: 01/08

LAKE MICHIGAN - Ludington Harbor - Shoaling - Chart 14937

Shoaling has been reported in Ludington Harbor Channel, in view of Ludington South Pierhead Light 6 (LLNR 18560). Depths were reported as shallow as 14 feet along the south edge of the channel and 24 feet mid-channel.

LNM: 27/06

LAKE MICHIGAN - Waukegan Harbor, IL - Shoaling - Chart 14904

Shoaling has been reported in the Waukegan Harbor Channel. The shoaling protrudes approximately 200 feet into the channel from the north. Available depths have been reduced to 10 feet southeast of the Waukegan North Breakwater.

LNM: 38/06

LAKE MICHIGAN -Shoaling - Illinois Waterway - Calumet River - Chart 14929

Shoaling has been reported in the vicinity of Acme Steel Been at Mile Maker 321 in the Calumet River. All mariners are to use caution when transiting this area.

LNM: 49/07

LAKE MICHIGAN - MI, Holland Harbor - Shoaling - Chart 14932

Shoaling has been reported in Holland Harbor. Depths of less than 16 feet were reported at the entrance to the channel.

LNM: 50/06

ST MARYS RIVER - De Tour Passage to Munuscong Lake - Chart 14882

Pipe Island Lighted Buoy "1" (LLNR 12865) has been changed to a year round lighted buoy.

LNM: 52/07

ST MARYS RIVER - Head of Nicolet to Whitefish Bay - Chart 14884

Pt. Iroquois Lighted Buoy 33 (LLNR 14465) has been changed to a year round lighted buoy. Range of the light is 3 miles.

Pt. Iroquois Lighted Buoy 39 (LLNR 14490) has been changed to a year round lighted buoy. Range of the light is 3 miles.

LNM: 52/07

ST MARYS RIVER - Sault Ste Marie - Ice Fields - Chart 14884

To keep adjacent ice fields intact, mariners transiting the St. Mary's River are asked to monitor the wake and displacement of their vessels to prevent incidental icebreaking. This is especially true in the West and Middle Neebish Channels, and in the vicinity of the ferries.

LNM: 50/07

LAKE SUPERIOR - Chequamegon Bay - Temporary Aid Established - Chart 14974

A temporary white styrofoam aid has been established to mark the end of underwater cabling in position 46-48.5N 090-47.9W.

LNM: 45/07

LAKE SUPERIOR - Isle Royale - EMERGENCY RESTRICTIVE ORDER - Chart 14976

Effective Tuesday September 18, 2007, the National Park Service instituted an Emergency Restrictive Order under 36 CFR 1.5(a)(2) prohibiting the discharge of untreated ballast water within Isle Royale National Park waters. This order affects vessels intending to transit within four and one half miles of the shore of Isle Royale and immediately surrounding islands, including Passage Island and Gull Islands. Please contact the National Park Service at 219-926-7561 Ext. 311 for more information.

LNM: 39/07

LAKE SUPERIOR - MI, Marquette Harbor - Shoaling - Chart 14970

Surveys preformed during July 2007 indicate shoaling in the federal navigation channel at Marquette Harbor, MI. Mariners are urged to use extreme caustion in the area. Questions regarding this notice may be directed to the Army Corps of Engineers Operation Office.

LNM: 32/07

LAKE SUPERIOR - St Louis River - Shoaling - Chart 14975

Shoaling has been reported near River buoys 58-61 (LLNR 16385, 16390, 16395, 16400) in the St Louis River. All mariners are recommend to use extreme caution when transiting this area as water depths are as low as 4 feet.

LNM: 19/07

LAKE SUPERIOR - Duluth Harbor - Chart 14975

Minnesota Channel (Eastern Section) Lighted Buoy "14" (LLNR 16235) will be temporarily relocated to position 46-43'11"N 092-09'38"W approximately 80 yards inside the channel to facilitate the Tar Coal cleanup Safety Zone until the summer of 2009.

LNM: 22/07

SECTION II - DISCREPANCIES

This section lists all reported and corrected discrepancies related to Aids to Navigation in this edition. A discrepancy is a change in the status of an aid to navigation that differs from what is published or charted.

DISCREPANCIES (FEDERAL AIDS)

LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM End
2080	Oswego Harbor West Pierhead	LT EXT	14813	B007-08	12/08	
	Light					
3000	Strawberry Island Cut Upper Range	LT EXT	14832	B004-08	05/08	
	Front Light					
4160	Cleveland Harbor Main Entrance Light	LT EXT	14839	B003-08	04/08	
6580	Monroe Harbor Buoy 3	OFF STA	14846	D010-08	08/08	
7380	Point Mouillee Access Channel Buoy 3	OFF STA	14854	D165-07	52/07	
7745	Fighting Island Channel Buoy 88	OFF STA	14853	D013-08	09/08	
8065	Trenton Channel Lighted Buoy 25	SINKING	14853	D005-08	04/08	
8880	St Clair Shores Breakwater Daybeacon 1	SINKING	14853	D015-08	10/08	

ne	Status	Position	ı	BNM Ref.	LNM St	LNM En
FORM DISCF						
LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM E
REPANCIES (I	PRIVATE AIDS) CORRECTED					
22055.4	Suamico Lighted Buoy 4	LT EXT	14918	M328-07	30/07	
	Light					
20390	Port Washington South Projection Jetty	LT EXT LT IMCH	14904	M542-07	46/07	
20390	Northpoint Marina Entrance Light 1	LT EXT	14927	WI4 / / -U /	40/07	
19925	Four-Mile Crib Light	LT EXT	14973	M477-07	40/07	
15950	Interstate Fishing Pier West Light	MISSING	14975	S129-07 S130-07	37/07	
15425 15945	Washburn Harbor North Breakwater Light 1 Interstate Fishing Pier East Light	DBN IMCH/NUM MSNG/DAMGD MISSING	14974 14975	S129-07	29/07 37/07	
15420	Light 2	DBN IMCH/NUM MSNG/DAMGD				
9840 15420	Washburn Harbor South Breakwater	LT EXT	14853 14974	D080-06	25/06 29/07	
8940	Black Creek Lighted Buoy 1 Recors Point Dock Lower Light	MISSING	14853	D000 01	21/07	
8745	Municipal Pier South Basin Light	MISSING	14853		38/07	
	South Light					
8735	Crescent Sail Yacht Club Breakwater	LT EXT	14853		38/07	
8155	Detroit Edison Cell Light South Detroit Edison Cell Light North	LT EXT	14853		38/07	
8145	Detroit Edison Cell Light South	LT EXT	14853		38/07	
8145	Great Lakes Steel Shoal Lighted Buoy 3	MISSING	18453		38/07	
7400 8140	South Huron Valley Outfall East Lighted Buoy Great Lakes Steel Shoal Lighted Buoy 1	MISSING MISSING	14853 14853		38/07 38/07	
7395	South Huron Valley Outfall Center Lighted Buoy	MISSING	14853		38/07	
7390	South Huron Valley Outfall West Lighted Buoy	MISSING	14853		38/07	
LLNR	Aid Name	Status	Chart No.	BNM Ref.	LNM St	LNM E
REPANCIES (I	PRIVATE AIDS)					
14430	Birch Point Range Front Light	WATCHING PROPERLY	14884	S034-08	12/08	12/0
14395	Brush Point Range Rear Light	WATCHING PROPERLY WATCHING PROPERLY	14884	S033-08	12/08	12/08
LLNR 14205	Aid Name Prush Point Pango Poor Light	Status WATCHING PROPERLY	Chart No.	BNM Ref.	LNM St	12/09
-	FEDERAL AIDS) CORRECTED			_,		
	3				-	
21345	Plum Island Lighted Buoy 1	OFF STA	14909	M034-08	06/08	
21340	Detroit Island Passage Buoy 2	MISSING	14909	M073-08	08/08	
21335	Waverly Shoal Lighted Bell Buoy 5	MISSING	14909	M073-08	08/08	
21305	Plum Island Range Front Light	REDUCED INT	14909	M023-08	04/08	
21295	Rowley Bay Buoy 4	OFF STA	14909	M028-08	05/08	
21290	Rowley Bay Buoy 3	MISSING	14909	M027-08	05/08	
16835	Passage Island Light	RAC INOP	14968	S199-07	52/07	
14760	L'Anse Buoy 1	OFF STA	14964	S195-07	51/07	
13955	Upper Nicolet Range Front Light	DBN DEST	14883	S027-08	11/08	
	Sand Point Midchannel Buoy S		14863	D003-08	03/08	

Position

Name

PLATFORM DISCREPANCIES CORRECTED

Status

LNM St LNM End

BNM Ref.

SECTION III - TEMPORARY CHANGES and TEMPORARY CHANGES CORRECTED

This section contains temporary changes and corrections to Aids to Navigation for this edition. When charted aids are temporarily relocated for dredging, testing, evaluation, or marking an obstruction, a temporary correction shall be listed in Section IV giving the

TEMPORARY CHAN	IGES						
LLNR	Aid Name		Status	Chart No.	BNM Ref.	LNM St	LNM End
15525	Bayfield Municipal Break	kwater Light	DISCONTINUED	14973	S158-07	44/07	
20680	Menomonee River Obstr Buoy	ruction Lighted	ESTABLISHED	14924		31/06	
EMPORARY CHAN	IGES CORRECTED						
LLNR	Aid Name		Status	Chart No.	BNM Ref.	LNM St	LNM End
9575	St Clair Flats Light 2		LWP	14853		21/07	29/08
LATFORM TEMPO	RARY CHANGES						
Name		Status		Position	BNM Ref.	LNM St	LNM En
one							
LATFORM TEMPO	RARY CHANGES CORRECTE	ED.					
Name		Status		Position	BNM Ref.	LNM St	LNM En
None							
his section contains ne mariner to decide thart Chart	ection contains corrections to s corrective actions affecting e w hich chart(s) are to be co Edition L	federally and pr chart(s). Corre	ctions appear numerica	to Navigation, as well ally by chart number, as individual elements o Source of	ind pertain to that f a typical chart o Curre	t chart only.	
This section contains the mariner to decide thart Chart Illumber Edition 1 2327 91st 1 2327 91st 1 2327 91st 1 2327 Plant Title: NY-NJ-NI Main Panel 22 1	ection contains corrections to s corrective actions affecting e w hich chart(s) are to be con Edition L n Date to Ed. 19-APR-97 L EW YORK HARBOR - RARITA 45 NEW YORK HARBOR IATIONAL DOCK CHANNEL B reen can	rederally and property chart(s). Corrected. The followast Local Notice of Mariners and Last LNM: 26/97	ivately maintained Aids ctions appear numerica ow ing example explains Horizontal	to Navigation, as wellally by chart number, as individual elements o Source of Correction	ind pertain to that f a typical chart o Curre	t chart only.correction correction ent Local to Mariners 27/97	
This section contains the mariner to decide thart Chart Illumber Edition 2327 91st 2327 91st Chart Title: NY-NJ-NI Main Panel 22 Temp) ADD NOTICE COrrective Action Temp) indicates tha	ection contains corrections to some corrective actions affecting which chart(s) are to be concerned by which chart corrections affecting some concerned by which chart corrections are concerned by which chart corrections affecting some concerned by the chart correction action is some concerned by the chart correction acti	rederally and proceed to the following chart (s). Corrected. The following control of the follow	ivately maintained Aids ctions appear numerica by ing example explains Horizontal Datum Referen I NAD 83	to Navigation, as well ally by chart number, as individual elements of Source of Ce Correction	Ind pertain to that If a typical chart of Curre Notice to	t chart only. correction int Local to Mariners 27/97 4-02-48.001	W ue.
his section contains the mariner to decide thart Chart Iumber Edition I	ection contains corrections to corrective actions affecting which chart(s) are to be concluded by which chart correction action is corrective and the light from the chart correction action is corrective and the light from the chart correction action is corrective and the light from the chart correction action is correction action in the chart correction action is correction action in the chart correction action is correction action in the chart correction action is correction.	rederally and proceedings of chart (s). Corrected. The followast Local Notice of Mariners Last LNM: 26/97 N RIVER UOY 3 Stemporary in nanseaward. The	ivately maintained Aids ctions appear numerica by ing example explains Horizontal Datum Referen I NAD 83	to Navigation, as well ally by chart number, as individual elements of Source of Ce Correction	Ind pertain to that If a typical chart of Curre Notice to	t chart only. correction int Local to Mariners 27/97 4-02-48.001	W ue.
his section contains the mariner to decide hart Chart Umber Edition I 2327 91st I hart Title: NY-NJ-NI Main Panel 22 Temp) ADD North I Government General General Indicates the earings of light section I General Indicates the earings of light section I General Indicates the earings of light section I General Indicates I have the earings of light section I General Indicates I have the earings of light section I General Indicates I have the earings of light section I General Indicates I have the earings of light section I General Indicates I have the earings of light section I General Indicates I have the earlings of light section I ha	ection contains corrections to corrective actions affecting which chart(s) are to be concluded by which chart shall be concluded by the chart correction action is stored are toward the light from the chart correction; be concluded by the chart correction action is stored are toward the light from the chart correction; are toward the chart correction.	rederally and property control of the control of th	ivately maintained Aids ctions appear numerica by ing example explains Horizontal Datum Referen INAD 83 ature. Courses and bea nominal range of lights B NAD 83 arbor;Rocky River	to Navigation, as well ally by chart number, as individual elements of Source of Ce Correction	Ind pertain to that If a typical chart of Curre Notice to	t chart only. correction int Local to Mariners 27/97 4-02-48.001	W ue. ise noted.
his section contains the mariner to decide thart Chart tumber Editio 1	ection contains corrections to corrective actions affecting which chart(s) are to be concluded by which chart so be concluded by the chart corrective action action is tors are toward the light from the concluded by the chart correction; to Vermilion; Beaver Crest 11147 MOSS POINT TO VERMING A correction action is concluded by the chart correction action is concluded by the concluded	rederally and property control of the control of th	ivately maintained Aids ctions appear numerica by ing example explains Horizontal Datum Referen INAD 83 ature. Courses and bea nominal range of lights B NAD 83 arbor;Rocky River	to Navigation, as well ally by chart number, as individual elements of Source of Cerrection CGD01 at 40- arings are given in degits expressed in naution	and pertain to that f a typical chart of Curre Notice to	t chart only. correction ent Local to Mariners	W .ue. ise noted. 12/08
nis section contains e mariner to decide hart Chart umber Editio l 2327 91st I hart Title: NY-NJ-NI Main Panel 22 femp) ADD N Gi Corrective Action femp) indicates tha earings of light sec	ection contains corrections to corrective actions affecting which chart(s) are to be concluded by which chart shall be concluded by the chart correction action is stored are toward the light from the chart correction; be concluded by the chart correction action is stored are toward the light from the chart correction; are toward the chart correction.	rederally and property control of the control of th	ivately maintained Aids ctions appear numerica by ing example explains Horizontal Datum Referen INAD 83 ature. Courses and bea nominal range of lights B NAD 83 arbor;Rocky River	to Navigation, as well ally by chart number, as individual elements of Source of Ce Correction CGD01 at 40- arings are given in degits expressed in nautice CGD09 at 41-44-5	and pertain to that f a typical chart of Curre Notice to	t chart only. correction ent Local to Mariners	W ue. ise noted.
nis section contains e mariner to decide nart Chart Limber Editio 1	ection contains corrections to corrective actions affecting which chart(s) are to be concluded by which chart correction action is corrective and the light from the chart correction action is corrective and the light from the chart correction; but to vermilion; beaver Crest 11147 MOSS POINT TO VERLAGE Erie Research Light Yellow (LLNR 4025)	efederally and property contents of the followast Local Notice of Mariners Last LNM: 26/97 N RIVER UOY 3 Stemporary in nanseaward. The Last LNM: 07/0ek;Vermilion Harmilion. Page/	ivately maintained Aids ctions appear numerica by ing example explains Horizontal Datum Referen INAD 83 ature. Courses and bea nominal range of lights B NAD 83 arbor;Rocky River	to Navigation, as well ally by chart number, as individual elements of Source of Cerrection CGD01 at 40- arings are given in degits expressed in naution	and pertain to that f a typical chart of Curre Notice f	t chart only. correction ent Local to Mariners . 27/97 4-02-48.001 from 000 tru less otherw	W .ue. ise noted. 12/08

Chart	6th E	0.22000	Last LNM: 25/07	NAD 83 ntor Harbor;Chagrin Rive	Ar.	12/08
Criart		572 GENEVA TO LORAI		nor narbor, chagilii Kive	3 1	
	ADD	Lake Erie Research Lig Yellow (LLNR 4025)	· ·		CGD09 at 41-44-53.400N	081-41-54.000W
	ADD	FI Y 4s Lake Erie Research Lig Yellow (LLNR 4025.1			CGD09 at 41-44-53.400N	081-41-54.600W
	ADD	FI Y 4s Lake Erie Research Lig Yellow (LLNR 4025.2			CGD09 at 41-44-53.400N	081-41-53.400W
	ADD	FI Y 4s Lake Erie Research Lig Yellow (LLNR 4036)	hted Buoy D		CGD09 at 41-48-49.800N	081-41-55.200W
	ADD	FI Y 4s Lake Erie Research Lig Yellow (LLNR 4036.1			CGD09 at 41-48-49.800N	081-41-55.800W
	ADD	FI Y 4s Lake Erie Research Lig Yellow (LLNR 4036.2 FI Y 4s			CGD09 at 41-48-49.800N	081-41-54.600W
842 Chart	15th Title: SMALL-CF		Last LNM: 07/08	NAD 83 including the Islands (be	ook of 35 charts)	12/08
		4 HARBOR PLANS 33 L			our or ou original,	
	SUBSTITUTE	Sounding in Feet; 2 (N	IOS NW-15392)		NOS 41-33-42.700N	082-48-56.800W
	SUBSTITUTE	Sounding in Feet; 3 (N	IOS NW-15392)		NOS 41-33-41.500N	082-48-58.900W
	SUBSTITUTE	Sounding in Feet; 3 (N	IOS NW-15392)		NOS 41-33-42.030N	082-48-58.010W
	CHANGE	DEPTH LEGEND-WEST 15392)	HARBOR, OH; 5 FEET O	CT 2007 (NOS NW-	NOS 41-33-39.300N	082-49-01.700W
	CHANGE	DEPTH LEGEND-WEST 15392)	HARBOR, OH; 6 FEET O	CT 2007 (NOS NW-	NOS 41-34-01.200N	082-48-44.300W
	CHANGE	Depth Legend - Cataw 11565)	ba Harbor to:; 6 1/2 FT	OCT 2004 (NOS NW-	NOS 41-33-03.400N	082-49-49.000W
	CHANGE	Depth Legend - West H	Harbor, OH; 4 FT OCT 20	007 (NOS NW-15392)	NOS 41-33-45.200N	082-49-23.500W
	CHANGE CHANGE		Harbor, OH; 4 FT OCT 20 Harbor, OH; 5 FT OCT 20			
			Harbor, OH; 5 FT OCT 20		41-33-45.200N NOS	082-49-33.100W
	CHANGE	Depth Legend - West H	Harbor, OH; 5 FT OCT 20		41-33-45.200N NOS 41-33-23.000N NOS 41-33-43.400N NOS 41-33-40.900N	082-49-33.100W 082-48-55.700W
	CHANGE ADD	Depth Legend - West H Sounding in Feet; 2 (N	Harbor, OH; 5 FT OCT 20 NOS NW-15392) NOS NW-15392)		41-33-45.200N NOS 41-33-23.000N NOS 41-33-43.400N NOS 41-33-40.900N NOS 41-33-57.600N	082-49-33.100W 082-48-55.700W 082-48-59.900W
	CHANGE ADD ADD	Depth Legend - West H Sounding in Feet; 2 (N Sounding in Feet; 4 (N	Harbor, OH; 5 FT OCT 20 NOS NW-15392) NOS NW-15392) NOS NW-15392)		41-33-45.200N NOS 41-33-23.000N NOS 41-33-43.400N NOS 41-33-40.900N NOS	082-49-33.100W 082-48-55.700W 082-48-59.900W 082-48-49.600W
	CHANGE ADD ADD ADD ADD	Depth Legend - West H Sounding in Feet; 2 (N Sounding in Feet; 4 (N Sounding in Feet; 5 (N	Harbor, OH; 5 FT OCT 20 NOS NW-15392) NOS NW-15392) NOS NW-15392) NOS NW-15392)	007 (NOS NW-15392)	41-33-45.200N NOS 41-33-23.000N NOS 41-33-43.400N NOS 41-33-40.900N NOS 41-33-57.600N NOS	082-49-33.100W 082-48-55.700W 082-48-59.900W 082-48-49.600W
	CHANGE ADD ADD ADD ADD	Depth Legend - West H Sounding in Feet; 2 (N Sounding in Feet; 4 (N Sounding in Feet; 5 (N Sounding in Feet; 5 (N Sounding in Feet; 5 (N Sounding in Feet; 5 (N	Harbor, OH; 5 FT OCT 20 NOS NW-15392) NOS NW-15392) NOS NW-15392) NOS NW-15392)	007 (NOS NW-15392)	41-33-45.200N NOS 41-33-23.000N NOS 41-33-43.400N NOS 41-33-40.900N NOS 41-33-57.600N NOS	082-49-33.100W 082-48-55.700W 082-48-59.900W 082-48-49.600W 082-48-48.600W
	CHANGE ADD ADD ADD ADD Extension 119	Depth Legend - West H Sounding in Feet; 2 (N Sounding in Feet; 4 (N Sounding in Feet; 5 (N Sounding in Feet; 5 (N HARBOR PLANS 33 F Depth Legend - West H	Harbor, OH; 5 FT OCT 20 NOS NW-15392) NOS NW-15392) NOS NW-15392) NOS NW-15392)	007 (NOS NW-15392) I. Page/Side: 33 007 (NOS NW-15392)	41-33-45.200N NOS 41-33-23.000N NOS 41-33-43.400N NOS 41-33-40.900N NOS 41-33-57.600N NOS 41-33-58.400N	082-49-33.100W 082-48-55.700W 082-48-59.900W 082-48-49.600W 082-48-48.600W
	CHANGE ADD ADD ADD Extension 119 CHANGE CHANGE	Depth Legend - West H Sounding in Feet; 2 (N Sounding in Feet; 4 (N Sounding in Feet; 5 (N Sounding in Feet; 5 (N DEPTH LEGEND - West H	Harbor, OH; 5 FT OCT 20 NOS NW-15392) NOS NW-15392) NOS NW-15392) NOS NW-15392) RIGHT SIDE EXTENTION Harbor, OH; 5 FT OCT 20	007 (NOS NW-15392) I. Page/Side: 33 007 (NOS NW-15392)	41-33-45.200N NOS 41-33-23.000N NOS 41-33-43.400N NOS 41-33-40.900N NOS 41-33-57.600N NOS 41-33-58.400N NOS 41-33-04.100N NOS	082-49-33.100W 082-48-55.700W 082-48-59.900W 082-48-49.600W 082-48-48.600W
1867 Chart	CHANGE ADD ADD ADD Extension 119 CHANGE CHANGE CHANGE 26th Title: Saginaw F	Depth Legend - West H Sounding in Feet; 2 (N Sounding in Feet; 4 (N Sounding in Feet; 5 (N Sounding in Feet; 5 (N DEPTH LEGEND - West H	Harbor, OH; 5 FT OCT 20 NOS NW-15392) NOS NW-15392) NOS NW-15392) NOS NW-15392) RIGHT SIDE EXTENTION Harbor, OH; 5 FT OCT 20 Last LNM: 36/07	I. Page/Side: 33 007 (NOS NW-15392) 007 (NOS NW-15392) 007 (NOS NW-15392) NAD 83	41-33-45.200N NOS 41-33-23.000N NOS 41-33-43.400N NOS 41-33-40.900N NOS 41-33-57.600N NOS 41-33-58.400N NOS 41-33-04.100N NOS	082-49-23.500W 082-49-33.100W 082-48-55.700W 082-48-59.900W 082-48-49.600W 082-48-48.600W 082-49-38.300W

14901 15th Ed. 01-AUG-06 Last LNM: 04/08 NAD 83 12/08

ChartTitle: Lake Michigan (Mercator Projection)

Main Panel 1361 LAKE MICHIGAN. Page/Side: N/A

CGD09

ADD South Manitou Island Lighthouse at 45-00-44.880N 086-05-41.280W

White (LLNR 18357)

F W 12 Stat Mi

14902 29th Ed. 01-JAN-05 Last LNM: 04/08 NAD 83 12/08

ChartTitle: North end of Lake Michigan, including Green Bay

Main Panel 1362 NORTH END OF LAKE MICHIGAN INCLUDING GREEN BAY. Page/Side: N/A

CGD09

ADD South Manitou Island Lighthouse at 45-00-44.880N 086-05-41.280W

White (LLNR 18357)

F W 12 Stat Mi

14912 17th Ed. 01-MAY-03 Last LNM: 26/07 NAD 83 12/08

ChartTitle: Platte Bay to Leland; Leland; South Manitou Harbor

Inset 1396 SOUTH MANITOU HARBOR MICHIGAN. Page/Side: N/A

CGD09

ADD South Manitou Island Lighthouse at 45-00-44.880N 086-05-41.280W

White (LLNR 18357)

F W 12 Stat Mi

SECTION V - ADVANCE NOTICES

This section contains advance notice of approved projects, changes to aids to navigation, or upcoming temporary changes such as dredging, etc.

Mariners are advised to use caution while transiting these areas.

SUMMARY OF ADVANCED APPROVED PROJECTS

Approved Project(s)

Project Date Ref. LNM

None

Advance Notice(s)

LAKE ERIE - Cleveland Harbor - Chart 14839

Cleveland Harbor Main Light (LLNR 4160) Change the flash characteristic to FI R 6s and the range to 12 St M. Install a user activated fog signal system; to operate the fog signal by keying the microphone on VHF Marine radio channel 79 five times.

LNM: 43/07

LAKE ERIE - Port Clinton - Chart 14846

Port Clinton Light "2" (LLNR 5865) increase the range of the light from 6 miles to 9 miles.

LNM: 51/07

LAKE ERIE - Sandusky River - Chart 14842

Discontinue the following aids to navigation due to shoaling, low lake levels and inaccessability by servicing personal:

Muddy Creek Bay Buoy 2 (LLNR 5057)

Muddy Creek Bay Buoy 6 (LLNR 5065)

Sandusky River Buoy 14 (LLNR 5070)

Muddy Creek Bay Buoy 9 (LLNR 5056)

Sandusky River Buoy 46 (LLNR 5095)

Sandusky River Buoy 42 (LLNR 5102)

Sandusky River Buoy 44 (LLNR 5110)

Sandusky River Buoy 40 (LLNR 5111)

Sandusky River Buoy 37 (LLNR 5115)

Sandusky River Buoy 38 (LLNR 5120)

Sandusky River Buoy 32 (LLNR 5129)

Sandusky River Buoy 36 (LLNR 5133)

Sandusky River Buoy 34 (LLNR 5137)

Sandusky River Buoy 30 (LLNR 5141)

Sandusky River Buoy 28 (LLNR 5145)

Sandusky River Buoy 26 (LLNR 5149)

Sandusky River Buoy 24 (LLNR 5153)

Sandusky River Buoy 23 (LLNR 5157)

Sandusky River Buoy 18 (LLNR 5161) Sandusky River Buoy 22 (LLNR 5163) Sandusky River Buoy 21 (LLNR 5166) Muddy Creek Bay Buoy 1 (LLNR 5169)

LNM: 12/08

DETROIT RIVER - Livingston Channel - Chart 14848

Propose to change the lantern from the existing incandescent lamps to an energy efficient LED, this will reduce the range of the light from 4 to 3 miles:

Livingston Channel Light "21" (LLNR 7260)

Livingston Channel Light "23" (LLNR 7250)

Livingston Channel Light "24" (LLNR 7255)

Livingston Channel Light "25" (LLNR 7240)

Livingston Channel Light "26" (LLNR 7245)

LNM: 09/07

ST CLAIR RIVER - Chart 14852

Propose to change the lantern from the existing incandescent lamps to an energy efficient LED, this will reduce the range of the light from 4 to 3 miles:

Fawn Island Upper End LB "42" (LLNR 9825)

LNM: 09/07

LAKE ST. CLAIR - Charts 14850, 14853

Lake St. Clair Light (LLNR 8525) discontinue the higher intensity beam upstream. Increase the range of the light from 6 to 9 miles.

LNM: 23/07

LAKE HURON - Chart 14860

Change the commissioning date of the following buoy to 28 April:

NOAA Lighted Weather Buoy -45008- (LLNR 10010)

LNM: 12/08

LAKE HURON - Harrisville to Forty Mile Point - Chart 14864

Sturgeon Point Light (LLNR 11345) change to private aid. Characteristics and range will remain the same.

LNM: 01/07

STRAITS OF MACKINAC - Cheboygan River - Chart 14881

Propose to change the lantern from the existing incandescent lamps to an energy efficient LED, this will reduce the range of the light from 4 to 3 miles:

Cheboygan Entrance Light Buoy 2 (LLNR 11780)

LNM: 27/07

LAKE MICHIGAN - Chart 14904

Change the commissioning date of the following buoys to 21 April:

NOAA Lighted Weather Buoy "45007" (LLNR 20595)

NOAA Lighted Weather Buoy "45002" (LLNR 18310)

LNM: 12/08

LAKE MICHIGAN - Grand Traverse Bay - Chart 14913

Change the commissioning date of the following buoy to 21 April:

South Point Lighted Bell Buoy "2" (LLNR 18100)

LNM: 12/08

LAKE MICHIGAN - Lake Charlevoix - Chart 14942

Charlevoix South Pier head Light (LLNR 17925) change the color of the day mark from white to red.

LNM: 51/07

LAKE MICHIGAN - Menominee and Marinette Harbors - Chart 14917

Establish the following buoys to mark the Regulated Navigation Area (RNA) on the Menominee River. The buoys will be maintained from 14 April to 07 November.

Menominee River RNA Buoy "A" (LLNR 21943) Yellow Nun with a black letter "A" in position 45-05-59.5N and 087-36-48.6W Menominee River RNA Buoy "B" (LLNR 21956) Yellow Can with a black letter "B" in position 45-06-03.5N and 087-37-14.5W

LNM: 05/07

LAKE MICHIGAN - Milwaukee Harbor - Chart 14924

Texas Rock Buoy "2" (LLNR 20735) change the buoy from a Red Nun "2" to a white and orange regulatory marker with black letters "DANGER ROCKS".

LNM: 31/07

LAKE MICHIGAN - Platte Bay to Leland - Chart 14912

Change the commissioning date of the following buoys to 21 April:

Pyramid Point Shoal Lighted Buoy "5" (LLNR 18350)

South Manitou Island Lighted Gong Buoy "8" (LLNR 18360)

Sleeping Bear Lighted Bell Buoy "7" (LLNR 18365)

LNM: 12/08

LAKE MICHIGAN - Port Washington to Waukegan - Chart 14904

Change the commissioning date of the following buoy to 21 April:

Milwaukee South Point Lighted Bell Buoy "1" (LLNR 20630)

LNM: 12/08

LAKE MICHIGAN - Sheboygan - Chart 14922

Sheboygan Breakwater Light (LLNR 20820) Install a user activated fog signal system; to operate the fog signal by keying the microphone on VHF Marine radio channel 79 five times.

LNM: 12/08

LAKE MICHIGAN - St. Joseph - Chart 14930

St. Joseph North Pier Inner Light (LLNR 19520) move light to rail and reduce range to 9 miles.

LNM: 49/06

LAKE MICHIGAN - St. Joseph and Benton Harbor - Chart 14930

Discontinue the following aids to navigation due to shoaling and low water levels:

- St. Joseph River Buoy -4- (LLNR 19531)
- St. Joseph River Buoy -4A- (LLNR 19531.1)
- St. Joseph River Buoy -6- (LLNR 19532)
- St. Joseph River Buoy -8- (LLNR 19533)
- St. Joseph River Buoy -10- (LLNR 19533.1)
- St. Joseph River Buoy -12- (LLNR 19533.2)
- St. Joseph River Buoy -13- (LLNR 19533.3)

LNM: 12/08

LAKE MICHIGAN - Upper Green bay - Chart 14909

Little Gull Island LBB2 (LLNR 21445) Move Aid Position further off of the shoal.

LNM: 51/07

LAKE MICHIGAN- Chicago Lake Front - Chart 14927

Change the commissioning date of the following buoys to 21 April:

Indiana Shoal Lighted Gong Buoy "2" (LLNR 19625)

Chicago Lake Front Northeast Shoal Lighted Buoy "2" (LLNR 19790)

LNM: 12/08

LAKE MICHIGAN - Algoma to Sheboygan - Chart 14903

Two Rivers North Pierhead light (LLNR 20925) change the characteristic from F R to FI R 2.5s. Increase the range of the light from 9 to 12 miles. Install a user activated fog signal; to operate the fog signal by keying the microphone on VHF Marine radio channel 79 five times.

LNM: 27/07

LAKE MICHIGAN - Waugoshance Point to Seul Point - Chart 14911

Seul Choix Point Light (LLNR 21490) reduce the range of the light from 26 miles to 15 miles.

LNM: 27/07

LAKE MICHIGAN - Waukegan to South Haven - Chart 14905

Michigan City East Pierhead Light (LLNR 19545) change the operation of the Fog Signal to a user activated system. Install a user activated fog signal system; to operate the fog signal by keying the microphone on VHF Marine radio channel 79 five times.

LNM: 49/06

LAKE MICHIGAN - Manitowoc Harbor - Chart 14922

Manitowoc Breakwall Light (LLNR 20860) Reduce the range of the light from 15 to 12 miles. Install a user activated fog signal system; to operate the fog signal by keying the microphone on VHF Marine radio channel 79 five times.

LNM: 01/07

LAKE MICHIGAN - Milwaukee Harbor - Chart 14924

Milwaukee Breakwater Light (LLNR 20635) Discontinue the floodlights. Install a user activated fog signal system; to operate the fog signal by keying the microphone on VHF Marine radio channel 79 five times.

LNM: 01/07

LAKE MICHIGAN - Port Washington to Waukegan - Chart 14904

Waukegan Harbor Light (LLNR 20315) Reduce the range of the light from 14 to 12 miles. Install a user activated fog signal system; to operate the fog signal by keying the microphone on VHF Marine radio channel 79 five times.

LNM: 01/07

LAKE MICHIGAN - Indiana Harbor - Charts 14926, and 14929

Indiana Harbor East Breakwater Light (LLNR 19675) reduce the range of the light from 20 to 12 miles. Install a user activated fog signal system; to operate the fog signal by keying the microphone on VHF Marine radio channel 79 five times.

LNM: 11/07

ST MARYS RIVER - Munuscong Lake to Sault Ste. Marie - Chart 14883

Propose to change the lantern from the existing incandescent lamps to an energy efficient LED, this will reduce the range of the light from 4 to 3 miles:

Munuscong Channel (Upbound) Lighted Buoy 5 (LLNR 13050)

Sailors Encampment Channel Lighted Buoy 17 (LLNR 13115)

Middle Neebish Channel Lighted Buoy 43 (LLNR 13285)

Middle Neebish Channel Lighted Buoy 59 (LLNR 13345)

Lake Nicolet Lighted Buoy 63 (LLNR 13380)

West Neebish Channel (Downbound) Lighted Buoy 53 (LLNR 13485)

Bayfield Channel Lighted Buoy 107 (LLNR 14170)

Munuscong Channel Lighted Buoy 29 (LLNR 13217)

Lake Nicolet Lighted Buoy 66 (LLNR 13395)

Pipe Island Lighted Buoy 12 (LLNR 12880)

Round Island Lighted Buoy 25 (LLNR 13740)

Cedar Point Lighted Bouy 23 (LLNR 14410)

Big Point Lighted Buoy 7 (LLNR 14265)

Lake Nicolet Lighted Buoy 83 (LLNR 13970)

West Neebish Channel (Downbound) Lighted Buoy 46 (LLNR 13525)

West Neebish Channel (Downbound) Light 16 (LLNR 13680)

Lake Nicolet Light 80 (LLNR 13465)

West Neebish Channel (Downbound) Light 28 (LLNR 13615)

West Neebish Channel (Downbound) Light 27 (LLNR 13620)

West Neebish Channel (Downbound) Light 14 (LLNR 13690)

LNM: 43/07

LAKE SUPERIOR - Beaver Bay to Pigeon Point - Chart 14967

Grand Portage Bay Entrance Light (LLNR 16635) increase the range of the light from 7 to 9 miles.

LNM: 23/07

LAKE SUPERIOR - Apostle Islands - Chart 14973

Michigan Island Light (LLNR 15275) increase the range of the light from 11 to 12 miles

LNM: 41/07

SECTION VI - PROPOSED CHANGES

Periodically, the Coast Guard evaluates its system of aids to navigation to determine whether the conditions for which the aids to navigation were established have changed. When changes occur, the feasibility of improving, relocating, replacing, or discontinuing aids are considered. This section contains notice(s) of non-approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to the District office unless otherwise noted (see banner page for address).

PROPOSED WATERWAY PROJECTS OPEN FOR PUBLIC COMMENT

Proposed Project(s) <u>Closing</u> <u>Docket No.</u> <u>Ref. LNM</u>

None

Proposed Change Notice(s)

LAKE ERIE - Black Rock Canal / Niagara River - Chart 14832, 14833

Propose to change the lantern from its current incandescent lamps to an energy efficient LED which will reduce the range of the lantern form 4 to 3 miles.

Black Rock Canal LB "1" (LLNR 2785)

Black Rock Canal LB "3" (LLNR 2795)

Black Rock Canal LB "9" (LLNR 2825)

Black Rock Canal LB "10" (LLNR 2830)

Strawberry Island LB "7" (LLNR 3025)

Tonawanda Channel LB "28" (LLNR 3155)

LNM: 11/08

LAKE ST. CLAIR - Charts 14850 and 14843

Propose to change the lantern from its current incandescent lamps to an energy efficient LED which will reduce the range of the lantern form 4 to 3 miles.

Clinton River Entrance LB "CR" (LLNR 8975)

Clinton River Entrance LB "1" (LLNR 8980)

Clinton River Entrance LB "2" (LLNR 8985)

North Channel Entrance LB "2NC" (LLNR 9305)

Middle Channel Entrance LB "1MC" (LLNR 9435)

Point Huron LB "1PH" (LLNR 8925)

St. Clair Flats Old Channel LB "20C" (LLNR 9530)

Gaukler Shoal Junction LB (LLNR 8855)

Gahkler Shoal LB "1" (LLNR 8850)

LNM: 10/08

LAKE HURON - Lexington Harbor - Chart 14862

Discontinue the following aids to navigation due to shoaling and low water levels:

LLNR Aid Name

10105 Lexington Harbor Buoy -5-10110 Lexington Harbor Buoy -6-

LNM: 03/08

LAKE HURON - Harrisville to Forty Mile Point - Chart 14864

Presque Isle Light (LLNR 11550) Change the aid from a federal aid to navigation to a private aid to navigation. The characteristic will remain the same

LNM: 20/07

STRAITS OF MACKINAW - Michigan Inland Route - Chart 14886

Propose to change the lantern from the existing incandescent lamps to an energy efficient LED, this will reduce the range of the light from 4 to 3 miles on the following aids:

Pickerel Channel Entrance Light "2" (LLNR 12135)

Crooked Lake Light "77" (LLNR 12120)

LNM: 12/08

ST MARYS RIVER - De Tour to Munuscong Lake - Chart 14882

Propose to change the lantern from the existing incandescent lamps to an energy efficient LED, this will reduce the range of the light from 4 to 3 miles.::

Lime Island Lighted Buoy "14A" (LLNR 12910)

Lime Island Lighted Buoy "16" (LLNR 12935)

Point Aux Frenes Lighted Buoy "22" (LLNR 12980)

Point Aux Frenes Lighted Buoy "24" (LLNR 12990)

Hay Point Reef Lighted Buoy "18A" (LLNR 12955)

LNM: 05/08

LAKE SUPERIOR - Apostle Islands - Chart 14973

Outer Island Light (LLNR 15255) Propose to change the lantern from the existing incandescent lamps to an energy efficient LED this will reduce the range of the light from 15 to 12 miles.

Devils Island Light (LLNR 15565) Propose to change the lantern from the existing incandescent lamps to an energy efficient LED this will reduce the range of the light from 15 to 12 miles.

LNM: 07/08

LAKE SUPERIOR - Big Bay Point to Redridge - Chart 14964

Huron Island Light (LLNR 14730) Propose to change the lantern from the existing incandescent lamps to an energy efficient LED this will reduce the range of the light from 15 to 12 miles.

Manitou Island Light (LLNR 15170) Propose to change the lantern from the existing incandescent lamps to an energy efficient LED this will reduce the range of the light from 18 to 12 miles.

LNM: 07/08

LAKE SUPERIOR - Duluth Superior Harbor - Chart 14975

Propose to change the lantern from the existing incandescent lamps to an energy efficient LED, this will reduce the range of the light from 4 to 3 miles:

Superior Front Channel Lighted Buoy "2" (LLNR 15705)

Superior Front Channel Lighted Buoy "14" (LLNR 15805)

Superior Front Channel Lighted Buoy "18" (LLNR 15820)

St. Louis Bay South Channel Western Section Lighted Buoy "13" (LLNR 16165)

LNM: 05/08

LAKE SUPERIOR - Isle Royale - Chart 14976

Passage Island Light (LLNR 16835) Propose to change the lantern from the existing incandescent lamps to an energy efficient LED this will reduce the range of the light from 17 to 12 miles.

Rock of Ages Light (LLNR 16655) Propose to change the lantern from the existing incandescent lamps to an energy efficient LED this will reduce the range from 17 to 12 miles.

LNM: 07/08

For any comments or questions on these proposed changes please contact

Doug Sharp of the Ninth District Aids to Navigation office at (216) 902-6070.

SECTION VII - GENERAL

This section contains information of general concern to the Mariners. Mariners are advised to use caution while transiting these areas.

Waterways Analysis and Management System Study - 2008

The Coast Guard is conducting a Waterways Analysis and Management System Study on the following waterways during 2008. The study focuses on the area's aid to navigation system, waterborne commerce, marine casualty information, emergency response plans, routine and emergency communication capabilities, and future development projects. Any company or individual wishing to provide comments or participate in a user survey should contact the office listed below each study area.

Lake Erie - Conneaut Harbor - Chart 14824 Contact: Commanding Officer USCG Sector Buffalo 1 Fuhrmann Blvd. Buffalo, N.Y. 14203 (716) 813-9524

Lake Erie - Erie Islands - Chart 14844 Contact: Commanding Officer USCG Sector Detroit 110 Mt. Elliot Ave. Detroit, Mi 48207 (313) 568-9523

Lake Huron - Saginaw Bay - Chart 14863, 14867

Page 14 of 17 Coast Guard District 9

LNM: 12/08 18 March 2008

Waterways Analysis and Management System Study - 2008

Contact: Commanding Officer USCGC Hollyhock (WLB 214) 2700 Omar Street Port Huron, MI 48060 (810) 982-2684

Lake Superior - Whitefish Bay - Chart 14884

Contact: Commanding Officer USCGC Buckthorn (WLI 642) 337 Water Street

Sault Ste. Marie, Mi. 48060

(906) 635-3288

Lake Michigan - Northern Green Bay, Little Bay De Noc - Chart 14908, 14909, 14915

Contact: Commanding Officer USCGC Mobile Bay (WTGB 103) P.O. Box 287 Sturgeon Bay, Wi. 54235

Lake Michigan - Manitowoc and Sheboygan - Chart 14922

Contact: Commanding Officer USCG Sector Lake Michigan 2420 South Lincoln Memorial Drive Milwaukee, Wi. 53207 (414) 741-7188

Lake Huron - Tawas Bay - chart 14863

Contact: Commander (Aid to Navigation Officer)

U.S. Coast Guard Sector Detroit

110 Mt. Elliot Ave.

Detroit, Michigan 48207-4380

(313) 568-9523

Lake Huron/Lake Michigan - Mackinaw Straits - chart 14881

Contact: Commanding Officer USCGC Mackinaw (WLBB 30) 632 Coast Guard Drive

Cheboygan, Michigan 49783-9501

(231) 596-2030

LNM: 07/08

Coast Pilot 6 - NEW EDITION

PUBLICATION-National Ocean Service-U.S. Coast Pilot 6, Great Lakes and their connecting waterways, 2008, 38th Edition, is ready for issue and may be obtained from

Federal Aviation Administration National Aeronautical Charting Office Distribution Division, AVN-530 10201 Good Luck Road Glenn Dale, MD 20769-9700 and authorized sales agents of the National Ocean Service. Price \$28.00. The 2008 Edition cancels the preceding 2007 Edition. All corrections to the previous edition issued in Notices to Mariners are incorporated in this edition.

Mariners are encouraged to use the convenient "RECORD OF CHANGES" form on Page V of this book. All Coast Pilot changes published in the U.S. Coast Guard Local Notice to Mariners, National Geospatial-Intelligence Agency Notice to Mariners, and on the internet at http://nauticalcharts.noaa.gov/nsd/cpdownload.htm are serially numbered (i.e., Change No. 1, Change No. 2, etc.) to assist you in tracking the changes. (NOS/08)

LNM: 10/08

***** REVISED LNM 12/08 *****

LAKE ERIE - OH - Port Clinton Harbor, Scheduled Bridge Rehabilitation, Chart 14842, Page 32

The Monroe Street (OH-163) Bridge at Mile 0.4 over the Portage River will be rehabilitated from 0800 on December 10, 2007 though 1800 on March 28, 2008. During this period, the bridge will not open for masted navigation. [47/07] [12/08]

LNM: 12/08

LAKE ERIE- OH - Toledo Harbor, Continuation of Bridge Rehabilitation, Chart 14847

Rehabilitation of the Martin Luther King Bridge at Mile 4.30 over Maumee River will continue through 1700 on May 31, 2008. A work barge (40- X 16-) may be in the vicinity of the navigation channel from 0700 through 1700, Monday through Thursday. During working hours, the barge will move for transiting marine traffic upon request to the bridge tender. When not in use, the barge will be moored under the south bridge span, clear of the navigation channel and lighted in accordance with navigation standards. Mariners are urged to pass with caution.

LNM: 12/08

LAKE ERIE - Lorain Harbor - Black River - Chart 14841

BayShore Contractors, LLC will be conducting maintenance dredging in the Lorain Harbor and the Black River in Lorain, OH. Operations will commence on March 15, 2008 thru April 14, 2008 the hours of operation are 24 hours a day / 7 days a week. The BUXTON II may be contacted VHF - FM channel 73 and 16. Mariners are requested to pay special attention to the buoys, and required day and night signs on dredge. For further information contact Berry King at (616) 836-0429.

LNM: 11/08

DETROIT RIVER - Entrance to Pte. Mouille - Chart 14848

The King Company INC. will be conducting maintenance dredging in the Detroit River and Entrance to Pte. Mouille, MI. Operations will commence on June 1, 2008 thru August 30, 2008 The hours of operation are 24 hours a day / 7 days a week. The BUXTON may be contacted VHF - FM channel 73 and 16. Mariners are requested to pay special attention to the buoys, and required day and night signs on dredge. For further information contact Mike Petrus at (616) 399-1784.

LNM: 10/08

LAKE MICHIGAN - Manitowoc, WI - Barge Loading - Chart 14922

Malcolm Marine will be conducting barge loading in the Manitowoc River (up river of the first railroad bridge.) Operations will commence 18 March 2008 and will be complete 21 March 2008. Hours of operations will be from daylight to dark Tuesday through Friday. The tug MANITOU may be contacted on channels 16 and 13. For further information contact Thomas R. Morrish, President at (231) 627-4333, Ext. 11.

LNM: 12/08

GREAT LAKES - GENERAL - MARINE EVENTS - SAFETY ZONES - SECURITY ZONES

Events listed below are those events that may have accompanying special local regulations. Mariners transiting these areas should contact the U.S. Coast Guard with any questions and are asked to exercise caution when navigating through the area of the event. Summary located in Enclosure (2)

SECTION VIII - LIGHT LIST CORRECTIONS

An Asterisk *, indicates the column in which a correction has been made to new information

(1) No.	(2) Name and Location	(3) Position	(4) Characteristic	(5) Height	(6) Range	(7) Structure	(8) Remarks	
2680	Buffalo Harbor Light	42-52-14.200N 078-54-09.198W	FI G 2.5s	71 22	12	White tower.	HORN: 2 blasts ev 30s (2s bl-2s si-2s bl-24s si). Operates by keying microphone five times on VHF-FM Ch. 79.	12/08
		44.44.04.0001					*	10/00
3870	Fairport Harbor West Breakwater Light	41-46-04.300N 081-16-52.200W	Iso W 6s	56 17	13	Tower.	HORN: 2 blasts ev 30s (2s bl-2s si-2s bl-24s si).	12/08
							*	
4025	Lake Erie Research Lighted Buoy A	41-44-53.400N 081-41-54.000W	FIY 4s			Yellow can.	Secured with two-point mooring. Private aid.	12/08
*	*	*	*	*	*	*	*	
4025.1	Lake Erie Research Lighted Buoy B	41-44-53.400N 081-41-54.600W	FIY4s			Yellow spar.	Buoy marks anchor location. Private aid.	12/08
*	*	*	*	*	*	*	*	
4025.2	Lake Erie Research Lighted Buoy C	41-44-53.400N 081-41-53.400W	FIY 4s			Yellow spar.	Buoy marks anchor location. Private aid.	12/08
*	*	*	*	*	*	*	*	

SECTION VIII - LIGHT LIST CORRECTIONS (Continued)

(1) No.	(2) Name and Location	(3) Position	(4) Characteristic	(5) Height	(6) Range	(7) Structure	(8) Remarks	
4036	Lake Erie Research Lighted Buoy D	41-48-49.800N 081-41-55.200W	FIY 4s			Yellow can.	Secured with two point mooring. Private aid.	12/08
*	*	*	*	*	*	*	*	
4036.1	Lake Erie Research Lighted Buoy E	41-48-49.800N 081-41-55.800W	FIY 4s			Yellow spar.	Bouy marks anchor location. Private aid.	12/08
*	*	*	*	*	*	*	*	
4036.2	Lake Erie Research Lighted Buoy F	41-48-49.800N 081-41-54.600W	FIY 4s			Yellow spar.	Buoy marks anchor location. Private aid.	12/08
*	*	*	*	*	*	*	*	
11495	Thunder Bay Island Light	45-02-14.167N 083-11-39.325W		63 19	17			12/08
14656	Marquette Power And Light Range Front Daybeacon	46-31-56.100N 087-23-36.500W	*			Orange and white diamond.	Private aid.	12/08
			*	*				
14657	Marquette Power And Light Range Rear Daybeacon 100 feet, 250° from front range beacon.	46-31-55.500N 087-23-38.600W				Orange and white diamond.	Private aid.	12/08
			*	*				

ENCLOSURES

(1) Summary of Dredging

SUMMARY OF DREDGIN2.pdf

Construction Operations in Effect

(2) Great Lakes - General - Marine Events

GREAT LAKES.pdf

Summary of Marine Events

(3) LAKE MICHIGAN - Sturgeon Bay and Canal

sturgeon bay wisconsin3.pdf

Proposed Changes to Navigation

(4) ST. LAWRENCE SEAWAY SYSTEM - Seaway Notices

Seaway Notice 1.pdf Seaway Notice 2.pdf Seaway Notice 3.pdf Seaway Notice 4.pdf Seaway Notice 5.pdf

The following are Notices that have been issued by the St Lawrence Seaway Management Corp.

LNM: 11/08

John E. Crowley, JR Rear Admiral, U. S. Coast Guard Commander, Ninth Coast Guard District

SUMMARY OF DREDGING/CONSTRUCTION OPERATIONS IN EFFECT

Oshkosh Harbor, WI

37/07

BRIDGE REPAIRS

The LNM column is where the entry originally appeared and where detailed information may be obtained. The dates listed for completions are tentative.

Location	LNM	Subject	Hours / Days	<u>Until</u>
<u>LAKE ONTARIO</u> Irondequoit Bay, NY	42/07	SEASONAL BRIDGE CLOSURE	24 HRS/ 7 DAYS A WK	01 APR 08
LAKE ERIE				
Ashtabula Harbor, OH	51/07	WINTER BRIDGE OPERATION	VARIOUS	01 APR 08
Ashtabula Harbor, OH	09/08	BRIDGE RESURFACED	0700-1700 / 7 DAYS	31 MAR 08
Toledo Harbor, OH	12/08	CONTINUATION OF BRIDGE REHABILITATION	VARIOUS	31 MAY 08
Port Clinton, OH	47/07, 12/08	SCHEDULED BRIDGE REHABILITATION	VARIOUS	28 MAR 08
DETROIT RIVER				
Trenton Channel, MI	51/07	SCHEDULED BRIDGE MAINTENANCE	0600-1430 /MON-FRI	TBD
Pte Mouille Access Char	nnel 10/08	MAINTENANCE DREDGING	24 HRS A DAY/ 7 DAYS	30 AUG 08
ST CLAIR RIVER				
Port Huron, MI	49/07	BRIDGE WINTER OPERATING SCHEDULE	VARIOUS	31 MAR 08
STRAITS OF MACKIN	IAC			
Cheboygan Harbor, MI	44/07	DAM REHABILITATION	0700-2200/ 7 DAYS	30 OCT 08
Mackinac Island, MI	35/07	HARBOR REPAIRS AND RENOVATIONS	0800-2000/ MON-SAT	15 MAY 08
LAKE MICHIGAN				
Chicago Harbor, IL	37/07	BRIDGE UNABLE TO OPEN	24 HRS A DAY/ 7 DAYS	TBD
Milwaukee Harbor, WI	40/07	WINTER BRIDGE OPERATING SCHEDULE	24 HRS A DAY/ 7 DAYS	12 APR 08
Two Rivers Harbor, WI	40/07	SCHEDULED BRIDGE DEMOLITION & CONSTRUCTION	24 HRS A DAY/ 7 DAYS	30 JUN 08
Milwaukee Harbor, WI	40/07	WINTER BRIDGE OPERATING SCHEDULE	0630-1530/ MON-FRI	01 APR 08
Milwaukee Harbor, WI	52/07	BRIDGE REHABILITATION	VARIOUS	31 MAR 08
Chicago Harbor, IL	43/06, 02/08	BRIDGE REHABILITATION	0700-1500/ MON-FRI	31 MAR 08
Wilmette Harbor, IL	07/08	MAINTENANCE DREDGING	24 HRS A DAY/ 7 DAYS	01 JUN 08
Holland Harbor	07/08	MAINTENANCE DREDGING	24 HRS A DAY/ 7 DAYS	30 MAY 08
Grand Haven Harbor	07/08	MAINTENANCE DREDGING	24 HRS A DAY/ 7 DAYS	30 MAY 08
Milwaukee Harbor, WI	10/08	BRIDGE REHABILITATION	0700-1600/ MON-SAT	31 MAY 08
Chicago Harbor, IL	11/08	BRIDGE CLOSURES	VARIOUS	27 NOV 08
Chicago Harbor, IL	11/08	BRIDGE MAINTENANCE	VARIOUS	03 APR 08
Milwaukee Harbor, WI Milwaukee Harbor, WI	11/08 11/08	BRIDGE REHABILITATION BRIDGE REHABILITATION	0700-1630/ MON-SAT VARIOUS	31 MAY 08 14 APR 08
Manitowoc, WI	12/08			21 MAR 08
Manitowoc, WI	12/08	BARGE LOADING	VARIOUS	ZT WAR US
LAKE SUPERIOR				
Duluth Harbor, MN	49/07 02/08	SCHEDULED BRIDGE REHABILITATION	VARIOUS	22 MAR 08
Daidti Harbor, Will	1,707 02700	SSILESCED BRIDGE REIMBIETHTION	7.11.1000	22 101/11/ 00
FOX RIVER				


01 MAY 08

VARIOUS

GREAT LAKES - GENERAL - MARINE EVENTS - SAFETY ZONES - SECURITY ZONES

Events listed below are those events that may have accompanying special local regulations. Mariners transiting these areas should contact the U.S. Coast Guard with any questions and are asked to exercise caution when navigating through the area of the event.

Location	LNM	Events	Dates	Time (Local)	POC or Sponsor	Number
LAKE ERIE - MARINE I	<u>EVENTS</u>					
Mentor Headlands, OH	07/08	Triathlon	10 Aug 08	0600-1100	Mickey Rzymek	
Cleveland, OH	08/08	Safety at Sea – Edgewater Yacht Club	30 Mar 08	0900-1700	Michael Dills	
Cleveland, OH	08/08	FLW Fishing Tournament	24-27 Sep 08	0700-1500	Kevin Hunt	
Cleveland, OH	08/08	Y-ME Breast Cancer Walk	11 May 08	0900-1030	Darby Bentoff O'Brien	
LAKE ERIE - SAFTY Z	ZONE					
Cleveland, OH	08/08	Queens Cup Canoe Race	06 Jun 08	1230-1700	John Harkness	



STURGEON BAY WISCONSIN

Scale 1:10,000 SOUNDINGS IN FEET



NOT FOR NAVIGATIONAL USE