MONTHLY EDITION NUMBER 45

ISSUED BY: COMMANDER, THIRTEENTH COAST GUARD DISTRICT (oan) 915 Second Avenue, Seattle, Washington 98174-1067 Telephone (206) 220-7270 FAX # (206) 220-7285

BROADCAST NOTICES TO MARINERS (BNMs)

This Local Notice to Mariners (LNM) includes information concerning waterways in the Thirteenth Coast Guard District promulgated by the following broadcasts:

BNM 1047-97 to 1065-97

LIGHT LIST REFERENCE: COMDTINST M16502.6, Light List Volume VI, 1997 Edition

Electronic Bulletin Board Service: (703) 313-5910 300 to 28.8 bps, 8 data bits, no parity, 1 stop bit **NIS watchstander, 24 hours a day at (703) 313-5900** *INTERNET ADDRESS*

HTTP://www.navcen.uscg.mil

ΩI

FTP://ftp.navcen.uscg.mil

I. SPECIAL NOTICE

LOCAL NOTICE TO MARINERS - MAILING LIST - ANNUAL VERIFICATION

Attached in enclosure (1) to this Local Notice to Mariners is a Mailing List Verification Form. If you wish to continue receiving the Thirteenth Coast Guard District's Local Notice to Mariners through 1998, please fill out this form completely and return it no later than 01 January 1998. If this form is not received by 02 January 1998 your name will be deleted from the mailing list. To avoid damage to this mailer, and to ensure delivery to our office, it is suggested that this mailer be returned in an envelope. Please note you must provide return postage. If you have any questions, contact Chuck Mellinger at Ph# (206)220-7280.

WASHINGTON - PUGET SOUND - PORT ORCHARD - DYES INLET - Marine Mammal Protection Act -

Recently a large pod of Orcas has been observed in Dyes Inlet near Bremerton, WA. All Mariners are cautioned to strictly abide by the provisions of the Marine Mammal Protection Act whenever encountering a Marine Mammal in the wild. Under the provisions of the Marine Mammal Protection Act, it is illegal to harass or attempt to harass a marine mammal.

The following guidelines are recommended to mariners to legally and safely observe marine mammals in the wild:

- i) Remain at least 100 yards away at all time.
- ii) Limit observing time to one half hour or less.
- iii) If vessels need to move around a whale, do it from behind the animal.
- iv) Do not follow or pursue a marine mammal.
- v) Do not encircle a marine mammal or trap them between another vessel or shore and your vessel.
- vi) When approached by a marine mammal, put your engine in neutral and allow it to pass. Do not offer food, or discard fish, fish waste or any other food item. Do not touch the animal.
- vii) Avoid excessive speed or sudden changes in speed or direction when in vicinity of a marine mammal.
- viii) Whales may surface in unpredictable locations. Emitting periodic noises may help whales know your location and avoid contact. If your engine is not running, occasionally tap the side of your boat with a hard object.

WASHINGTON - LAKE WASHINGTON SHIP CANAL - HIRAM M. CHITTENDEN LOCKS - Scheduled Closure -

The large lock chamber at the Hiram M. Chittenden Locks in Ballard will be closed from 2230 local 14 November until 1600 local 29 November 1997. The small lock chamber will be operational throughout this maintenance period with the normal restraints.

OREGON - PORT OF PORTLAND - WILLAMETTE RIVER PORTLAND TO NEWBERG - ELK ROCK - Shoaling Information -

Mariners are advised to use caution when transiting in the vicinity of ELK ROCK BUOY 10 (LLNR 15005) and ELK ROCK BUOY 10A (LLNR 15010) due to shoaling and low water level.

Chart 18528

WASHINGTON - SEQUIM - Outfall Work -

Outfall extension operations in Sequim, on the east side of Gibson Spit, has commenced and conclude the first week of November 1997. Floating equipment will have anchor lines and mooring buoys deployed during these operations. Proper lights and day shapes will be deployed. The mooring buoys will show a flashing Yellow light. The floating equipment will monitor VHF-FM Channels 14 and 16. Mariners are urged to use extreme caution when transiting in the vicinity of the floating equipment.

Chart 18471

OREGON - NEWPORT OREGON - YAQUINA BAY - Breakwater Extension - Construction on the North Marina Breakwater in Newport, OR, has commenced. Construction on the breakwater will continue through the end of the year. A crane barge will be anchored on scene with four anchors located in the south side of the entrance channel to the marina. The anchors will be marked with lighted buoys showing a yellow light. The crane barge will monitor VHF-FM Channels 16 and 66. Chart 18581

REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

I. SPECIAL NOTICE (continued)

USA - LORAN-C - PROPOSED DECOMMISSION - Request for LORAN-C Study Comments -

The Department of Transportation is conducting a study of the proposed decommissioning of the LORAN-C system. Interested parties are requested to fill out the form on enclosure (2) and mail to the appropriate address.

WASHINGTON - PUGET SOUND - KINGSTON FERRY TERMINAL - Deployment of Current Meters -

During the week of 03 November 1997 two current meters will be deployed in the vicinity of the Kitsap County sewage outfall near the Kingston Ferry terminal. Once deployed, the meters will remain in place for a period of approximately 30 days. The meters will be set in approximate position 47²47'44.5"N 122²29'18.0"W with a distance from shore of about 1,500 feet. The meters will consist of two subsurface buoys directly below a 28 inch diameter steel buoy. The two subsurface buoys will be located at a depth of about 20 and 40 feet below MLLW. In addition to a radar reflector, the steel buoys will also show a flashing yellow light.

Chart 18446

II. DISCREPANCIES - DISCREPANCIES CORRECTED

THE FOLLOWING AIDS TO NAVIGATION ARE NOT WATCHING AS ADVERTISED IN THE LIGHT LIST VOLUME VI, THIRTEENTH DISTRICT SECTION:

Underlined text denotes new discrepancy since last LNM.

FEDERAL AIDS

LL # Aid Name Status Chart BNM LNM

15186	WILLAPA BA	AY ENTRAN	ICE BUOY	C	MISSIN	NG
18504	0957-97	41/97				
15590	POINT CHE	HALIS RAN	GE FRON	T LIGHT	MISSIN	NG DAYBOARDS
18502	0973-	97 42/9	7			
15615	GRAYS HAF	RBOR SOUT	H REACH	I A RR LIGH	łT	MISSING TOP
DAYBOARD	18502	2 0416	6 - 97 1	5/97		
16100	QUILLAYUT	E RIV ENT	SML BOAT	ΓWRNG SN	1	IMPROPER
CHARACTER	RISTIC	18480	0913-97	7 40/97		
17410	WEST OLYN	MPIA SHOA	L LIGHT 1		EXTIN	GUISHED
18465	1065-	97 45/9	7			
19000	CAP SANTE	DAYBEAC	ON 3	DEST	ROYED)
18427	0537-97	20/97				
19015	CAP SANTE	LIGHT 6	E	EXTINGUISI	HED/ LE	ANING
18427	0988-97	42/97				

PRIVATE AIDS

			Status						
10080			RIA WEST				EXIIN	IGUISHED	
40440			1007-97				- >/ - 1		
10440			NA MILL FR		AKE LIGH	I	EXIIN	IGUISHED	
			1060-97						_
						ST LIGH	HT	EXTINGUISHE)
	18524	_	0997-97	43/97					
16850		SHIPN	MATES LIG	HT		EXTI	NGUISH	HED	
18441		0833-	97 35/8	97					
17535		POINT	THUDSON	MARINA	LIGHT		TEMP	DISCONTINUE	D
	18441		0450-97	16/971	7857	SEA	BECK M	ARINA LIGHT A	ı
	EXTIN	IGUISH	HED		18440	0996	-97	43/97	
18375		BELLE	EVUE MAR	INA DOCŁ	K LIGHT A		EXTIN	IGUISHED	
			1025-97						
18375		BELLE	EVUE MAR	INA DOCŁ	KLIGHT B		EXTIN	IGUISHED	
	18440		1025-97	43/97					
19281		SQUA	LICUM CR	WATERV	VY RANGI	E FRON	T LT	EXTINGUISHEI	C
	18424		0993-97	43/97					
19557		CAPE	SAN JUAN	I COMM N	MOORAGE	LIGHT	С	EXTINGUISHEI	C
	18434		0978-97	42/97					
19557		CAPE	SAN JUAN	I COMM N	MOORAGE	LIGHT	В	EXTINGUISHEI	C
	18434		0978-97	42/97					
19557		CAPE	SAN JUAN	I COMM N	//OORAGE	LIGHT	Α	EXTINGUISHEI	C
			0978-97						

NOTE: Mariners are cautioned that portions of missing structures may remain. THE FOLLOWING AIDS TO NAVIGATION DISCREPANCIES HAVE BEEN CORRECTED SINCE THE LAST LOCAL NOTICE TO MARINERS:

FEDERAL AIDS

LL # Aid Name Status Chart BNM LNM

NONE

PRIVATE AIDS

LL # Aid Name Status Chart BNM LNM

NONE

III. TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED

LEGEND: TRUB = Temporary Unlighted Buoy

TRLB = Temporary Lighted Buoy

TRLT = Temporary Light

THE FOLLOWING AIDS TO NAVIGATION HAVE BEEN TEMPORARILY CHANGED:

LL # Aid Name Status Chart BNM LNM

09520 SIUSLAW RIVER CHANNEL DBN 14 TRUB

18583 0238-96 08/96

09560 SIUSLAW RIVER CHANNEL DAYBEACON 26 TRUB

18583 0351-96 09/96

09660 YAQUINA BAY BOAT BASIN WEST LB TEMPORARILY

DISCONTINUED 18581 0906-97 40/97 09856 GARIBALDI CHANNEL LT 14 TRUB

18558 0953-95 32/95

16790 SHILSHOLE BAY BREAKWATER LIGHT 3 SOUND SIGNAL

DISCONTINUED 18446 1315-96 48/96

18850 LACONNER RANGE FRONT LIGHT 18 TEMPORARILY

DISCONTINUED 18427 0735-97 30/97

18855 LACONNER RANGE REAR LIGHT TEMPORARILY

DISCONTINUED 18427 0736-97 30/97 19005 CAP SANTE DAYBEACON 3 TRUB

18427 0550-97 20/97

THE FOLLOWING TEMPORARY AIDS TO NAVIGATION HAVE EITHER BEEN RESTORED TO NORMAL OPERATION OR DISCONTINUED:


LL # Aid Name Status Chart BNM LNM

16980 THREE TREE POINT LIGHT WATCHING PROPERLY

18474 0934-97 40/97

IV. CHART CORRECTIONS

Corrective action affecting charts is contained in this section. Chart corrections are listed numerically by chart number. The correction listed pertains to that chart only. It is up to the mariner to decide what charts are to be corrected. The following example explains the individual elements of a typical correction.



The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. (Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles.

```
28<sup>th</sup> ed., 06/29/96 LAST LNM 32/97 NAD 83 WA - PUGET SOUND -
18448
SEATTLE TO OLYMPIA
                                                 (CGD13)45/97
       Add
                     Three Tree Point Yacht Club Racing Buoy A
              White Spar (Priv maint)
       47<sup>2</sup>23'47.7"N 122<sup>2</sup>19'52.9"W
   Three Tree Point Yacht Club Racing Buoy I
   White Spar (Priv maint)
                                                                              47<sup>2</sup>23'12.2"N
       122219'58.9"W
   Three Tree Point Yacht Club Racing Buoy J
   White Spar (Priv maint)
                                                                              47<sup>2</sup>22'57.0"N
       122<sup>2</sup>22'51.0"W
   Three Tree Point Yacht Club Racing Buoy L
              White Spar (Priv maint)
       47224'41.9"N 122220'40.9"W
```

18450 13th ed., 08/22/92 LAST LNM 14/97 NAD 83 WA - SEATTLE HARBOR - (CGD13)45/97

ELLIOTT BAY AND DUWAMISH WATERWAY

Add Colman Ferry Terminal Light A, words (Priv maint)

47²36'11.4"N 122²20'28.5"W

18474 5th ed., 03/25/95 LAST LNM 29/97 NAD 83 WA - PUGET SOUND -

SHILSHOLE BAY TO (CGD13)45/97

COMMENCEMENT BAY

Add Three Tree Point Yacht Club Racing Buoy A

White Spar (Priv maint)

47²23'47.7"N 122²19'52.9"W

Three Tree Point Yacht Club Racing Buoy I

White Spar (Priv maint) 47²23'12.2"N

47²22'57.0"N

122²19'58.9"W

Three Tree Point Yacht Club Racing Buoy J

White Spar (Priv maint)

122222'51.0"W

Three Tree Point Yacht Club Racing Buoy L

White Spar (Priv maint)

47²24'41.9"N 122²20'40.9"W

Saltwater State Park Buoy, words (Priv maint)

47²22'23.4"N 122²19'39.4"W

Sitcum Waterway Light, words (Priv maint)

47216'20.0"N 122225'06.0"W

V. ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION

WASHINGTON - PUGET SOUND - EAST BAY - Range Information -

During the week of 17 November 1997, Olympia Inner Range Rear Light (LLNR 17480) will be changed from an all around light to a directional light with a 28 degree spread, visible 14 degrees each side of rangeline. Olympia Inner Range Front Light (LLNR 17480) will be changed to have a higher intensity beam on rangeline.

Charts 18445, 18448, and 18456

VI. PROPOSED CHANGES IN AIDS TO NAVIGATION

Comments are requested on or before 21 November 1997, Attn: Mr. John Barberi. WASHINGTON - GRAYS HARBOR - Range Information -

The Coast Guard proposes to discontinue the daymarks on Point Chehalis Range Front Light (LLNR 15585) and Point Chehalis Range Rear Light (LLNR 15590). Comments and/or suggestions regarding this change should be sent to the address on page one of this Local Notice to Mariners.

Chart 18502

Comments are requested on or before 21 November 1997, Attn: Mr. John Barberi.

WASHINGTON - SWINOMISH CHANNEL SOUTH ENTRANCE - Range Information - The Coast Guard proposes to discontinue La Conner Range Front Light 18 (LLNR 18850) and Range Rear Light (LLNR 18855). Comments and/ or suggestions regarding this discontinuance should be sent to the address on page one of this Local Notice to Mariners.

Chart 18427

Comments are requested on or before 28 November 1997, Attn: Mr. John Barberi.

WASHINGTON - PUGET SOUND - SHILSHOLE BAY -

The Coast Guard proposes to discontinue Shilshole Bay Breakwater Light 3 Sound Signal (LLNR 18790). Comments and/or suggestions regarding this discontinuance should be sent to the address on page one of this Local Notice to Mariners.

Charts 18445, 18446, 18447, 18473

VII. GENERAL

DREDGING IN PROGRESS OR PLANNED WITHIN THE 13th COAST GUARD DISTRICT. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION AND REDUCE THEIR WAKE WHEN TRANSITING THESE AREAS:

Location Area Start Complete Chart

Snohomish River Jetty Island 10/29/97 12/30/97 19443

VII. GENERAL (continued)

FISHERIES/BIOLOGICAL SAMPLING, PIER CONSTRUCTION, HYDROGRAPHIC SURVEYS, ETC., CURRENTLY IN PROGRESS WITHIN THE 13th COAST GUARD DISTRICT. ALL MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION WHEN TRANSITING THESE AREAS:

Location Area Start Complete Type of Work

Duwamish River 14/16th Avenue Bridge 09/15/97 11/14/97 Bridge

Maintenance

Tacoma Blair Waterway 01/28/97 To Be Announced 11th St.

Bridge Demolition

Snohomish River State Route 529 Bridges 05/06/97 To Be Announced

Replacement of old lift cables

Interstate 5 Bridge Columbia River 11/17/97 11/21/97 Bridge

Maintenance

Lake Washington Ship Canal Montlake Bridge 11/22/97 11/22/97

UW Football Game Traffic

Lake Washington Ship Canal Montlake Bridge See Below 03/01/98

UW Basketball Game Traffic

WASHINGTON - PUGET SOUND - Marine Events - Puget Sound Area - AREA/LOCATION DATE TIME EVENT SPONSOR

PHONE #

West Point/ Jeff Head/ 11/15/97 1000-1500 Sail Boat Race Shilshole

Bay YC 763-9100

Meadow Point

Commencement Bay 11/15/97 1000-1400 Sail Boat Race Windseekers

830-5207

Des Moines Marina 11/16/97 1000-1700 Sail Boat Race Three Tree Point

YC 878-5514

Commencement Bay 11/22/97 1000-1400 Sail Boat Race Windseekers

830-5207

WASHINGTON - SNOHOMISH RIVER - Dredging Operations -

Dredging operations have commenced in the Snohomish River at Everett, Washington. These operations will be conducted from Jetty Island, River Mile one to one mile upstream of the Interstate-5 Bridge. The pipeline dredge LOFGREN will monitor VHF-FM Channels 12 and 16. Dredging will be 24 hours per day, Monday through Saturday. These dredging operations will be concluded 30 December 1997.

Charts 18443 and 18444

OREGON - WASHINGTON - COLUMBIA RIVER - Bridge Information -

The vertical lift spans of the dual Interstate 5 Bridges across the Columbia River at Vancouver, Washington, need not open for the passage of vessels from 0530 local 17 November 1997 until 1800 local 21 November 1997.

Charts 18524 and 18526

WASHINGTON - LAKE WASHINGTON SHIP CANAL - Bridge Information -

The draw of the Montlake Bridge need not open for the passage of vessels from 1000 local to 1245 local and 1500 local to 1800 local on 22 November 1997. The closures are to accommodate Husky Football game traffic.

Chart 18447

WASHINGTON - LAKE WASHINGTON SHIP CANAL - Bridge Information -

The drawspan of the Montlake Bridge need not open for the passage of vessels at these local times on the following dates:

1997 1998

1445 to 1530 1045 to 1130 December 20, 21 March 1

1645 to 1730 1645 to 1730

November 23, 29 January 10, 14, 24,

December 20, 21 February 5, 7, 12, 19, 21, 26,

2045 to 2130 2045 to 2130

November 15, 18, 25 January 05, 08, 15, 17, 22, 29, 31 December 04, 06, 20, 30 February 05, 07, 12, 19, 21, 26

These temporary closures of the drawspan are to accommodate heavy traffic associated with University of Washington basketball games.

Chart 18447

WASHINGTON - PUGET SOUND - DUWAMISH RIVER - Bridge Information - The drawspan of the 14th/16th Avenue Bridge at river mile 3.8 need not open for the passage of vessels unless two hours notice is provided from 0700 local to 1800 local from 15 September to 14 November 1997, while maintenance is being conducted.

Chart 18450

VIII. CORRECTIONS TO LIGHT LIST, VOLUME VI; PACIFIC COAST AND PACIFIC ISLANDS 1997:

An asterisk *, indicates the column in which a correction has been made or new information added.

(1) (2) (3) (4) (5) (6) (7) (8)No. Name and location Position Characteristic Ht Rng Structure Remarks Umpqua River FIR6s 9275 - Light 6A 43 40.5 16 4 TR on pile Ra ref. 124 11.6 45/97 TR on pile. 9325 - Channel daybeacon 20 43 44.9 16

124 08.4

45/97

Eureka

123 15.6

• 45/97

VIII. CORRECTIONS TO LIGHT LIST, VOLUME VI; PACIFIC COAST AND PACIFIC ISLANDS 1997: (continued)

An asterisk *, indicates the column in which a correction has been made or new information added.

(3) (1) (2) (4) (5) (7) (6) (8)Rng No. Name and location Position Characteristic Ht Structure Remarks Fisher Island 12 10715 CLEAVELAND LIGHT 3 FIG 4s 4 SG on dolphin. 45/97 Longview 10750 BARLOW POINT LIGHT 13 QG 10 5 SG on dolphin. 45/97

Cottonwood Island

10840 - DIKE LIGHT 29A 46 05.5 FI G 6s 17 4 SG on dolphin.

122 55.0

45/97

10860 - LIGHT 35 FI G 4s 15 4 SG on pile.

45/97

10885 - LIGHT 39 FI G 4s 26 4 SG on pile.

45/97

Kalama

10935 HUNTER BAR LIGHT 1 45 59.5 FI G 2.5s 22 5 SG on dolphin.

122 51.2

45/97

Martin Island

10975 - DIKE LIGHT 63 45 57.1 FI G 2.5s 15 3 SG on dolphin.

122 48.4

• 45/97

Vancouver

11225 KELLEY POINT JUNCTION 45 39.2 FI (2+1) R 6s 21 5 JR on dolphin. Ra ref. 14850 LIGHT 122 45.8

45/97

Government Island South Channel

Lady Island

11495 - RANGE REAR LIGHT Iso W 6s 55 KRB on tower on dolphin. Visible 3² each side of 580 yards, 255.5² from rangeline. front light.

45/97

Cape Horn

11605 - LIGHT 67 FI G 4s 28 4 SG on tower.

45/97

11625 CANDIANA LIGHT 69 45 34.5 FI G 4s 28 4 SG on skeleton tower.

122 11.4

• 45/97

IX. ADDITIONAL ENCLOSURES:

- 1. Annual Mailing List Verification for LNM.
- 2. Department of Transporation LORAN-C Study of the proposed decommissioning of LORAN-C system.

If you have any questions, comments, or need additional information concerning this or other LNMs or the LNM Mailing List (e.g. additions, deletions, corrections) contact the address or phone number on the front page.

W. D. WIEDENHOEFT