

## PA/SI REFERENCES – Hardesty Federal Complex

Hardesty Federal Complex  
601-607 Hardesty Avenue  
Kansas City, Jackson County, Missouri 64116  
EPA Region 7  
EPA ID No. MON000703320  
GSA Order No. GS-06P-02-GXM-0004

References for the Preliminary Assessment (PA) dated November 4, 2002, Terracon Project No. 50017083, and the Site Inspection (SI) dated November 4, 2002, Terracon Project No. 02027042

The references used in the preparation of the PA and SI reports, as numbered below, are included in this binder attachment. However, only the title page of general references and of large documents (such as References 21, 22, and 41) have been included in this attachment.

1. U.S. Environmental Protection Agency, "Standard Operating Procedure to Determine Site Latitude and Longitude Coordinates," 1991. Calculation worksheet for Hardesty Federal Complex.
2. WorldClimate.com, Average Temperature, compiled from monthly data for the Kansas City/Municipal Airport between 1893 and 1993, accessed December 3, 2001.
3. National Oceanic and Atmosphere Administration, Normal Monthly Precipitation, compiled by the National Climatic Data Center, accessed December 17, 2001.
4. Tracie Ragland, Terracon, Field Log for Preliminary Assessment Reconnaissance of the Hardesty Federal Complex, Terracon Project No. 50017083, November 28, 2001.
5. Tracie Ragland, Terracon, Photodocumentation Log of the Hardesty Federal Complex Preliminary Assessment, November 28, 2001.
6. Environmental Data Resources, Inc. (EDR), Southport, Connecticut, "Sanborn Map Report, 601 Hardesty Avenue," Inquiry No. 708022.2s, 1909, 1922, 1940, and 1942.
7. Missouri Department of Natural Resources, Initial Site Screening, "Missouri Superfund Pre-CERCLIS Site Screening Form, Kansas City Records Center, Jackson County," September 11, 2000.
8. Terracon, Lenexa, Kansas, "Phase I Environmental Site Assessment, Hardesty Federal Center," Terracon Project No. 50997737, August 19, 1999.
9. Terracon, Lenexa, Kansas, "Phase II Environmental Audit for the Hardesty Complex," Terracon Project No. 50997097, November 11, 1999.

10. Quantem Laboratories, Oklahoma City, Oklahoma, "Environmental Chemistry Analysis Report," Hardesty Complex, Fly Ash, February 22, 2000.
11. United States Army, War Department, Office of the Quartermaster General, Construction Division Zone VII, "Completion Report Covering Construction and Completion of Clothing Renovating Plant at Kansas City Quartermaster Depot," 1941.
12. General Services Administration, Public Buildings Service, Construction Management Division, Region 6, Kansas City, Missouri, "Demolition Plan, Federal Center, 601 Hardesty, Kansas City, Missouri," December 1979.
13. Art Gendreau, Assistant Director for the General Services Administration, and Tom Thomas, Maintenance Supervisor for the General Services Administration, personal interview with Tracie Ragland, Terracon, December 5, 2001. Re: Historic Operations at the Hardesty Federal Complex.
14. Missouri Department of Natural Resources, Hazardous Waste Program, "Notification of Regulated Waste Activity, 633 Hardesty Avenue, Building 6," March 26, 1998.
15. James R. Macy, Regional Director, Missouri Department of Natural Resources, Division of Environmental Quality, Kansas City Regional Office, letter of correspondence to Jerry Groom, Federal Aviation Administration, March 16, 2001. Re: Notice of Violation #4974.
16. Thomas A. Curtis, Manager, Federal Aviation Administration, letter of correspondence to James R. Macy, Regional Director, Missouri Department of Natural Resources, Division of Environmental Quality, Kansas City Regional Office, April 19, 2001. Re: Response to Notice of Violation #4974.
17. Michael R. Miller, Environmental Specialist, Missouri Department of Natural Resources, Division of Environmental Quality, Kansas City Regional Office, letter of correspondence to Jerry Groom, Federal Aviation Administration, May 18, 2001. Re: Notice of Violation #4974.
18. Missouri Department of Natural Resources, Hazardous Waste Program, "Generator's Hazardous Waste Summary Report – Part I, 633 Hardesty Avenue," March 2, 1999 and July 7, 2000.
19. Missouri Department of Natural Resources, Hazardous Waste Program, "Notification of Regulated Waste Activity, Building 11, Door 4," May 18, 1994, and July 22, 1994.
20. General Services Administration, Public Buildings Service, Construction Management Division, Region 6, Kansas City, Missouri, "Master Plan, Federal Center, 607 Hardesty, Kansas City, Missouri," April 18, 1984.

21. United States Department of Agriculture, Soil Conservation Service, "Soil Survey of Jackson County, Missouri," September 1984.
22. Environmental Data Resources, Inc. (EDR), Southport, Connecticut, "The EDR Radius Atlas with Geocheck, 601 Hardesty Avenue," Inquiry No. 708022.1s, November 30, 2001.
23. Cape Environmental Management, Inc., Waukegan, Illinois, "Former Building 4 UST Closure Assessment Report, Federal Center, 607 Hardesty Avenue, Kansas City, Missouri," June 2000.
24. Cape Environmental Management, Inc., Waukegan, Illinois, "Former USTs Site Characterization Draft Report, Federal Center, 607 Hardesty Avenue, Kansas City, Missouri," April 2001.
25. John Reddy, City of Kansas City, Missouri, Water Supply Division, personal interview with Tracie Ragland, Terracon, December 5, 2001. Re: Kansas City Municipal Water Supply.
26. City of Kansas City, Missouri, Water Supply Division, "Schematic Layout of Pump Stations, Meters, Feeder Mains, and Reservoirs," May 13, 1994.
27. Sharon Beistel, Missouri Department of Natural Resources, Division of Geology and Land Survey, facsimile correspondence, January 4, 2002. Re: Water well search.
28. U.S. Geological Survey, 7.5-minute topographic quadrangle maps of Missouri: North Kansas City, 1964, photorevised 1970 and 1975; Liberty, 1965, photorevised 1970 and 1975; Kansas City, 1991; and Independence, 1964, photorevised 1970 and 1975.
29. Federal Emergency Management Agency and Environmental Systems Research Institute, Inc., Hazard Information and Awareness Site, Flood Hazard Map, accessed December 18, 2001.
30. Nick Laposha, Missouri Department of Conservation, Protection Division, Kansas City, Missouri Regional Office, telephone conversation with Tracie Ragland, Terracon, December 21, 2001. Re: Commercial and Recreation Fishing in the Missouri River and Blue River.
31. U.S. Department of the Interior, Fish and Wildlife Service, National Wetlands Inventory, 7.5-minute topographic quadrangle maps of Missouri: Kansas City, 1994; Independence, 1993, and Blue Springs, 1993.
32. Gene Gardner, Policy Coordinator, Missouri Department of Conservation, Headquarters, letter of correspondence to Tracie Ragland, Terracon, December 19, 2001. Re: Public Lands, Sensitive Species/Communities, Hardesty Federal Complex.

33. City of Kansas City, Missouri, City Planning and Development Department, "2000 Census Area Profiles, Hardesty and Independence," 0 to 1 Mile Radius, 1 to 2 Mile Radius, 2 to 3 Mile Radius, 3 to 4 Mile Radius, Radius Profiles prepared November 26, 2001.
34. Steven Lebofsky, Development Specialist, City of Kansas City, Missouri, City Planning and Development Department, Hand-written Note Included in the "2000 Census Area Profiles, Hardesty and Independence" to Tracie Ragland, Terracon, November 26, 2001. Re: Census Area Profiles ¼ and ½ radii.
35. Ken Hannan, Missouri Department of Natural Resources, Environmental Services Program, telephone conversation with Tracie Ragland, Terracon, November 30, 2001. Re: Previous Spill of Paint Thinner at 619 Hardesty Avenue.
36. Charles M. Scott, Field Supervisor, U.S. Fish and Wildlife Service, letter of correspondence response, January 9, 2002. Re: Public Lands, Sensitive Species/Communities, Hardesty Federal Complex.
37. Dave Hartshorn, General Services Administration, Heartland Region Safety Office, "Oil-Filled Electrical Equipment Inventory Report," January 14, 2002.
38. Dave Hartshorn, General Services Administration, Heartland Region, Safety and Environmental, "Asbestos Inventory Report for Federal Center, Buildings 3, 6, 7, 9, 10, 11, and 13," December 15, 1992.
39. Dave Hartshorn, General Services Administration, Heartland Region, Safety and Environmental, telephone conversation with Tracie Ragland, Terracon, March 4, 2002. Re: Future use of the subject site.
40. Test America, Inc., Laboratory Analytical Results: Sand, Ash, Groundwater, and Soil Samples, Hardesty Federal Complex, Report Date February 25, 2002.
41. Missouri Department of Natural Resources, Division of Environmental Quality, Hazardous Waste Program, Cleanup Levels for Missouri, Revised September 1998, and Tier I Soil and Groundwater Cleanup Standards, September 1, 2001 Update.
42. IATL, Laboratory Analytical Results: Lead Dust Wipe, February 25, 2002.
43. Tracie Ragland, Terracon, Photodocumentation Log of the Hardesty Federal Complex Site Inspection, February 19, 2002.
44. Test America, Inc., Laboratory Analytical Results: Groundwater Samples, Hardesty Federal Complex, Report Dates June 10, 2002, June 13, 2002, and July 8, 2002.
45. Three Gables Preservation, Kansas City, Missouri, "Cultural Resources Assessment, Hardesty Federal Center, 607 Hardesty Avenue, Kansas City, Missouri," August 19, 1999

46. Karen Kelly, Independence Water Department, telephone conversation with Tracie Ragland, Terracon, October 15, 2002. Re: City of Independence drinking water.
47. <http://capp.water.usgs.gov/gwa/gwa.html>, James A. Miller and Cynthia L. Appel, U.S. Geological Survey "GROUND WATER ATLAS of the UNITED STATES, Kansas, Missouri, and Nebraska," HA 730-D, published in 1997.
48. Tracy Winter, Missouri Department of Natural Resources, Kansas City Regional Office, Water Pollution & Soil Conservation Division, Public Drinking Water, telephone conversation with Tracie Ragland, Terracon, October 17, 2002. Re: state-approved wellhead protection plans.
49. Center for Agricultural, Resource and Environmental Systems, University of Missouri, Columbia, Missouri, Wellhead Maps, January 2002.
50. Missouri Department of Transportation (MDOT) and Mid America Regional Council (MARC), Aerial Photographs, 1961 (MDOT), 1967 (MARC), 1973 (MDOT), 1980 (MARC), and 1989 (MDOT).
51. Test America, Inc., Laboratory Analytical Results: Groundwater Samples, Hardesty Federal Complex, Report Date October 14, 2002.
52. Terracon, Lenexa, Kansas, "Lead Removal Work Plan, Indoor Firing Range, Building 9, Hardesty Federal Complex," Terracon Project No. 02027042, September 9, 2002.

