ANCHORAGE

IIINFAII

IIINFΔII

H-1C I-1B

L-1C

H-1B, L-1A, 3E

GULKANA (GKN) (PAGK) 4 NE N62°09.30' W145°27.26' UTC-9(-8DT) Ş Р 1586 BL4.9 H50(ASP) 15-33

FUEL --- (NC-100LL, A) SERVICE --- S2 AIRPORT REMARKS --- Attended Jun-Sep Mon-Fri 1800-0200Z±. Oct-May Mon-Fri 1900-0000Z[‡]. Moose and Caribou on and around arpt. Migratory birds on and in venty of arpt dur spring. Personnel and equipment may be working on the rwy at any time. Rwy condition not monitored, recommend visual inspection prior to landing. Fuel avbl 24 hrs with credit card call 907-822-4331. Rwy 15-33 parallel taxiway 2100 X 60 is maintained as ski strip in winter. Visual inspection required before landing. Beacon twr and other obstacles on N apch end, Rwy 33 slope 0.8% up NW. Airframe/powerplant svc covers small single/twin propeller

engine acft less than 12500 lbs. ACTIVATE MIRL Rwy 15-33 and VASI Rwys 15 and 33—CTAF. (1) Rwy 15, TCH 49' GS 3.0°, Rwy 33. TCH 49' GS 3.0°.

- 115.6) (TWEB GLA 248) (WX CAM).
- COMMUNICATIONS-(CTAF 122.9) (TIE-IN FSS KENAI ENA-NOTAM GKN)

RC0 -255.4 122.2 (V) (KENALESS) ANCHORAGE CENTER APP/DEP CON -317.5 119.5

AIRSPACE: CLASS E svc 1500-06307± other times CLASS G.

RADIO AIDS TO NAVIGATION


3 \hat{C} C ¢3 500 G . 151 ~ ° 0 \sim ~ \sim n C 2 \mathcal{C} α \sim ¢ 3 3 \sim $\hat{}$ C ß \hat{c} 43 33 $\hat{}$ \sim G C $\hat{\Omega}$ 0 *(*3 α a \sim a

(H)ABVORWDME 115.6 GKN Chan 103 N62°09 23' W145°26 84' At Fld 1548/23F TWFB GLENNALLEN NDB(HW-SAB) 248 GLA N62°11.73' W145°28.06' 148° 2.5 NM to Fld./23E. TWEB. RADIO/NAV/WEATHER REMARKS -- For a toll free call to Kenai FSS dial 1-866-864-1737. Wx information avbl on CTAF (call sign Gulkana WX) or phone 907-822-3668 1500-0030Z‡.

GUNNUK MOUNTAIN N56°58 87' W133°48 35' RC0 -122.175 (SITKA FSS)

§ GUSTAVUS (GST) (PAGS) 0 NE N58°25.52' W135°42.45' UTC-9(-8DT) P 35 L4.(1) 9.(2) 10(3) H67(ASP) 11-29 S60, D100 02-20(4) FUEL --- (NC-100LL, A) SERVICE --- S2

AIRPORT REMARKS --- Unattended. Class I, ARFF Index A. ARFF svcs, arpt condition report and arpt maintenance are available during scheduled air carrier ops, at other times arpt maintenance on irregular basis. Recommend visual inspection prior to using. Construction Jun-Nov. CLOSED to air carrier ops with more than 30 passenger seats except PPR in writing to: Regional Director, Department of Transportation and Public Facilities, Southeast Region, 6860 Glacier Hwy, Juneau, AK 99801-7999. Parachute jumping onto arpt rwy, twy and acft parking apron prohibited. Birds, bear and moose on and invof rwy, Limited snow removal, ice control, rwy maint and arpt hazardous conditions (exclusive of holidays) only avbl and reported during arpt maint duty hrs. Rwy 02-20 not maintained or monitored 15 Oct-30 Apr annually. Recommend daylight ops only. 9' fence 554' south of Rwy 02-20. Transient aircraft parking available east side of Rwy 02-20. Be alert, soft asp. Aircraft over 12,500 lbs. notify arpt manager Monday-Friday 1700-0100Z[‡], 24 hr prior to arrival at 907-697-2251. Arpt maintenance duty hrs Nov 1-Mar 31



\$40

Mon-Sun 1300-2200Z[±], Apr 1-Oct 31 Mon-Fri 1600-0000Z[±], ACTIVATE MIRL Rwy 11-29, VASI and REIL Rwys 11 and 29—CTAF. Be alert: See General Notices—ENROUTE CTAF FREOS. ①MIRL Rwy 11-29. ②Rwy 11. Rwy 29, TCH 39', GS 3.0°. ③Rwy 11. Rwy 29. ④Rwy 20 thld dsplcd 136'.

COMMUNICATIONS-(CTAF 122.5) (TIE-IN FSS JUNEAU JNU-NOTAM GST) RC0 -122.65 (V) (JUNEAU FSS) ANCHORAGE CENTER APP/DEP CON -360.65 133.2 **RADIO AIDS TO NAVIGATION** NDB(HW) 219 GAV N58°25.31' W135°42.28' At Fld.86/25E. Unusable bvd 25 NM. RADIO/NAV/WEATHER REMARKS -For a toll free call to Juneau FSS dial 1-800-WX-BRIEF.

