	NTSB ID: FTW85FA254	Aircraft Registration Number: N9075Y
	Occurrence Date: 06/13/1985	Most Critical Injury: None
	Occurrence Type: Accident	Investigated By: NTSB

Location/Time

Nearest City/Place DALLAS	State TX	Zip Code 75205	Local Time 1815	Time Zone CDT	
------------------------------	-------------	-------------------	--------------------	------------------	--

Airport Proximity: On Airport/Airstrip	Distance From Landing Facility: 0
----------------------------------------	-----------------------------------

Aircraft Information Summary


Aircraft Manufacturer Robinson	Model/Series R-22 /R-22	Type of Aircraft Helicopter
-----------------------------------	----------------------------	--------------------------------


Revenue Sightseeing Flight: No	Air Medical Transport Flight: No
--------------------------------	----------------------------------

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

(This area is currently blank for the narrative statement.)

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: FTW85FA254				
		Occurrence Date: 06/13/1985				
		Occurrence Type: Accident				
Landing Facility/Approach Information						
Airport Name DALLAS REDBIRD		Airport ID: RBD	Airport Elevation 659 Ft. MSL	Runway Used 0	Runway Length	Runway Width
Runway Surface Type: Concrete						
Runway Surface Condition: Dry						
Approach/Arrival Flown: NONE						
VFR Approach/Landing: Simulated Forced Landing						
Aircraft Information						
Aircraft Manufacturer Robinson		Model/Series R-22 /R-22		Serial Number 0252		
Airworthiness Certificate(s): Normal						
Landing Gear Type: Skid						
Amateur Built Acft? No		Number of Seats: 2	Certified Max Gross Wt. 2350 LBS		Number of Engines: 1	
Engine Type: Reciprocating		Engine Manufacturer: LYCOMING		Model/Series: O-320	Rated Power: 160 HP	
- Aircraft Inspection Information						
Type of Last Inspection 100 Hour		Date of Last Inspection 05/1985	Time Since Last Inspection 32 Hours		Airframe Total Time Hours	
- Emergency Locator Transmitter (ELT) Information						
ELT Installed?/Type No		ELT Operated?	ELT Aided in Locating Accident Site?			
Owner/Operator Information						
Registered Aircraft Owner D. J. FARMS, INC.		Street Address 209 NW 17TH ST				
		City SEMINOLE		State TX	Zip Code 79360	
Operator of Aircraft W. N. COPE		Street Address P.O. BOX 822				
		City CEDAR HILL		State TX	Zip Code 75104	
Operator Does Business As: SELECT LEASING				Operator Designator Code:		
- Type of U.S. Certificate(s) Held: None						
Air Carrier Operating Certificate(s):						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 91: General Aviation						
Type of Flight Operation Conducted: Instructional						

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: FTW85FA254
	Occurrence Date: 06/13/1985
	Occurrence Type: Accident

First Pilot Information

Name On File	City On File	State On File	Date of Birth On File	Age 35
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Occupational Pilot? Civilian Pilot	Certificate Number: On File
--------	---------------------	------------------------------------	-----------------------------

Certificate(s): Airline Transport; Flight Instructor

Airplane Rating(s): Multi-engine Land; Single-engine Land

Rotorcraft/Glider/LTA: Helicopter

Instrument Rating(s): Airplane

Instructor Rating(s): Helicopter

Current Biennial Flight Review?

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--w/ waivers/lim.	Date of Last Medical Exam: 07/1984
------------------------	------------------------------------------------------	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	8165	1200	860	229	622	77	216	7076		
Pilot In Command(PIC)	8000	1200	810	214	400	76	216	6976		
Instructor										
Instruction Received										
Last 90 Days	97	77	19	1				77		
Last 30 Days										
Last 24 Hours	1	1						1		

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

Flight Plan/Itinerary

Type of Flight Plan Filed: None

Departure Point Same as Accident/Incident Location	State	Airport Identifier RBD	Departure Time 1815	Time Zone CDT
-------------------------------------------------------	-------	---------------------------	------------------------	------------------

Destination Local Flight	State	Airport Identifier	
-----------------------------	-------	--------------------	--


Type of Clearance: None

Type of Airspace: Class D

Weather Information

Source of Wx Information:


No record of briefing

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: FTW85FA254
	Occurrence Date: 06/13/1985
	Occurrence Type: Accident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
RBD	1840		0 Ft. MSL	0 NM	0 Deg. Mag.
Sky/Lowest Cloud Condition: Clear			0 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: None		0 Ft. AGL	Visibility: 15	SM	Altimeter: "Hg
Temperature: °C	Dew Point: °C	Weather Conditions at Accident Site: Visual Conditions			
Wind Direction: 135		Wind Speed: 5	Wind Gusts:		
Visibility (RVR): 0 Ft.	Visibility (RVV) 0	SM			
Precip and/or Obscuration:					

Accident Information		
Aircraft Damage: Destroyed	Aircraft Fire: None	Aircraft Explosion: None

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot					
Student Pilot				1	1
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants					
Other Crew					
Passengers					
- TOTAL ABOARD -				2	2
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	0	2	2

 National Transportation Safety Board FACTUAL REPORT AVIATION	NTSB ID: FTW85FA254	
	Occurrence Date: 06/13/1985	
	Occurrence Type: Accident	

Administrative Information

Investigator-In-Charge (IIC)

F. ROTH

Additional Persons Participating in This Accident/Incident Investigation:

J ROBERTSON
DALLAS, TX