

100-hour inspection 13-4

A

absolute pressure 3-25
 acceleration 3-17
 acceleration due to gravity 3-1
 AC circuits 10-61
 AC generators 10-46
 AC motor 10-153, 10-160
 acoustic emission inspection 8-24
 AC series motor 10-159
 action and reaction 3-18
 addition 1-1
 advisory circulars (ACs) 12-27
 aerodynamic heating 3-52
 aerodynamics 3-39
 aircraft cleaning 6-19
 aircraft logs 8-2
 aircraft maintenance manual 12-45
 aircraft nuts 5-45
 aircraft registration 12-39
 Aircraft Specifications 4-2, 4-7, 12-30
 airfoils 3-41
 airframe and powerplant (A&P) 12-13
 Airloc fasteners 5-69
 Air Transport Association (ATA) 100 12-36
 Airworthiness Certificate 12-4, 12-38
 Airworthiness Directives (ADs) 8-4, 12-9, 12-30
 Alclad aluminum 5-23
 Allen wrench 9-4
 allowance 2-7
 alodizing 6-18
 alteration 12-16
 alterations 12-46
 alternating current 10-44, 10-55
 alternator 10-160, 10-161, 10-162, 10-165, 10-178
 alternator rectifier unit 10-163
 altimeter inspections 8-15
 aluminum 5-6, 5-7, 6-13
 aluminum alloy 5-6, 5-22, 6-13
 ammeter 10-70, 10-71
 amp-hour 10-92
 ampere 10-17
 amplifier 10-118
 AND gate 10-125
 angle of attack 3-41
 angle of incidence 3-41

annealing 5-9, 5-13, 5-21, 5-26, 5-27
 annual inspection 8-12, 13-5
 anodizing 6-14, 6-18
 anti-servo tab 3-47
 anti-torque rotor 3-54
 anti-torque systems 3-54
 apparent power 10-66
 Archimedes' principle 3-28
 area 1-18, 1-21
 arm 4-2
 armature 10-134, 10-135, 10-137, 10-146, 10-161
 artificial aging 5-23
 aspect ratio 1-9, 3-41
 assembly drawing 2-2
 atmosphere 3-35
 atmospheric density 3-37
 atmospheric pressure 3-24, 3-36
 atom 10-2
 attraction 3-1
 autorotation 3-59
 Auxiliary Power Units (APUs) 11-19
 aviation fuel 11-27
 Aviation Maintenance Alerts 12-31
 axes of rotation 3-42

B

balance tab 3-48
 ballast 4-23
 band-pass filter 10-117
 band-stop filter 10-117
 Barcol tester 5-29
 barometer 3-35
 battery 10-90, 10-92
 bending 3-14
 Bernoulli's principle 3-32, 3-39
 bill of material 2-6
 binary number system 1-26
 blade flapping 3-59
 blind rivets 5-60
 block and tackle 3-11
 block diagram 2-13
 bolts 5-41, 5-43
 Boots self-locking 5-47
 borescope 8-18
 boundary layer 3-41
 box-end wrenches 9-4
 Boyle's law 3-26

| | |
|------------------------------|------|
| break line..... | 2-17 |
| Brinell hardness tester..... | 5-28 |
| British thermal unit..... | 3-4 |
| BTU..... | 3-19 |
| buoyancy..... | 3-28 |
| buoyant force..... | 3-28 |
| buttock line..... | 2-7 |

C

| | |
|--|----------------------|
| calipers..... | 9-21 |
| calorie..... | 3-19 |
| camber..... | 3-41 |
| Camloc fasteners..... | 5-69 |
| capacitance..... | 10-51, 10-52, 10-84 |
| capacitive reactance..... | 10-56 |
| capacitive reactance X_C | 10-55 |
| capacitor..... | 10-51, 10-52, 10-114 |
| capacitors..... | 10-53, 10-55 |
| capacitor start motor..... | 10-156 |
| captive fasteners..... | 5-67 |
| carbon composed resistor..... | 10-25 |
| carbon dioxide (CO_2) extinguishers..... | 11-6 |
| carbon steel..... | 5-2, 5-4, 5-20 |
| carbon tetrachloride..... | 11-6 |
| carburizing..... | 5-21 |
| casehardening..... | 5-21, 5-27 |
| casting..... | 5-30 |
| cathode-ray tube (CRT)..... | 10-79 |
| centerline..... | 2-16 |
| center of gravity (CG)..... | 3-42, 4-3 |
| center of gravity range..... | 4-17 |
| CG envelope..... | 4-25 |
| Charles' law..... | 3-26 |
| checklists..... | 8-2 |
| cherrylock rivets..... | 5-62 |
| chisels..... | 9-9 |
| chord line..... | 3-41 |
| chrome-molybdenum steel..... | 5-4 |
| chrome-nickel..... | 5-4 |
| chrome-vanadium..... | 5-4 |
| chromium..... | 5-4 |
| circle..... | 1-20 |
| circuit breaker..... | 10-30, 10-31 |
| circuit protection devices..... | 10-30 |
| circular magnetization..... | 8-26 |
| circular motion..... | 3-18 |
| classification of fires..... | 11-5 |
| cleaning..... | 6-10 |
| clevis bolts..... | 5-43 |
| close tolerance bolts..... | 5-41 |
| Code of Federal Regulations (CFRs)..... | 8-4 |
| coefficient of linear expansion..... | 3-24 |

| | |
|--|---|
| cold working..... | 5-31 |
| combination sets..... | 9-18 |
| combination wrench..... | 9-5 |
| common denominators..... | 1-2 |
| commutator..... | 10-131, 10-136 |
| composite material..... | 5-32, 5-33 |
| compound..... | 10-1 |
| compound DC motor..... | 10-148 |
| compound wound DC generator..... | 10-139 |
| compressibility effects..... | 3-49 |
| compression..... | 3-14 |
| compression ratio..... | 1-9 |
| compression wave..... | 3-33 |
| computer graphics..... | 2-1 |
| conduction..... | 3-20 |
| conductors..... | 10-3, 10-12, 10-19, 10-20, 10-21, 10-24 |
| continuous inspections..... | 8-15 |
| convection..... | 3-21 |
| conventional flow..... | 10-16 |
| conventional system..... | 1-25 |
| copper..... | 5-11 |
| copper alloy..... | 5-11 |
| corrosion..... | 6-1, 6-2 |
| corrosion prone areas..... | 6-8 |
| corrosion treatment..... | 6-10 |
| cosine..... | 1-24 |
| cotter pin..... | 5-79, 5-84 |
| counter electromotive force (emf)..... | 10-149 |
| countersink..... | 9-17 |
| coupling..... | 10-120 |
| crowfoot wrench..... | 9-6 |
| Cryofit fittings..... | 7-13 |
| cube root..... | 1-13 |
| current..... | 10-17, 10-42, 10-83 |
| current limiter..... | 10-30 |
| cutting plane line..... | 2-17 |
| cycle..... | 10-48 |

D

| | |
|----------------------------|--------------------------------|
| d'Arsonval meter..... | 10-70 |
| Dalton's law..... | 3-27 |
| dash number..... | 2-5 |
| datum..... | 2-7, 4-2 |
| DC circuit..... | 10-21 |
| DC generator..... | 10-130, 10-138, 10-141 |
| DC motor..... | 10-142, 10-144, 10-147, 10-151 |
| decimal..... | 1-4, 1-5, 1-6, 1-27 |
| decimal number system..... | 1-4 |
| defueling..... | 11-30 |
| denominator..... | 1-2 |
| density..... | 3-2 |
| density altitude..... | 3-37 |

| | |
|---|--|
| depth micrometer | 9-21 |
| detail drawing..... | 2-2 |
| detailed inspection | 12-20 |
| detail view | 2-9 |
| Deutsch rivets..... | 5-74 |
| diagonal pliers..... | 9-3 |
| dies | 9-17 |
| difference | 1-1 |
| differential pressure..... | 3-25 |
| digital image..... | 2-22 |
| dimension line..... | 2-16 |
| diode..... | 10-102, 10-103, 10-104, 10-107, 10-109 |
| direct chemical attack | 6-3 |
| direct current (DC)..... | 10-17, 10-44 |
| directional control | 3-46 |
| dissimilar metal corrosion..... | 6-4 |
| dissymmetry of lift..... | 3-58 |
| dividend..... | 1-2 |
| dividers..... | 9-21 |
| division..... | 1-2 |
| divisor | 1-2 |
| doping | 10-101 |
| Doppler effect | 3-34 |
| double flare..... | 7-5 |
| drag | 3-39 |
| drills | 9-12 |
| drive screws | 5-71 |
| dry disk rectifier | 10-106 |
| dry powder extinguishers..... | 11-8 |
| duckbill pliers..... | 9-3 |
| dynamic stability | 3-43 |
| Dzus fasteners | 5-68 |
| E | |
| eddy current | 10-69, 10-152, 10-159 |
| eddy current inspection | 8-20 |
| effective value | 10-50 |
| elastic stop..... | 5-47 |
| electrical symbol | 2-18 |
| electric ground power units..... | 11-25 |
| electricity..... | 10-23 |
| electrochemical attack..... | 6-3 |
| electrodynamometer..... | 10-76 |
| electromagnet | 10-12, 10-15 |
| electromagnetism | 10-12 |
| electromotive force (emf) | 10-16 |
| electron flow..... | 10-16 |
| electrons | 10-2, 10-3 |
| electrostatic discharge (ESD)..... | 10-6 |
| electrostatic field | 10-5 |
| empty weight | 4-4 |
| empty weight center of gravity | 4-4 |
| empty weight center of gravity range | 4-18 |
| emulsion cleaners..... | 6-24 |
| energy..... | 3-3, 10-21, 10-23 |
| engine fires | 11-15 |
| engine operation..... | 11-13 |
| equipment change | 4-22 |
| ethics | 13-6 |
| exclusive NOR gate | 10-128 |
| exclusive OR gate | 10-128 |
| exfoliation | 6-14 |
| expansion wave | 3-51 |
| exploded view drawing | 2-11 |
| exponent | 1-12 |
| extension line | 2-17 |
| extreme condition check | 4-21 |
| extremes | 1-9 |
| extruding | 5-31 |
| eyebolt..... | 5-43 |
| F | |
| FAA Form 337, Major Repair and Alteration | 12-15 |
| ferromagnetic | 10-11 |
| ferrous metals | 5-2, 6-11 |
| field effect transistor..... | 10-111 |
| files | 9-10 |
| filtering | 10-114 |
| finish mark | 2-7 |
| fire extinguishers | 11-6, 11-8 |
| fire protection | 6-22, 11-5 |
| fire safety | 11-5 |
| first class lever | 3-9 |
| fittings | 7-7 |
| Cryofit..... | 7-13 |
| flared | 7-10 |
| MS flareless | 7-10 |
| swaged | 7-10 |
| universal | 7-10 |
| fixed capacitors | 10-53 |
| fixed resistor | 10-25 |
| flaps | 3-48 |
| flared fittings | 7-10 |
| flareless fittings | 7-7 |
| flareless tube | 7-7 |
| flare nut wrench | 9-6 |
| flat files | 9-10 |
| flathead pin | 5-79 |
| flexible hose | 7-18 |
| flexible hose fluid lines | 7-17 |
| fluid | 3-27 |
| fluid line end fittings | 7-9 |
| fluid line identification | 7-8 |

| | |
|-----------------------------------|----------|
| fluid lines..... | 7-1 |
| flexible hose..... | 7-17 |
| fluid pressure..... | 3-29 |
| force | 3-4 |
| Foreign Object Damage (FOD) | 11-4 |
| forging..... | 5-30 |
| four forces of flight | 3-39 |
| fractions..... | 1-2, 1-3 |
| frequency..... | 10-48 |
| frequency of sound..... | 3-34 |
| fretting corrosion..... | 6-6 |
| friction..... | 3-5, 3-6 |
| fueling hazards | 11-28 |
| fueling procedures..... | 11-28 |
| fuel servicing..... | 11-27 |
| fulcrum..... | 4-3 |
| full-wave rectifier..... | 10-106 |
| full section..... | 2-3 |
| fuse | 10-30 |

G

| | |
|-------------------------------------|------------------------------|
| gaskets..... | 5-38 |
| gauge pressure..... | 3-25 |
| gear..... | 3-11, 3-12 |
| general gas law..... | 3-27 |
| generator | 10-44, 10-46, 10-133, 10-140 |
| generator control units (GCU) | 10-170 |
| grades of fuel..... | 11-27 |
| ground support air units | 11-26 |

H

| | |
|--|------------------|
| hacksaws | 9-8 |
| half-round files | 9-10 |
| half-wave rectifier | 10-105 |
| half section | 2-3 |
| halogenated hydrocarbon extinguishers..... | 11-6 |
| hammers | 9-1 |
| hand cranking | 11-14 |
| hand files | 9-10 |
| hand snips..... | 9-8 |
| hand taps | 9-17 |
| hardening..... | 5-20 |
| hard landing inspection | 8-16 |
| hardness testing | 5-28 |
| head of pressure | 3-29 |
| hearing protection | 11-4 |
| heat..... | 3-19 |
| heat-treating equipment | 5-15 |
| heat energy | 3-19, 3-20 |
| heat treatment..... | 5-14, 5-19, 5-22 |
| helicopter aerodynamics | 3-53 |

| | |
|------------------------------------|-------------------------|
| helicopter axes of flight..... | 3-56 |
| helicopters | 3-58, 4-27, 11-5, 11-11 |
| helicopter weight and balance..... | 4-27 |
| henry | 10-59 |
| hermaphrodite caliper | 9-21 |
| Hi-Tigue | 5-67 |
| hidden line..... | 2-17 |
| high-pass filter..... | 10-116 |
| hook spanner | 9-6 |
| hose identification | 7-17 |
| hot start..... | 11-19 |
| hot working | 5-12 |
| human factors | 13-9 |
| hung start..... | 11-19 |
| hydraulic ground power units | 11-26 |
| hydraulic transmission | 10-172 |
| hydrometer | 3-2, 4-15, 10-92 |
| hypersonic | 3-50 |
| hypotenuse | 1-24 |
| hysteresis..... | 10-69, 10-152, 10-159 |

I

| | |
|---------------------------------------|---------------|
| illustrated parts catalog | 8-4 |
| impact drivers..... | 9-8 |
| impenetrability | 3-2 |
| improper fraction | 1-2 |
| inclined coil iron vane meter..... | 10-78 |
| inclined plane | 3-13 |
| Inconel..... | 5-12 |
| inductance | 10-57, 10-85 |
| induction motor | 10-154 |
| inductive reactance | 10-60 |
| inductor | 10-59, 10-114 |
| inductor-type inverter | 10-98 |
| inertia | 3-17 |
| inside calipers..... | 9-21 |
| inside micrometer..... | 9-21 |
| Inspection Authorization | 13-5 |
| inspection of composites | 8-32 |
| inspection of welds | 8-33 |
| inspections | 8-1 |
| 100-hour | 13-4 |
| altimeter | 8-15 |
| annual | 8-12, 13-5 |
| eddy current | 8-20 |
| magnetic particle | 8-24 |
| transponder | 8-15 |
| installation drawing | 2-3 |
| insulators | 10-3 |
| integrated circuit | 10-128 |
| intergranular corrosion | 6-5 |
| internal and external wrenching | 5-49 |

| | |
|------------------------|--------|
| interpolate | 10-138 |
| inverter | 10-96 |
| ion | 10-3 |
| isometric drawing..... | 2-11 |

J

| | |
|----------------|-------|
| jet fuel | 11-27 |
| Jo-bolt | 5-43 |
| joules | 10-21 |

K

| | |
|-------------------------------|-------|
| K-Monel..... | 5-12 |
| kinematics | 3-16 |
| kinetic energy..... | 3-4 |
| kinetic theory of gases | 3-26 |
| Kirchhoff's current law..... | 10-41 |
| Kirchhoff's voltage law | 10-36 |
| knife file | 9-11 |

L

| | |
|--|---------------------|
| lag hinge..... | 3-53 |
| laminated structure..... | 5-34 |
| lateral axis | 3-45 |
| lateral control | 3-46 |
| lateral stability..... | 3-44 |
| Law of Conservation..... | 3-1 |
| LC filters | 10-115 |
| lead-acid battery..... | 10-90, 10-92, 10-93 |
| lead-acid car | 10-90 |
| lead-acid cell | 10-92 |
| leader line..... | 2-17 |
| lead float files | 9-11 |
| leading edge slats | 3-49 |
| leading edge slots | 3-48 |
| least common denominator (LCD) | 1-2 |
| left-hand rule | 10-45 |
| Lenz's Law..... | 10-58 |
| lever..... | 3-9 |
| lift..... | 3-39, 3-40 |
| light-emitting diode (LED) | 10-108 |
| lightning strike | 8-17 |
| light sport aircraft (LSA) maintenance | 12-44 |
| linear potentiometer | 10-29 |
| liquid crystal display (LCD)..... | 10-108 |
| load cells | 4-13 |
| loading graph | 4-25 |
| lockbolts..... | 5-43 |
| lockwashers..... | 5-50 |
| lodestone | 10-8, 10-11 |
| logic circuit | 10-124, 10-125 |

| | |
|---------------------------------|--------|
| logic flowchart | 2-15 |
| longitudinal axis..... | 3-46 |
| longitudinal control..... | 3-45 |
| longitudinal magnetization..... | 8-26 |
| longitudinal stability | 3-44 |
| loudness..... | 3-34 |
| low-pass filter..... | 10-116 |

M

| | |
|--|----------------------|
| machine | 3-8 |
| machine screws | 5-70 |
| Mach number | 3-34 |
| magnaglo inspection | 8-27 |
| magnesium | 5-6, 5-9 |
| magnesium alloys..... | 5-7, 5-9, 5-26, 6-15 |
| magnetic amplifier | 10-122 |
| magnetic field..... | 10-7 |
| magnetic flux..... | 10-8 |
| magnetic particle inspection | 8-24 |
| magnetism..... | 10-7 |
| magnetomotive force | 10-11 |
| magnets | 10-11 |
| main rotor systems | 3-53 |
| maintenance alteration | 12-9, 12-14 |
| maintenance records..... | 12-15, 12-18, 12-43 |
| major alterations..... | 12-20, 13-4 |
| major repairs | 12-20, 12-46, 13-4 |
| Malfunction or Defect Report | 12-31 |
| mallets | 9-1 |
| manganese | 5-11 |
| manufacturer's maintenance manual | 8-3, 12-18 |
| mass..... | 3-1 |
| Material Safety Data Sheet (MSDS)..... | 11-3 |
| material symbol..... | 2-18 |
| matter | 3-1, 10-1 |
| maximum landing weight | 4-4 |
| maximum ramp weight | 4-4 |
| maximum takeoff weight | 4-4 |
| maximum weight | 4-3 |
| maximum zero fuel weight | 4-4 |
| maxwell | 10-11 |
| mean aerodynamic chord | 4-31 |
| means | 1-9 |
| measuring tools | 9-18 |
| mechanic | 13-1 |
| mechanical advantage | 3-8, 3-9 |
| Mechanic Certificate | 13-1 |
| megohmmeter | 10-75 |
| metal-oxide-semiconductor FET (MOSFET) | 10-112 |
| metal cutting tools..... | 9-8 |
| metalworking process | 5-12 |
| Methyl ethyl ketone (MEK)..... | 6-24 |

| | |
|------------------------------|------------|
| METO horsepower..... | 4-5 |
| metric | 10-3 |
| metric system | 1-25 |
| micrometer | 9-22, 9-24 |
| micrometer calipers..... | 9-21 |
| microprocessor..... | 10-130 |
| mill files | 9-10 |
| minimum fuel..... | 4-5 |
| mixed numbers..... | 1-4 |
| molecule | 10-1 |
| moment | 4-3 |
| momentary pressure | 3-33 |
| Monel | 5-12 |
| MOSFET | 10-112 |
| motion | 3-16 |
| moving iron vane meter | 10-76 |
| MS flareless fittings..... | 7-10 |
| multimeter | 10-82 |
| multiplication | 1-1 |

N

| | |
|--------------------------------|------------|
| N-type semiconductor | 10-102 |
| NAND gate | 10-127 |
| needlenose pliers..... | 9-3 |
| negative numbers | 1-11 |
| neutrons..... | 10-2 |
| Newton's first law | 3-17 |
| Newton's second law | 3-18 |
| Newton's third law | 3-18, 3-40 |
| nickel..... | 5-12 |
| nickel-cadmium batteries | 10-94 |
| nickel-cadmium cells | 10-94 |
| nickel alloy..... | 5-12 |
| nickel steel | 5-4 |
| nitriding..... | 5-22 |
| nomogram | 2-21 |
| non-self-locking nuts | 5-45 |
| nondestructive inspection..... | 8-18 |
| NOR gate | 10-127 |
| normalizing | 5-13, 5-21 |
| normal shock wave | 3-51 |
| NOTAR | 3-55 |
| nucleus | 10-2 |
| numerator | 1-2 |
| nutplates | 5-71 |

O

| | |
|--------------------------|-----------------------------------|
| oblique drawing | 2-11 |
| oblique shock wave | 3-51 |
| octane rating..... | 11-27 |
| Ohm's law | 10-17, 10-18, 10-22, 10-35, 10-61 |

| | |
|---|---------------------|
| ohmmeter | 10-70, 10-73, 10-74 |
| ohms..... | 10-18 |
| one-view drawing..... | 2-9 |
| open-end wrenches..... | 9-4 |
| operating center of gravity range | 4-18 |
| operational amplifier | 10-121 |
| OR gate | 10-126 |
| original equipment manufacturer (OEM) | 12-36 |
| orthographic projection | 2-7 |
| oscilloscope..... | 10-79, 10-80 |
| outside calipers..... | 9-21 |
| outside micrometer..... | 9-21 |
| overhaul manual..... | 8-4 |
| oxygen hazards..... | 11-27 |

P

| | |
|---------------------------------|-------------------------|
| P-type semiconductor | 10-102 |
| packings | 5-36 |
| paint removal | 6-10 |
| parallel AC circuits | 10-63 |
| parallel circuit | 10-23, 10-40 |
| parallel DC circuits | 10-40 |
| part number | 2-5 |
| Pascal's law | 3-30 |
| pencil compasses..... | 9-21 |
| penetrant inspection | 8-19 |
| percentage | 1-10, 1-11 |
| permanent ballast | 4-23 |
| permanent magnet inverter | 10-96 |
| permeability | 8-25 |
| perspective drawing | 2-11 |
| phantom line..... | 2-17 |
| phase | 10-49 |
| photoconductive cells | 10-29 |
| photodiode..... | 10-108 |
| pictorial drawing | 2-11 |
| pin rivets..... | 5-67 |
| pitch..... | 3-34 |
| plastics..... | 5-32 |
| pliers..... | 9-3 |
| PN junction | 10-102, 10-103 |
| PNP transistor | 10-111 |
| polyurethane enamel | 6-19 |
| porosity | 3-2 |
| positive numbers | 1-11 |
| potential difference | 10-17 |
| potential energy | 3-3 |
| potentiometer | 10-28 |
| power..... | 3-4, 3-7, 10-21 |
| powered parachute | 3-62, 4-29, 4-30, 11-12 |
| powerplant cleaning | 6-23 |
| power rectifier diode | 10-107 |

| | |
|---|-------------------|
| powers | 1-12 |
| powers of ten..... | 1-12 |
| precipitation heat treating | 5-24 |
| precipitation heat treatment..... | 5-27 |
| preflight inspections | 8-5 |
| pressure | 3-24 |
| preventive maintenance | 6-7, 12-4, 12-20 |
| preventive maintenance alteration | 12-9 |
| primary cell..... | 10-90 |
| product | 1-1 |
| professionalism | 13-14 |
| progressive inspection..... | 12-20, 13-5 |
| progressive inspections | 8-12 |
| properties of metals..... | 5-1 |
| proportion..... | 1-9 |
| protons..... | 10-2 |
| pull-thru rivets..... | 5-61 |
| pulleys | 3-10 |
| punches | 9-3 |
| Pythagorean Theorem | 1-25 |
| resonance..... | 3-35, 8-22, 10-65 |
| retentivity | 10-11 |
| revision block..... | 2-6 |
| revolved section | 2-3 |
| rheostat..... | 10-28 |
| right-hand motor rule | 10-144 |
| rigid fluid lines | 7-1 |
| rigid rotor system | 3-53 |
| rivets..... | 5-54 |
| Rivnuts | 5-71 |
| Rockwell hardness tester..... | 5-28 |
| roll pin..... | 5-79 |
| root | 1-12 |
| rotary inverter..... | 10-96 |
| roundnose pliers | 9-3 |
| round or ratail files | 9-10 |
| routine inspection..... | 12-20 |
| rubber | 5-35 |
| rules..... | 9-18 |
| rust..... | 6-11, 6-13 |

Q

| | |
|----------------|-----------------|
| quenching..... | 5-9, 5-17, 5-24 |
| quotient | 1-2 |

R

| | |
|------------------------------------|--|
| radiation | 3-22 |
| radical sign | 1-13 |
| radiographic inspection..... | 8-31 |
| radiographic interpretation..... | 8-31 |
| ram pressure | 3-30 |
| rarefaction (expansion) wave | 3-33 |
| ratcheting box-end wrench..... | 9-5 |
| ratio | 1-7 |
| reamers..... | 9-13 |
| reciprocating engines | 11-13 |
| rectifiers..... | 10-104 |
| reference number | 2-5 |
| reheat treatment..... | 5-24 |
| reinforced plastic..... | 5-34 |
| relays | 10-34 |
| remainder | 1-2 |
| removed section | 2-4 |
| repair | 12-16 |
| repairmen | 13-1, 13-4 |
| repair stations | 12-13, 13-4 |
| residual fuel..... | 4-4, 4-15 |
| resistance..... | 10-17, 10-18, 10-19, 10-20, 10-43, 10-61 |
| resistive circuit | 10-22 |
| resistor color code | 10-25 |
| resistors | 10-25 |

| | |
|-------------------------------|-------------------|
| resonance..... | 3-35, 8-22, 10-65 |
| retentivity | 10-11 |
| revision block..... | 2-6 |
| revolved section | 2-3 |
| rheostat..... | 10-28 |
| right-hand motor rule | 10-144 |
| rigid fluid lines | 7-1 |
| rigid rotor system | 3-53 |
| rivets..... | 5-54 |
| Rivnuts | 5-71 |
| Rockwell hardness tester..... | 5-28 |
| roll pin..... | 5-79 |
| root | 1-12 |
| rotary inverter..... | 10-96 |
| roundnose pliers | 9-3 |
| round or ratail files | 9-10 |
| routine inspection..... | 12-20 |
| rubber | 5-35 |
| rules..... | 9-18 |
| rust..... | 6-11, 6-13 |

S

| | |
|----------------------------------|---------------------|
| SAE | 5-2 |
| SAE numerical index | 5-3 |
| saturable-core reactor..... | 10-123 |
| saturated | 3-38 |
| schematic diagram | 2-13 |
| Schottky diode | 10-108 |
| scientific notation | 1-13 |
| screwdrivers | 9-1 |
| screws..... | 5-70 |
| scriber | 9-21 |
| sealants | 5-38, 5-39 |
| sealing compound | 5-38 |
| secondary cell..... | 10-90 |
| second class lever..... | 3-9 |
| sectional view drawing | 2-3 |
| sectioning line | 2-17 |
| self-inductance | 10-58 |
| self-locking nuts | 5-46 |
| self-plugging rivets | 5-60, 5-62 |
| self-tapping screws..... | 5-71 |
| semi-rigid rotor system | 3-53 |
| semiconductors | 10-3, 10-101 |
| series-parallel DC circuit | 10-42 |
| series AC circuits | 10-61 |
| series circuit | 10-23, 10-34, 10-40 |
| series DC circuit..... | 10-34 |
| series DC motor | 10-147 |
| series wound DC generator..... | 10-138 |
| service bulletins (SB)..... | 8-3, 12-37 |
| servicing aircraft | 11-22 |

| | |
|--|---------------------|
| servo tab | 3-48 |
| severe turbulence inspection | 8-16 |
| shaded pole induction motor | 10-155 |
| shape symbol | 2-18 |
| shear stress | 3-15 |
| sheet spring | 5-48 |
| shock absorber cord | 5-36 |
| shock wave | 3-50 |
| shop safety | 11-1 |
| shunt DC motor | 10-148 |
| shunt resistor | 10-70 |
| shunt wound DC generator | 10-139 |
| signed numbers | 1-11 |
| silicon | 5-12 |
| sine | 1-24 |
| sine wave | 10-80 |
| single fixed pulley | 3-10 |
| single flare | 7-5 |
| single movable pulley | 3-10 |
| single phase induction motor | 10-155 |
| sketches | 2-20 |
| slide calipers | 9-25 |
| socket wrench | 9-5 |
| solenoid | 10-16 |
| solid-state | 10-101 |
| solid-state inverter | 10-99 |
| solid shank rivets | 5-56 |
| solution heat treatment | 5-9, 5-23, 5-26 |
| solvent cleaners | 6-23 |
| sound | 3-32 |
| sound intensity | 3-34 |
| special flight permit | 8-18 |
| special inspections | 8-16 |
| special purpose diode | 10-108 |
| specific gravity | 3-2 |
| specific heat | 3-22 |
| specific weight | 3-2 |
| speed | 3-16 |
| speed of sound | 3-33, 3-50 |
| sphere | 1-23 |
| spirit level | 4-14, 9-18 |
| split phase motor | 10-156 |
| square files | 9-10 |
| square root | 1-13 |
| squirrel cage motor | 10-153 |
| stability | 3-43 |
| stabilizing | 5-9 |
| stainless steel | 5-4 |
| stainless steel self-locking | 5-47 |
| standard atmosphere | 3-38 |
| standard weights | 4-18 |
| static electricity | 10-4 |
| static inverter | 10-98, 10-99 |
| static pressure | 3-29 |
| static stability | 3-43 |
| station numbering system | 2-7 |
| steel | 5-2 |
| steel alloy | 5-2 |
| stitch line | 2-17 |
| strain | 3-16 |
| strap wrenches | 9-7 |
| stress | 3-14 |
| stress corrosion | 6-6 |
| stress relieving | 5-27 |
| structural repair manual (SRM) | 8-4, 12-38 |
| structural screws | 5-70 |
| subsonic speed | 3-50 |
| subtraction | 1-1 |
| sum | 1-1 |
| supersonic speed | 3-50 |
| supplemental type certificates (STC) | 12-31 |
| surface area | 1-23 |
| surface corrosion | 6-4 |
| suspected unapproved parts (SUPs) | 12-27 |
| swaged fittings | 7-10 |
| switches | 10-31, 10-32, 10-33 |
| synchronous motor | 10-157 |
| T | |
| tangent | 1-24 |
| Taper-Lok | 5-67 |
| tapered potentiometer | 10-29 |
| taper pin | 5-79 |
| taper tap | 9-17 |
| taps | 9-17 |
| tap testing | 8-32 |
| tare weight | 4-5 |
| taxiing aircraft | 11-21 |
| taxi signals | 11-21 |
| Teflon™ | 7-18 |
| temperature | 3-23 |
| tempering | 5-21 |
| tension | 3-14 |
| thermal efficiency | 3-20 |
| thermal expansion | 3-24 |
| thermal hardening | 5-27 |
| thermal protectors | 10-31 |
| thermistors | 10-29 |
| thermocouples | 10-24 |
| thermoplastic material | 5-32 |
| thermosetting plastic | 5-32 |
| third class lever | 3-10 |
| threaded fastener | 5-39 |
| thread micrometer | 9-21 |
| three phase induction motor | 10-153 |

| | |
|--|----------------------------|
| three square files | 9-10 |
| thrust | 3-18, 3-39 |
| tiedown procedures | 11-9, 11-11 |
| titanium | 5-9, 5-10, 5-27, 6-16 |
| titanium alloy | 5-9, 5-10, 6-16 |
| title block | 2-4 |
| tolerance | 2-7 |
| torque | 3-4, 3-7, 10-143 |
| torque wrench | 5-53, 9-7 |
| torsion | 3-14 |
| total pressure | 3-30 |
| towing aircraft | 11-19 |
| transformer | 10-66, 10-67, 10-68, 10-69 |
| transistor | 10-109, 10-111, 10-112 |
| transonic speed | 3-50 |
| transponder inspections | 8-15 |
| trapezoid | 1-19 |
| triangle | 1-19 |
| triangular files | 9-10 |
| trigonometry | 1-24 |
| trim tabs | 3-47 |
| troubleshooting flowchart | 2-15 |
| true power | 10-66 |
| tube beading | 7-7 |
| tube bending | 7-3 |
| tube cutting | 7-2 |
| tube flaring | 7-5 |
| tubing materials | 7-1 |
| turbofan engines | 11-17 |
| turboprop engines | 11-15, 11-16 |
| turnbuckle | 5-78 |
| turnlock fasteners | 5-68 |
| twist drills | 9-12 |
| Type Certificate Data Sheet (TCDS) | 4-2, 4-7, 8-4, 12-31 |

U

| | |
|----------------------------------|------|
| ultrasonic inspection | 8-21 |
| uniform motion | 3-16 |
| universal fittings | 7-10 |
| universal numbering system | 2-5 |
| unusable fuel | 4-18 |
| useful load | 4-4 |

V

| | |
|-------------------------|--------|
| vacuum tube | 10-113 |
| valence electrons | 10-3 |
| varactor | 10-108 |

| | |
|---------------------------|--------------|
| variable capacitors | 10-54 |
| variable resistors | 10-27 |
| varmeter | 10-78 |
| velocity | 3-16 |
| venturi | 3-32, 3-40 |
| vernier scale | 9-23 |
| vertical axis | 3-46 |
| viewing plane line | 2-17 |
| visible line | 2-17 |
| Vixen files | 9-11 |
| voltage | 10-44, 10-82 |
| voltage divider | 10-37 |
| voltage regulation | 10-178 |
| voltmeter | 10-70, 10-72 |
| volume | 1-21, 1-23 |
| vortex generators | 3-42 |

W

| | |
|-------------------------------------|-------------------|
| warding file | 9-11 |
| washers | 5-50 |
| waterline | 2-7 |
| water vapor | 3-37 |
| watt | 10-21 |
| wattmeter | 10-78 |
| wavelength | 3-33 |
| weighing points | 4-16 |
| weight | 3-1, 3-39 |
| weight-shift-control aircraft | 3-60, 4-29, 11-12 |
| weight and balance records | 4-32 |
| weight and balance report | 4-1, 4-7, 4-32 |
| whole numbers | 1-1 |
| wingtip vortices | 3-42 |
| wire-wound resistors | 10-27 |
| wiring diagram | 2-15 |
| wood file | 9-11 |
| work | 3-4, 3-5 |
| wrenches | 9-4 |

Z

| | |
|-------------------|----------------|
| zener diode | 10-107, 10-179 |
| zone number | 2-6 |