§ 1917.11

| 29 CFR citation | OMB control number. |
|-----------------------|---------------------|
| 1917.50(c)(3) | 1218-0003 |
| 1917.50(c)(4)(i) | 1218-0003 |
| 1917.50(c)(5)(ii) | 1218-0003 |
| 1917.50(c)(5)(iii) | 1218-0003 |
| 1917.50(e) | 1218-0003 |
| 1917.50(g)(1) | 1218-0003 |
| 1917.50(h) | 1218-0003 |
| 1917.71(a) | 1218-0196 |
| 1917.71(b)(2)(i) | 1218-0196 |
| 1917.71(b)(2)(ii) | 1218-0196 |
| 1917.71(b)(6)(ii) | 1218-0196 |
| 1917.71(f)(4) | 1218-0196 |
| 1917.111(b) | 1218-0196 |
| 1917.113 | 1218-0196 |
| 1917.115(c) | 1218-0196 |
| 1917.116(e) | 1218-0196 |
| 1917.116(g) | 1218-0196 |
| 1917.117(a) | 1218-0196 |
| 1917.117(b) | 1218-0196 |
| 1917.117(d) | 1218-0196 |
| 1917.117(e) | 1218-0196 |
| 1917.117(f) | 1218-0196 |
| 1917.117(I) | 1218-0196 |
| 1917.118(e)(4)(i) | 1218-0196 |
| 1917.119(e) | 1218-0196 |
| 1917.122(a) | 1218-0196 |
| 1917.122(b) | 1218-0196 |
| 1917.128(b)(1)–(b)(4) | 1218-0196 |
| 1917.151(e)(5) | 1218-0196 |
| 1917.152(d)(2)(v) | 1218-0196 |
| 1917.152(d)(2)(vi) | 1218-0196 |

[64 FR 61505, Nov. 12, 1999]

Subpart B—Marine Terminal Operations

§1917.11 Housekeeping.

- (a) Active work areas shall be kept free of equipment and materials not in use, and clear of debris, projecting nails, strapping and other sharp objects not necessary for the work in progress.
- (b) Hatch beams, covers and pontoons placed in terminal working areas shall be stowed in stable piles with beams secured against tipping or falling. Alternatively, beams may be laid on their sides. When beams and pontoons are stowed in tiers more than one high, dunnage or other suitable material shall be used under and between tiers.
- (c) Cargo and material shall not obstruct access to vessels, cranes, vehicles or buildings. Means of access and egress within buildings shall be similarly unobstructed.
- (d) Dunnage, lumber, or shoring material in which there are visibly protruding nails shall be removed from the immediate work area or if left in the

area, the nails shall be rendered harmless

[48 FR 30909, July 5, 1983, as amended at 62 FR 40196, July 25, 1997]

§1917.12 Slippery conditions.

The employer shall eliminate, to the extent possible, conditions causing slippery working and walking surfaces in immediate work areas used by employees.

§ 1917.13 Slinging.

- (a) Drafts shall be safely slung before being hoisted. Loose dunnage or debris hanging or protruding from loads shall be removed.
- (b) Bales of cotton, wool, cork, wood pulp, gunny bags or similar articles shall be hoisted only by straps strong enough to support the weight of the bale. At least two hooks, each in a separate strap, shall be used.
- (c) Unitized loads bound by bands or straps may be hoisted by the banding or strapping only if the banding or strapping is suitable for hoisting and is strong enough to support the weight of the load.
- (d) Additional means of hoisting shall be employed to ensure safe lifting of unitized loads having damaged banding or strapping.
- (e) Case hooks shall be used only with cases designed to be hoisted by these hooks.
- (f) Loads requiring continuous manual guidance during handling shall be guided by guide ropes (tag lines) that are long enough to control the load.
- (g) Intermodal containers shall be handled in accordance with §1917.71(f).
- (h) The employer shall require employees to stay clear of the area beneath overhead drafts or descending lifting gear.
- (i) Employees shall not be permitted to ride the hook or the load.

[48 FR 30909, July 5, 1983, as amended at 62 FR 40197, July 25, 1997]

§1917.14 Stacking of cargo and pallets.

Cargo, pallets and other material stored in tiers shall be stacked in such a manner as to provide stability against sliding and collapse.