

**SSC-10A 1998 - 2001 MODEL YEAR NORTH AMERICAN PRODUCED CAMRY V6
CRUISE CONTROL ACCELERATOR CABLE**

Dear Toyota Customer:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Toyota has determined that a defect, which relates to motor vehicle safety, exists in certain 1998 - 2001 Model Year Toyota Camry V6 vehicles equipped with cruise control and produced at one of two assembly lines in North America.

WHAT IS THE PROBLEM?

During assembly it is possible that the accelerator cable housing may have been deformed on certain 1998 - 2001 Model Year Toyota Camry V6 vehicles equipped with cruise control and produced at one of two assembly lines in North America. After extended use of the vehicle, the accelerator inner-cable may wear away and eventually break. Should the cable break, the throttle may return to idle or in the worst case remain in its most recent position regardless of accelerator pedal operation. This condition may result in a vehicle accident.

WHAT WILL TOYOTA DO?

Toyota dealers will replace the accelerator cable from the cruise control actuator to the throttle body at **NO COST** to you

WHAT SHOULD YOU DO?

Contact any authorized Toyota dealer and make an appointment to replace the cruise control accelerator cable as soon as possible.

The labor time necessary to replace the cruise control accelerator cable will take approximately thirty minutes. However, depending upon the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

Please present this notice to the dealer when you bring the vehicle in for the repair.

If you no longer own the vehicle, please indicate so on the enclosed postage paid form, providing us with the name and address of the new owner.

WHAT IF YOU HAVE OTHER QUESTIONS?

Please contact any Toyota dealer or call the Toyota Customer Assistance Center at 1-800-331-4331.

If you believe that the dealer or Toyota has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S.W., Washington, D.C. 20590, or call the toll free Auto Safety Hot Line at 800-424-9393 (Washington, D.C. area residents may call 366-0123).

We have sent this notice in the interest of your continued satisfaction with our products, and we sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Toyota.

Sincerely,

TOYOTA MOTOR SALES, U.S.A., INC.