

NON - CONFORMITY REPORT / MRB

No.: 814237

Date: 030422



Vendor:

KAVLICO CORPORATION
14501 LOS ANGELES AVENUE
MOORPARK
93021 CA
AMERICA

Your contact:
Shelly Brazelton
001-805 523 2580

Our contact:
Katrine Alm
0418-476631
katrine.alm@haldex.com

Part No. : 102727 TRYCKGIVARE

Receipt No.:

Comments :

4 = Pressure signal not ok (date code 2x0833, 0853, 0773), 2 = Temp signal not ok (date code 0833, 0843)

DISPOSITION OF NON-CONFORMING PRODUCT

Sign: Katrine Alm

Quantity

Non Conf.	Return	Scrap	Sorted	Reworked	Accepted	Ac. w Remark
6	6	0	0	0	0	0

We will deduct the costs for this complaint in the next payment.

Correction actions shall be reported within 10 days.

Answer expected in 8D format.

Haldex Traction AB

Instrumentgatan 15
SE-261 51 LANDSKRONA

Telephone +46 418 476500
Telefax +46 418 476599
E-mail info@haldex.com
www http://www.haldex.com
VAT no SE556040-2736 01

Bankgiro 5217 - 7532
Postgiro 6198304 - 5
Orgnr 556040-2736
Bankers SE Banken
Swiftaddress ESSESESM