

Description: 2007 Pontiac G6 GTVehicle Production Date:/
 Body Style: 2D Conv
 Drive Train: 3.9L Inj 6 Cyl 4A FWD
 VIN: 1G2ZH351974154653 License:
 Mileage: 205,012
 OEM/ALT: A Search Code: SASK

Color:

Point(s) of Impact

Options:

PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
 POWER STEERING, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
 TELESCOPIC STEERING COLUMN, PREMIUM SOUND SYSTEM, ANTI-LOCK BRAKE SYS.
 TRACTION CONTROL, ALUM/ALLOY WHEELS, LEATHER STEERING WHEEL
 POWER ADJUSTABLE EXTERIOR MIRROR, TINTED GLASS, SUBWOOFER, ANTI-THEFT SYSTEM
 AUTOMATIC HEADLIGHTS, DAYTIME RUNNING LIGHTS, AM/FM STEREO CD CHANGER
 FRONT BUCKET SEATS, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER LIFTGATE\\TRUNK
 STEERING WHEEL AUDIO CONTROLS

Additional Equipment:

THIS APPRAISAL MAY CONTAIN THE USE OF AFTERMARKET AND/OR LKQ PARTS.

Line Item	Labor Type	Op	Line Item Description	Dollar Amount	Labor Units
1	BDY	OV	Frnt Bumper Cover Assy Entry#:001054		2.8#
2	BDY	RP	Frnt Bumper Cover Entry#:000008 Part#/Type:Existing		2.5*#
3	REF	RO	Frnt Bumper Cover Entry#:AUTO		C 2.6
4	BDY	RR	L Front Combination Lamp Assembly Entry#:000034 Part#/Type:** QUAL REPL PART	195.00	INC
5	BDY	CA	Headlamps Entry#:AUTO		0.4
6	REF	RO	Hood Outside Entry#:001100		C 2.5
7	BDY	RI	R Hood Washer Nozzle Entry#:003788		0.2#
8	BDY	RI	L Hood Washer Nozzle Entry#:003789		0.2#
9	BDY	RR	L Fender Panel Entry#:000138 Part#/Type:** QRP CAPA	141.96	1.2#
10	REF	RO	L Fender Outside Entry#:AUTO		C 1.5
11	REF	RO	L Fender Edge Entry#:AUTO		0.5
12	BDY	RR	L Fender Liner Entry#:000146 Part#/Type:25956106	84.50 GM PART	INC
13	BDY	RP	Alloy Wheel Entry#:002562 Part#/Type:Sublet	326.21	* 0.3*
14			Lt frt tire slightly damaged		
15			Lt frt tire worn to replacement		
16	MCH	AL	Four Wheel Entry#:001338	-M	2.7
17	BDY	RI	L Rocker Moulding Entry#:003072		INC
18	BDY	RP	L Frnt Door Shell Entry#:001848 Part#/Type:Existing		1.5*#
19	REF	RO	L Frnt Door Outside Entry#:AUTO		C 1.6
20	BDY	RR	L Frnt Door Repair Panel Entry#:001850 Part#/Type:15933008	367.50 GM PART	6.5#
21	REF	RO	L Frnt Add For Jambs Entry#:AUTO		C 0.5
22	BDY	RR	L Frnt Sound Absorber Entry#:001852 Part#/Type:25777560	20.45 GM PART	
23	BDY	RI	L Antenna Entry#:004705		0.4
24	BDY	RP	L Quarter Outer Panel Entry#:002953 Part#/Type:Existing		6.0*

25	REF	RO	L Quarter Panel Outside			C	2.1
			Entry#:AUTO				
26	BDY	RR	L Quarter Wheelhouse Liner	65.20			0.5#
			Entry#:002474 Part#/Type:25822943	GM PART			
27			R Quarter Wheelhouse Liner Prev Damaged from Rocks				
28	BDY	RI	L Rear Combination Lamp				INC
			Entry#:002384				
29	BDY	RR	License Lamp Assembly	0.00	*		INC#
			Entry#:004691 Part#/Type:20807070	GM PART			
30	BDY	OV	Rear Bumper Cover Assy				1.6
			Entry#:AUTO				
31	BDY	RR	Rear Bumper Cover	486.00			INC
			Entry#:002074 Part#/Type:19120700	GM PART			
32	REF	RO	Rear Bumper Cover			C	2.2
			Entry#:AUTO				
33			lower textured				
34	BDY	RR	L Rear Otr Bumper Bracket	24.00			INC#
			Entry#:004066 Part#/Type:25909898	GM PART			
35	BDY	RI	Rear Bumper Assy				INC
			Entry#:AUTO				
36	REF	AO	Clear Coat				3.1
			Entry#:AUTO				
37		AC	Paint/Materials	629.52	*		
			Entry#:AUTO				
38		AC	Shop Materials	167.68	*		
			Entry#:AUTO				
39	BDY	* RI	MUDFLAPS X 3				0.6*
			Entry#:900500 Part#/Type:Existing				
40	REF	* RF	MASK FOR OVERSPRAY (JAMS/OPENINGS)				0.3*
			Entry#:900500 Part#/Type:Existing				
41	REF	* RF	FILL, SAND AND FEATHER (BY SIGHT)				0.5*
			Entry#:900500 Part#/Type:Existing				
42	REF	* RF	CORROSION PROTECTION (.2 PER ADDITIONAL PANEL)				0.7*
			Entry#:900500 Part#/Type:Existing				

* - Judgment Item

				Add'l Labor Amount	Sublet Amount	Totals	
I.	Labor Subtotals	Units	Rate				
	Body	24.7	69.63	0.00	326.21	2,046.07	T
	Bdy-S	0.0	69.63	0.00	0.00	0.00	T
	Refinish	18.1	69.63	0.00	0.00	1,260.30	T
	Glass	0.0	69.63	0.00	0.00	0.00	T
	Mechanical	2.7	69.63	0.00	0.00	188.00	T
	Frame	0.0	69.63	0.00	0.00	0.00	T
	Taxable Labor					3,494.37	
		GST - E Tax	@	5.000		174.72	
		Labor Tax	@	5.000		174.72	
			@	5.000			
	Non-Taxable Labor						
	Labor Summary		45.5			3,843.81	
II.	Part Replacement Summary					Amount	
	Taxable Parts					1,384.61	
	Parts Adjustments					0.00	
		GST - E Tax	@	5.000		69.23	
	Glass Adjustments		@	0.000		0.00	
		Sales Tax	@	5.000		69.23	
	Non-Taxable Parts						
	Parts Adjustments					0.00	
	Glass Adjustments		@	0.000		0.00	
	Total Replacement Parts Amount					1,523.07	
III.	Additional Costs					Amount	
	Taxable Costs					797.20	
		Sales Tax	@	5.000		39.86	
		GST - E Tax	@	5.000 %		39.86	

Non-Taxable Costs

Total Additional Costs 876.92

Paint Material Method: Rates

Init Rate = 34.78 , Init Max Hours = 99.9, Addl Rate = 0.00

IV. Adjustments	Amount
Betterment	0.00
Betterment Credit	0.00
Insurance Deductible	200.00-
Deductible Reduction Credit	0.00
Insurance Prepaid Amount	0.00
Appearance Allowance	0.00
Related Prior Damage	0.00
Customer Responsibility	200.00-
Total Labor:	3,843.81
Total Replacement Parts:	1,523.07
Total Additional Costs:	876.92
Gross Total:	6,243.80
Total GST:	283.81
Total Adjustments:	200.00-