

130 Liberty Street - Case Study

Robert Smilowitz


Weidlinger Associates

New York • Cambridge • Mountain View • Washington, DC •
Santa Monica • Albuquerque • Edinburgh, UK


Gash in North Face







Floor Plan Above 2nd Level



Area of Initial Debris Impact



Approximate Areas of Failure



Beam-Column Connection



Damaged Beam-Column Connection



Failed Shear Connection



