# Multiple Contaminant Case Studies

Tom Sorg
USEPA
Cincinnati, OH

Workshop on Inorganic Contaminant Issues
August 21-23, 2007
Cincinnati, OH

#### Demonstration Sites with Multiple Contaminants

Sites	Well Flow	Contaminants		
	gpm	Arsenic – ug/L	Other	
Homedale, ID	10 Homes	52	U – 31 ug/L, NO <sub>3</sub> – 11 mg/L	
Lake Isabella, CA	38	35	U – 32 ug/L	
Fruitland, ID	250	50	NO <sub>3</sub> – 14 mg/L	
Vale, ID	525	17	NO <sub>3</sub> – 10 mg/L	
STMGID Reno, NV	350	88	Sb – 16 ug/L	
Greenville, WI	375	34	Ra – 7 pC/L	
Carmel, ME	30	21	Sb – 14 ug/L	
Lyman, NE	250	20	U – 38 ug/L	
North Smithfield, RI	18	20	Ra – 7 pC/L	



### **Contaminant - Chemistry**

Contaminant	Symbol/	MCL	Occurrence in Water
	Formula	mg/L	
Arsenic	As	0.010	Anion
Nitrate	NO <sub>3</sub>	10 as N	Anion
Uranium	U	0.030	Anion / Cation
Antimony	Sb	0.006	Anion
Radium	Ra	5 pC/L	Cation



#### Contaminant – BAT and Other Technologies

Contaminant	Anion	Cation	Coagulation/	RO/	Adsorptive
	Exchange	Exchange	Filtration	ED	Media
Arsenic	Yes	No	Yes	Yes	Yes
Nitrate	Yes	No	No	Yes	No
Uranium	Yes	No	yes	Yes	Yes
Antimony	?	No	?	Yes	Yes
Radium	No	Yes	No	Yes	No



#### Demonstration Sites with Multiple Contaminants

Sites	Well Flow	Contaminants		
	gpm	Arsenic – ug/L	Other	
Homedale, ID	10 Homes	52	U – 31 ug/L, NO <sub>3</sub> – 11 mg/L	
Lake Isabella, CA	38	35	U – 32 ug/L	
Fruitland, ID	250	50	NO <sub>3</sub> – 14 mg/L	
Vale, ID	525	17	NO <sub>3</sub> – 10 mg/L	
STMGID Reno, NV	350	88	Sb – 16 ug/L	
Greenville, WI	375	34	Ra – 7 pC/L	
Carmel, ME	30	21	Sb – 14 ug/L	
Lyman, NE	250	20	U – 38 ug/L	
North Smithfield, RI		20	Ra – 7 pC/L	



#### Sunset Ranch Development - Homedale, ID

- Located 40 miles west of Boise
- Composed of ten homes with nine participating in study
- Served by a 10-inch, 130-ft-deep well equipped with a 15-hp submersible pump rated at 20 gpm
- No centralized water treatment, several having water softeners and/or RO units
- Water stored in a pressure tank located in community pump house






## Homedale, ID - Source Water Quality

Parameter	Unit	Sunset Ranch Development	Remarks
Total As (as As[V])	μg/L	46.5 – 62.6	Mostly As (V)
Nitrate (as N)	mg/L	5.8 – 13.6	-
Total Uranium	μg/L	23.4 – 31.0	~100% soluble
рН	S.U.	7.2 – 7.8	-
TDS	mg/L	648 – 730	-
Hardness (as CaCO <sub>3</sub> )	mg/L	216 – 251	-
Total Alk (as CaCO <sub>3</sub> )	mg/L	283 – 317	-
Sulfate	mg/L	151 – 210	-
Silica (as SiO <sub>2</sub> )	mg/L	59.8 – 95.9	-
Total Iron	μg/L	<25 – 568	Mostly particulate
Total Vanadium	μg/L	29.1 – 39.0	~100% soluble
Fluoride	mg/L	0.6 - 5.2	



## Nine POU Systems - Homedale, ID

- Water softening to prevent scaling of RO membranes
- Kinetico RO Plus Deluxe As/NO<sub>3</sub> Removal System





#### Water Softener

#### POU RO System







# POU RO System Sampling


- 20 locations total
  - Wellhead (IN)
  - After water softener at each residence (WS1-9)
  - After reverse osmosis at each residence (RO1-9)
  - Reject water discharge line (RW1)
- Sampling Schedule
  - Monthly sampling from all locations
  - Speciation conducted quarterly at wellhead and R1 residence





#### POU RO System Performance – TDS Removal


**TDS Results for Sunset Ranch Development** 





### POU RO System Performance – Arsenic Removal


**Total Arsenic Results for Sunset Ranch Development** 





### POU RO System Performance – Nitrate Removal


Nitrate (as N) Results for Sunset Ranch Development





### POU RO System Performance – Uranium Removal

**Total Uranium Results at Sunset Ranch Development** 




Note: Average concentration for nine

water softeners and RO units.



### POU RO System Performance – Vanadium Removal

**Total Vanadium Results at Sunset Ranch Development** 





# Homedale, ID – RO System Results

Parameter	Unit	Sunset Ranch Development	RO Treated Water*	Percent Removal
Total As (as As[V])	μg/L	46.5 – 62.6	0.4	99
Nitrate (as N)	mg/L	5.8 – 13.6	1.0	90
Total Uranium	μg/L	23.4 – 31.0	<0.1	99
TDS	mg/L	648 – 730	26.2	96
Hardness (as CaCO <sub>3</sub> )	mg/L	216 – 251	0.5	99
Total Alk (as CaCO <sub>3</sub> )	mg/L	283 – 317	12.4	96
Sulfate	mg/L	151 – 210	167	99
Silica (as SiO <sub>2</sub> )	mg/L	59.8 – 95.9	2.8	96
Total Iron	μg/L	<25 – 568	< 0.025	>78
Total Vanadium	μg/L	29.1 – 39.0	0.2	99
Fluoride	mg/L	0.6 – 5.2	0.1	92

<sup>\*</sup> Average



### Demonstration Sites with Multiple Contaminants

Sites	Well Flow	Contaminants		
	gpm	Arsenic – ug/L	Other	
Homedale, ID	10 Homes	52	U – 31 ug/L, NO <sub>3</sub> – 11 mg/L	
Lake Isabella, CA	38	35	U – 32 ug/L	
Fruitland, ID	250	50	NO <sub>3</sub> – 14 mg/L	
Vale, ID	525	17	NO <sub>3</sub> – 10 mg/L	
STMGID Reno, NV	350	88	Sb – 16 ug/L	
Greenville, WI	375	34	Ra – 7 pC/L	
Carmel, ME	30	21	Sb – 14 ug/L	
Lyman, NE	250	20	U – 38 ug/L	
North Smithfield, RI	18	20	Ra – 7 pC/L	



# Upper Bodfish at Lake Isabella, CA

- 50 gpm HIX system by VEETech
- Influent:
   As 35 μg/L
   U 32 μg/L
   pH 7.5
- Vendor anticipated working capacity 15,000 to 20,000 BV






#### Lake Isabella, CA - Source Water Quality

Parameter	Unit	Source Water Concentration*	Remarks
Total As (as As[V])	μg/L	36.5 – 47.3	Mostly As (V)
Total Uranium	μg/L	27– 39	~100% soluble
TDS	mg/L	234	-
рН	S.U.	6.8 – 7.2	-
Hardness (as CaCO <sub>3</sub> )	mg/L	70 – 96	1
Total Alk (as CaCO <sub>3</sub> )	mg/L	88 – 145	-
Sulfate	mg/L	36 – 41	-
Silica (as SiO <sub>2</sub> )	mg/L	40 – 48	-
Total Iron	μg/L	<25	Mostly particulate

<sup>\*</sup>Range of 28 – 29 samples during study



#### Arsenic and Uranium Removal at Lake Isabella, CA





#### Lake Isabella, CA – RSSCT/Full Scale System Test Results

		Media Run Length (BV)	
Test	Media	10-μg/L Arsenic	30-μg/L Uranium
Full-Scale	ArsenX <sup>np</sup>	33,100	> 33,100
RSSCT	ArsenX <sup>np</sup>	28,000	> 50,000
	E33	44,000	12,000
	GFH	50,000	25,000
	MetsorbG	21,000	> 24,000*
	Adsorbsia GTO	16,000	26,000

<sup>\*</sup> Column failed due to pressure buildup and bed compaction.



#### Lake Isabella, CA – Media Disposal Issue

#### Uranium Concentration on ArsenX<sup>np</sup>

Uranium on the media calculated to be 0.13% by weight and, therefore, above the 0.05% "unimportant limit."

Media classified as low level radioactive waste.

**Disposal options investigated:** 

- 1. Partial onsite regeneration
- 2. Complete off site regeneration
- 3. Disposal and replacement

Utility returning treatment system to EPA. Closing well down.



#### Demonstration Sites with Multiple Contaminants

Sites	Well Flow	Contaminants		
	gpm	Arsenic – ug/L	Other	
Homedale, ID	10 Homes	52	U – 31 ug/L, NO <sub>3</sub> – 11 mg/L	
Lake Isabella, CA	38	35	U – 32 ug/L	
Fruitland, ID	250	50	NO <sub>3</sub> – 14 mg/L	
Vale, ID	525	17	NO <sub>3</sub> – 10 mg/L	
STMGID Reno, NV	350	88	Sb – 16 ug/L	
Greenville, WI	375	34	Ra – 7 pC/L	
Carmel, ME	30	21	Sb – 14 ug/L	
Lyman, NE	250	20	U – 38 ug/L	
North Smithfield, RI		20	Ra – 7 pC/L	



## Fruitland, ID & Vale, OR - Source Water Quality

Parameter	Unit	Fruitland, ID	Vale, OR
Population		4,000	1,976
Flow	gpm	250 (D)/160 (A)	540 (D)
Total As (as As[V])	μg/L	42.1	16.5-20
Nitrate (as N)	mg/L	14	8-12
Sulfate	mg/L	53	75-84
рН	unit	7.6	7.5
Total Alk (as CaCO <sub>3</sub> )	mg/L	379	158
TDS	mg/L	651	446
Uranium	μg/L	22.4	6.1
Vanadium	μg/L	34.0	46.8
TOC	mg/L	2.2	2.1

D = design, A = actual



### IX System Design


Parameter	Unit	Fruitland, ID	Vale, OR
Resin Type		Purolite A-300E (SBA)	Purolite Arsenex II (SBA)
Resin Quantity	ft <sup>3</sup>	50 (per tank)	110 (per tank)
		100 (total)	220 (total)
Resin Vessels	gpm	2, 48"Dx72"H	2, 63"Dx86"H
		in parallel	in parallel
Hydraulic Loading	gpm/ft <sup>2</sup>	10(D)/6.3(A)	12.5(D)
EBCT	min	3.0(D)/4.7(A)	3.0(D)
Estimated Run Length	BV	400-500	550
Salt Saturator		1, 15-ton	2, 11-ton
Regeneration Level	lb/ft <sup>3</sup>	10	8
Brine Recycle		No	Yes



#### Fruitland,ID










#### RESEARCH & DEVELOPMENT

# System Performance Fruitland, ID




#### Fruitland, ID - Total Arsenic Removal






#### Fruitland, ID - Total Nitrate Removal








# Fruitland, ID - Total As/Nitrate Breakthrough Curves

Raw water

I As = 37.7 u

Total As =  $37.7 \mu g/L$ 

Nitrate = 8.6 mg/L as N





# Fruitland, ID - System Problems

Performance (IX Runs)

Early projections – 400 - 500BVs

Actual performance – 285 -315 BVs

Early leakage of arsenic

No removal of either As or NO<sub>3</sub>

Public notification require (NO<sub>3</sub>)



# Fruitland, ID – System Problems

# Equipment

Regeneration system – improper and incomplete regeneration.

(Brine: 0 - 4 - 8%)

(Settings: Co-current/Counter-current)

Ultimate problem: Fouling of resin that reduced length of runs and increased salt usage.




#### Trace Detect Continuous Arsenic Monitor

Fruitland, ID






#### Fruitland Well #6 - First Six Days of Operation









### Vale, OR – System Problems

Performance (IX Runs)
Early projections – 550 to 680 BVs
Actual performance – 150 to 365 BVs



### Vale, OR – System Problems

## Equipment

Regeneration system – High use of salt.

(Brine: 12%)

Ultimate problem: Fouling of resin that reduced length of runs and increased salt usage.



#### Demonstration Site with Multiple Contaminants

Sites	Well Flow	Contaminants	
	gpm	Arsenic – ug/L	Other
Homedale, ID	10 Homes	52	U – 31 ug/L, NO <sub>3</sub> – 11 mg/L
Lake Isabella, CA	38	35	U – 32 ug/L
Fruitland, ID	250	50	NO <sub>3</sub> – 14 mg/L
Vale, ID	525	17	NO <sub>3</sub> – 10 mg/L
STMGID Reno, NV	350	88	Sb – 16 ug/L
Greenville, WI	375	34	Ra – 7 pC/L
Carmel, ME	30	21	Sb – 14 ug/L
Lyman, NE	250	20	U – 38 ug/L
North Smithfield, RI		20	Ra – 7 pC/L



#### STMGID, Reno, NV Treatment Plant

- 350 gpm GFH system by USFilter
- Influent:


As  $39 \mu g/L$ Sb  $15 \mu g/L$ SiO<sub>2</sub> 69 mg/L pH 7.4

 Vendor anticipated working capacity 38,000 BV





## Arsenic and Antimony Removal Using GFH at STMGID, Reno, NV







# Arsenic RSSCT Study – STMGID Site (As 39 ug/L, pH 7.4, $SiO_2$ – 69 mg/L)

Media	Lab Test	Field Test
	BVs to 10 ug/L	BVs to 10 ug/L
GFH	11,000	16,200
E33	NA	8,700
KemIron (1)	NA	12,400
KemIron (2)	NA	9,400
Adsorbia GTO	4,500	NA
ARM 200	7,900	NA
ArsenX <sup>np</sup>	7,900	NA
Metsorb G	NA	5,200



# Antimony RSSCT Study – STMGID Site (As 39 ug/L, pH 7.4, $SiO_2$ – 69 mg/L)

Media	Lab Test (BVs)	Field Test (BVs)
	to 10 ug/L	T0 10 ug/L
GFH	<2,000	3,000
E33	NA	2,800
KemIron (1)	NA	4,900
KemIron (2)	NA	8,000
Adsorbia GTO	NA	NA
ARM 200	Low	NA
ArsenX <sup>np</sup>	Low	NA
Metsorb G	NA	4,500



## STMGID - Media Change (330 cf)

Media Replacement (\$60,000)

GFH – 1 tank

KemIron - 2 tanks

Arsenic break through to 10 ug/L at 3,700BVs

Utility considering the conversion of adsorptive media process to coagulation/filtration







RESEARCH & DEVELOPMENT







RESEARCH & DEVELOPMENT

## Response to Call for Help To Remove Toilet Seat

Response to call for help to remove toilet seat!

Two policemen

Two EMS staff

Two firemen

Two volunteer firemen

Response for help on water treatment plant problem.

Equipment manufacturer - ?



#### Demonstration Site with Multiple Contaminants

Sites	Well Flow	Contaminants	
	gpm	Arsenic – ug/L	Other
Homedale, ID	10 Homes	52	U – 31 ug/L, NO <sub>3</sub> – 11 mg/L
Lake Isabella, CA	38	35	U – 32 ug/L
Fruitland, ID	250	50	NO <sub>3</sub> – 14 mg/L
Vale, ID	525	17	NO <sub>3</sub> – 10 mg/L
STMGID Reno, NV	350	88	Sb – 16 ug/L
Greenville, WI	375	34	Ra – 7 pC/L
Carmel, ME	30	21	Sb – 14 ug/L
Lyman, NE	250	20	U – 38 ug/L
North Smithfield, RI	18	20	Ra – 7 pC/L



### Carmel ES, Carmel, ME

#### **RO Pilot Study**



Source water AsV 21-30 ug/L Sb 10 – 12 ug/L TDS 240 – 250 mg/L pH 7.5





#### Carmel ES, Carmel, ME - RO Pilot Study March, 2006 – July, 2007

Substance	Source Water	RO Treated Water
As – ug/L	21 – 30	0.2
Sb – ug/L	10 – 12	<0.1
TDS – mg/L	240 – 250	4
pH - units	7.5	5.6

Plan to install RO system under arsenic demonstration study



## Acknowledgements

- Battelle Memorial Institute Columbus OH
- Water utilities participating in the arsenic demonstration program



**Tom Sorg** 

513/569-7370

sorg.thomas@epa.gov