

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: JUNE 15, 2004

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "**CI-208-020320**")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "**PE-214-020320**")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection)

CP (Complaint)

MD (Manufacturer Defect)

ID (Part 574)

MI (Manufacturer Inquiry)

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive

FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure

FAIL - I: inspection failure

FAIL - L: labeling or instruction failure

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
1	101	Controls and Displays (Inspection)	Vehicle	Insp.-1
2	102	Transmission Shift Lever Sequence, etc. (I)	Vehicle	Insp.-2
3	103	Windshield Defrosting & Defogging Systems	Vehicle-1	TEST
4	104	Windshield Wiping & Washing Systems	Vehicle-2	TEST
5	105	Hydraulic Brake System	Vehicle-3	TEST
6	106	Brake Hoses	Equip.-1	TEST
7	108	Lamps, Reflective Devices, etc.	Equip.-2	TEST
8	109	Passenger Car New Pneumatic Tires	Equip.-3	TEST
9	110	Passenger Car Tire Selection & Rims	Vehicle-4	TEST
10	111	Rearview Mirrors	Vehicle-5	TEST
11	113	Hood Latch Systems (Inspection)	Vehicle	Insp.-3
12	114	Theft Protection	Vehicle-6	TEST
13	116	Hydraulic Brake Fluids	Equip.-4	TEST
14	117	Retreaded Pneumatic Tires (Inspection)	Equipment	Insp.-4
15	118	Power Operated Window Systems	Vehicle-7	TEST
16	119	Truck/Bus New Pneumatic Tires	Equip.-5	TEST
17	120	Truck/Bus Tire Selection & Rims	Vehicle-8	TEST
18	121	Air Brake Systems	Vehicle-9	TEST
19	122	Motorcycle Brake Systems	Vehicle-10	TEST
20	123	Motorcycle Controls & Displays (Inspection)	Vehicle	Insp.-5
21	124	Accelerator Control Systems	Vehicle-11	TEST
22	125	Warning Devices	Equip.-6	TEST
23	129	Passenger Car New Non-Pneumatic Tires	Equip.-7	TEST
24	131	School Bus Pedestrian Safety Devices	Vehicle-12	TEST
25	135	Passenger Car Brake Systems	Vehicle-13	TEST
26	201	Occupant Protection in Interior Impact	Vehicle-14	TEST
27	202	Head Restraints	Vehicle-15	TEST
28	203	Impact Prot. for Driver from Strg. Control	Vehicle-16	TEST
29	204	Steering Control Rearward Displacement	Vehicle-17	TEST
30	205	Glazing Materials (Inspection)	Equipment	Insp.-6
31	206	Door Locks & Door Retention Components	Equip.-8	TEST
32	207	Seating Systems	Vehicle-18	TEST
33	208	Occupant Crash Protection	Vehicle-19	TEST

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
34	209	Seat Belt Assemblies	Equip.-9	TEST
35	210	Seat Belt Assembly Anchorages	Vehicle-20	TEST
36	212	Windshield Mounting	Vehicle-21	TEST
37	213	Child Restraint Systems	Equip.-10	TEST
38	214	Side Impact Protection	Vehicle-22	TEST
39	216	Roof Crush Resistance	Vehicle-23	TEST
40	217	Bus Window Retention & Release	Vehicle-24	TEST
41	218	Motorcycle Helmets	Equip.-11	TEST
42	219	Windshield Zone Intrusion	Vehicle-25	TEST
43	220	School Bus Rollover Protection	Vehicle-26	TEST
44	221	School Bus Body Joint Strength	Vehicle-27	TEST
45	222	School Bus Passenger Seating	Vehicle-28	TEST
46	223	Rear Impact Guards	Equip.-12	TEST
47	224	Rear Impact Protection (Inspection)	Vehicle	Insp.-7
48	225	Child Restraint Anchorage Systems	Vehicle-29	TEST
49	301	Fuel System Integrity	Vehicle-30	TEST
50	302	Flammability of Interior Materials	Equip.-13	TEST
51	303	Fuel System Integrity of CNG Vehicles	Vehicle-31	TEST
52	304	CNG Fuel Container Integrity	Equip.-14	TEST
53	305	Electric Vehicles	Vehicle-32	TEST
54	401	Interior truck Release	Vehicle	TEST
55	500	Low Speed Vehicle Requirements	Vehicle-33	TEST
SUMMARY: 34 vehicle standards, 14 equipment standards, 7 inspection standards				

REPORTS ACCEPTED DURING MAY 2004 FOR FY 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	HSNO/ RESULT
114	VER 001	NISSAN	2004 NISSAN QUEST MINIVAN 4-DOOR	PASS 637176
114	VER 002	HYUNDAI	2004 HYUNDAI XG350 4-DOOR SEDAN	PASS 637177
114	VER 003	MAZDA	2004 MAZDA MAZDA 6 4-DOOR SEDAN	PASS 637178
114	VER 004	MINIBUS	2004 MITSUBISHI ENDEAVOR MPV 4-DOOR	PASS 637179
114	VER 005	TOYOTA	2004 TOYOTA SIENNA MINIVAN 4-DOOR	PASS 637180
114	VER 006	GMC	2004 PONTIAC GRAND PRIX 4-DOOR SEDAN	PASS 637181
114	VER 007	VOLKSWAGEN	2004 VOLKSWAGEN TOUAREG MPV 4-DOOR	FAIL-P ¹ 637182
114	VER 008	FORD	2004 FORD ECONOLINE VAN	PASS 637183
120	TRC 005	FORD	2004 FORD ECONOLINE VAN	PASS 637098
124H	GTL 001	HONDA	2004 HONDA ELEMENT MPV 4-DOOR	PASS 637102
124H	GTL 002	FORD	2004 FORD FREESTAR MINIVAN 4-DOOR	PASS 637128
124H	GTL 003	DAIMLER/ CHRYSLER	2004 CHRYSLER PACIFICA MPV 4-DOOR	PASS 637130
124H	GTL 004	NISSAN	2004 NISSAN QUEST MINIVAN 4-DOOR	PASS 637146
124L	GTL 002	DAIMLER/ CHRYSLER	2004 CHRYSLER PACIFICA MPV 4-DOOR	PASS 637142
124L	GTL 003	FORD	2004 FORD FREESTAR MINIVAN 4-DOOR	PASS 637143
124L	GTL 004	HONDA	2004 HONDA ELEMENT MPV 4-DOOR	PASS 637144
124L	GTL 005	NISSAN	2004 NISSAN QUEST MINI 4-DOOR	PASS 637147
135	TRC 006	FORD	2004 FORD ECONOLINE VAN	PASS 637141
206	KAR 008	GMC	2004 SATURN ION DOOR LATCH/HINGE	PASS 637101
206	KAR 009	DAIMLER/ CHRYSLER	2004 CHRYSLER PT CRUISER DOOR LATCH/HINGE	PASS 637100

¹ The Touareg is equipped with a device that allows the ignition key to be removed when the transmission is not in park position. Upon removal of key steering is not prevented as required by (FMVSS 114).

REPORTS ACCEPTED DURING MAY 2004 FOR FY 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	HSNO/ RESULT
206	KAR 010	TOYOTA	2004 TOYOTA COROLLA MATRIX DOOR LATCH/HINGE	PASS 637152
206	KAR 014	GMC	2004 CHEVROLET AVEO DOOR LATCH/HINGE	PASS 637154
206	MGA 007	VOLKSWAGEN	2004 AUDI AUDI S4 DOOR LATCH/HINGE	PASS 637145
206	MGA 008	DAIMLER/ CHRYSLER	2004 CHRYSLER PACIFICA DOOR LATCH/HINGE	PASS 637105
206	MGA 009	DAIMLER/ CHRYSLER	2004 DODGE RAM 1500 QUAD DOOR LATCH/HINGE	PASS 637139
206	MGA 010	DAIMLER/ CHRYSLER	2004 DODGE STRATUS DOOR LATCH/HINGE	PASS 637110
206	MGA 011	DAIMLER/ CHRYSLER	2004 JEEP LIBERTY DOOR LATCH/HINGE	PASS 637151
206	MGA 020	MITSUBISHI	2004 MITSUBISHI ENDEAVOR DOOR LATCH/HINGE	PASS 637099
209	DTB 013	TOYOTA	2004 TOYOTA SCION XA SEAT BELT ASSY.	PASS 637103
209	DTB 014	TOYOTA	2004 TOYOTA SCION XB SEAT BELT ASSY.	PASS 637104
209	DTB 015	TOYOTA	2004 LEXUS RX330 SEAT BELT ASSY.	PASS 637153
209	UST 009	GMC	2004 CHEVROLET AVEO SEAT BELT ASSY.	PASS 637112
209	UST 011	GMC	2004 CHEVROLET COLORADO REG/CR SEAT BELT ASSY.	PASS 637113
209	UST 015	GMC	2004 PONTIAC GRAND PRIX SEAT BELT ASSY.	PASS 637114
209	UST 019	MAZDA	2004 MAZDA MAZDA 6 SEAT BELT ASSY.	PASS 637115
213	UST 001	EVENFLO	2004 EVENFLO DISCOVERY CHILD RESTRAINT	PASS 637132
213	UST 002	EVENFLO	2004 EVENFLO EXPRESS COMB. CHILD RESTRAINT	PASS 637133
213	UST 003	EVENFLO	2004 EVENFLO COMET COMB. CHILD RESTRAINT	PASS 637134
213	UST 004	EVENFLO	2004 EVENFLO CHASE COMB. CHILD RESTRAINT	PASS 637136
213	UST 005	EVENFLO	2004 EVENFLO CHASE DXL COMB. CHILD RESTRAINT	PASS 637137
213	UST 006	EVENFLO	2004 EVENFLO VISION COMB. CHILD RESTRAINT	PASS 637138
213	UST 007	EVENFLO	2004 EVENFLO TRIUMPH CONV. CHILD RESTRAINT	PASS 637135

REPORTS ACCEPTED DURING MAY 2004 FOR FY 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/GRP	MFR/DISTRIB	MY/MAKE/MODEL/STYLE	HSNO/RESULT
213	UST 008	EVENFLO	2004 EVENFLO TITAN CONV. CHILD RESTRAINT	PASS 637123
213	UST 009	EVENFLO	2004 EVENFLO TITAN 5 CONV. CHILD RESTRAINT	PASS 637124
213	UST 010	EVENFLO	2004 EVENFLO VANGUARD CONV. CHILD RESTRAINT	PASS 637125
213	UST 011	EVENFLO	2004 EVENFLO VANGUARD 5 CONV. CHILD RESTRAINT	PASS 637126
213	UST 012	EVENFLO	2004 EVENFLO PORT ABOUT 3 CHILD RESTRAINT	PASS 637127
213	UST 013	EVENFLO	2004 EVENFLO PORT ABOUT 5 CHILD RESTRAINT	PASS 637129
213	UST 014	EVENFLO	2004 EVENFLO VICTORY 5 CONV. CHILD RESTRAINT	PASS 637131
213	UST 015	EVENFLO	2004 EVENFLO TRIBUTE CONV. CHILD RESTRAINT	PASS 637122
213	UST 016	EVENFLO	2004 EVENFLO TRIBUTE 5 CONV. CHILD RESTRAINT	PASS 637117
213	UST 017	EVENFLO	2004 EVENFLO TOT TAXI CHILD RESTRAINT	PASS 637118
214	TRC 016	SUZUKI	2004 SUZUKI FORENZA 4-DOOR SEDAN	PASS 637097
214	TRC 018	GMC	2004 CHEVROLET AVEO 4-DOOR SEDAN	PASS 637150
214	VER 004	GMC	2004 CHEVROLET MALIBU 4-DOOR SEDAN	PASS 637149
214	VER 005	MITSUBISHI	2004 MITSUBISHI GALANT 4-DOOR SEDAN	PASS 637148
218	UST 001	STRATEGIC SPORT	2003 ZAMP S-1 PARTIAL	FAIL-P,L ² 637106
218	UST 002	ARAI	2004 ARAI QUANTUM 2 COMPLETE	PASS 637107
218	UST 003	TONG HO HSING	2004 SKID LID U-67PC PARTIAL	FAIL-L ³ 637108
218	UST 004	ARAI	2004 ARAI ASTRAL X COMPLETE FACIAL	PASS 637109

² The Strategic Sport model Zamp S-1 helmet had six penetration test failures, two retention system failures where the chinstrap stretched more than one inch when tested under load, and were not labeled to identify manufacturer and model.

³ The Tong Ho Hsing model designation was not present and the label with the date of manufacture, size, etc., detached from the helmet upon immersion in water.

REPORTS ACCEPTED DURING MAY 2004 FOR FY 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	HSNO/ RESULT
218	UST 005	AGV	2003 AGV X-RS COMPLETE FACIAL	PASS 637119
218	UST 006	AFX	2004 AFX X-15R COMPLETE FACIAL	PASS 637120
218	UST 007	NEXL SPORTS	2004 NEXL 05 PARTIAL	⁴ FAIL-P 637121

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L - LABELING

⁴ The NexL model 05 failed penetration and retention testing where the chinstrap stretched more than one inch when tested under load.

TIRE REPORTS ACCEPTED MAY 2004 FOR 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	HSNO/ RESULT
109	SSS 047	KELLY-SPRINGFIELD TIRE CO.	2004 SUMMIT GT RADIAL PJXO2RKR2803	PASS 6276471
109	STL 001	MICHELIN NORTH AMERICAN INC.	2004 MICHELIN HYDROEDGE NH-3003	PASS 6276472
109	STL 002	UNIROYAL GOODRICH TIRE MFG.	2004 B.F. GOODRICH PRECEPT TOURING AP2903	PASS 6276473
109	STL 003	UNIROYAL GOODRICH TIRE MFG.	2004 UNIROYAL LAREDO AWR AP-2603	PASS 6276474
109	STL 004	BRIDGESTONE/ FIRESTONE INC.	2004 BRIDGESTONE B420 OB-1903	PASS 6276475
109	STL 005	BRIDGESTONE/ FIRESTONE INC.	2004 FIRESTONE AFFINITY TOURING S2 W2903	PASS 6276476
109	STL 006	DUNLOP TIRE CORP.	2004 DUNLOP SP SPORT 4000 A/S EV-2103	PASS 6276478
109	STL 007	DUNLOP TIRE CORP.	2004 DUNLOP SP SPORT 5000 EV-2403	PASS 6276479
109	STL 008	COOPER TIRE & RUBBER CO.	2004 COOPER MATRIX MULTI-MILE 3D-1403	PASS 6276480
109	STL 009	BRIDGESTONE/ FIRESTONE INC.	2004 FIRESTONE AFFINITY LH30 W2-3003	PASS 6276481
109	STL 010	TOYO RUBBER INDUSTRY CO. LTD.	2004 TOYO 800 ULTRA CX-703	PASS 6276482
109	STL 011	BRIDGESTONE/ FIRESTONE INC.	2004 BRIDGESTONE BT70S Y7-4401	PASS 6276483
109	STL 012	BRIDGESTONE/ FIRESTONE INC.	2004 FIRESTONE SUPREME SI VN-2003	PASS 6276484
109	STL 013	TOYO RUBBER INDUSTRY CO. LTD.	2004 TOYO SPECTRUM TOURING 9T-1903	PASS 6276485
109	STL 014	UNIROYAL GOODRICH TIRE MFG.	2004 B.F. GOODERICH TOURING T/A TR4 BE-1803	PASS 6276486
109	STL 015	BRIDGESTONE/ FIRESTONE INC.	2004 BRIDGESTONE POTENZA RE950 H4-1302	PASS 6276487
109	STL 016	COOPER TIRE & RUBBER CO.	2004 COOPER MASTER CRAFT P794 3D-4702	PASS 6276488
109	STL 017	KELLY-SPRINGFIELD TIRE CO.	2004 MULTI-MILE EXEL PJ-3202	PASS 6276489
109	STL 018	HANKOOK TIRE CO.	2004 HANKOOK MILEAGE PLUS GT T7-3902	PASS 6276490
109	STL 019	GENERAL TIRE CO.	2004 ULTREX IV RADIAL A/S A3-1603	PASS 6276491
109	STL 020	BRIDGESTONE/ FIRESTONE INC.	2004 BRIDGESTONE POTENZA LS-T EJ-1903	PASS 6276492
109	STL 021	GENERAL TIRE CO.	2004 GENERAL EXCLAIM A3X03LY3702	PASS 6276493

TIRE REPORTS ACCEPTED MAY 2004 FOR 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	HSNO/ RESULT
109	STL 022	UNIROYAL GOODRICH TIRE MFG.	2004 UNIROYAL TIGERPAW AWP AP-2703	PASS 6276494
109	STL 023	GOODYEAR TIRE & RUBBER CO.	2004 MULTI-MILE GRAND AM MK-5001	PASS 6276495
109	STL 024	UNIROYAL GOODRICH TIRE MFG.	2004 B.F. GOODRICH CONTROL T/A M80 BH-1803	PASS 6276496
109	STL 025	UNIROYAL GOODRICH TIRE MFG.	2004 B.F. GOODRICH TOURING T/A HR4 BE-2502	PASS 6276497
109	STL 026	UNIROYAL GOODRICH TIRE MFG.	2004 B.F. GOODRICH TOURING T/A VR4 BE-2502	PASS 6276498
109	STL 027	GENERAL TIRE CO.	2004 GENERAL AMERI-G4S A3-2903	PASS 6276499
109	STL 028	TOYO RUBBER INDUSTRY CO. LTD.	2004 TOYO PROXES H4 CX-1601	PASS 6276500
109	STL 029	DUNLOP TIRE CORP.	2004 DUNLOP D65T DB-3003	PASS 6276501
109	STL 030	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR EAGLE RH MK-1503	PASS 6276502
109	STL 031	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR RAGATTA 2 PD-3203	PASS 6276503
109	STL 032	CONTINENTAL MATADOR TIRES S.R.	2004 CONTINENTAL TOURING CONTACT AS A3-2503	PASS 6276504
109	STL 033	KELLY-SPRINGFIELD TIRE CO.	2004 SUMMIT PREMIUM PLUS II PJ-2803	PASS 6276505
109	STL 034	BRIDGESTONE/ FIRESTONE INC.	2004 BRIDGESTONE TURANZA ER33 EJ-903	PASS 6276506
109	STL 035	GOODYEAR TIRE & RUBBER CO.	2004 SUMMIT TOURING MK-4602	PASS 6276507
109	STL 036	GENERAL TIRE CO.	2004 GENERAL AMERI-GS60 AC-2003	PASS 6276508
109	STL 037	COOPER TIRE & RUBBER CO.	2004 MASTERCRAFT A/S IV 3D-4202	PASS 6276509
109	STL 038	BRIDGESTONE/ FIRESTONE INC.	2004 BRIDGESTONE TURANZA H REVO EL-4600	PASS 6276510
109	STL 039	KELLY-SPRINGFIELD TIRE CO.	2004 REMINGTON MAXXUM II PJ-1703	PASS 6276511
109	STL 040	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR AQUATRED MK-3103	PASS 6276512
109	STL 041	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR NASCAR EAGLE #1 MK-2803	PASS 6276513
109	STL 042	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR INTEGRITY MK-1903	PASS 6276514
109	STL 043	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR CONQUEST M6-4802	PASS 6276515

TIRE REPORTS ACCEPTED MAY 2004 FOR 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	HSNO/ RESULT
109	STL 044	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR EAGLE LS MGX0BMWR3203	PASS 6276516
109	STL 045	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR EAGLE GA 4BX0E2DR2703	PASS 6276517
109	STL 046	KELLY-SPRINGFIELD TIRE CO.	2004 ARIZONIAN SILVER EDITION PJ-3203	PASS 6276518
119	STL 047	KELLY-SPRINGFIELD TIRE CO.	2004 ROCKY MOUNTAIN ALL SEASON PJ-3003	PASS 6276520
109	STL 048	KELLY-SPRINGFIELD TIRE CO.	2004 MULTI-MILE GRAND TOUR TR PJ-2803	PASS 6276521
109	STL 049	BRIDGESTONE/ FIRESTONE INC.	2004 BRIDGESTONE POTENZA RE750 EL-1103	PASS 6276522
119	STL 050	GOODYEAR TIRE & RUBBER CO.	2004 MULTI-MILE MK MK-103	PASS 6276523
119	STL 051	NANKANG RUBBER TIRE CORP.	2004 NANKANG EX-601 U8-1402	PASS 6276524
109	STL 052	KELLY-SPRINGFIELD TIRE CO.	2004 FULDA CARAT ASSURO PJ-603	PASS 6276525
119	STL 053	KELLY-SPRINGFIELD TIRE CO.	2004 GRAND SPIRIT RADIAL HR+4 PJ-1101	PASS 6276526
109	STL 054	KELLY-SPRINGFIELD TIRE CO.	2004 FULDA CARAT EXTREMO PJ-4100	PASS 6276527
109	STL 055	KELLY-SPRINGFIELD TIRE CO.	2004 ROAD HUGGER RADIAL GT-A PJ-2803	PASS 6276528
109	STL 056	PIRELLI S.P.A.	2004 PIRELLI P6 FOUR SEASONS XT-1103	PASS 6276529
109	STL 057	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR INTEGRITY 3D-1903	PASS 6276530
109	STL 058	BRIDGESTONE/FIRESTONE INC.	2004 FIRESTONE FIREHAWK SZ50 WI-4302	PASS 6276531
109	STL 059	MICHELIN NORTH AMERICAN INC.	2004 MICHELIN ENERGY LX4 M3-1903	PASS 6276532
109	STL 060	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR EAGLE RS-A M6-3103	PASS 6276533
119	SSS 001	BRIDGESTONE/FIRESTONE INC.	2004 PEERLESS FORCE A/T W1HKW421603	PASS 6276536
119	SSS 002	UNIROYAL GOODRICH TIRE MFG.	2004 B.F. GOODRICH RADIAL LONGTRAIL T/A ANHKHK112202	PASS 6276537
119	SSS 003	GOODYEAR TIRE & RUBBER CO.	2004 KELLY SAFARI AWR MDHK0603	PASS 6276538
119	SSS 004	BRIDGESTONE HOFU PLANT	2004 BRIDGESTONE G159 UNISTEEL MC3TTVABW2403	PASS 6276539
119	SSS 005	KELLY-SPRINGFIELD TIRE CO.	2004 KELLY SAFARI CSR PJHKKPCV0803	PASS 6276540

TIRE REPORTS ACCEPTED MAY 2004 FOR 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	HSNO/ RESULT
119	SSS 006	COOPER TIRE & RUBBER CO.	2004 DOMINATOR SPORT A/T UP11XDJ1403	PASS 6276541
119	SSS 007	JIANGSU HANTA TIRE BIAS PLANT	2004 HANKOOK DYNAMIC RADIAL Z36 BJTYK3H0103	PASS 6276542
119	SSS 008	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR WRANGLER AT/S MDHKL RHV2403	PASS 6276543
119	SSS 009	HANKOOK TIRE KUMSAN PLANT	2004 HANKOOK DYNA PRO A/S 5MTYJNH2303	PASS 6276544
119	SSS 010	GENERAL TIRE CO.	2004 GENERAL AMERI* 550 AS ADHKCWA1802	PASS 6276545
119	SSS 011	BRIDGESTONE KURUME PLANT	2004 FIRESTONE STEELTEX RADIAL R4S EHD6DCM1303	PASS 6276546
119	SSS 012	CIA HULERA TORNEL S.A. DE C.V.	2004 DENMAN EXPRESS DXA 5F2FA42303	PASS 6276547
119	SSS 013	COOPER TIRE & RUBBER CO.	2004 MASTERCRAFT M528 3D3TFM35102	PASS 6276548
119	SSS 014	CONTINENTAL MATADOR TIRES S.R.	2004 MASTER MATADOR 6Y3TKLU32702	PASS 6276549
119	SSS 015	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR G159 UNISTEEL MC3TVABW2403	PASS 6276568
119	SSS 016	GOODYEAR DUNLOP TIRE N.A. LTD.	2004 REMINGTON R377 DA3T718W0903	PASS 6276569
119	SSS 017	HANGZHOU GENERAL RUBBER FACTORY	2004 WEST LAKE CR90 7DUBCK31403	PASS 6276571
119	SSS 018	SUMITOMO RUBBER IND. LTD.	2004 SUMITOMO ST 758 U23T3XCW0403	PASS 6276572
119	SSS 019	GENERAL TIRE & RUBBER CO.	2004 GENERAL AMERI-MSL A33T9TM3003	PASS 6276573
119	SSS 020	GOODYEAR DUNLOP TIRE N.A. LTD.	2004 DUNLOP SP 381 DA3TMA1W1903	PASS 6276574
119	SSS 021	SOUTH CHINA TIRE & RUBBER CO.	2004 WANLI S-3073 STEEL RADIAL 4HBA1303	PASS 6276575
119	SSS 022	KUMHO & CO. INC.	2004 KUMHO KLD 01 LONGMARK Y03TYF5M4202	PASS 6276576
119	SSS 024	BRIDGESTONE/FIRESTONE CANADA INC.	2004 FIRESTONE FIREHAWK INDY 500 VNT6503003	PASS 6276577

Note: The tire description usually includes an ID number. The tire ID number changes by production week and it is not a tire serial number. Tire ID numbers that are identical indicate that the tires were manufactured during the same week, not that they are the same tire.

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH MAY 2004
(CI NUMBER SYSTEM EXAMPLE: "CI-208-031220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2003)**

CI NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
CI-108-010831	Astex USA/HID conversion/Headlamp/Electrical dimensional marking req.	MI
CI-108-031205B	Santeca Electronics/2003 Thunder Beam HID conversion/Replaceable light source and ballasts may not comply with S7.7	MI
CI-218-030805	Strategic Sports BVI Ltd./2003 Zamp-S1/Penetration at ambient at low temperature	CT
CI-108-040101F	Global Premier LLC/HID Conversion/Replaceable light sources and ballasts may not comply with S7.7	MI

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

NONE

CAUSE:

CT Compliance Test

IN Inspection

CP Complaint

ID Part 574

MI Manufacturer Inquiry

MD Manufacturer Defect

**PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH MAY 2004
(PE NUMBER SYSTEM EXAMPLE: "PE-208-031220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2003)**

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-108-030602	United Marine Inc./2003 Trailer lamp assembly/Complaint relative to photometry	MI
PE-208-030501	Toyota/2003 Toyota Tacoma/Sled test-neck compression > 4000	IN
PE-116-040115	Star Brite Inc./2004 Star Brite/Hvy duty brake fluid/High temperature stability	CT
PE-213-040422	Century/2004 Graco/Century 1500 Ste child restraint/Exceeded chest G - 72.3 G's reqt: less than or equal to 60 G's	CT
PE-217-030801	Atwood Mobile Products/Emergency exit window/Push out window/Window retention	MI
PE-217-030819	Liberty Bus Inc./2003 Liberty Freedom/School bus/Positive door opening device < 90 degrees	CT
PE-221-030828	Amtran Corp./2003 Amtran IC3S5/Joint tensil strength less than 60%	CT
PE-222-030815	Liberty Bus Inc./2003 Liberty Freedom/Schoolbus/Passenger seat pulled out of floor	CT
PE-VAR-031120	Legendary Motorcars and Coachworks/2003 Lincoln Navigator/Various test failures (108, 111, 120, 205 and 217)	IN

PEs OPENED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-218-040430	NexL Sports Products/2004 NexL motorcycle helmet/Penetration at ambient at high temperature	CT

PEs CLOSED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE
PE-120-021227	Blue Bird Body Co./2002 School Bus/Tire inflation pressure/Closed by NHTSA 11/28/03
PE-225-031128	Accubuilt/2003 Accubuilt Bus under 4,536 KG/Not enough tether anchorages/Manufacturer's noncompliance report 12/10/2003
PE-304-030905	Structural Composites Ind./2003 StructuralComposites/CNG fuel container ruptured during bonfire test/Manufacturer's noncompliance report 5/20/2004
PE-575-031124	Goodyear Tire & Rubber Co./2003 Kelly-Springfield Mohave/Mfr. graded "A" our test resulted in grade "B" on concrete/Closed by NHTSA 3/15/2004

CAUSE:

CT Compliance Test

IN Inspection

CP Complaint

ID Part 574

MI Manufacturer Inquiry

MD Manufacturer Defect